



Transport  
Canada

Transports  
Canada

TP 6980E

*Issue 1/2006*



# feedback

Canadian Aviation Service Difficulty Reports

## table of contents

|   |              |
|---|--------------|
| HANGAR NOISE .....                                | inside cover |
| FIXED WING .....                                  | 1            |
| ENGINES .....                                     | 6            |
| AME SYMPOSIA NEWS .....                           | 8            |
| HEADS UP .....                                    | 9            |
| EQUIPMENT ADS .....                               | 10           |
| SUSPECTED UNAPPROVED PARTS .....                  | 10           |
| FAA SPECIAL AIRWORTHINESS BULLETINS (SAIBs) ..... | 11           |
| FAA UNAPPROVED PARTS NOTIFICATION (UPNs) .....    | 12           |
| SDR LIST .....                                    | 14           |

# hangar *noise*

*A Message for Aircraft Maintenance Personnel*

## Acquisition of Type Certification Holder Responsibilities to Viking Air Ltd. for the DHC-1 through DHC-7

Viking Air Limited of Sidney, British Columbia, has acquired the Type Certificates (TC) for seven de Havilland aircraft products from Bombardier Aerospace. These legacy aircraft include the DHC-1 Chipmunk (TC A-19), DHC-2 Beaver (TC A-22), DHC-3 Otter (TC A-27), DHC-4 Caribou (TC A-49), DHC-5 Buffalo (TC A-77 & A-124 Special Purpose), DHC-6 Twin Otter (TC A-82) and DHC-7 Dash 7 (TC A-120).




Since 1983, Viking Air has held the exclusive rights to spare parts manufacturing and distribution for the venerable DHC-2 Beaver and the DHC-3 Single Otter aircraft, and has been a major supplier to Bombardier on the DHC-6 Twin Otter and DASH Series product lines. Viking Air now provides a complete range of services for de Havilland's out of production aircraft, including spare part manufacturing and distribution, sales and customer service, technical support, and engineering services.

Historically, de Havilland has produced aircraft of unmatched quality and reputation, and the global demand for de Havilland products remains incredibly strong. This acquisition opens up a number of new market opportunities for Viking Air. This represents a major opportunity to establish a product oriented aerospace industry in Western Canada and enhance an already vibrant aviation presence in this region.

In all, approximately 3,500 de Havilland Canada aircraft were produced from 1947 to 1988, the largest fleet of aircraft produced in post war Canada. A large percentage of these aircraft are still in use today. The prototype DHC-2 Beaver, DHC-6 Twin Otter and DASH 7 are currently housed at the Canadian Aviation Museum in Ottawa, along with several other de Havilland Canada heritage aircraft.

Viking Air's infrastructure, professionalism and personnel have demonstrated to Transport Canada their commitment and support in accepting the responsibilities imposed by the acquisition of these Type Certificates.

 Viking Air is now responsible for the requirements of the Civil Aviation Regulations (CAR) 511, Approval of the Type Design of an Aeronautical Product. Viking Air will address all issues in regards to Continuing Airworthiness for the aircraft for which they now hold type design responsibilities. Transport Canada welcomes Viking Air Limited as a Canadian Type Certificate Holder of de Havilland aircraft, which have been part of Canadian history since 1946.

For more information or copies of **feedback** or other Civil Aviation publications, call 1 800 305-2059 or visit our Web site at [www.tc.gc.ca/civilaviation/certification](http://www.tc.gc.ca/civilaviation/certification).

To ensure continued delivery, send any address changes to:

Transport Canada, Civil Aviation Communications Centre (AARA), Place de Ville, Ottawa, ON, K1A 0N8.

© Copyright - Her Majesty the Queen in Right of Canada, as represented by the Minister of Transport (2006)

Permission is granted by the Department of Transport, Canada, to copy and/or reproduce the contents of this publication in whole or in part provided that full acknowledgement is given to the Department of Transport, Canada, and that the material be accurately reproduced. While use of this material has been authorized, the Department of Transport, Canada, shall not be responsible for the manner in which the information is presented, nor for any interpretations thereof.

The information in this publication may not be updated to reflect amendments made to original content. For up-to-date information, contact the Department of Transport, Canada.

The information in this publication is to be considered solely as a guide and should not be quoted as or considered to be a legal authority. It may become obsolete in whole or in part at any time without notice.

### Notice/Disclaimer:

Service Difficulty Reports (SDR) are normally published verbatim. Transport Canada assumes no responsibility for the accuracy or content of any of these reports. Only grammatical or spelling errors are corrected and content may be reduced as well as personal references deleted.


***Cette publication est aussi disponible en français.***

## fixed wing

AÉROSPATIALE ATR 42


### Electrical Harness Arcing

SDR # 20050427005



Shortly after aircraft departure, the No.2 AC generator went off-line. The aircraft returned to its point of departure for verification by maintenance personnel. Technicians replaced the generator control unit (GCU), which did not rectify the problem. Further investigation revealed that arcing had occurred between the AC electrical harnesses at the "D" flange location of the engine case.

*The arcing caused a noticeable portion of the engine case at the D flange location to be damaged. Short circuits in electrical systems constitute a serious fire hazard and also may cause the destruction of electrical wiring and damage to units of electrical equipment. Visual inspection of proper routing and clearances for electrical wiring harnesses are not always given the same attention as other system installations. This service difficulty is an example of the significance of wiring harness routing and clearance. ✖*




BEECH C90A

### Resistor Overheated

SDR # 20051216003


An overheated resistor, R145, was discovered at the top of the forward bulkhead behind the instrument panel during a routine inspection. The fluorescent light resistor, P/N 2K40D10, was scorched and had slightly burned the insulation located behind the glare shield.

A company fleet-wide campaign produced three (3) similar defects.



*Transport Canada (TC) recommends maintainers to carry out a detailed inspection of this area to ensure that adequate clearance between the secured resistor assembly and aircraft insulation is maintained.*

*The operator noted that resistor, P/N D25K10R, has been superseded by P/N 2K40D10. ✖*



BEECH 200

### Bulkhead Cracked


SDR # 20051208008

While troubleshooting a pressurization snag on the aircraft undergoing maintenance at an operator's facility, maintenance discovered a 3.5" long crack in a section of the bulkhead lower flange attached at the rear spar at FS 227. The crack was causing a major pressurization leak that could be felt outside of the aft spar box on the exterior of the aircraft. No specific repair instructions are provided in the maintenance manual for this damage.



Upon completion of repairs a pressurization test was completed and the aircraft returned to service.


*This defect underlines the importance of careful visual inspection when the aircraft is undergoing maintenance. ✖*





## BEECH 1900D


SDR # 20051129002

**Aileron Spring Fractured**

While taxiing the aircraft, the flight crew noticed a full left bias deflection in the aileron system. Maintenance discovered that one of the aileron/rudder interconnect springs had fractured near the end ring that provides connection to the bridle. This defect may have been induced during phase inspection requirements in removal of the springs during tensioning procedures. The tool marks from a set of pliers or other mechanical means during the removal process may have scored the spring, providing areas for stress risers to develop.



*The operator issued a supplemental inspection into their process control to avoid future occurrences of this defect. Maintainers should remain vigilant when inspecting this area and judiciously use the correct tool to prevent damage to aircraft hardware. ✖*




## BOEING 737

SDR # 20051128009


**Nose Gear Extension/Retraction Anomalies**

The subject aircraft had intermittent history associated with nose gear extension/retraction anomalies. The Pilot reported that the gear lever had to be cycled twice to get the nose gear to extend. A visual inspection was carried out with no obvious faults. The aircraft was ferried back to base with the nose gear selected down.



Upon arrival the transfer cylinder and lock actuator were replaced, along with the nose ski actuator, without successful rectification of the anomaly. The selector valve was then replaced and a test flight conducted, which verified positive operation. Selector valve, P/N 10-61213-1, appeared to have cured the snag. During troubleshooting it also appeared that greasing the points of the nose gear made a difference.

During a recent heavy check this issue was further investigated. Flex line, P/N BACH8A04NM0274T, is a Teflon flex line supplying hydraulic fluid to the nose gear ski actuator. This line was found kinked. It is believed that this finding also contributed to the extension/retraction anomalies by restricting the flow to the nose gear ski actuator.



The aircraft is being monitored as part of the reliability program review.

*During troubleshooting the operator noted that nose gear grease fittings were missing and has established an inspection of Main and Nose Landing Gear grease fitting throughout the fleet. It should be noted that some defects can be rectified with part replacement but further investigation and inspection is a prudent approach. Those hidden anomalies can lay dormant and eventually fail causing more down time and possible safety hazards. ✖*

**BOEING 737**


SDR # 20051222008

**Flap Fairing Attachment Bolt Migration**

During ground inspection it was discovered that the AFT attachment bolt of the No. 3 flap fairing had migrated inboard and punctured a hole through the composite fairing. The aircraft was removed from service for repairs.




Upon further investigation, three (3) of the fairing AFT attachment bolts were found without cotter pins installed, two nuts had backed off and the third had separated completely allowing the bolt to migrate. This aircraft had recently had a base visit during which the fairing was removed for access. An investigation is underway with the facility that performed the work.



*Human Factors concerns are still prevalent throughout the aviation community. Try to stay out of those elements that cause Human Factors issues to infuse themselves while carrying out your professional duties as an aviation technician. ✖*

**BOEING 767**


SDR # 20040920001

**Horizontal Stabilizer Trim Actuator - Severe Corrosion**

The horizontal stabilizer actuator assembly, P/N 251T4310-1, was removed from the airplane after maintenance personnel observed rusty grease on the ball screw. Following examination both bearings, P/N 105KS, (Ref: CMM 27-41-01, Item 95) and pinion (Item 100) were found heavily corroded inside the housing assembly, P/N 251T4324-1. The bearings were so corroded that they broke apart upon removal.


The SDR submitter also stated that water ingress is suspected to have occurred (water accumulation) in the housing assembly P/N 251T4324-1. Additionally, the web service difficulty reporting (WSDR) database contains a number of other past and more recent SDRs reporting similar corrosion problems on the horizontal stabilizer actuator.

*Transport Canada Civil Aviation (TCCA) reported this SDR to the FAA expressing our concerns about severe corrosion of the stabilizer trim actuator, and the possibility of reduced controllability of the aircraft. The FAA requested that Boeing make a Safety Determination on the effects of severe corrosion and the effect of the stabilizer trim actuator jamming and reduced controllability of the aircraft. ✖*




**BOMBARDIER CL600-2B19****Engine Pylon Formed Angles Cracked**

SDR # 20051208010



While replacing the engine pylon bolts as per Service Bulletin (SB) 601R-54-005, the AME working in the area noticed that both the left and right side formed angles inside the engine pylon at FS640, Stringer 10, were cracked. Both the left side angle, P/N 601-37003-81, and the right side angle, P/N 601-37003-82, were removed and replaced.




*As in this case, an astute technician also found another defect in the immediate area. Good work! ✂*

**CESSNA 152****Rear Rudder Bar Worn**


SDR #20051211002

During a 100-hour inspection of a Cessna 152, the rear rudder bar was found to have a hole worn through it on the co-pilot side.



The plastic centre console is attached to the rudder pedal covers with screws. If the screws are too long, they will wear into the rudder bar over time. This could eventually cause the rudder bar to fail causing the loss of rudder control.

This was the second identical finding on a similar airplane.



*Always ensure that correct parts are installed! ✂*

**CESSNA A185F****Serviceable Grease Fittings**

SDR # 20051004001

A Cessna 185 aircraft was on WIPAIRE(amphibious) floats, Model 3450A, and upon landing, the pilot noticed that the aircraft was pulling to the left. After inspection, the problem was found to be originating from the right front float wheel. The wheel was disassembled, and corrosion was discovered on the block nose gear swivel, P/N 21AD6318-005, and on the scissor, P/N 30A06000-024. The lower portion of the scissors was missing lubrication. The left wheel was inspected as a precaution, no defects were found.

*This is the time of year for maintenance to be carried out on amphibious floats. Serviceable grease fittings with routine grease schedules can prevent costly operational down-time. ✂*




## DE HAVILLAND DHC 8-200

SDR # 20050602005

**Excessive Elevator Control Travel**

An abnormal amount of elevator travel was observed during flight control range of travel checks. Maintenance discovered one upper elevator stop bumper assembly was missing and the other upper elevator stop bumper assembly split. No damage was noted to the surrounding structure.

Bumpers had been replaced 215 cycles earlier, and the elevator stop bumper assemblies were replaced in accordance with the Aircraft Maintenance Manual, AWL TR 2-20 and CF-2001-08.




Canadian Airworthiness Directive CF-2001-08R1 indicated that a DHC-8 aircraft experienced an elevator trim problem in flight, due to a broken or missing elevator stop bumper. Investigation revealed that failure of the elevator stop bumper could lead to an elevator over-travel and damage to the elevator trailing edge if it impacts the top portion of the rudder. The damaged elevator can then jam the spring tab, which could result in reduced controllability of the aircraft. A life limit was therefore introduced for the elevator stop bumpers and revised when in-service experience indicated that the elevator stop bumpers were deteriorating prior to the original life limit.

Transport Canada has received four (4) reports of deteriorating or missing elevator stop bumpers since the issuance of this Airworthiness Directive.

Stay vigilant during inspection of this area for deteriorating or missing elevator stop bumpers and report any reportable Service Difficulties as per CAR 591. ✖


## PIPER PA 28R200

SDR # 2005123004

**Wing Spar Cracked**

During scheduled maintenance, a wing main spar extrusion crack was discovered near the main landing gear sidestay support brackets on the left and right sides. The spar cracks run spanwise in the fillet radius and extend through the full thickness of the spar web. The longest crack is about 1.25" long.

These defects were initially detected through an inspection hole looking at forward side of spar web and later confirmed by removal of sidestay supports and inspection from aft side.



Maintainers should keep this in mind while inspecting this area; the sidestay brackets are the subject of Airworthiness Directive 97-01-01R1. The wing spar is a principal spanwise member in the structure of a wing and is subjected to even greater stresses during flight and landing. Cracks are thus more probable to occur at landing gear attachments on the rear spar. ✖

# engines

## GENERAL ELECTRIC LTD CF34-3B1 (CL600-2B19)

SDR # 20051128001

### High Pressure Compressor (HPC) Variable Geometric (VG) System Turnbuckles - Fractured

A CAR 573-accepted, European Aviation Safety Agency (EASA) 145 maintenance organization, performing maintenance on Canadian-operated engines has reported failures of three Stage 2 VG turnbuckles, affecting two engines operating in regular revenue service. The subject engines were last inspected by this AMO. The details of the failure were a separation of the VG shaft side turnbuckle rod end, with failure occurring in the threaded portion where it meets the jam nut on the turnbuckle assembly. The failure mode has been confirmed to be low cycle fatigue (LCF), resulting from a side (bending) load induced by interference of the turnbuckle assembly with the torque shaft clevis.

One of the two engines found with the broken turnbuckle condition experienced an in-flight shutdown (IFSD). The IFSD occurred because failure of both turnbuckles did not allow the HPC Stage 2 vanes to track properly.


The other engine was found with only one broken turnbuckle and thus did not result in an operational event. The VG system can work properly for some time on one turnbuckle, however if both turnbuckles fail, an IFSD can occur.

*The EASA-145 AMO (SDR submitter) has instituted specific shop procedures pending corrective action by the original equipment manufacturer (OEM). The first procedure is to inspect the Stage 2 VG turnbuckles for correct installation and replace any incorrectly installed VG turnbuckles that failed the inspection to ensure that interference will not occur.*

*The CF34 inlet guide vanes (IGV) and the first five stages of stator vanes are variable, and the main fuel control schedules their position as a function of the desired VG scheduling. The VG system has two turnbuckles for each of the 5 VG stages. Actual position of the variable geometry is transmitted through a feedback cable and the turnbuckles.*

*The engine type certificate holder (TCH) has worked closely with the foreign AMO and will soon issue a Service Bulletin (SB) addressing this problem. The TCH has reviewed the CF34-3 manuals and agree that a note within the manual may have been misinterpreted, which created the potential for the interference condition to exist. Other factors such as final rigging, position of the jam nut flats and safety wire orientation, were contributing factors in the reported VG stage 2 turnbuckle fractures. This condition is also possible on the VG system stage 3, however VG stage 2 is more critical due to turnbuckle length.*

*Pending corrective action by the TCH, Transport Canada Civil Aviation (TCCA) recommends that operators inspect, at the first opportunity, the VG turnbuckle rigging, the safety wire methods employed and a non-interference fit between the VG turnbuckle and the torque shaft clevis. ✖*



## HONEYWELL (GARRETT) TFE731 Series (Falcon 900)

SDR # 20051020003

### Main Fuel Pump Element

The SDR submitter reported that the fuel filter bypass indicators on the main fuel pump assembly are frequently indicating a bypass condition. However further examination revealed that the filters were clean. One of the fleet aircraft had numerous problems with the engine filter elements tripping the bypass indicator. Extensive maintenance action was carried out on 10 separate occasions over 294 flight hours to address fuel filter bypass indications that proved to be erroneous and unfounded. The fuel, fuel tanks, manifold screens, cannon plugs and differential pressure switches were examined/tested with no defects found.

The filters can be left in service for up to 600 hours, but the filter bypass indicators are tripping anywhere from 5 to 500 hours, with the average time being less than 100 hours. All the main fuel pump filter assemblies (3) on this recent event were also tested and found serviceable.



The engine OEM has now issued a service bulletin recommending a replacement filter element. The submitter stated that these problems are particularly frequent on the Falcon 900 and the HS 125 aircraft.


An SDR service history search revealed numerous reports on the subject part number P/N 897513-1, filter element. These occurrences with faulty and erratic bypass indications occurred during flight and on the ground. In numerous cases, the aircraft had to abort or delay take-off or cancel flights due to these problems.

Most of the previous SDRs reported these events (engine fuel annunciator light) occurring at high engine power settings (take-off roll). Transport Canada Civil Aviation recommends that owners and operators comply with Honeywell Service Bulletin TFE731-73-3149, that introduces a replacement filter element, P/N 897830-1. ✖

## ROLLS ROYCE AE3007A1 (Embraer 145)

SDR # 20051125004

### Turbine Over-Temperature



During flight, the crew reported an engine internal turbine temperature (ITT) over-temperature event of 1045 degrees Celsius for 36 seconds. This overheat condition resulted in an uncommanded in-flight shutdown (IFSD).

Engine disassembly at Rolls Royce revealed a number 1 (HPT) high pressure turbine blade failures, at the blade roots.

**Total Time Since New (TSN): 8 408 hrs**



Although technicians and flight crews take every precaution to prevent over-temperature of the engine, such events do occur. Often the cause of turbine over-temp is a malfunction of engine fuel control or a malfunction in the engine itself.

An SDR service history review revealed numerous reports on damaged turbines caused by exceeding the temperature limitations of the respective engines, especially during engine start-up. ✖

## ROLLS ROYCE BR700-715A1-30 (Boeing 717)

SDR # 20051007001

### HP Compressor Bearing Failed

During cruise flight at 33 000 thousand feet AGL, the auto-throttles began moving back and forth. The #1 engine appeared to be making a growling noise and losing power while the #2 engine was increasing power to compensate. Additionally, the #1 engine surged three to five times followed by a smell of smoke in the cabin. Engine oil pressure decayed to 2 or 3 psig and a visual alert (red box around the oil pressure indicator) was observed by the crew.

At this point, the pilot reduced the #1 engine to idle and shut off fuel to this engine. Fan speed (N1) and gas generator speed (N2) spun down normally and the aircraft made an uneventful landing at the nearest alternate airport.

Maintenance reported that the #1 low pressure turbine (LPT) rotated normally and no oil leaks were evident in the engine or exhaust area. The oil quantity was low but there was still oil remaining in the oil tank sight glass.

Following a more detailed examination by maintenance personnel, the engine was removed and routed to Rolls Royce facility for engine teardown and evaluation. Engine disassembly revealed failure of #3 bearing of the HP compressor.

The SDR database contains several SDRs related to compressor section distress. ✖

TELEDYNE CONTINENTAL MOTORS TCM 10-520-F (Cessna U206G)

SDR # 20051031003

**Engine Power Loss**

Shortly after recent engine overhaul (seven (7) hours previously), the flight crew reported engine difficulties to ground maintenance control. The engine was surging and sputtering, and the aircraft was barely able to maintain the present altitude of 2 500 feet. Nothing the pilot was doing rectified the problem. After confirming that the fuel and fuel pump troubleshooting made no difference, maintenance and operations personnel advised the pilot to land immediately at the nearby airfield.

Following an uneventful landing, maintenance engineers determined that the #6 cylinder had zero compression and also bent push rods. Upon removal of the defective cylinder, it was found that the exhaust valve had fractured and the valve stem proceeded to hammer itself into the valve seat, push rods and piston.

Serviceable engine parts were installed and the aircraft then departed for homebase. However, during approach, the engine began to run rough. Following a successful landing, maintenance personnel again discovered bent push rods but with no collateral damage to any cylinders or valves.

The engine was removed and sent back for warranty action. Root cause of exhaust valve failure has not yet been determined.

*The head of the exhaust valve is exposed to the heat of combustion during the combustion period. Any condition, which prevents the exhaust valve from seating properly for the required time will cause the valve to exceed the critical heat limits during periods of high power output. It is essential to always follow the engine manufacturer's specifications for valve clearances. Various methods are required for setting valves to obtain correct and consistent clearances. In all cases, follow the exact procedure prescribed by the engine manufacturer. ✖*

## AME **SYMPOSIA** news

### CONGRATULATIONS...

**...to the winners of our door prizes:**

**Alvin Lal** - Pacific AME symposium in Vancouver

**Matthew Shumilak** - Central AME symposium in Winnipeg

**Trevor Shpyth** - Western AME symposium in Calgary

## heads **UP**

### “Keeping Your Inlet Clean”

Inlet Barrier Filters (IBF)  
TSB Aviation Safety Information A0500023-1 (A05W0140)

The Transportation Safety Board (TSB) has published an Aviation Safety Information Letter (825-A05W0140) that endorses the use of Inlet Barrier Filters, (IBF) in preventing both erosion and foreign object damage (FOD). Below is a partial transcript of the information conveyed in this letter:

*Anecdotal evidence indicates that the installation of engine inlet barrier filters (IBFs), under supplemental type certificates (STCs), on certain models of light helicopters has reduced the incidence of compressor blade erosion and external FOD, and increased compressor life. Many operators have recognized the advantages of IBFs and have installed these filters on applicable models within their fleet. At the present time, there is no STC that permits IBFs to be installed in Bell 204 or Bell 205 airframes. However, there is a least one Bell 205 IBF STC currently in the certification process, with approval expected in the near future.*

*Turbine-powered helicopters are at risk of FOD and erosion induced compressor failure, and subsequent engine failure, if solid contaminants are ingested into the engine during operation. FOD and compressor blade erosion may occur when mud and other debris from foot wear is not removed from helicopter decks prior to engine start, and when helicopters land and depart from unprepared landing sites, where dust and loose ground material may be drawn into the engine air intake, without adequate air inlet filtration systems. The risk of compressor blade failure in turbine powered helicopters, such as what occurred in this incident, will be reduced by taking whatever design, maintenance and operational precautions are necessary to ensure that the airflow through the engine is free of all possible solid contamination in all conditions.*

*For safety, Transport Canada Civil Aviation reminds the importance of careful attention to any debris entering the inlet area of your engine and recommends the installation, where available, of either an original equipment manufactured (OEM) or aftermarket STC inlet barrier filter (IBF) on your helicopter be considered. ✕*

feedback feedback feedback

#### Notice/Disclaimer

“Service Difficulty Reports (SDRs) are normally published verbatim. Transport Canada assumes no responsibility for the accuracy or content of any of these reports. Only grammatical or spelling errors are corrected and content may be reduced as well as personal references deleted.”



## equipment **ADs**

Transport Canada (TC) endeavours to send copies of new airworthiness directives (ADs), which are applicable in Canada to the registered owners of the affected products. Equipment/appliance ADs are often only distributed to our regional offices because the owners of aircraft affected by this type of AD are not generally known.

The following new ADs on equipment have been received by TC in the last three months. AMEs and operators of the affected products are encouraged to obtain further information or a copy of the ADs from their regional TC office, their local TCC, their PMI, or from the Civil Aviation AD website at:

<http://www.tc.gc.ca/aviation/applications/cawis-swimn>

| Manufacturer        | Ad Number   | Origin | Description   |
|---------------------|-------------|--------|---|
| HAMILTON SUNDSTRAND | 2005-23-11  | US     | Remove compressor impeller assemblies from service.   |
| MICROTURBO          | F-2005-180  | FR     | Maintaining Airworthiness - No engines presently operating commercially within Canada although one engine is installed to an Amature Build aircraft Review and compliance is to be assessed by owner. |
| POLICE EQUIPMENT    | HB-2005-428 | SW     | POLICE EQUIPMENT EC135-AC62-POL - Prohibition of use / Modification / Release to service  |
| SCHON               | A-2005-004  | AS     | Hot Air Balloon Envelopes   |
| SHADIN              | 2005-25-08  | US     | Equipment AD - Shadin ADC-2000 air data computers (ADC), part numbers (P/N) 962830A-1-S-8, 962830A-2-S-8, 962830A-3-S-8, configurations B, C, and D   |
| VEGA                | F-2005-169  | FR     | Equipment/Furnishings - Strengthening of assemblies   |

## suspected Unapproved **PARTS** (SUPs)



There were no Service Difficulty Reports (SDRs) received between 1 October and 31 December 2005 that indicated any suspected unapproved parts.

In Canada, in accordance with Canadian Aviation Regulation (CAR) 591.0, SUPs should be reported indicating your suspicion of an unapproved part on a regular SDR form or on the Internet at: [www.tc.gc.ca/wsdrs](http://www.tc.gc.ca/wsdrs) ✕

# FAA Special Airworthiness Bulletins (SAIBs)

An SAIB is an information tool that alerts, educates, and makes recommendations to the general aviation community. It is non-regulatory information and guidance that does not meet the criteria for an Airworthiness Directive (AD).

<http://www.faa.gov/aircraft/safety/alerts/SAIB/>

| NUMBER     | MANUFACTURER   | MODEL/DESCRIPTION   | DATE       |
|------------|--|---|------------|
| SW-06-19   | Robinson Helicopter Company  | R44, R44 II   | 12/28/2005 |
| NM-06-18   | Gulfstream American  | G-73 12/23/2005   |            |
| CE-06-17   | Schweizer Aircraft Corporation                                       | Tow Hook Models 1D112-15 and 1D112-16   | 12/20/2005 |
| CE-06-16   | Aeromot-Industria Mecanico Metalurgica Ltda                          | AMT-100, AMT-100 (modified to AMT-200) AMT-200, AMT-200S, AMT-300                       | 12/16/2005 |
| SW-06-15   | Sikorsky Aircraft Corporation  | S-76 series rotorcraft  | 12/16/2005 |
| NE-06-03R1 | Schweizer Aircraft Corporation                                       | 269 series rotorcraft   | 12/15/2005 |
| NE-06-14   | Performance Variable e.K.  | Parachutes  | 12/12/2005 |
| NE-06-13   | Turboprop airplanes  | Using propellers with four or more blades   | 12/12/2005 |
| NE-06-12   | Rolls-Royce Corporation  | 250-C30R/3, -C30R/3M, -C47B, and -C47M engines  | 12/02/2005 |
| CE-06-11   | Sierra Hotel Aero, Inc. (North American Aviation, Ryan Aeronautical) | Navion (all models and all serial numbers)  | 11/29/2005 |
| CE-06-10   | deHavilland Inc.   | DHC-2 Mk. I, II, and III 11/18/2005   |            |
| CE-06-09   | Sukhoi   | SU-29 11/15/2005  |            |
| NE-06-08   | <b>corrected copy</b> Lycoming                                       | Four and six cylinder, dual magneto engines with rear mounted propeller governor drives | 11/09/2005 |
| CE-06-07   | Cirrus Design Corporation (CDC)                                      | SR20 and SR22   | 11/04/2005 |
| CE-06-06   | Aircraft   | Equipped with steel fuel tanks  | 10/27/2005 |
| CE-06-05   | NAS-649 series   | Turnbuckles   | 10/27/2005 |
| CE-06-04   | Aero Accessories, Inc. (Brand name Tempest)                          | Dry vacuum pumps (new production or overhauled)   | 10/18/2005 |
| NE-06-03   | <b>corrected copy</b> - Schweizer Aircraft Corporation               | 269 series rotorcraft   | 10/18/2005 |
| NE-06-02   | CFM International, S.A.  | CFM56-2, -3, & -5 engines   | 10/18/2005 |
| CE-06-01   | Garmin   | GTX 327, GTX 330, and GTX 330D transponders   | 10/14/2005 |

# **FAA Unapproved PARTs Notification (UPNs)**

Published by: FAA, AIR-140, P.O. Box 26460, Oklahoma City, OK 73125. UPNs are posted on the Internet at:  
<http://www.faa.gov/avr/sups/upn.cfm>

## **No. 2004-00167 issued December 15, 2005**

### **AFFECTED AIRCRAFT**

All aircraft.

### **PURPOSE**

The purpose of this notification is to advise all aircraft owners, operators, maintenance organizations, manufacturers, and parts suppliers and distributors regarding raw metal sold with altered material certification.

### **BACKGROUND**

Information received during a Federal Aviation Administration (FAA) suspected unapproved parts investigation revealed that M&M International Aerospace Metals, Inc. (M&M), located at 1382 West McNab Road, Fort Lauderdale, FL 33309, may have knowingly sold raw metal that was offered as meeting the applicable Mil Spec but did not. M&M sold the raw metal to various distributors, type certificate holders, production approval holders, experimental aircraft distributors, as well as a variety of military and commercial applications.

Evidence indicates that M&M may have deliberately altered material certifications in order to satisfy customer requirements when they knew that the material did not meet the full requirements. The following changes were found:

- § Specification numbers were added.
- § Quantities were changed.
- § Heat-treat certifications were altered.
- § Chemical analysis requirements were added.
- § Hardness test results were changed.
- § Names of required mills were changed to match purchase order requirements.

The Offices of the Inspector General for the Department of Transportation, Department of Defense, Department of Energy (DOE), National Aeronautics and Space Administration, and the FAA conducted an investigation. DOE and FAA performed tests on the materials and examined purchase orders; these tests revealed nonconformance with the purchase orders.

### **RECOMMENDATIONS**

Regulations require that type-certificated products conform to their type design. Aircraft owners, operators, maintenance organizations, manufacturers, and parts suppliers and distributors should inspect their records for raw metal purchased from M&M and examine those records for alterations. If material certifications are suspected of being altered, it is recommended that the original certificate supplier be contacted for a copy of the original certification, or independent tests be run for the original purchase order requirements. If the material is determined to be nonconforming, the stock – or parts made from the stock – should undergo an engineering analysis that is based on the material's location or use in its proposed application.

### **FURTHER INFORMATION**

Further information concerning this investigation and guidance regarding the above-referenced raw material can be obtained from the FAA Manufacturing Inspection District Office (MIDO) given below. The FAA would appreciate any information concerning the discovery of this material from any source, the means used to identify the source, any action allowing the material to remain in service, and any action taken to remove the material from service.

This notice originated from the FAA Orlando MIDO, 5950 Hazeltine National Drive, Suite 405, Orlando, FL 32822, telephone (407) 855-9050, fax (407) 438-1900; and was published through the FAA Suspected Unapproved Parts Program Office, AVS-20, telephone (703) 668-3720, fax (703) 481-3002.



## UPN's (cont'd)

**No. 2005-00157 issued December 16, 2005**

### **AFFECTED PRODUCTS**

Aircraft components and instruments that were approved for return to service by Gross Instrument Corp.

### **PURPOSE**

The purpose of this notification is to advise all aircraft owners, operators, manufacturers, maintenance organizations, and parts distributors regarding improper maintenance performed on aircraft components and instruments.

### **BACKGROUND**

Information received during a Federal Aviation Administration (FAA) suspected unapproved parts (SUP) investigation revealed that between January 2003 and September 2005, Gross Instrument Corp. (GIC), located at 125-12 Liberty Avenue, Richmond Hill, NY 11419, maintained and approved for return to service various aircraft components and instruments contrary to the regulations. GIC formerly held FAA Air Agency Certificate No. Q11R427K.

Evidence indicates that GIC approved components and instruments for return to service that were not maintained in total compliance with the manufacturer's maintenance manuals or other data acceptable to the FAA. GIC failed to accomplish specified inspections and tests, and/or lacked documentation for certain replacement parts. Discrepancies included (1) failure to perform required dimensional inspections, (2) use of test equipment that was not calibrated as required, and (3) failure to complete requisite steps of the repair and overhaul processes.

### **RECOMMENDATIONS**

Regulations require that type-certificated products conform to their type design. Aircraft owners, operators, maintenance organizations, and parts distributors should inspect their aircraft, aircraft records, and/or parts inventories for any aircraft components or instruments that were approved for return to service by GIC between January 2003 and September 2005.

If these components or instruments are found installed on aircraft, appropriate action should be taken. If components or instruments are found in existing inventory, it is recommended that they be segregated to prevent installation until their eligibility for installation is determined.


A partial list of components and instruments that may have been approved for return to service by GIC can be viewed at: <http://www.faa.gov/aircraft/safety/programs/sups/upn/2005/> under UPN # 2005-00157.

### **FURTHER INFORMATION**

Further information concerning this investigation and guidance regarding the above-referenced components and instruments can be obtained from the FAA Flight Standards District Office given below. In addition to the above recommendations, the FAA would appreciate any information concerning the discovery of the components or instruments from any source, the means used to identify the source, and the action taken to remove these components or instruments from service.

This notice originated from the New York Flight Standards District Office, 990 Stewart Avenue, Suite 630, Garden City, NY 11530, telephone (516) 228-8029, fax (516) 228-8827; and was published through the FAA Suspected Unapproved Parts Program Office, telephone (703) 668-3720, fax (703) 481-3002.

# service difficulty reports



Received by Transport Canada from  
1 October 2005 to 31 December 2005

MAKE/MODEL JASC PART NAME PART NO. PART CONDITION SDR NO. RGN

## aircraft

### AERO COMMANDER

|     |      |                    |            |         |             |     |
|-----|------|--------------------|------------|---------|-------------|-----|
| 690 | 2750 | UPPER BRACKET ASSY | 510003357  | CRACKED | 20051209005 | PNR |
| 690 | 5210 | ANGLE              | 2330270501 | CRACKED | 20051209006 | PNR |

### AEROSPATIALE

|            |      |                    |                |                 |             |     |
|------------|------|--------------------|----------------|-----------------|-------------|-----|
| AS 332L    | 0000 | FLAP HINGE BUSHING | 330A33316620   | WORN/CRACKED    | 20051123003 | ATL |
| AS 332L    | 6310 | COUPLING SHAFT     | 19E2268A       | CRACKED         | 20051017013 | ATL |
| AS 350B    | 7931 | TRANSMITTER        | 704A37642043   | UNSERVICEABLE   | 20051128012 | QUE |
| AS 350B2   | 2913 | HYDRAULIC PUMP     | 704A34310006   | SPLINES WORN    | 3 SDRs      | VAR |
| AS 350B2   | 6210 | BEARING            | 704A33633211   | DELAMINATION    | 20051125010 | PAC |
| AS 350B2   | 6210 | M/R BLADE          | 355A11002009   | CRACKED         | 20051115004 | PNR |
| AS 350B3   | 6730 | SERVO              | SC5083         | PISTON BENT     | 20051018005 | PNR |
| AS 350BA   | 0000 | ACCUMULATOR        | 366A541088     | CRACKS          | 20051208007 | ONT |
| AS 350BA   | 0000 | MAIN ROTOR SERVO   | AC67244        | SLOW RETRACTION | 20051220006 | QUE |
| AS 350BA   | 2435 | BRUSH              | 150SG100920XL2 | HALF LIFE       | 20051017012 | PNR |
| AS 350BA   | 2910 | HYD CUT-OFF SWITCH | MS2771923      | INTERMITTENT    | 20051012011 | PAC |
| AS 350BA   | 6220 | SPHERICAL STOP     | 704A33633208   | DELAMINATED     | 20051003014 | QUE |
| AS 350BA   | 6410 | TAIL ROTOR BLADES  | 355A12004008   | CRACKED         | 20051003013 | ONT |
| AS 350BA   | 6420 | BUSHING            |                | CRACKED         | 20051107001 | PNR |
| AS 350D    | 0000 | PIPE               | 350A72100509   | U/S             | 20051209002 | PNR |
| ATR 42 300 | 2421 | NO.2 AC GENERATOR  | 200322         | NO OUTPUT       | 2 SDRs      | ONT |
| ATR 42 300 | 2434 | HALL EFFECT SENSOR |                | FAILED          | 20051017001 | ONT |

### AIRBUS

|          |      |                       |             |                     |             |     |
|----------|------|-----------------------|-------------|---------------------|-------------|-----|
| A310 304 | 2751 | FLAP ASSEMBLY         |             | FAULTY              | 20051130001 | QUE |
| A319 112 | 5347 | CAPT SEAT ASSEMBLY    | TAAI233PE01 | WON'T LOCK IN PLACE | 20051117003 | ONT |
| A319 114 | 2572 | VENT EXTRACT FAN      | EVT3454H    | BURNED              | 20051206002 | QUE |
| A330 243 | 3220 | NSE WHL STR SEL VALVE | C24780003   | UNRELIABLE          | 20051202005 | QUE |
| A330 342 | 3231 | ACTUATOR FREE FALL    | AR03404     | INOPERATIVE         | 20051104018 | QUE |
| A330 343 | 3201 | THS ACTUATOR          | 47172       | WRONG PART          | 20051101004 | QUE |
| A330 343 | 3244 | #6 MAIN WHEEL TIRE    | 300828      | BLOWN               | 20051208001 | QUE |

### BAE - UK

|      |      |                  |           |              |             |     |
|------|------|------------------|-----------|--------------|-------------|-----|
| 3112 | 2424 | GEN CONTROL UNIT | 51539002B | FAILED       | 20051214001 | PNR |
| 3112 | 2434 | GENERATOR        | 230790069 | SEPARATED    | 20051011005 | PNR |
| 3112 | 2435 | BUSHERS          | 230791281 | WIRES-FRAYED | 20051003009 | PNR |

### BAE - USA

|              |      |                       |               |              |             |     |
|--------------|------|-----------------------|---------------|--------------|-------------|-----|
| BAE 125 800A | 2751 | O/B MICRO SWT BRACKET | 1407000130001 | BROKEN       | 20051130010 | ONT |
| BAE 125 800A | 5280 | STRUT ASSY MICRO SWT  | 25NF24771     | BROKEN WIRES | 20051130009 | ONT |

### BEECH

|       |      |                        |             |                 |             |     |
|-------|------|------------------------|-------------|-----------------|-------------|-----|
| 100   | 3213 | MLG TORQUE LINKS       | 508103237   | CRACKED         | 20051109004 | PAC |
| 100   | 3297 | WIRE                   | G13A22      | FELL OFF        | 20051202001 | PNR |
| 1900D | 0000 | SPRING                 | 1295240051  | FRACTURED       | 20051129002 | ONT |
| 1900D | 3260 | UPLOCK SWITCH          |             | INTERMITTENT    | 2 SDRs      | VAR |
| 200   | 5345 | DUAL AFT BODY STRAKES  |             | RIVETS THROUGH  | 20051208009 | ONT |
| 200   | 3245 | GOODYEAR TUBES         | 302039402   | CUT             | 20051220008 | PAC |
| 200   | 5630 | EMERG EXIT WINDOW      | 1014301833  | CRACKED & DELAM | 20051209001 | ONT |
| 200   | 5411 | BULKHEAD LWR FLANGE    |             | R4ACKS          | 20051208008 | ONT |
| 200   | 2130 | PRESS CONTROL          | 13034611    | U/S             | 20051021001 | PAC |
| 200   | 3230 | ACTUATOR               | ADI79990033 | LEAK            | 20051013009 | PNR |
| 200   | 3233 | SWIVEL                 | 9981004311  | BROKEN LINK     | 20051114007 | NCR |
| 200   | 3250 | NOSE STEERING LINK     | 50820189    | BROKEN IN HALF  | 20051017002 | NCR |
| 200   | 5610 | HEATED WINDSHIELD      | 10138402521 | SHATTERED       | 3           | VAR |
| 350   | 0000 | HOSE ASSY. (BLEED AIR) | 1013800159  | BURST           | 20051213006 | QUE |
| 99    | 1000 | NUT                    | 817911018   | BELOW STANDARD  | 20051122001 | ATL |
| A100  | 0000 | BULKHEAD / INTRCOSTAL  |             | CHAFED/CRACKED  | 20051206004 | ONT |
| A100  | 2422 | RELAY                  |             | OVERHEAT        | 20051122003 | QUE |
| A100  | 2424 | RESISTOR               | EA85098     | OPEN CIRCUIT    | 20051107004 | ATL |
| A100  | 5312 | BULKHEAD/INTERCOSTAL   |             | CHAFED/CRACKED  | 3 SDRs      | ONT |
| A100  | 5315 | BEAM                   | 504200337   | CRACKED         | 20051024007 | ONT |
| B100  | 2612 | FIRE DETECTION         | 30215B      | FAILED          | 20051004006 | QUE |
| B100  | 2721 | RUDDER TRIM TAB        | 96630000335 | DISBONDED       | 20051019004 | PAC |
| B100  | 3220 | BALLET ASSY.           | 50820042601 | BROKEN          | 20051025007 | PAC |
| B100  | 3310 | LIGHT PANEL            |             | BURNT           | 20051202003 | QUE |
| B100  | 5313 | STRINGER               |             | CRACKED         | 20051109002 | PAC |
| B200  | 3010 | WING DE-ICE BOOT       | SMR504108   | TORN LOOSE      | 20051116003 | PNR |
| B200  | 3230 | MOTOR                  | 481         | FAILED          | 20051003007 | PNR |
| B200  | 3233 | ACTUATOR               | 11238002221 | IND. FAILER     | 20051206010 | PNR |
| B200  | 5312 | AFT BULKHEAD           | 9744001967  | CRACKED         | 20051116005 | PNR |
| B200  | 5330 | WEB SKIN               | 9744001967  | CRACKED         | 20051103004 | PNR |
| B200C | 3233 | ACTUATOR               | 99810057651 | FAILED          | 20051215001 | ONT |

MAKE/MODEL JASC PART NAME PART NO. PART CONDITION CTRL NO. RGN

|      |      |                     |              |                |             |     |
|------|------|---------------------|--------------|----------------|-------------|-----|
| B300 | 0000 | SPAR ASSY L/H       | 10111007315  | BOLTS CORRODED | 20051222004 | ATL |
| B300 | 5210 | ANGLE               | 504300431329 | CRACKED        | 20051202008 | PAC |
| B300 | 5610 | PILOTS'S WINDSHIELD | 10138402515  | PANE FRACTURED | 20051003002 | ONT |
| C90  | 2731 | ELEV TAB ACTUATOR   | 50524161606  | OVERHAULED     | 20051027007 | ATL |
| C90A | 0000 | RESISTOR            | 2K40D10      | OVERHEATED     | 4 SDRs      | ONT |

### BELL TEXTRON - CAN

|        |      |                         |                |                   |             |     |
|--------|------|-------------------------|----------------|-------------------|-------------|-----|
| 206B   | 0000 | T/R BLADE               | 206016201131   | SLEEVE MOVMENT    | 20051220011 | PAC |
| 206B   | 5342 | STABILIZER              | 20602011900    | CRACKED           | 20051017008 | QUE |
| 206B   | 6220 | STATIC STOP             | 206011160101   | CRACKED           | 20051205008 | QUE |
| 206B   | 7323 | GOVERNOR                | 252476914      | SURGING           | 20051017007 | QUE |
| 206B 1 | 6320 | PLANETARY GEAR          | 206040010103   | UNSUITABLE        | 20051027008 | QUE |
| 206L   | 5244 | HINGE                   | 206033111023   | BROKEN            | 20051012007 | QUE |
| 206L   | 5302 | TAIL BOOM               | 206033001003FM | CRACKED           | 20051202002 | ONT |
| 206L 1 | 2432 | CONTACTOR               | SM20ACD200A21  | BURNED            | 20051004004 | ONT |
| 206L 1 | 5302 | FITTING                 | 206031403005   | CRACKED           | 20051005004 | NCR |
| 206L 1 | 5310 | TUNNEL WEB              | 206333110      | CRACKED           | 20051122002 | PNR |
| 206L 1 | 6330 | RESTRAINT               | 206033506101   | DELAMINATED       | 20051018006 | PAC |
| 206L 4 | 5530 | VERTICAL STABILIZER     |                | SKINS DAMAGED     | 20051220003 | QUE |
| 407    | 0000 | FREEWHEELING CLUCH ASSY |                | CRACKS            | 20051223004 | QUE |
| 407    | 0000 | SEAL                    | 209340265103   | LOOSE             | 20051223002 | QUE |
| 407    | 5530 | VERTICAL STABILIZER     |                | SKINS DAMAGED     | 20051220002 | QUE |
| 407    | 5430 | SKIN                    | 206033003161   | CRACKED           | 20051208006 | ATL |
| 412EP  | 3212 | TEE FITTING             | 412073855101   | WRONGLY INSTALLED | 20051117002 | QUE |
| 412EP  | 6320 | SUN GEAR                | 205040229003   | WRONG MATERIAL    | 20051101002 | QUE |
| 430    | 2820 | FUEL CHECK VALVE        | 222366687101   | DAMAGED           | 20051109003 | QUE |
| 430    | 6720 | T/R CONTROL TUBE        |                | CHAFED            | 2 SDRs      | QUE |

### BELL TEXTRON - USA

|        |      |                    |              |               |             |     |
|--------|------|--------------------|--------------|---------------|-------------|-----|
| 205A 1 | 3270 | FORWARD CROSS TUBE | 212321103    | CRACKED       | 20051001001 | PNR |
| 212    | 5302 | PANEL ASSY, L/H    | R05032813041 | DEBONDED      | 20051006011 | PNR |
| 212    | 6320 | BEARING            | 2SS9         | UNSERVICEABLE | 20051124003 | PAC |

### BELLANCA

|       |      |            |       |          |             |     |
|-------|------|------------|-------|----------|-------------|-----|
| 8GCB# | 8520 | CRANKSHAFT | 74965 | CORRODED | 20051205007 | PNR |
|-------|------|------------|-------|----------|-------------|-----|

### BOEING

|          |      |                              |                 |                 |              |     |
|----------|------|------------------------------|-----------------|-----------------|--------------|-----|
| 727 225  | 3240 | BOLT                         | BACB30MT10HT13  | SHEARED         | 20051027004  | PAC |
| 737 275C | 0000 | TEFLON HYD. FLEX LINE        | BACB8A04NM0274T | KINKED          | 20051128009  | PNR |
| 737 275C | 4130 | CARGO G NET FITTING          |                 | CORRODED        | 20051101008  | PNR |
| 737 275C | 5260 | AIRSTAIR UPPER HINGE FITTING |                 | CORRODED        | 20051101009  | PNR |
| 737 522  | 1400 | CLAMP                        |                 | CONTAMINATION   | 20051125005  | ATL |
| 737 522  | 2700 | WIRE                         | W32200518       | SHORTED TO GND  | 20051123009  | ATL |
| 737 522  | 2780 | RELAY                        | R123            | FAULTY          | 20051024003  | ATL |
| 737 522  | 3220 | CIRCUIT CARD                 | 1061226216      | FAULTY          | 20051024002  | ATL |
| 737 522  | 5350 | NWHEEL STEERING CABLE        | BACC2C3D00625EG | MISRIGGED       | 20051229001  | ATL |
| 737 522  | 5730 | SCREW                        | BACB30NN4K12    | STRIPPED        | 20051003001  | ATL |
| 737 522  | 7830 | THRUST REVERSER              |                 | STUCK           | 20051024006  | ATL |
| 737 529  | 2750 | BELLCRANK                    | 65C308461       | CORRODED        | 20051007003  | ATL |
| 737 76N  | 2330 | VIDEO DISPLAY UNIT           | 50401100003     | SMOKE           | 20051026002  | PNR |
| 737 7CT  | 0000 | TURBINE ROTOR ASSY           | 38403031        | CRACKS          | 20051124009  | PNR |
| 737 7CT  | 2330 | VIDEO DISPLAY UNIT           | 50401100003     | BURNT SMELL     | 2 SDRs       | PNR |
| 737 7CT  | 3230 | GND SPLR INTERLOCK VAL       | 38805           | SERVICEABLE     | 20051213008  | PNR |
| 737 8Q8  | 2700 | BOLT                         | BACB30LE8DK83   | MIGRATED        | 20051222008  | ONT |
| 757 258  | 0000 | TERMINAL                     | 35108           | DISCOLOURED     | 20051021003  | PAC |
| 757 258  | 2910 | EDP                          | 35088066        | HYDRAULIC LOSS  | 20051024005  | PAC |
| 757 28A  | 0000 | FUEL FLOW GOVERNOR           | FFG052AC        | UNSERVICEABLE   | 20051229002  | NCR |
| 767 375  | 0000 | EQUIP. COOL FAN              | 732591A         | SEIZED          | 200511221006 | QUE |
| 767 375  | 5241 | DOOR STRICKER                | AR47013         | BURNT           | 20051031002  | QUE |
| 767 38E  | 0000 | HF RADIOS                    |                 | OVERHEAT        | 20051110002  | QUE |
| 767 38E  | 2530 | COFFEE MAKER                 | 3510004403      | BURNED          | 20051206001  | QUE |
| 767 38E  | 2530 | MID GAL COFFEE MAKER         | 4110001145      | INSUL'N BURNED. | 20051125007  | QUE |

### BOMBARDIER

|                    |      |                        |               |                  |             |     |
|--------------------|------|------------------------|---------------|------------------|-------------|-----|
| BD 100 1A10        | 2910 | LH PRESS MANIFOLD LINE | 1005354174003 | UNKNOWN          | 20051026004 | NCR |
| BD 700 1A10        | 3244 | MLG TIRE               | 382K032       | BLOWN            | 20051213002 | QUE |
| CL600 2B19 (RJ100) | 0000 | COPILOT WINDSHIELD     |               | CRACKED          | 20051117001 | QUE |
| CL600 2B19 (RJ100) | 2400 | CONTACTOR              |               | BURNT            | 20051222001 | NCR |
| CL600 2B19 (RJ100) | 2400 | RELAY                  | D1822A        | OVERHEATED       | 20051212001 | NCR |
| CL600 2B19 (RJ100) | 2400 | RELAY/CONTACTOR        |               | BURNT            | 20051011001 | QUE |
| CL600 2B19 (RJ100) | 3230 | NLG SYSTEM             | 16040         | TBD              | 20051011003 | QUE |
| CL600 2B19 (RJ100) | 3260 | NOSE GEAR              |               | FOD              | 20051130007 | PAC |
| CL600 2B19 (RJ100) | 4920 | APU                    | 5490000       | FAILED           | 20051129003 | ATL |
| CL600 2B19 (RJ100) | 5240 | FITTING ASSY - SLIDE   | 601R38593     | CRACKED/CORRODED | 20051206003 | ATL |
| CL600 2B19 (RJ100) | 5312 | AFT PRESS. BULKHEAD    |               | CRACKED          | 2 SDRs      | QUE |
| CL600 2B19 (RJ100) | 5400 | TENSION BOLT           | NAS6204L11    | SHEARED          | 20051013003 | ATL |

| MAKE/MODEL               | JASC | PART NAME                  | PART NO.      | PART CONDITION  | SDR NO.     | RGN | MAKE/MODEL                   | JASC | PART NAME                     | PART NO.       | PART CONDITION     | SDR NO.     | RGN |
|--------------------------|------|----------------------------|---------------|-----------------|-------------|-----|------------------------------|------|-------------------------------|----------------|--------------------|-------------|-----|
| CL600 2B19 (R/J100)      | 5420 | ANGLE (FORMED)             | 601370038182  | CRACKED         | 20051208010 | ATL | DHC 7 102                    | 5600 | WINDSHIELD                    | 06422          | CRACKED            | 20051027006 | ONT |
| CL600 2B19 (R/J100)      | 5610 | CAPTAIN SIDE WINDOW        | 601R3303311   | SHATTERED       | 2 SDRs      | VAR | DHC 8 100                    | 2922 | FLEX HOSE ASSEMBLY            | DSC252B40124   | FRACTURED          | 20051115001 | NCR |
| CL600 2B19 (R/J100)      | 5754 | LEADING EDGE SKIN          | 60012112      | DAMAGED         | 20051104017 | PAC | DHC 8 100                    | 3246 | MLG WHEEL                     | 314353         | BROKEN             | 20051012001 | NCR |
| CL600 2B19 (R/J100)      | 5754 | PITOT HEAD                 | 6670658       | BENT            | 20051228003 | PAC | DHC 8 102                    | 2700 | SPOILER ACTUATOR              | A44700009      | CRACKED            | 20051208011 | ATL |
| CL600 2B19 (R/J100)      | 7600 | CONTROL CABLE              | 1600980005    | UNKNOWN         | 20051012006 | ATL | DHC 8 102                    | 2916 | RELIEF VALVE ASSEMBLY         | 3811208102     | STICKING           | 20051116002 | ATL |
| CL600 2B19 (R/J100)      | 7800 |                            |               | DETACHED        | 20051019000 | QUE | DHC 8 102                    | 3230 | HYDRAULIC LINE                | 82970410119    | CHAFED             | 20051214003 | ATL |
| CL600 2B19 (R/J440)      | 7200 | RH ENGINE                  |               | BLADES DAMAGE   | 20051222003 | NCR | DHC 8 102                    | 5210 | ELECTRIC DOOR LATCH           | 02T10021       | NORMAL             | 20051219003 | PAC |
| CL600 2B19 (R/J440)      | 7320 | R/H MAIN FUEL CONTROL      | UNKNOWN       | UNKNOWN         | 20051222002 | NCR | DHC 8 102                    | 0000 | SERVO WIRE BUNDLE             | 2210P22210P1   | SHORTED            | 2 SDRs      | PNR |
| CL600 2B19 (R/J700)      | 2740 | HOR STAB MCU               |               | UNKNOWN         | 20051019001 | QUE | DHC 8 300                    | 3220 | FLEXIBLE HOSE ASSY            | DSC252B40124   | RUPTURED           | 20051205001 | NCR |
| CL600 2B19 (R/J700)      | 3252 | SHIMMY DAMPER              | 498003        | EF50182         | 20051028001 | NCR | DHC 8 300                    | 3230 | ALT DOWN IND. CABLE           | 82455025303    | DIODE FAILURE      | 20051221005 | NCR |
| CL600 2B19 (R/J700)      | 5280 | LH INBOARD MLG DOOR        | CC67010520951 | MISSING         | 20051022003 | NCR | DHC 8 311                    | 3050 | RADOME                        | 4426X212       | DAMAGED            | 20051104016 | PAC |
| CL600 2B19 (R/J700)      | 5280 | LH MLG DOOR                |               |                 | 20051003018 | NCR | DHC 8 311                    | 3230 | VALVE                         | 574205A        |                    | 20051103011 | PAC |
| CL600 2B19 (R/J700)      | 5610 | COCKPIT SIDE WINDOW        |               | CRACKED         | 4 SDRs      | VAR | DHC 8 400                    | 2430 | BUS BAR                       | 697070212      | SHORTED            | 20051102005 | NCR |
| CL600 2D15               | 3252 | NUT - APEX                 | 412321        | LOOSE           | 20051020002 | ATL | DHC 8 400                    | 2742 | PITCH TRIM ACTUATOR           | 03994001011    | FAILED             | 20051114001 | NCR |
| <b>CANADAIR</b>          |      |                            |               |                 |             |     | DHC 8 400                    | 3200 | PITCH TRIM UNIT               | 5114904        | SEPARATED          | 20051026001 | NCR |
| CL215 1A10               | 3222 | STRUT SUB ASSY. LWR        | 1603012       | FISSURE         | 20051014001 | QUE | DHC 8 400                    | 3220 | NLG CTR WOVW2 HARNESS         | 471515         | SENSOR U/S         | 3 SDRs      | NCR |
| CL215 1A10               | 5311 | FRAME ASSY                 | 21531062882   | NEW             | 20051228001 | ATL | DHC 8 400                    | 3220 | NLG DR SOLENOID SEQ VLV       | 483023         | FAULTY             | 2 SDRs      | NCR |
| CL215 1A10               | 5312 | FRWD CABIN BLKHD           | NA            | CRACKED         | 20051102008 | NCR | DHC 8 400                    | 3246 | CONE & SEAL ASSY              | LM29700LA902A1 | BROKEN             | 20051031001 | NCR |
| CL215 1A10               | 5700 | ANGLE                      | 2153003126    | CRACKED         | 20051004009 | PNR | DHC 8 400                    | 5600 | CO-PILOT'S WINDSHIELD         | 80260008       | CRACKED            | 20051102004 | NCR |
| CL215 6B11 (CL415)       | 2810 | FUEL CELL                  |               | UNKNOWN         | 20051102006 | QUE | DHC 8 400                    | 5711 | FRONT SPAR, OUTER CTR         | 85713502       | CRACKED            | 20051107003 | NCR |
| CL600 2A12 (601)         | 7312 | FUEL HEATER                | 5023T57P02    | CRACKED         | 20051121001 | QUE | DHC 8 400                    | 6120 | PROP CONTROL UNIT             |                | FAILURE            | 20051115003 | NCR |
| CL600 2B16 (604)         | 3230 | PIN, UPLOCK                | 200811620     | BROKEN          | 20051005006 | QUE | DHC 8 400                    | 7314 | ENG DRIVEN PUMP               | 6617302        | SHAFT SHEARED      | 20051011011 | NCR |
| <b>CESSNA</b>            |      |                            |               |                 |             |     | DHC 8 400                    | 7323 | OVERSPEED GOVERNOR            | 697072003      | LOOSE BOLTS        | 20051124001 | NCR |
| 150M                     | 2421 | ALTERNATOR                 | 633661        | SHAFT BROKEN    | 20051222005 | ONT | DHC 8 400                    | 7930 | LOW OIL PRESSURE SWITCH       |                | DEFECTIVE          | 20051017002 | NCR |
| 152                      | 2421 | ALTERNATOR                 |               | UNSERVICEABLE   | 20051130002 | PNR | <b>DIAMOND - CANADA</b>      |      |                               |                |                    |             |     |
| 152                      | 2510 | RUDDER BAR                 | 04115262      | WORN            | 20051211002 | PNR | DA 20 C1                     | 2400 | GROMMET                       | RB215          | WORN               | 20051024004 | ATL |
| 152                      | 5711 | BRACKET                    | 04320049      | CRACKED         | 20051129004 | QUE | DA 20 C1                     | 2750 | SPLINNED SEAL                 |                | LOOSE              | 20051215002 | ATL |
| 172E                     | 0000 | FRONT SPAR ASSEMBLY        | 053200198     | CRACKED         | 20051221007 | ONT | DA 20 C1                     | 5551 | WASHER                        | MS932013       | WRONG SIZE         | 20051102001 | ATL |
| 172L                     | 5730 | INBOARD AFT LWR SKIN       | 052300710     | CRACKED         | 20051011007 | PAC | <b>DORNIER</b>               |      |                               |                |                    |             |     |
| 172M                     | 0000 | ENGINE MOUNT               | 05510171      | CRACKED         | 20051220004 | PAC | 328 100                      | 0000 | R/H HORIZ STAB BOOT           | 29S7D524008    | UNKNOWN            | 20051223016 | PAC |
| 172M                     | 2820 | FUEL TUBE                  | 05011874      | WORN            | 20051202006 | PAC | <b>DOUGLAS</b>               |      |                               |                |                    |             |     |
| 172M                     | 3246 | WHEEL HUB                  | D30256        | CRACKED         | 20051125009 | PAC | DC3CS1C3G                    | 8550 | BULKHEAD FITTING              | AN8324D        | CRACKED            | 20051128010 | PNR |
| 172M                     | 7120 | ENGINE MOUNT               | 05510171      | BROKEN          | 20051004005 | QUE | <b>EMBRAER</b>               |      |                               |                |                    |             |     |
| 172M                     | 8011 | STARTER DRIVE GEAR         |               | FAILED          | 20051114005 | PNR | ERJ 170 200LR                | 2560 | ESCAPE SLIDE                  | 4A40302        | PARTIALLY DEPLOYED | 20051101007 | QUE |
| 172M                     | 2430 | ALTERNATOR CTRL UNIT       | VR515G        | SHORTED         | 20051125006 | ONT | ERJ 170 200LR                | 2565 | DOOR SLIDE HANDLE             |                | U/S                | 20051125001 | QUE |
| 172P                     | 5753 | LEADING EDGE CTR RIB       | 0523914       | CRACKED         | 20051102007 | PAC | <b>EUROCOPTER DEUTCHLAND</b> |      |                               |                |                    |             |     |
| 172P                     | 7414 | BEARING                    | M3006         | STIFF           | 20051123002 | PAC | BO105 S CDN BS 40000         |      | DIMMING MODULE                | 27E462         | CORRODED           | 20051205004 | ONT |
| 182P                     | 0000 | ROD                        | 07436082      | BROKEN          | 20051220005 | QUE | <b>EUROCOPTER FRANCE</b>     |      |                               |                |                    |             |     |
| 208                      | 5521 | SPAR ASSY ELEVATOR TIP     | 26340141      | CORRODED        | 20051124002 | PAC | EC 120 B                     | 2910 | O-RING                        | 809510         | DEFORMED           | 20051208004 | ONT |
| 208B                     | 3414 | AIR SPEED INDICATOR        | C6610640237   | INDICATOR STUCK | 20051123004 | PNR | <b>FAIRCHILD</b>             |      |                               |                |                    |             |     |
| 310R                     | 3213 | BELL CRANK GEAR IDLER      | 08411066      | CRACKED         | 20051201001 | QUE | SA227AC                      | 2100 | COOLING TURBINE               | 20475546       | LEAKY              | 20051013006 | ONT |
| 337C                     | 3230 | CIRCUIT BREAKER            | S13605        | ARCHED/BURNT    | 20051108010 | PNR | SA227CC                      | 2435 | STARTER GENERATOR             | 23079010       | INTERMITTANT       | 20051213007 | ONT |
| 421B                     | 0000 | BELL CRANK                 | 08411066      | BROKEN          | 20051220007 | ONT | <b>FOKKER - ND</b>           |      |                               |                |                    |             |     |
| 421B                     | 8011 | CONTACT                    | 231697        | WELDED/MELTED   | 20051026007 | PNR | F28 MK1000                   | 5240 | SERVICES EMERG DR             |                | CRACKS             | 20051012009 | PNR |
| 550                      | 2701 | CHANNELS                   | 5565096       | CRACKED/BROKEN  | 20051011008 | PAC | <b>FOUND BROS</b>            |      |                               |                |                    |             |     |
| 550                      | 3241 | CAP ASSY                   | 15802101      | FAILED          | 20051220001 | ONT | FBA 2C1                      | 3246 | FLY-WIRE ATTACH LUG           | F343240        | FAILED             | 20051110003 | NCR |
| 550                      | 7830 | LONGERON TAB               | 202001551     | CRACKED         | 20051011010 | PAC | <b>GIPPSLAND AERONAUTIC</b>  |      |                               |                |                    |             |     |
| 560                      | 2120 | SEGMENT ASSEMBLY           | 651532629     | COLLAPSED       | 20051007005 | PNR | GA 8                         | 0000 | TRIM CABLE                    | W83420         | BROKEN             | 20051117005 | PNR |
| 650                      | 2710 | TURNBUCKLE                 | MS21251B5S    | CHAFED          | 20051018001 | QUE | <b>GULFSTREAM - USA</b>      |      |                               |                |                    |             |     |
| A185F                    | 3246 | PIVOT DE LA FOURCHE        |               | DEBUT CORROSION | 20051004001 | QUE | 690D                         | 3230 | UPLOCK CYLINDER               | 713058503      | FAILED             | 20051129005 | ATL |
| U206F                    | 2410 | ALTERNATOR                 |               | SEPARATED       | 20051101006 | PNR | <b>HAWKER SIDDELEY-UK</b>    |      |                               |                |                    |             |     |
| <b>CIRRUS</b>            |      |                            |               |                 |             |     | HS 748 2A                    | 3230 | LANDING GEAR SELECTOR LINKAGE |                | ICE ACCUMULATION   | 20051128002 | QUE |
| SR20                     | 0000 | CRANKCASE                  |               | CRACK           | 20051202004 | ONT | HS 748 2A                    | 3232 | CONNECTING ROD                | 5D11580        | BROKEN             | 20051125008 | NCR |
| SR20                     | 7800 | EXHAUST HEADER             | 10351002      | CRACKED         | 20051003016 | ONT | <b>HILLER</b>                |      |                               |                |                    |             |     |
| SR20                     | 7800 | NUT                        | 22022         | MISSING         | 20051003017 | ONT | UH12D                        | 6210 | MAIN FOTOR BLADE              | 2253110104     | FAILED             | 20051212002 | PNR |
| SR22                     | 7160 | BOLT                       | AN334         | WORN            | 20051108002 | ONT | <b>HUGHES</b>                |      |                               |                |                    |             |     |
| SR22                     | 7810 | SPRING                     | 51381001      | WORN            | 20051108003 | ONT | 369D                         | 6210 | MAIN ROTOR BLADE              | 369D2110052    | CRACK              | 20051117006 | PNR |
| <b>CONVAIR - CANADA</b>  |      |                            |               |                 |             |     | 369D                         | 6210 | MAIN ROTOR BLADE              | 500P2100103    | TIP CAP LOSS       | 20051123006 | PNR |
| 440                      | 2910 | HYD LINE FITTING           | MS2190512D    | CRACKED         | 20051006001 | QUE | 369D                         | 7921 | BRACKET, MOUNTING FAN         | 369D2562611    | CRACKED            | 20051117004 | PNR |
| <b>DASSAULT</b>          |      |                            |               |                 |             |     | <b>ISRAELI INDUSTRIES</b>    |      |                               |                |                    |             |     |
| FALCON 10                | 2913 | HYDRAULIC PUMP             | 4005303       | OVERHAULED      | 20051209004 | ONT | 1124                         | 3020 | TUBE ASSEMBLY                 | F10A5P202413   | BEYOND REPAIR      | 20051101001 | ONT |
| FALCON 50                | 2120 | ECU EXHAUST DUCT           | F50B721508A3  | BLEED AIR LEAK  | 20051017003 | QUE | 1124                         | 3250 | CABLE                         | 503028533      | FRAYED             | 20051110001 | ATL |
| <b>DEHAVILLAND - CAN</b> |      |                            |               |                 |             |     | K 1200                       | 5230 | AIRFRAME STRUCTURE            |                | CRACKED            | 20051115006 | PAC |
| DHC 3T                   | 2731 | ELEVATOR SERVO TAB         | AA112911002   | CRACKED         | 20051017005 | ONT | <b>LEARJET</b>               |      |                               |                |                    |             |     |
| DHC 5A                   | 5400 | FRAMENACELLE STA123.10C5WM | 126238        | CRACKED         | 20051219001 | PAC | 45                           | 2400 | STARTER GENERATOR             |                | UNKNOWN            | 20051228002 | ONT |
| DHC 6                    | 2730 | RIB HORN ELEVATOR          | C6TE102627    | NEW             | 20051024009 | NCR | 45                           | 5753 | GIMBAL ASSY                   | 1457711        | LOST PIN           | 20051002002 | PNR |
| DHC 6                    | 2750 | HINGE ARM ADAPTER          | C6W104632     | CRACKED         | 20051124006 | PAC | 45                           | 7200 | ENGINE                        |                | BIRD STRIKE        | 20051205002 | ONT |
| DHC 6                    | 5753 | INTERMEDIATE RIB           | C6W12104546   | CRACKED         | 20051124008 | PAC | 55                           | 3233 | UPLOCK ACTUATOR               | 24170161       | FAILURE            | 20051103009 | PAC |
| DHC 6 100                | 5300 | SIDE FRAME R/H             | C6FSM2528S12  | CRACKED         | 20051018003 | PAC | <b>PIAGGIO</b>               |      |                               |                |                    |             |     |
| DHC 6 200                | 0000 | PITOT HEAD                 | PH506L        | FAILING         | 20051108004 | PAC | P180 AVANTI                  | 3246 | INNER WHEEL                   | 314611         | CRACKED            | 20051117008 | ONT |
| DHC 6 300                | 2916 | HYDRAULIC RESERVOIR        | C6HF10571     | CRACKED         | 20051116007 | PNR | <b>PILATUS - SW</b>          |      |                               |                |                    |             |     |
| DHC 6 300                | 3222 | FLOATING PISTON            | 713321        | DAMAGED         | 20051206008 | PNR | PC 12 45                     | 2200 | EADI INDICATOR                | 066031252500   | INTERMITTENT       | 20051103006 | ONT |
| DHC 6 300                | 5730 | WING BOX ASSEMBLY          |               | DISBONDED       | 20051012005 | PAC | PC 12 45                     | 2730 | STOP                          | 5552012186     | MISSING            | 2 SDRs      | ONT |
| DHC 7                    | 3320 | LIGHT FIXTURE              | BR6314101     | CHARRED         | 20051130012 | PAC | PC 12 45                     | 2740 | PITCH TRIM ADAPTER            | 065001640100   | FAULTY             | 2 SDRs      | ONT |
| DHC 7                    | 5230 | BOLT                       | MS2125006020  | CORRODED        | 20051124005 | PAC | PC 12 45                     | 2750 | FLAP PWR DRIVE UNIT           | 952D1005       | DEFECTIVE MOTOR    | 20051116010 | QUE |



| MAKE/MODEL                 | JASC | PART NAME                | PART NO.       | PART CONDITION    | SDR NO.     | RGN |
|----------------------------|------|--------------------------|----------------|-------------------|-------------|-----|
| PC 12 45                   | 2752 | FLAP ACTUATOR            | 9787320309     | BINDING           | 20051028005 | ONT |
| PC 12 45                   | 3418 | STOCK PUSHER COMPUTER    | 9754423104     | INTERNAL MALFUNC  | 20051129006 | ONT |
| PC 12 45                   | 3497 | MAIN WIRE BUNDLE         |                | CHAFED            | 20051011004 | PNR |
| <b>PIPER</b>               |      |                          |                |                   |             |     |
| PA18                       | 0000 | REAR STRUT ATTACH PAD    |                | EXTREME CORROSION | 20051221002 | ONT |
| PA18 150                   | 0000 | LONGERON                 |                | ROTTED            | 20051221003 | ONT |
| PA28 140                   | 3340 | SCREW                    | 6367400        | U/S               | 20051103010 | PNR |
| PA28 160                   | 5751 | ALLERON SUPPT ASSEMBLY   | 62102000       | CRACKED           | 20051006016 | ONT |
| PA28R 200                  | 7414 | DISTRIBUTOR GEAR         |                | BROKEN            | 20051117007 | PNR |
| PA28R 200                  | 0000 | MAIN SPAR                |                | CRACKED           | 20051230004 | ONT |
| PA30                       | 3221 | ARM ASSEMBLY             | 21890          | FAILED            | 20051116004 | PNR |
| PA31                       | 5280 | BACKET                   | 46357000       | CRACKED           | 2 SDRs      | ATL |
| PA31 350                   | 2300 | AUDIO PANEL              | GMA340         | U/S               | 20051025006 | ATL |
| PA31 350                   | 3230 | LINK ASSEMBLY            | 40336000       | CRACKED           | 2 SDRs      | PNR |
| PA31 350                   | 3250 | BOLTS                    | AN37A          | SHEARED           | 20051011009 | PAC |
| PA31P                      | 3400 | GPS SYSTEM               | KLN90B         | UNRELIABLE        | 20051219005 | PNR |
| PA31T                      | 0000 | FRESH AIR PIPE           |                | DISCONNECTED      | 20051208005 | ONT |
| PA31T                      | 2130 | CABLE                    | 46129002       | BROKEN            | 20051117009 | ONT |
| PA31T                      | 2130 | EVAPORATOR ASSY          | 4624500        | HOSE DETACHED     | 20051103012 | ONT |
| PA31T                      | 2731 | ELEV TAB CONTROL SYS     |                | LOOSE RIVET       | 20051012003 | ONT |
| PA31T                      | 3230 | HYD RETURN LINE          | 8000420        | PIERCED           | 20051012002 | ONT |
| PA31T2                     | 3230 | GEAR RETRACTION ARM      | 42042002       | CRACKED           | 20051012004 | ONT |
| PA42 720                   | 3211 | FITTING                  | 4028600        | CRACKED           | 20051108005 | PNR |
| <b>ROBINSON</b>            |      |                          |                |                   |             |     |
| R44                        | 0000 | BOLT                     | A6502          | CRACKED           | 20051208012 | PNR |
| R44                        | 2510 | ANCHOR ASSY              | C3485          | CRACKED           | 20051124004 | PNR |
| R44 II                     | 0000 | TRANSMISSION             | C2641          | WORN              | 20051207001 | PNR |
| R44 II                     | 2435 | BENDIX DRIVE GEAR        | BC3151004      | CHIPPED TOOTH     | 20051004008 | PNR |
| R44 II                     | 2562 | ELT                      | PS400010       | U/S               | 2 SDRs      | PNR |
| R44 II                     | 2820 | PUMP                     | B8187B         | LOW PRESSURE      | 20051101005 | PNR |
| R44 II                     | 3030 | TRANSMISSION             | C2641          | WORN              | 2 SDRs      | PNR |
| R44 II                     | 6510 | DAMPER BEARING           | C04111         | SPUN              | 20051212005 | PNR |
| R44 II                     | 6730 | SERVO                    | D2121          | LEAKING           | 2 SDRs      | PNR |
| <b>SCHWEIZER</b>           |      |                          |                |                   |             |     |
| 269C 1                     | 6230 | TUBE ASSEMBLY            | 269A21725      | CRACKED           | 20051003015 | QUE |
| <b>SHORT &amp; HARLAND</b> |      |                          |                |                   |             |     |
| SC7 3                      | 2562 | ELT                      |                |                   | 20051012008 | PNR |
| <b>SIKORSKY</b>            |      |                          |                |                   |             |     |
| S61N                       | 5610 | WINDSHIELD RIGHT         | S6120612272    | UNSERVICEABLE     | 20051022001 | PAC |
| S61N                       | 6220 | CLEVIS UPPER             | S611221010082  | NEW PART U/S      | 20051118002 | PAC |
| S61N                       | 6310 | BEARING                  | SB2158102      | NEW PART U/S      | 20051121002 | PAC |
| S64E                       | 6320 | ADAPTOR CLAMP            | MS173204       | FAILED            | 20051013004 | PAC |
| S76A                       | 0000 | NOZZLE ASSY              | 7635109105068  | NEW               | 20051216002 | PAC |
| S76A                       | 6320 | FLUID ADAPTER            | RF981213       | WORN              | 20051123001 | NCR |
| S76A                       | 6320 | HOSE, TRANS OIL          | MS8005K280P    | UNSERVICEABLE     | 20051123005 | PAC |
| S76A                       | 7921 | BEARING, BALL            | W200PP         | SEIZED            | 20051213003 | QUE |
| S76C                       | 6320 | BEARING                  | SB3615102      | NEW PART U/S      | 20051121003 | PAC |
| <b>SOCATA</b>              |      |                          |                |                   |             |     |
| TB 21                      | 5350 | ANTI SPIN EDGE           | TB202801300900 | CORRODED          | 20051108007 | ONT |
| <b>SWERINGEN</b>           |      |                          |                |                   |             |     |
| SA226TC                    | 5315 | WEB                      | 272008478      | CRACKED           | 20051027009 | PAC |
| SA226TC                    | 5711 | SPAR FITTING             | 2722136006     | CRACKED           | 20051108009 | PNR |
| <b>engines</b>             |      |                          |                |                   |             |     |
| <b>ALLISON</b>             |      |                          |                |                   |             |     |
| 250-C20                    | 7240 | COMBUSTION CASE          | 6870992J       | CRACKED           | 20051025005 | PNR |
| 250-C20                    | 7321 | FUEL CONTROL             | 23034702       | DECELERATION      | 20051211001 | PNR |
| 250-C20B                   | 0000 | ROTOR/STATOR             |                | DAMAGED           | 20051109001 | ONT |
| 250-C20B                   | 7250 | TURBINE ASSY             | 23038241       | EXCESS VENTING    | 20051003008 | NCR |
| 250-C20B                   | 7920 | IDLER GEAR (SCAVENGE)    | 6845867        | FRACTURED         | 20051017010 | PNR |
| 250-C28B                   | 7323 | EXTENSION/RETRACTION ROD |                | FAILED            | 20051003011 | PNR |
| 250-C28B                   | 7532 | BLEED VALVE              | 23005367       | NOT CLOSING       | 20051003003 | PAC |
| 250-C30S                   | 7250 | 3RD STG TURB WHEEL       | 6898663        | FRACTURED         | 20051004002 | QUE |
| 250-C47B                   | 7250 | FIRST STAGE WHEEL        | 23053299       | DAMAGED           | 20051004007 | PAC |
| AE-3007A1                  | 7200 | ENGINE                   |                | EICAS U/S         | 20051209003 | QUE |
| AE-3007A1                  | 7250 | HP TURBINE BLADE         | 23073795       | FAILED            | 20051125004 | QUE |
| <b>AVCO LYCOMING</b>       |      |                          |                |                   |             |     |
| AEIO-360-A1B6              | 7414 | IMPULSE COUPLING         | M3100          | MISSING           | 20051130006 | ONT |
| HO-360-C1A                 | 8500 | CARBURATOR               | 1060301        | FAILED            | 20051007004 | QUE |
| HO-360-C1A                 | 8520 | CRANKSHAFT               | 13B27123       | CRACKED           | 20051206006 | ATL |
| IO-360-C1C                 | 8530 | STUD                     | 50153813       | BROKEN            | 20051104015 | PNR |

| MAKE/MODEL                        | JASC | PART NAME                | PART NO.    | PART CONDITION   | SDR NO.     | RGN |
|-----------------------------------|------|--------------------------|-------------|------------------|-------------|-----|
| IO-540-AE1A5                      | 7314 | FUEL PUMP                | LW15473     | LEAKING          | 20051004003 | PNR |
| IO-540-AE1A5                      | 7414 | HOUSING                  | 10400075    | CRACKED          | 20051220009 | PNR |
| O-320-D2J                         | 8530 | CYLINDER                 | 05K21100    | CRACKED IN HALF  | 20051003004 | PNR |
| O-320-E2D                         | 7322 | CARBURETOR               | 105217      | WORN             | 20051202007 | PAC |
| O-320-E2D                         | 8011 | STARTER CONTACTOR        | 111138D     | SEIZED           | 20051026009 | PAC |
| O-320-E3D                         | 8530 | CYLINDER                 | 75184       | CRACKED          | 20051213005 | PNR |
| O-360-C2E                         | 8520 | CRANKSHAFT               | 74968       | CORRODED         | 20051101003 | PNR |
| TIO-540-A2B                       | 7314 | SPLINE DRIVE             | UKN         | SHEARED          | 20051130011 | PAC |
| TIO-540-A2B                       | 8530 |                          | LW13447     | CRACKED          | 20051005012 | PAC |
| TIO-540-A2C                       | 7310 | FUEL PUMP                | 200F5002    | GOOD             | 20051207003 | PNR |
| TIO-540-A2C                       | 8500 | TURBO CHARGER            |             | FAILED           | 20051003012 | PNR |
| TIO-540-J2BD                      | 6122 | PROP GOVERNOR            | F624A       | SHAFT SHARED     | 20051007007 | PAC |
| TIO-540-J2BD                      | 8500 | R/H ENGINE               |             | UNKNOWN          | 20051005009 | PAC |
| TIO-540-J2BD                      | 8530 | PISTON RINGS             |             | WORN             | 20051220010 | PNR |
| TIO-540-J2BD                      | 0000 | CRANKCASE                | KO509       | CRACKED          | 20051230003 | PNR |
| TIO-540-R2AD                      | 8520 | CRANKSHAFT               | 13F17785    | BROKEN           | 20051214002 | ONT |
| TIO-540-R2AD                      | 8520 | CRANKSHAFT               | 13F17760    | SEPARATED        | 20051221004 | ONT |
| <b>CFM INTERNATIONAL</b>          |      |                          |             |                  |             |     |
| CFM56-3C1                         | 7310 | ENGINE FUEL DIST         |             | LEAKING          | 20051129001 | ATL |
| <b>GARRETT</b>                    |      |                          |             |                  |             |     |
| TPE731-5BR                        | 7310 | FUEL FILTER              | 8975131     | INDICATOR U/S    | 20051020003 | PNR |
| TPE331-12UHR                      | 7910 | RIGID OIL LINE           | 3108081     | CRACKED          | 20051027001 | PNR |
| TPE331-5-252D                     | 7712 | ENGINE                   |             | TBD              | 2 SDRs      | PNR |
| TPE331-6-252B                     | 2612 | FIRE DETECTOR            | 302158      | FAILED           | 20051130004 | QUE |
| <b>GENERAL ELECTRIC</b>           |      |                          |             |                  |             |     |
| CF34-3B1                          | 7230 | HPC STAGE 2 TURNBUCKLE   | 4020T51P02  | FRACTURED        | 20051128001 | NCR |
| CF34-3B1                          | 7830 | R/H ENGINE               | CF343B1     | LEVER ARMS LOOSE | 20051112002 | NCR |
| CF34-8C1                          | 7310 | VG SECONDARY ACT         | 4120T03P04  | LEAKING          | 20051028002 | NCR |
| C77-9B                            | 7200 | ENGINE #2                |             | TBD              | 20051124002 | PNR |
| <b>HONEYWELL</b>                  |      |                          |             |                  |             |     |
| AS907-1-1A                        | 7931 | ENGINE                   |             | CONTAMINATION    | 20051212004 | QUE |
| <b>PRATT &amp; WHITNEY-CANADA</b> |      |                          |             |                  |             |     |
| JT15D-1A                          | 7250 | ENGINE TURBINE SECTION   |             | TBD              | 20051208002 | ATL |
| JT15D-4C                          | 7200 | ENGINE                   |             | TBD              | 20051129018 | QUE |
| JT15D-5                           | 7200 | ENGINE                   |             | TBD              | 20051223001 | QUE |
| JT15D-5D                          | 7200 | ENGINE                   |             | TBD              | 20051129012 | QUE |
| PT6A-11                           | 7230 | ENGINE COMP SECTION      |             | CONTAMINATION    | 20051104005 | QUE |
| PT6A-112                          | 8300 | ENGINE GEARBOX           |             | SEIZED           | 20051006013 | QUE |
| PT6A-114A                         | 7200 | ENGINE                   |             | UNKNOWN          | 2 SDRs      | QUE |
| PT6A-114A                         | 7230 | CT SHROUD SEG RETAIN     | 311074102   | DISTORTED        | 20051028004 | PNR |
| PT6A-114A                         | 7250 | ENGINE                   |             | CONTAMINATION    | 20051205003 | ONT |
| PT6A-21                           | 7200 | ENGINE                   |             | UNKNOWN          | 20051005011 | QUE |
| PT6A-25C                          | 7532 | BLEED VALVE              |             | OUT OF LIMITS    | 20051006014 | QUE |
| PT6A-28                           | 7930 | OIL PRESSURE GAUGE       | 973840091   | NEEDLE STUCK     | 20051025002 | QUE |
| PT6A-34                           | 0000 | ROD-END CONNECTOR        | 3011587     | STIFF - STUCK    | 20051223015 | PNR |
| PT6A-34                           | 7200 | ENGINE                   |             | UNKNOWN          | 2 SDRs      | QUE |
| PT6A-34                           | 7314 | ENG DRIVEN FUEL PUMP     | 02532310103 | SPLINES SHEARED  | 3 SDRs      | VAR |
| PT6A-34                           | 7600 | BRACKET-REV TELEFLEX     | 3012525     | CRACKED          | 20051013005 | PNR |
| PT6A-36                           | 7200 | ENGINE                   |             | CONTAMINATION    | 20051109007 | PNR |
| PT6A-42                           | 7200 | ENGINE                   |             | VIBRATIONS       | 20051223012 | QUE |
| PT6A-50                           | 6120 | PROP CONTROL SYS         |             | TBD              | 2 SDRs      | VAR |
| PT6A-50                           | 7230 | ENGINE COMP SECTION      |             | TBD              | 20051006006 | QUE |
| PT6A-61                           | 6121 | CIRCUIT BREAKER          | 454688      | ERRATIC FUNCTION | 20051130005 | ONT |
| PT6A-65AG                         | 7200 | ENGINE                   |             | FLAME-OUT        | 20051006003 | QUE |
| PT6A-65B                          | 7200 | ENGINE                   |             | TBD              | 20051104012 | QUE |
| PT6A-66                           | 7250 | TURBINE SECTION          |             | TBD              | 20051223003 | QUE |
| PT6A-67B                          | 6122 | PROP GOVERNOR            | 8210137     | CONTAMINATION    | 20051103007 | ONT |
| PT6A-67B                          | 7310 | FUEL CONTROL UNIT        |             | SURGED           | 20051006015 | QUE |
| PT6A-67D                          | 2435 | STARTER GENERATOR        | 23078019    | FAULTY           | 20051130008 | ATL |
| PT6A-67D                          | 7250 | CT BLADES WITH A STEP    | 311899101   | RUBBED           | 20051006007 | PNR |
| PT6A-68                           | 7200 | ENGINE                   |             | TBD              | 2 SDRs      | QUE |
| PT6T-3                            | 7312 | FUEL HEATER              |             | UNSERVICEABLE    | 20051017009 | QUE |
| PT6T-3B                           | 7210 | ENGINE REDUCTION GEAR    |             | UNSERVICEABLE    | 20051025003 | QUE |
| PT6T-3B                           | 7230 | ENGINE COMPRESSOR        |             | DAMAGED          | 20051223005 | QUE |
| PT6T-3DF                          | 7310 | FUEL TUBE                |             | LEAKING          | 20051104009 | QUE |
| PW120                             | 0000 | TOWERSHAFT               |             | FRACTURED        | 20051129009 | QUE |
| PW120                             | 7712 | CONNECTOR, TORQUE SENSOR |             | CONTAMINATED     | 20051129015 | QUE |
| PW120A                            | 7712 | TORQUE SENSOR            |             | FAULTY           | 20051223007 | QUE |
| PW121                             | 7200 | ENGINE                   |             | CONTAMINATION    | 20051223009 | QUE |
| PW121                             | 7210 | ENGINE REDUCTION GEAR    |             | TBD              | 3 SDRs      | VAR |
| PW121                             | 7712 | TORQ SIGNAL CONTROL      | 30005000044 | UNSERVICEABLE    | 20051006012 | QUE |
| PW123                             | 7920 | ENGINE OIL DIST          |             | LEAKING          | 20051104010 | QUE |
| PW123C                            | 7260 | ENGINE ACCESSORY DRIVE   |             | CONTAMINATION    | 20051104002 | QUE |
| PW124B                            | 7230 | NO. 2 BEARING            | 310784501   | FAILURE          | 20051017011 | ATL |
| PW125B                            | 7714 | PACKING                  |             | HARDENED/BROKEN  | 20051006005 | QUE |

| MAKE/MODEL                     | JASC | PART NAME                | PART NO.      | PART CONDITION   | SDR NO.     | RGN |
|--------------------------------|------|--------------------------|---------------|------------------|-------------|-----|
| PW126A                         | 7311 | FUEL /OIL COOLER         |               | U/S              | 20051006010 | QUE |
| PW127E                         | 7920 | OIL FILLER HOUSING       |               | LEAKING          | 20051129014 | QUE |
| PW127F                         | 6123 | CIRCUIT BOARD            |               | CRACKED          | 20051223008 | QUE |
| PW127F                         | 7200 | ENGINE                   |               | TBD              | 3 SDRs      | QUE |
| PW150A                         | 7310 | FUEL MANIFOLD            | AS3209010&012 | MISSING          | 20051205006 | QUE |
| PW150A                         | 7930 | OIL PRESSURE SWITCH      | 312249        | U/S              | 20051104003 | QUE |
| PW305A                         | 7200 | ENGINE                   |               | TBD              | 20051104007 | QUE |
| PW305A                         | 7714 | N1 SPEED SENSOR          | 30B615004     | UNSERV/ICEABLE   | 20051104014 | QUE |
| PW305B                         | 7910 | ENGINE                   |               | OIL LEAK         | 20051006008 | QUE |
| PW308C                         | 7200 | ENGINE                   |               | TBD              | 20051129011 | QUE |
| PW545B                         | 7200 | ENGINE                   |               | TBD              | 20051129013 | QUE |
| <b>PRATT &amp; WHITNEY-USA</b> |      |                          |               |                  |             |     |
| JFTD12A-4A                     | 7321 | ENGINE FUEL CONTROL      |               | FAILED           | 2 SDRs      | PAC |
| JT8D-15                        | 7220 | ENGINE AIR INLET SECTION |               | SURGE            | 20051110002 | PNR |
| JT8D-15A                       | 7250 | 4TH ST TURBINE DISC      | 500310401     | BLADE PC MISSING | 20051103008 | ONT |
| R-2000-7M2                     | 8530 | CYLINDER                 | 153084        | CRACKED          | 20051121004 | PNR |
| R-985-AN-14B                   | 8520 | MASTER ROD BEARING       | 32983         | BROKEN PIECE     | 20051025001 | PAC |
| R-985-AN-14B                   | 8530 | CYLINDER                 |               | SEPARATED        | 20051213004 | ONT |
| <b>ROLLS ROYCE - GERMANY</b>   |      |                          |               |                  |             |     |
| BR700-715A1-30                 | 7230 | ENGINE COMP SECTION      |               | TBD              | 20051007001 | QUE |
| SPEY 511-8                     | 7200 | ENGINE                   |               | CONTAMINATION    | 20051014002 | QUE |
| <b>ROLLS ROYCE - UK</b>        |      |                          |               |                  |             |     |
| RE211TRENT772B60               | 7200 | ENGINE                   |               | ENG SHUT DOWN    | 20051116009 | QUE |
| RE211TRENT772B60               | 7230 | #2 ENGINE (R/H )         |               | BIRDSTRIKE       | 20051111001 | QUE |
| RE211TRENT772B60               | 7260 | #1 ENGINE                |               | LOST COUPLING    | 20051205005 | QUE |
| RE211TRENT772B60               | 7900 | INPUT SHAFT              |               | SHEARED          | 20051108001 | QUE |
| <b>TELEDYNE CONTINENTAL</b>    |      |                          |               |                  |             |     |
| IO-360-G                       | 7414 | IGNITION HARNESSES       | IO8216743     | DETERIOATED      | 20051027005 | ONT |
| IO-520-A                       | 6122 | PROPELLER GOVERNOR       |               | TBD              | 20051115005 | QUE |
| IO-520-D                       | 7313 | FUEL INJECTOR NOZZLE     |               | FOD              | 20051108008 | PAC |
| IO-520-F                       | 7321 | FUEL CONTROL ASS.        | 6297032       | LEAKING          | 20051116006 | PNR |
| IO-520-F                       | 8530 | #6 CYLINDER VALVE & RODS |               | BUSTED VALVE     | 20051031003 | PNR |
| IO-520-L                       | 8011 | STARTER ADAPTER          | 643259A18     | BROKEN           | 20051115002 | ONT |
| IO-550-F                       | 8530 | CYLINDER                 | TIST760CA     | CRACK            | 20051111003 | PAC |
| O-200-A                        | 1000 | WASHER                   |               | PASSED THRU      | 20051104008 | ONT |
| TSIO-520-E                     | 8530 | CYLINDER                 | AEC631397     | CRACKED          | 2 SDRs      | QUE |

#### LEGEND

**JASC** Joint Aircraft System Code number defining assembly/system/component  
**SDR NO.** TCA assigned SDR control number - please quote in any correspondence or inquiries  
**RGN** TCA region of SDR submitter:

**PAC** = Pacific,  
**ONT** = Ontario,  
**ATL** = Atlantic,  
**VAR** = more than one Region  
**PNR** = Prairie Northern,  
**QUE** = Quebec,  
**NCR** = Ottawa (HQ),

| MAKE/MODEL | JASC | PART NAME          | PART NO.    | PART CONDITION | SDR NO.     | RGN |
|------------|------|--------------------|-------------|----------------|-------------|-----|
| ARRIEL 1B  | 7320 | FUEL CONTROL       | 0164548660R | OVERHAULED     | 20051116013 | PNR |
| ARRIEL 1B  | 7421 | IGNITER            |             | U/S            | 2 SDRs      | PAC |
| ARRIEL 1D1 | 7250 | FREE TURBINE BLADE | 0292803080  | FAILED         | 20051003006 | PAC |

### propeller

|                     |      |                     |         |            |             |     |
|---------------------|------|---------------------|---------|------------|-------------|-----|
| <b>HARTZELL</b>     |      |                     |         |            |             |     |
| HC-B3R30-4B         | 6113 | BACK PLATE          | D1870RP | CRACKED    | 20051114002 | PAC |
| HC-B3TN-3DY         | 6120 | BETA RING/BETA RODS |         | FAILED     | 20051026008 | PAC |
| <b>MCCAULEY</b>     |      |                     |         |            |             |     |
| D3A32C              | 6114 | PROPELLER           |         | LEAKING    | 20051007008 | PNR |
| <b>MT PROPELLER</b> |      |                     |         |            |             |     |
| MT-186R-140-3D      | 6100 | PROPELLER           |         | PROP BOLTS | 20051007002 | QUE |

### equipment

|                             |      |                           |             |               |             |     |
|-----------------------------|------|---------------------------|-------------|---------------|-------------|-----|
| <b>AKC TECHNOLOGIES</b>     |      |                           |             |               |             |     |
| E01                         | 2560 | BATTERY CASE              | E0103&E0102 | LEAKING       | 20051026005 | PNR |
| <b>AVTECH CORP</b>          |      |                           |             |               |             |     |
| 519012                      | 2300 | MOTHERBOARD CARD#1        | 5190601     | CORRODED      | 20051219004 | QUE |
| <b>BEECH AIRCRAFT CORP</b>  |      |                           |             |               |             |     |
| 1003890181                  | 0000 | PRESSURE SWITCH           | 10038901819 | NO INDICATION | 20051003005 | PAC |
| <b>BOMBARDIER</b>           |      |                           |             |               |             |     |
| VHP430KH3                   | 2431 | THERMAL BARRIER BREAKDOWN |             | FAILED        | 20051017004 | ONT |
| <b>HONEYWELL INC</b>        |      |                           |             |               |             |     |
| 1319B                       | 4920 | TURBINE ROTOR ASSY        | 38403031    | TBD           | 20051118001 | PNR |
| <b>MICHEL ELECTRONICS C</b> |      |                           |             |               |             |     |
| MX385                       | 2312 | NAV / COM                 | 0           | U/S           | 20051130003 | PNR |
| <b>ROLLS ROYCE</b>          |      |                           |             |               |             |     |
| 250C20B                     | 2435 | STARTER GENERATOR         | 23032018    | PART ARCING   | 20051003010 | NCR |



**Canadian Aviation Regulations (CARs)**  
[www.tc.gc.ca/civilaviation/regserv/affairs/cars/menu.htm](http://www.tc.gc.ca/civilaviation/regserv/affairs/cars/menu.htm)  
**Airworthiness Directives**  
[www.tc.gc.ca/aviation/applications/cawis-swim](http://www.tc.gc.ca/aviation/applications/cawis-swim)  
**Service Difficulty Alerts**  
[www.tc.gc.ca/CivilAviation/certification/continuing/Alert/menu.htm](http://www.tc.gc.ca/CivilAviation/certification/continuing/Alert/menu.htm)  
**Service Difficulty Advisories**  
[www.tc.gc.ca/CivilAviation/certification/continuing/Advisory/menu.htm](http://www.tc.gc.ca/CivilAviation/certification/continuing/Advisory/menu.htm)  
**Web Service Difficulty Reporting System (WSDRS)**  
[www.tc.gc.ca/wsdrr/](http://www.tc.gc.ca/wsdrr/)  
**Airworthiness Notices**  
[www.tc.gc.ca/civilaviation/maintenance/aarpc/ans/menu.htm](http://www.tc.gc.ca/civilaviation/maintenance/aarpc/ans/menu.htm)  
**Airworthiness Manual Advisory Index**  
[www.tc.gc.ca/CivilAviation/certification/guidance/menu.htm](http://www.tc.gc.ca/CivilAviation/certification/guidance/menu.htm)  
**Aircraft Maintenance & Manufacturing Staff Instructions (MSI)**  
[www.tc.gc.ca/civilaviation/maintenance/aarpc/msi/menu.htm](http://www.tc.gc.ca/civilaviation/maintenance/aarpc/msi/menu.htm)  
**Aircraft Maintenance and Manufacturing Policy Letters (MPL)**  
[www.tc.gc.ca/civilaviation/maintenance/aarpc/mpl/menu.htm](http://www.tc.gc.ca/civilaviation/maintenance/aarpc/mpl/menu.htm)

# feedback feedback feedback

contact information contact information contact information

## headquarters headquarters headquarters

Transport Canada Civil Aviation, Continuing Airworthiness AARDG  
Place de Ville, Tower C, 330 Sparks Street, Ottawa, ON K1A 0N8  
Tel: (613) 952-4357, Fax: (613) 996-9178

regional offices regional offices regional offices

### Atlantic

Transport Canada  
P.O. Box 42  
95 Foundry St., 6th Floor  
Moncton, NB  
E1C 8K6  
(506) 851-7114

### Prairie and Northern

Transport Canada  
344 Edmonton Street  
Winnipeg, MB  
R3C 0P6  
(204) 983-3152  
1-888-463-0521

### Ontario

Transport Canada  
4900 Yonge St., Suite 300  
Willowdale, ON  
M2N 6A5  
(416) 952-0352


### Quebec

Transport Canada  
700 Leigh Capreol  
Dorval, QC  
H4Y 1G7  
(514) 633-3319

### Pacific

Transport Canada  
800 Burrard St., Suite 620  
Vancouver, BC  
V6Z 2J8  
(604) 666-8777

**feedback** (TP 6980E) is published quarterly by the Continuing Airworthiness Division of Transport Canada, informing the aviation community of reported day-to-day problems that affect aircraft airworthiness in Canada.



The articles contained in **feedback** are derived from Service Difficulty Reports (SDRs) submitted by Aircraft Maintenance Engineers (AMEs), owners, operators and other sources.

For additional information concerning **feedback** or the Service Difficulty Reporting Program, contact your nearest Transport Canada Centre.



T.A. McNamara  
Editor  
Information Programs  
Tel: (613) 952-4360  
mcnamat@tc.gc.ca

### Where to find us in cyberspace

<http://www.tc.gc.ca/civilaviation/certification/menu.htm>

<http://www.tc.gc.ca/cawis-swimn/>

<http://www.tc.gc.ca/wsdrs/>



B. Goyaniuk  
Chief  
Continuing Airworthiness  
Tel: (613) 952-4356  
goyanib@tc.gc.ca

Canada