

PACIFIC REGION TECHNICAL NOTES

NO. 78-036

OCT. 3, 1978

THE DRY LIGHTNING OUTBREAK OF AUGUST 4TH, 1978

Bryan Jensen, Fire Weather Presentation Technician Kamloops Forest District

On August 4th, at approximately 1030 PDT dry lightning struck the Clearwater Ranger District and in the chain of events that followed lightning occuring on the 4th resulted in over 200 forest fires being reported by the 8th.

The following is a sequence of meteorological and presentation events commencing the afternoom of Thursday, August 3rd.

The upper ridge remained dominant in the Kamloops Forest District on the morning of the third but a southwesterly flow was developing in western portions of the district. A broad upper low just off the north coast, although weakening slightly, was drifting eastward. Forest conditions in the district were extremely dry and hazardous.

A Satellite photo for 1645Z of the 3rd indicated an area of moisture and instability rotating around the low and moving into the southwesterly flow that was developing in the Forest District.

The Fire Weather Forecast for Prince George Quesnel Lakes appeared most applicable to the situation and with minor adjustments for wind, that forecast was issued to all Rangers and the Duty Officer by 1600 PDT. The forecast gave a risk of dry lightning for the evening of Friday, Aubust 4th.

By the morning of August 4th, the upper ridge had shifted eastward allowing the upper low off the north coast to drift inland. Several lightning fires were reported in the Prince Rupert Forest District that morning. To the south, the area of instability and moisture had drifted into Washington and with a southwesterly flow, threatened B.C. with dry lightning.

After discussion with Fire Weather Forecaster, H.Raynor and duty briefer Bob Duffy at the Kamloops Weather Office, the following forecast was issued to the Duty Officer and all Ranger Districts. Dry lightning was expected to cross the

U.S.A border into the Kamloops Forest District by late morning.

At approximately 0945PDT an update based on satellite data was received from the Rire Weather Forecast Office warning of dry lightning by afternoon with the "hardest hit" areas to be the Monashee and N. Thompson. Support for this update was indicated by a 1500Z or 0800PDT observation of CB cloud in the Stampede Pass area of northern Washington. Note that no significant convective cloud appeared on any weather sequence between 0900PDT (1600Z) and 1100PDT (1800Z). Towering cumulus reported at Blue River at 1800Z indicated thunderstorms to follow, probably by afternoon.

At approcimately 1100PDT dry lightning was reported at the Clearwater Ranger District and at 1845Z (1145PDT) thunder was reported at Blue River. These two reports were the first indication on the AES circuitsof thunderstorm activity anywhere in the Kamloops Forest District. Immediately following the lightning report from the Clearwater Ranger District, a warning was issued to all Rangers to expect dry lightning at any time and to expect mostof it in the N.Thompson and Monashee areas. By early afternoon, dry lightningwas a fact in all eastern and northern portions of the Kamloops Forest District.

In retrospect, the first onslaught of lightning in the N. Thompson seems to have been triggered by cooling aloft as the upper low crossed thenorth coast and by upslope conditions along the N. Thompson River with more westerly winds in that area. The main body of lightning that followed and caused more activity came into the province from the U.S. and was as forecast, both dry and concentrated in the Monashee and North Thompson River areas.


The reason for so many fires developing was of course, the extreme dryness of the forest and the lightning activity without rainfall. Except for the initial timing of the lightning activity and the area it struck, actual conditions followed forecast conditions quite closely. Timing was only out by perhaps an hour or two, the area of first lightning, however, was further in error.

The only problem then, was the location of the initial onslaught in the N. Thompson area. Nothing in the AES weather network indicated sufficient buildups to signify lightning activity prior to its occurrence. In retrospect, (although I did not see this photo til later) the satellite photo shows fairly active conditions up the N. Thompson River but in association with the reported conditions from the network, this activity would not signify lightning activity. (see photo Aug 4 - 1545Z)

In my opinion, the only mechanism or report that could definitely have located and determined the buildups of cumulus cloud on the 4th, was radar. Conditions observed in the district did not suggest requesting radar report from Mount Lolo prior to the lightning activity developing, only an operational weather radar, I feel would have spotted the N. Thompson storm early enough to give some warning of where the lightning would first hit.


From a meteorological and presentation point of view, the lightning storm of Friday, August 4th, was well forecast in view of available data. A warning of dry lightning for Friday was available well in advance, the most significant portion of the lightning outbreak was extremely well forecast with respect to timing and area of most activity and very little adjusting of forecast conditions was required to properly warn the district.

To summarize, the only problem with the forecasts issued to the Kamloops Forest District on the morning of August 4th was where the initial strike would be and in this case an operational radar would have been the only way to determine the initial strike zone.




SATELLITE PHOTO

FOR 1645 2 Aug 3, 1978



SATELLITE PHOTO

FOR 1545 2 Aug 4, 1978



FORECASTS

FPCN33 CYUR 032045

THE RESERVE OF THE PARTY OF THE

FIRE WEATHER FORECAST FOR PRINCE GEORGE QUESNEL LAKES

FOR FRIDAY. AUGUST 04 1978

WEATHER ZONES 14 15 16 18 19

UPPER RIDGE MOVING SLOWLY EASTHARD ACCROS DISTRICT FRIDAY GIVING

SOUTHWEST FLOW OF WARM DRY AIR. SUNNY AND WARMER FRIDAY. POOR

RECOVERY UPPER LEVELS TONIGHT, WINDS LIGHT EASTEREY SOUTHWESTERY I

DRY LIGHTNING FRIDAY NIGHT :

1PH FOST THE RH WIND ACHNO RH

HUDTA CP 21 25 SE 5 5

ALEAZA 23 24 8E10 5

VALEMOUNT RS 25 26 SE11 5

HORSEFLY RS 25 29 8812 5

BLUE RUR AP 29 24 NE 6 5

ISSUED AT OSOOPDT AUG 4, 1978

Southerly flow at high levels over district. Moisture from south with scattered dry lightning moving up from south should reach border district by late morning. Winds light except stronger in main Nouth-South valleys, and gusting to 50 near thunderstorms. Humidities low.

Five day outlook...calls for cooler with more thundershowers over weekend.

FPCN36 CYVR 041500 AMD

ISSUED 0957PDT

FIRE WEATHER FORECAST FOR SOUTH INTERIOR

FOR FRIDAY AUGUST 04 1978

WEATHER ZONES 20 21

LATEST REPORTS AND SAT. PIC SUGGEST A POCKET OF POTENTIAL DRY THUNDERSTORMS JUST SOUTH OF THE OKANAGAN BORDER MOVING NORTH.
BEST GUESS IS THAT MONASHEES AND NORTH THOMMPSON WOULD HARDEST HIT BY THIS AFTERNON.

END

ISSUED AT 1109 PDT

Dry lightning probable all areas this morning and continuing for the afternoon. Heaviest concentration in Monashee and N. Thompson.

OBSERVATIONS

AY SAUSO KWBC 2341500 UIL RS 1455 EL0 OVC 7 219/60/55/3405/017/ OCNL BINOVC 307 15// BLI SA 1459 250 SCT 30 282/61/52/1811/012/ 315 BFI SA 1450 GO SCT E80 BKN 150 BKN 8 \$2/38/0508/014 SEA SA 1450 80 SCT E150 BKN 200 OVC 25 266/60/53/2106/014/BINGVVCC 307 1072 🔪 SMP_SA 1455 20 SCT E35 BKN 90 EKN 230 OVC 25 188/54/52/2412/015/CB SW MOVG NEMDT CU ALQDS F IN VLY SW OCHL OBSCG STN/ 103 1963 EAT SA 1452 80 SCT 110 SCT 250 - SCT 30 142/70/52/3410/988/ 803 EPH SA 1451 & SCT 100 SCT 250 SCT 25 142/81/48/3506/998/ 302 YKM SA 1457 70 SCT 100 SCT 200 SCT 50 144/73/55/2608/998/ 305 1161 MNH SA 1445 120 SCT E200 BKN 35 76/46/0907/997 GEG SA 1455 CLR 30 160/70/53/0610/006/FEN CU S-W/ 307 1150 CTB SA 1455 CLR 60 188/68/49/2908/016/ 408 HVR SA 1458 CLR 65 195/62/41/1983/012/WND LGT VRB 000 GTF SA 1455 CLR 50 197/68/43/2289/019/ 103 MSO SA 1452 CLR 36 219/58/40/8000/022/ FEW UI S 002 1001 TV M IN TEMP HLN SA 1455 CLR 40 226/58/42/3103/024/ 105 BTM SA 1452 CLR GØ 216/57/32/0000/031/ FEW C1/ DU2 LVM SA 1458 CLR 30 226/59/43/1205/028/ 182V SACNI CYVR Ø416ØØ YVR SA 1600 11 SCT 120 SCT 250 - SCT 15 202/17/13/1204/013/CFLACICIL YHC SA 1600 300 SCT 15+ 199/18/11/1004/012/CII = WAE SA 1600 8 SCT 50 SCT 13 181/19/14/1803/011/K2CF1 VSBY W 5 K = YLY SA 1600 140 SCT 290 - SCT 350 - SCT 15 146/24/13/2018G31/998/ ACI CII CCI = 7 WCL 0000/9.+/ 66/ 41/1805/305/000= YKA SA 1600 E140 BKN 240 BKN 30 149/23/11/1408/999/AC7CI2 QAQOM YNY 115.2 Ø417ØØ/183Ø = YRV SA 1600 130 SCT 320 - BKN 15+ 15+ 187/17/11/2701/009/ACICI2 = WGE SA 1600 100 SCT 250 - SCT 15+ 18/11/0000/AC1CI1 = WCP SA 1600 120 SCT 300 - BKN 15+ 175/18/10/3000/006/AC2CI1 = YPU SA 1600 110 SCT 15+ 150/15/6/2002/002/ACL = YQZ SA 1600 160 SCT 240 - SCT 15 147/18/10/0000/997/ACICIL =

YXT SA 1600 53 SCT 280 - BKN 15 177/16/7/1710/005/CL2 CI2 =
ZST SA 1600 E37 BKN 280 BKN 15 170/17/31/1910/003/CU7 CI1 =
YZP SA 1600 10 SCT E32 BKN 100 BKN 15+ 167/15/11/2403/002/CL2SC5 AS2
TCU ASCTD SHWR E =

YYD SA 1600 60 SCT 280 - BKN 25 145/18/12/0000/998/CFI CII TR CF =

YZY SA 1600 120 SCT 230 - BKN 15+ 141/18/8/1704/996/ACI CI2 =

YXS SA 1600 200 - BKN 45 142/18/8/2001/996/CI3 =

YPZ SA 1600 250 SCT 15+ 145/20/12/1105/997/CI1 =

YTC SA 1600 E18 OVC 10 189/13/13/1810 E/009/SC!0 =
YCJ SA 1600 15 SCT 82 SCT E170 BKN 210 BKN 15+ 194/14/13/2011/010/
TCUIAC4ACI CI 112 =

SA Ø 41 600

YWL SA 1600 160 SCT 260 - BKN 15+ 145/22/7/1412/001/AC3CS 0236=

```
SA Ø 41 700
 YWL SA 1700 160 SCT 260 - BKN 15+ 143/24/7/1210/000/AC2CI3 99956=
 SACNI CYEG Ø41700
YXC 250 SCT 25 190/23/10/1604/014/CIL =
 YAZ SA 1700 CLR 20 216/17/12/3113/017/ =
 YXX SA 1700 300 SCT 30 205/19/12/2507/212/CII = 1
 YHE SA 1700 100 SCT 300 SCT 15+ 191/22/10/2306/009/AC1 CI1 =
 WHE * 9.4
              194/ 22/ 12/2910/010//
                                          ØØ2 =
WKV 120 SCT 250 SCT 10 19/9/3210/AC1CII =
 YDC SA 1700 90 SCT E120 BKN 250 BKN 15+ 159/21/9/0000/007/ACIAC7CII
Ξ.
YYF SA 1700 150 SCT 270 - SCT 15 150/25/13/3504/000/AC2C13 K =
 YLW SA 1700 140 SCT 300 - BKN 20 153/26/12/0000/001/AC2CI2 =
YCG SA 1700 280 - SCT 15+ 175/24/12/3605/007/CI2 =
```

```
SACNI CYVR Ø417ØØ
  YVR SA 1700 11 SCT 250 - SCT 15 203/18/13/1510/013/CF1CI1 =
  YHC SA 1700 300 SCT 15+ 201/19/11/0604/013/CII =
  YPW 30 SCT 15 18/13/3104/013/CUL
  WAE SA 1700 8 - SCT 50 SCT 13 180/21/14/1706/009/K2CF1 VSBY W6 =
  YLY SA 1700 350 SCT 15 140/26/12/2010G18/996/CI1 =
DWCL 9009/9.+/ 73/ 44/1606/005/000=
  YKA SA 1700 60 SCT 150 SCT E240 BKN 30 144/25/10/1102/998/CUIAC5 CS2
    QAQOM YNY 115.2 Ø41700/1830, TR CU =
  YRV SA 1700 130 SCT 170 SCT 300 - BKN 15+ 182/20/11/2501/007/ACIAC2
  CI2 CC ASOCTD =
  WCP SA 1700 70 SCT 250 - BKN 15+ 1 @ /20/11/0702/004/CU1CI4 =
  YPU SA 1700 35 SCT 110 SCT 15+ 154/19/7/2004/000/CFIACL TR CLD =
  YQZ 160 SCT 250 - SCT 15 142/21/10/0000/996/ACICII =
  YXS SA 1700 230 SCT 250 - SCT 40 141/21/8/1503/996/CC1CI1 VSBY W 6 K
  YZY SA 1700 120 SCT 240 - SCT 15+ 135/23/9/1807/994/AC1CI1 =
  YPZ SA1700 140 - SCT 15+ 145/22/10/2503/997/AC1 =
  YYD SA 1700 60 SCT 150 SCT 250 - BKN 25 144/19/11/2903/997/CUI AC2 CI2
      CS ASOCTD =
  YXT SA 1700 45 SCT 280 - BKN 15 178/17/7/1713/006/CU2CII =
  ZST SA 1700 E45 BKN 280 BKN 15 171/17/10/2107/003/CU6CI2 =
```

YZP SA 1700 15 SCT E32 BKN 100 BKN 15+ 170/17/11/1907/003/

CU3 SC4AS2 TCU ASCTD =

SA CN1 . CYVR Ø 41800 YVR SA 1800 11 SCT 250 - SCT 15 204/20/13/1507G014/CF1C11 106 = YHC SA 1800 CLR 15+ 201/21/13/0803/013/ 106 = WAE SA 1800 10 - SCT 50 - SCT 13 179/21/14/1813/009/KICII VSBY W+S 8 804 = WEYLY SA 1800 65 SCT 15 130/27/12/1913@29/993/CF1 814 = 2CWCL 0000/9.+/ -78/ 48/1610/003/000= YKA SA 1800 150 SCT 240 SCT 270 - BKN 30 141/26/11/2702/996/AC2CC1CI2 QAQOM YNY 115.2 041700/1830 810 9858= YRV SA 1800 130 SCT 170 SCT E300 BKN 15+ 174/20/10/0000/005/ACIACICIG 8 WGE SA 1800 250 - SCT 15+ 23/10/2304E/CI2 TAKEN AT 1740 = WCP SA 1800 E70 BKN 300 BKN 15+ 164/23/12/0502/003/1CU6CI2 813 FIRST. T YWL 160 SCT E260 BKN 15+ 144/25/8/1406/000/AC1C15 705 = YPU SA 1800 35 SCT 110 SCT 15+ 145/23/7/2305/998/CFIACI TR CLD 814 = YQZ SA 1800 250 SCT 15 136/23/9/0000/993/CIL 813 = YXS SA 1800 230 SCT 270 - SCT 40 137/23/8/2401/995/CC1 CI 806 = YZY 120 SCT 240 - SCT 15+ 138/23/10/1907/993/AC1CI1 TR AC 810 = YPZ SA 1800 50 SCT 140 - SCT 15+ 142/23/11/2207/996/CULACE 805 YYD SA 1800 60 SCT 150 SCT 250 - BKN 25 144/20/11/3102/997/CUI ACI CI3 CS ASOCTD ØØØ = / YXT SA 1800 45 SCT 280 - BKN 15 177/18/7/1610/005/CU2CI1 TCU ASOCTD 002 = ZST SA 1800 E45 BKN 280 BKN 15 173/18/10/1912/004//CU6CI2 107 = YPR SA 1800 E30 OVC 15R-- 184/14/12/1610/008/SC10 WRO E22 307 = XZP SA 1800 E18 BKN 100 BKN 15+ 166/18/12/1307/002/ICU7ACL CB TOP N 000 = YTC SA 1800 E15 OVC 10 192/15/13/1410 E/010/5 C10 204 = WFM SA 1800 70 SCT 15+ /20/10/2706/ACI RPL = SE YCJ SA 1800 15 SCT 82 SCT E160 BKN 210 BKN 15+ 194/16/14/1815/011/ TCUIACIAC5 CI VIRGA 210 =

> SACNI CYVR Ø41845 WCP SP Ø41845 E 70 BKN 300 BKN 15+ T /3404/CB6CI3