

Isolating The Living Space From
Fungi and Gases In The Soil and
Foundation

Prepared for:

Canada Mortgage and Housing Corporation
Project Implementation Division
682 Montreal Road
Ottawa, Ontario
K1A 0P7

Prepared by:

Scanada Consultants Limited
436 MacLaren Street
Ottawa, Ontario
K2P 0M8

This project was carried out with the assistance of a grant from Canada Mortgage and Housing Corporation under the terms of the Housing Technology Incentives Program (HTIP). The views expressed are those of the author and do not represent the official views of the Corporation.



Scanada
Consultants
Limited

436 MacLaren Street
Ottawa, Ontario
K2P 0M8

Tel: (613) 236-7179
Envoy ID: Scanada.Ott

6521-26/88

ISOLATING THE LIVING SPACE FROM FUNGI AND GASES IN THE SOIL AND
FOUNDATION: A PILOT RETROFIT

Report to: Housing Technology Incentives Program, CMHC
from: Scanada Consultants Limited, Ottawa, 31 March 1990

(Final report 31 August 1990: IAQ test results
received and incorporated)



Fig. 1 The Pilot Case

ISOLATING THE LIVING SPACE FROM FUNGI AND GASES IN THE SOIL AND FOUNDATION: A PILOT RETROFIT

Report to: Housing Technology Incentives Program, CMHC
from: Scanada Consultants Limited, Ottawa, 31 March 1990
(Final report 31 August: IAQ test results included)

INTRODUCTION

A portion of the outdoor air supply to a house may enter by way of the surrounding soil. That portion may increase (relatively) in houses built or retrofitted to be more nearly airtight. The "soil gases" entrained in that flow can be most undesirable. Thus a portion of what is thought to be safe "fresh air" may be anything but.

While the complete elimination of soil gas entry appears to be a practicable goal in new construction, it is not so readily achievable at reasonable cost in existing houses. Considerable efforts to restrict such entry may be justified, however, in existing houses where gas entry is linked to real problems: clearly excessive radon, for example, or methane, or simply the transfer of fungal spores into the indoor air from the soil or the foundation itself.

As briefly reviewed in the next section, there are now a few distinct approaches to keeping soil gases out of the indoor air, and these are more or less tailorable to existing houses. One Ottawa case was brought forward in 1988 in which fungal-related health problems appeared to be linked to the rubble stone foundations - and perhaps the soil outside - and seemed serious enough to call for considerable retrofit to restrict the entry of soil gases, gas-borne spores and surface spores into the indoor air.

In the project now reported, the original objective was to develop and demonstrate a practicable interior retrofit "system" that isolates the indoor air rather completely from both the foundation and the soil, thereby rendering the indoor air of this Ottawa case acceptably free of fungal spores. The further object was to consider how such an approach can apply to the more general case. As will be seen, the objective itself had to be tailored substantially to the circumstances.

BACKGROUND

Isolation of an existing house from the ground can be attempted in several ways:

- i) Airtighten the basement envelope below grade, indoors, or line it with an air tight liner.
- ii) Recognizing that airtightness can be very difficult to achieve or maintain, provide a space between such a liner and the basement envelope and vent the space to the outdoors, generally maintaining the space at a lower pressure than that of the indoor air.
- iii) Use such a "vented interior jacket" only over the leakier areas - some or all of the basement walls, say - and seal or line the remainder of the basement as in i).
- iv) Excavate outside the basement walls and install a liner and insulation/drainage layer to the perimeter drains; seal or line the floor from inside. (The owners had already chosen this approach, but agreed to delay implementation until a presumably lower cost interior approach has been tried in this project.)
- v) Isolate the house proper from the basement, sealing off the first floor and air handling paths; if necessary, maintain the basement at a lower pressure than in the house proper.

On first viewing, it was thought that method iii), the "vented wall jacket", could best be applied to handle the Ottawa fungus case, and that was proposed (for trial purposes, pending the homeowner's pursuance of method iv). As will be seen, the first tests and first review of all circumstances led instead to the choice of method v) for trial purposes. A brief note on the basic methods ii) and iii) will serve to show their developmental track and general applicability and will help in explaining how the Ottawa case was redirected.

The "vented interior jacket" method

Today's materials and techniques make it practicable to form a nearly airtight membrane inboard of existing foundations; the provision of a vent-depressurized airspace between the membrane and the foundation can then make the whole work well in isolating indoor space from everything outside the membrane, if leaks from the airspace to the indoors and the outdoors are indeed minimal.

In February 1987 Dr. David Eyre of the Saskatchewan Research Council delivered a monograph on his depressurized buffer idea to Scanada, as a subcontractor on EMR's project "Avoiding moisture problems when retrofitting Canadian houses to conserve energy". Circulated then within EMR, Dr. Eyre's concept was next simplified by Scanada and proposed as an Unsolicited Proposal to Supply and Services Canada on 27 January 1988, still aimed directly at the retrofit of existing houses but with more emphasis on its ability to bar soil gases and radon, not just moisture. As a reviewer of the UP, CMHC suggested that the idea be brought forward to the Housing Technology Incentives Program as an immediately promising solution for the subject Ottawa fungus case, and perhaps as a test and demonstration of wider potentials.

THE HOUSE "AS FOUND": THE NEED TO REVISE THE ISOLATION METHOD

The job addressed here was to retrofit the subject house in Ottawa to free the air of fungal spores; the spores had been implicated by others as affecting the health of at least one householder. The house is a 1920's 2-1/2 storey frame/brick veneer construction with 195 sq. m. floor area and a rubblework basement about 80 sq. m. in plan (Figure 1, cover). The latter appeared to be the home of essentially all the fungus. Part of the second storey and all of the third is divided off as a second dwelling unit with its own interior stairway and exit at grade. The undivided basement underlies the whole, and the gas warm air heating system (converted from oil) serves both: the house envelope contains just one indoor air volume common to both dwelling units.

Prior to this project, an initial viewing had found that a) the fungus appeared to cover much of the south and west walls and some of the north wall of the basement; b) the fungus appeared to be somewhat within as well as on the surface of the these rubble walls; c) the walls appeared air-leaky to the soil, d) much of the wall area could be cleared for access, although extensive floor-to-ceiling shelving would have to be removed, a west wall oil tank would have to be removed or "contained" in the jacket (the tank is no longer used) and the furnace room on the north wall would have to be isolated. Further, the occupants at that time were willing, if not eager, to undertake such a disruptive process. Therefore the project was initially proposed to:

- a) Characterize the house "as now" (spore counts, types, fungi locations, airtightness characteristics...)
- b) Design & install the "vented wall jacket".
- c) Characterize the house "as retrofitted", as above. (The spores themselves would, it was hoped, serve as a "tracer gas" to show the before-and-after status)
- d) Monitor through the winter in two operational modes, again checking the spore counts and other indicators:

- i) jacket mechanically exhaust-vented,
- ii) jacket passively exhaust-vented.

The interval between the initial proposal and contracting stretched to several months (perhaps largely due to niggling questions about "ownership" of the vented jacket idea). There were considerable changes made in that period:

- The householder treated the fungus area surfaces with fungicide, sealed return air ducting to a degree, began continuous exhaust venting of the basement, and cut open the perimeter of the "fire ceiling" of the basement to allow inspection and sealing of the header zone.
- Noting considerable improvement (in all but the occasional seepage of water from outdoors), and appreciating the fact that the "interior jacket" approach should be considered as experimental in nature, the householder decided to accept the house owner's suggestion of proceeding with method v), i.e.: excavate and install an exterior liner/insulation-drainage layer around the basement walls. (This house is accessible outdoors around essentially all of its perimeter.) Understandably, the householder was no longer keen to rip down his shelving and so on to allow the jacket trial, although he remained open to helping demonstrate the concept of basement isolation as at least a temporary trial.

A further element was now added to support a change of plan: The first full tests of the house revealed:

- extremely little air leakage below grade through walls or floor (fan test with smoke pencil; four small wall leaks were close to grade and the air smelled of outdoors only, as if the paths were up through the rubble stone and not through the soil);

(Since interconnecting holes and paths were seen to extend into - and apparently through - the rubble stone, it follows that the clay soil itself is acting as an essentially airtight barrier. Recent tests for CMHC are showing that clays, silty clays and even damp silty sands may indeed act as air barriers, allowing very little "soil gas" entry.)

- a dry, airleaky house, readily amenable to maintenance of good air quality if the basement moisture and fungal growth were well controlled. Formaldehyde and other indicators were found to be at typical levels, i.e. very low. So, at least at this point, were the fungal spore counts.
- the first floor and heating ducting provided a remarkably free circuit between basement and upstairs. Tracer gas analysis, simultaneously in both zones, showed the basement tracer conveyed directly upstairs without even diffusing through the basement.

The test results are appended, Appendix 1.

The question not answered in this first testing was in regard to the extent of fungal growth within the rubble stone wall itself. In any case, the decision was made to alter the isolation design as follows.

REVISED APPROACH

Where rubble basements, or others such as brick or concrete block with porous, chambered walls, are damp or fungus-laden both superficially and within the walls, the essential problem may be to isolate the indoor air from the walls, not just from the soil. If the basement is cluttered with stored goods and fixed shelving (or if the household prefers to use it simply as an unheated cellar) then the solution may be to seal off the house from the basement at the first floor. That solution may fit a good number of houses; it fits the Ottawa fungus case well as a relatively non-disruptive trial solution.

The Ottawa case was especially amenable to this approach: with two households above the basement, a fire-resistant gypsum drywall ceiling had been installed across the underside of the first floor, as some jurisdictions call for. This had been done tokenly, but was completed under much of the return ducting, and some of the supply ducting, and was more or less ready for final bulkheading and sealing in several of such key areas. The fire ceiling had always been incomplete at the perimeter header, and had already been cut back more in that zone, by the householder, to allow inspection and attempts at header insulation and sealing. The (comprehensive sealing undertaken in this project serves to complete the important gas-seal integrity of this ceiling, which is important for fire safety performance. For full fire barrier purposes - which the ceiling never fulfilled - all sealed areas could be plastered or clad appropriately.)

Figure 1 is a photograph of the house. Figure 2 illustrates the barrier procedure followed in this case. CanAm Air Leakage Control undertook all the perimeter sealing and other gap filling/bulkheading to complete the ceiling plane as shown. The duct chase was also sealed off at the furnace room. All air leaks through the foundation above grade, and the few found just below, were also located by fan depressurization/smoke pencil and plugged with polyurethane. The householder sealed the stairway walls and weatherstripped the basement door.

It can be seen that the junction line of the rubblework with the brick/header/subfloor/sole plate planes could not be reached by the urethane to known and full effect; basement air can migrate through the rubble, up into the first floor walls or into the gaps between the floorboards, and thence into the room air above. However, that would be the case with the jacket retrofit as well, unless its "buffer" space were depressurized - which is exactly the case with the floor plane seal: the basement should be exhaust-depressurized with respect to the upstairs air if complete isolation is desired. The general airtightening of the basement - not just the first floor - may make it practicable to vent-depressurize it with just the 75 cfm fan that the householder had already installed.

The furnace is enclosed in its own room, with a fire door and token fire resistance lining around much of the room. For various reasons the room was not made airtight, so the largest pathway from basement area to upstairs is still by way of the return air side of the furnace itself. The householder has installed a makeup air opening of 150 mm diameter to the outdoors.

RESULTS

Testing of the house and sealed floor plane is reported in Appendix 2:

- airtightness: floor barrier
 basement alone
- soil gas volatile organic compounds (VOC's)
- basement air voc's
- fungus in soil gas
 basement
 upstairs

As before, no contaminants were found at worrisome concentrations. (However, the validity of fungal test procedure is suspect, as noted in the appendix.)

Isolation of upstairs from cellar now seems relatively complete. The floor plane barrier, including furnace pathways, now has an ELA of about 421 cm². Most of this remaining opening is probably into the return side of the furnace. The floor plane alone probably had an ELA of 1500 cm² or more before sealing (but much of that would have been as freely open to the attic and outdoors as it was open to the house indoor space above).


The basement alone - excluding the furnace and the first floor - is now very tight, with an ELA of about 421 cm². The below-grade portion has always been essentially airtight due to the clay soil. Soil gases as such have probably never had much of a role in the indoor conditions of this house.

DISCUSSION AND CONCLUSIONS

The option of isolating the house proper from the basement is a practicable one, even with a warm air heating system. The furnace should perhaps be isolated in its own vented room, but, even without that, the completion of the floor barrier plane below all ducting (as here done), with some further attention to the return air side of the furnace/plenum itself, seems able to provide good separation of basement from upstairs. Where needed, slight depressurization of the basement can then ensure no air movement from it or the soil to the house above.

The floor seal job here used the remnant of a fire ceiling because it was there and should be made good in any case. In most houses, the procedure would be to install polyethylene film across the basement under all ducts, joists and beams, and seal it around posts and to the perimeter header. This would be an easier and cheaper job than what was done here. With rubble or concrete block walls, the perimeter would also have to be capped, probably with urethane foam much as done here. A typical basement of 100m² might entail about \$1500 to seal the floor plane/ducting completely, or about \$2200 (\$700 extra) if polyurethane were needed to cap the foundation and seal to the perimeter. Stored materials and wall built-ins do not interfere seriously with the job of separating basement from upstairs at the first floor plane.

Where the basement space must be used by occupants with allergies seriously affected by below-grade contaminants, the contaminants must be removed or isolated. If they are related to dampness, fungi or possibly soil gases, then a) the basement must be cleared out and effectively lined or b) the walls must be dug clear on the outside and insulated/drained/barriered and the floor made good.



Project: <u>S8910</u>	<u>Appendix 2</u>	By: <u>REP</u>	Page 1 of 1
Job. No.: <u>S8910</u>	Job Title: <u>HTIP ISOLATE FUNGUS CELLAR</u>	Date: <u>31 Aug 1990</u>	




FIG. 2 FLOOR SEALING

APPENDIX 1 - THE HOUSE AS FOUND

- Airtightness Test
- Fungal Sampling
- Formaldehyde and Radon
- Tracer Gas Test
- Moisture Analysis
- Householder Survey

AIRTIGHTNESS TEST RESULTS
(AS PER CAN/CGSB - 149.10 - M86)

#20
Basement Door
Closed*

FLUE
SEALED

#20 CLOSED 8 MAR 89
Ext.Temp. = -12 C Wind Speed = 5 km/h
Envelope Area = 469 m² Volume = 685 m³
Pressure With Fan Sealed - Start: -4 Pa Finish: -4 Pa

PRESS.(Pa)		TI (C)	FLOW(L/S)			RELATIVE ERROR(%)
MEAS'D.	ADJ'D.		MEAS'D.	ADJ'D.	FITTED	
60.0	64.0	17.0	1100.00	1043.58	1020.98	2.17
55.0	59.0	17.0	1005.00	953.45	952.65	0.08
50.0	54.0	17.0	900.00	853.84	883.45	3.47
45.0	49.0	17.0	842.00	798.81	813.29	1.81
40.0	44.0	17.0	790.00	749.48	742.06	0.99
24.0	28.0	17.0	540.00	512.30	504.97	1.43
20.0	24.0	17.0	475.00	450.64	442.85	1.73
15.0	19.0	17.0	379.00	359.56	362.96	0.94

C = 29.5698

n = .851615

E.L.A. = 843.89 cm²

N.L.A. = 1.799 cm²/m²

Q @ 10Pa = 210.12 L/S

Q @ 50Pa = 827.40 L/S

Air Change per Hour @ 50Pa = 4.348

SXX= 1.914649E+12

SXY= 1.630544E+12

SYX= 1.396603E+12

SYX= 17.17897

Correlation Coefficient= .9971293

Relative Standard Error = 4.30%

* PFT's etc. run with basement door closed

AIRTIGHTNESS TEST RESULTS
(AS PER CAN/CGSB - 149.10 - M86)

FLUE
SEALED

#20 OPEN* 8 MAR 89
Ext. Temp. = -12 C Wind Speed = 5 km/h
Envelope Area = 469 m² Volume = 685 m³
Pressure With Fan Sealed - Start: -4 Pa Finish: -4 Pa

PRESS. (Pa)		TI	FLOW(L/S)			RELATIVE
MEAS'D.	ADJ'D.	(C)	MEAS'D.	ADJ'D.	FITTED	ERROR(%)
60.0	64.0	16.6	1263.00	1199.05	1207.49	0.70
55.0	59.0	16.6	1177.00	1117.40	1132.24	1.33
50.0	54.0	16.5	1129.00	1072.02	1055.64	1.53
45.0	49.0	15.0	1034.00	984.37	977.54	0.69
40.0	44.0	15.0	947.00	901.54	897.76	0.42
35.0	39.0	14.9	861.00	819.81	816.05	0.46
30.0	34.0	14.9	775.00	737.93	732.12	0.79
25.0	29.0	14.9	670.00	637.95	645.56	1.19
18.0	22.0	16.8	553.00	524.82	518.84	1.14
15.0	19.0	16.8	470.00	446.05	462.03	3.58

C = 44.99058

n = .7910408

E.L.A. = 1116.82 cm²

N.L.A. = 2.381 cm²/m²

Q @ 10Pa = 278.08 L/S

Q @ 50Pa = 993.29 L/S

Air Change per Hour @ 50Pa = 5.220

SXX = 5.602919E+12

SXY = 4.432138E+12

SYX = 3.51382E+12

SYX = 11.25465

Correlation Coefficient = .9988869

Relative Standard Error = 2.08%

* Basement door open to begin study of isolating basement
by way of first floor

* Gas furnace (water heater) flue sealed No makeup
vent

Open 1117
Closed 844
273 floor diff. but
basement involved



**ÉCO-RECHERCHES (CANADA) INC.
ECO-RESEARCH (CANADA) INC.**

121 Boul. Hymus, Pointe Claire, Québec H9R 1E6 Téléphone: (514) 697-3273 Téléc: 05-822554 Fax: 697-2090

52910

June 14, 1989

Scanada Consultants Ltd.,
436 MacLaren Street,
Ottawa, Ontario
K2P 0M8

Attention: Mr. R.E. Platts

Dear Mr. Platts:

Attached please find the completed report for the air samples taken for bacteria, yeasts and moulds at the Beauchamp house, McLeod Street, Ottawa on February 27, 1989.

We would like to draw your attention to the fact that one of the moulds (*Aspergillus fumigatus*) identified is known to be toxic to humans and a second (*Alternaria alternata*) has proved toxic in experiments.

We hope this is to your satisfaction. Please don't hesitate to contact us if you have any questions.

Yours very truly,

ECO-RESEARCH (CANADA) INC.

Pamela Wishart, B.Sc.

PW:rm
Encl.



ÉCO-RECHERCHES (CANADA) INC.
ECO-RESEARCH (CANADA) INC.

121 Boul. Hymus
Pointe Claire, Québec H9R 1E6
Téléphone: (514) 697-3273 Fax: (514) 697-2090

5891

Scanada Consultants Ltd.,
436 MacLaren Street,
Ottawa, Ontario
K2P 0M8

June 14, 1989

Attention: Mr. R.E. Platts

CERTIFICAT D'ANALYSE
CERTIFICATE OF ANALYSIS

Laboratory No.: 290761

Re: Sampling of bacteria, moulds and yeasts
at the Beauchamp house, McLeod St., Ottawa
on February 27, 1989.

Sampling Method: Biotest TCS
Centrifugal Air Sampler

Sample identification	Results	
	Bacteria CFU/m ³ air)	Yeasts and moulds (CFU/m ³ air)
#1 2nd floor south Living room Fungus only	-	13
#2 3rd floor (corridor) Fungus only	-	6
#3 Basement north-west Fungus, bacteria	69	175
#4 Basement, south-west Fungus, bacteria	131	19
#5 Basement, 5th stairs (on the middle) Fungus, bacteria	138	6
#6 Bedroom Fungus, bacteria	38	0

TOUS LES RÉSULTATS SONT EXPRIMÉS EN MG/L (PPM) À MOINS D'INDICATION CONTRAIRE.
LES ÉCHANTILLONS CONCERNANT CE RAPPORT SERONT CONSERVÉS PENDANT UNE PÉRIODE DE 30 JOURS À PARTIR DE LA DATE MENTIONNÉE CI-
HAUT À MOINS QUE D'AUTRES INSTRUCTIONS SPÉCIALES SOIENT TRANSMISES À CET EFFET.

ALL RESULTS EXPRESSED IN MG/L (PPM) UNLESS OTHERWISE STATED.
UNLESS OTHERWISE INSTRUCTED ANY SAMPLE PERTAINING TO THIS REPORT WILL BE DISCARDED 30 DAYS AFTER REPORT DATE.



58910

<u>Sample identification</u>	<u>Bacteria</u> <u>CFU/m³ air)</u>	<u>Yeasts and</u> <u>moulds (CFU/m³ air)</u>
#7 Living room Fungus, bacteria	138	6
#8 Kitchen Fungus, bacteria	106	6

The mould samples found in the basement were sent for identification. The following moulds were found:

<u>Name</u>	<u>Habitat</u>	<u>Toxicity</u>
Phialophora fastigiata	Widely spread: Wood, wood pulp, soil and seeds.	-
Cladosporium cladosporioides	Cosmopolitan and very common; air, soil textiles, paint, grains cereals, decomposing vegetable matter, etc.	-
Broomella acuta	Saprophyte: plants and other substrates.	-
Alternaria alternata	Cosmopolitan Saprophyte common to numerous plants, soil, foodstuffs, textiles, etc.	Toxic in experimental trials.
Aspergillus fumigatus	Very common contaminant, frequently found on damp organic matter and composts which they cause rapid decomposi- tion with the production of heat. They grow well at 45°C. Causes avian and human aspergilloses. Must be handled with care.	Produces several metabolites some of which are highly toxic: fumagillin, helvolic acid, gliotoxin, guionone derivatives, alkaloids similar to those from rye ergot.



58910

Unfortunately we are unable to state which moulds were found in which location in the basement, however, the moulds may well be found in many areas of the cellar now.

Pamela Wishart
Pamela Wishart, B.Sc.

Ginette Dessureault
Ginette Dessureault,
Microbiologist

:rm

Also Walkinshaw test results - Letter April 4 to
householder:

Basement 28% RH 17.5°C 175 CFU/m³
Alternaria
including few penicillium

Bedroom 2nd Fl. 39% RH 38 non sp.
19.2°C isolates

"Samples were in the borderline of normal"

Bathroom 2nd Fl. 37% RH 125 P. sp.
20°C non spor.
isolates

OTTAWA FUNGUS CASE

"As Found" cont'd

Formaldehyde - PF 1 (AQR) dosimeter, 1 week

Living room 0.015 ppm

Master B.R. 0.026

Radon - R.A.D. Surveymeter, 1 week

Not detectable... less than 0.001 WL

TRACER
GAS TEST

58910

NAHB-RESEARCH FOUNDATION
AIMS

05-01-1989

PROJECT: INDOOR IAQ
HOUSE: ALLEN 0-20START: 14:00 (02-25-1989)
STOP: 14:00 (03-04-1989)FILE: 110RI
ANALYZED: 04-26-1989

***** RATES *****

OVERALL INFILTRATION RATE = $-1.1 \pm 107.3 (m^3/h)$
OVERALL AIR EXCHANGE RATE = $-0.001 \pm 0.111 (1/h)$

ZONE	LOCATION	SOURCE RATE (nL/m)	QTY	EXFILTRATION RATE (nL/h)	SD	INFILTRATION RATE (m ³ /h)	SD	ACH	SD
1	BASEMENT	35.0	2	2521	-444.0	212.0	219.9	53.7	1.279
2	LIV RM	24.4	2	2518	442.9	118.8	-221.0	149.1	-0.279

ZONE-ZONE	RATE	SD	ZONE-ZONE	RATE	SD
1 - 2	780.5	282.7	2 - 1	116.6	42.2

ZONE	RATE \pm SD (m ³ /h)	ACH \pm SD (1/h)	ZONE	RATE \pm SD (m ³ /h)	ACH \pm SD (1/h)
1	336.5 \pm 91.4	1.957 \pm 0.540	2	559.6 \pm 152.0	0.706 \pm 0.195

***** ANALYSIS *****

ZONE	VOL	SOURCE TYPE	PMCP	PMCH	AVG. TRACER CONC. (pL/L) \pm SD
1	172	PMCP	14.50 \pm 1.45	3.02 \pm 0.30	
2	792	PMCH	20.22 \pm 2.02	8.71 \pm 0.87	

CATS#	PMCP	PMCH	PDCH	PDCH	CONCENTRATION (pL/L)
1	2280	14.497	3.020	0.000	0.000
2	500	20.225	8.713	0.000	0.000

C.F.: PDCH PMCP PMCH PDCH COEFFICIENTS FILE
0.98 0.98 0.99 0.00 3WSCLLL1

***** NOTES *****

The standard deviation in the source strength has been set at 10 %.
The standard deviation in the volume measurement has been set at 5 %.
C11 IS LESS THAN C12
EXFILTRATION RATE FOR ZONE 1 IS NEGATIVE
INFILTRATION RATE FOR ZONE 2 IS NEGATIVE

Need do over, Tracer not well mixed (?)
More CAT tubes needed for 1st & 2nd floor
Ideal case would be for 3-zone analysis

For more information
on analysis, call MR. BEN-HUAT SONG,
of AIMS Laboratory @ (301) 249-4000,
-1- to D Maryland.

MOISTURE ASSESSMENT

1

S8909 MAPP VALIDATION : FIELD OBSERVATIONS

Ottawa
Case 20 Homeowner Anon Tel. home Scania File S8910
Address Ottawa Tel. office S8909-#20
Date/time/technologist 25 Feb REP 1400 hrs
1989

CONDITIONS AND HOUSE PERFORMANCE

25 Feb.
[Outdoors: temp. -7?; apparent wind speed/direction 0-5 km/hr
Nearest sta. temp. -9; measured wind speed/direction _____
Indoors: Main floor temp. 21°C RH 23%
MARCH 8 Basement temp. 13°C RH 30%
Upper floor temp. _____ RH _____

Condensation on Indoor surface of double-glazed* windows: NONE
(on centreline, note height of condens. from bottom of glass, and presence of metal thermal bridge at that edge; note height up to which condens. is frozen. Ignore sunlit windows.)

a) Windows with all curtains/blinds open (for past 1 hr. min.):

window no.	1	2	3	4	5
location					

- a) none or almost none
- b) bottom area of glass
- c) up to mid-height
- d) all or almost all glass

b) Windows with heavy drapes or blinds closed (mark H) or sheer curtains pulled across (mark L, light) for at least past 2 hrs:

window no.	6	7	8	9	10
location					

- a) none or almost none
- b) bottom edge of glass
- c) up to mid-height
- d) all or almost all glass

* If single-glazed, mark SG.

Householder's observations of windows through monitoring period:

Disregarding sunlit windows, kitchen, bathroom, and basement, and windows where drapes, curtains or blinds are closed through the day, the condensation pattern in daytime on the indoor surface of double glazed* windows is:

	a) none or almost none (check ____)	b) bottom area of glass	c) up to mid-hgt	d) all or almost all glass
1) On cold mornings	✓			
2) Through cold days	✓			
3) through most days	✓			

Householder's recollection from midwinter periods generally

In this year's midwinter weeks ✓ and/or those of the last few years (specify) ✓, the window condensation has been about the same ✓ or somewhat worse or somewhat less than the pattern recorded above for this monitoring period.

Within those years, occupancy changes or house renofits occurred as follows, with approximate dates noted and also when condensation pattern changed: _____

Other visual observations (generally with the householder, at beginning or end of monitoring period):

Interior surface condensation or telltale mould, dustmarking, water stains on ceiling or below windows _____.

Describe: _____

* If single-glazed, mark SG.

Gross leaks into envelope:*from basement into exterior walls - several*

Where possible, check in attic around chimney _____, plumbing stack _____ vent pipes _____, gas vents _____; closet tops _____ and dropped ceilings _____, exhaust ducts _____, balloon frame wall tops _____, and attic hatches _____, or doors _____; and describe any gross leaks ie. those where 4 or more fingers could be poked freely through the ceiling plane, or of equivalent area. (Reasonably fitted hatches and electrical fixtures are not gross leaks.) _____

Check around exterior walls at under-sink pipe penetrations _____, bathtubs against exterior walls (looking from underneath where possible) _____, openings from the basement area into the exterior walls ☒; and around recessed medicine cabinets _____, radiator housings _____, exhaust fan housing _____; and warm air ducts in walls _____ or where floor registers or boots intrude under interior finish _____; and describe any gross leaks, ie. where at least one finger could be poked into the exterior cavity, or of equivalent area. _____

*✓ ducts/pipes/wiring - main entry*Envelope moisture observations/measurements*not accessible*

Attic: Visible frost, ice, wetness, mould on sheathing and rafters or truss chords: Describe, including notes on frost thickness and density if accessible, and extent (coverage area) of moisture or telltales:

If accessible, probe and record moisture meter readings on wettest area of sheathing _____ and rafters/chords _____.

Also read close-by dry-looking surfaces of each _____

Record attic temperature at time of meter rdg. _____

Exterior walls and header (band joist) area, where accessible:

From outside: Moisture probe bottom edge of sheathing every four meters or so, and record all, noting location around perimeter wherever rdg. exceeds 15 in cold weather. Identify type of sheathing. _____

Moisture probe underside of window sills, inside drip kerf if any, at corners and in centre. Record all, noting location wherever rdg. exceeds 15 in cold weather _____

From interior: Moisture probe interior surface of exterior sheathing wherever accessible through electrical cover plates (those that can be removed without marring interior paint or finish.) Record all readings, and record locations of any exceeding 15. _____

HOUSE CHARACTERISTICS AND HOUSEHOLD DATA

(All data on house dimensions, volume, surface area must be recorded separately with the ELA report, following the CGSB test protocol and satisfying the A.G. Wilson outline of 13 Dec 88.)

1. Gathering basic data needed to categorize airleakiness visually (part of basis of "MAPP Pass")

- (1) Year built _____; group: pre 1920 ☒; 1921-45 _____; 1946-1960 _____; 1961 to 1970 _____; post 1970 _____;
- (2) Bldg. type: 1 storey _____ 1.5 _____ 2 _____ 2.5 ☒; raised basement _____; split level _____.

(3) Construction category:

- a) Balloon frame ✓ or other pre 1945 inc. solid masonry _____. (Note no. of stories inc. 3 or 3.5 for this pre '45 group _____) Note stucco classes are separate, below.
- b) Platform frame, board subfloor general _____.
- c) Platform frame, 1.5 storey, plywood subfloor _____.
- d) Pre 1945 fully stuccoed _____.
- e) Platform frame plywood subfloor general _____.
- f) Post 1945 fully stuccoed (incl. over foundation). _____
Note other degrees of stucco and cladding tightness are covered below.

(Disregard any ELA test experience in filling in 4 to 15)

(4) Tight cladding: House is predominantly covered with:

- a) Wood clapboard heavily painted/repainted, laps and ends thereby sealed; caulked to window trim, corners etc. _____
 - N^o b) Panel type siding (plywood, hardboard) with joints battened; caulked to window trim, corners etc. _____
 - c) Stucco not included in category 3d) or 3f); not covering full house and/or not applied over foundation/sill area _____. (It still comprises a tight cladding but not extremely tight as in 3f)
 - d) Re-siding applications over existing siding where rigid insulation and/or "house wrap" has been applied and caulked to all openings, covers ... and across sill to foundation _____
 - e) Other apparently tight cladding _____ Describe _____
- 5) Unknown cladding, possibly tight: Re-siding applications over older painted clapboard, panel or stucco cladding.
- 6) Loose cladding (airleaky): brick veneer ✓ proprietary lop siding over building paper _____, other _____.

- 7) Tight windows: For a house of this age, the windows appear unusually tight because:
- a) Generally painted shut, heavily painted or caulked trim; the operable windows can not be hand rattled ... seem unusually tight _____.
 - b) Windows unusually well weatherstripped, trim caulked _____.
 - c) Aluminum self-storing storms, well sealed to window easing or trim _____.
 - d) Tight new windows, well installed and sealed to casing or trim inside and/or outside _____.
- 8) Windows seem just normally tight for house of this age ✓.
- 9) Windows seem abnormally loose, airleaky, more so than age of house would suggest. _____
- 10) Entry doors seem unusually tight _____ or about normal ✓ or unusually loose, airleaky _____ for house of this age.
- 11) Basement seems unusually tight _____ (eg. cast concrete incl. floor, unusually crack-free, or extensive interior finishing for house of this age); or about normal _____ or unusually air-leaky ✓. Foundation construction and floor drain are covered in part 2,17.)
- 12) House has been commercially airtightened: all interior, and sill area _____.
- 13) Attic has been fully insulated with cellulose fibre at least 100 mm thick ✓ *as accessible in upper attic* or with mineral wool where poly v.b. and general sealing was done over old insulation. _____.
- 14) Walls have been fully insulated with cellulose fibre part .
- 15) House is far from compact: unusually irregular or extended or winged shape _____ and/or overhanging floors _____ and/or rooms over garage or carport _____ offer generous perimeter and surface areas; abnormally high surface/volume ratio. _____

*Rubblework
Foundation*

2. Gathering Basic data needed to follow MAPP in detail

Some or most of the following may be needed for a given case:

A. Information that May Be Needed to Assess Moisture Generation

- (1) Number of occupants 1 2 3 4 ⑤ 6 7 8
- (2) Number normally home only at night 1 2 3 4 ⑤ 6 7 8
- (3) Clothes dryer yes[✓] no[]
- (4) -vented outdoors in heating season (HS) yes[✓] no[]
- (5) Hanging laundry to dry indoors in HS
 -the odd piece or two, now and then []
 -a little of the washing, regularly [✓]
 -most or all of the washing, regularly []
- (6) Kitchen fan* (disregard charcoal or other recirculating types) yes[] no[✓]
- (7) -used in HS when cooking, boiling water or dishwashing
 almost always[]
 whenever needed to clear windows or odours[]
 rather seldom[]
- (8) Bathroom fan(s)* in bathroom(s) where most bathing/showering is done yes[] no[✓]
- (9) -used in HS when bathing/showering almost always[✓]
 whenever needed to clear windows[]
 sometimes[]
- [* Check to see that fans do not exhaust into the attic.]
- (10) Humidifiers none[] portable[] on warm air[✓] *drum type*
- (11) -used during HS almost always[✓]
 sometimes[]
 seldom[]
- (12) -if on warm air furnace...setting in midwinter, %RH[40]
- (13) Dehumidifiers none[] basement, summer-fall []
- (14) -if other usage and/or placement, identify... []

- (15) Hobbies or activities likely to give off moisture freely, and not specially vented? Identify*...

[* Examples include indoor greenhouse or hydroponic gardens, large aquariums, whirlpool baths, hairdressing salons... Not included are most arrays of house plants; or saunas, photography labs or other facilities or activities that add little moisture to the air, or only now and then.]

- (16) Foundation type

mostly basement[✓]
mostly crawlspace[]
mixed[]
slab-on-grade[]

- (17) Foundation wall

concrete[]
conc. block[]
stone, brick...[✓]

- (18) Dirt floor

none[]
about quarter of floor*[✓]
about half of floor[]
most or all of floor[]

[* "floor" meaning whole plan area of house on ground]

- (19) Dirt floor appears in winter to be

dry[]
damp[✓]
wet[]

- (20) Ground cover (polyethylene [] or other[])

yes[] no[✓]

- (21) Water pools on ground cover, fall-winter

yes[] no[✓]

- (22) Water floods over considerable area of basement floor (any material or finish) in fall-winter

never or rarely[]
some years[✓]
often[]

- (23) Floor drain

yes[✓] no[]

- (24) -usually open to storm/drain tile in HS

yes[] no[✓]

- (25) Water seepage through considerable area of foundation walls (liquid water) in HS

yes[✓] no[]

- (26) Areas of efflorescence, mould and/or dampness on foundation walls in HS

essentially none[]

75 cfm fan
Basement vented to
help control mold
+ IAQ

a few small spots[]
many spots and/or some large areas[✓]

- (27) Temperature of basement area in HS well below 15 C [✓]
(or most of area...) around 15 C []
well above 15 C []

- (28) Plan area of house on ground [66.4 m²]
[ft²]

B. Information Relating to Midwinter Air Change Rate
(climatic data are built in to the MAPPs for the various locations)

- (29) Airleakiness: ELA, standard fan depress. m²[.112]

- (30) House height: the height above grade
(disregarding unheated attic...) is about: one storey[]
or between one and
two stories, eg.,
raised basement, or
bungalow on sloped grade[]
two or more storeys[✓]

- (31) House exposure: * First, the general
"terrain" around much of the site
can best be described as:
1. ocean or large lake []
 2. flat terrain, few if any obstructions to winds []
 3. rural, low bldgs. & scattered trees []
 4. urban, industrial or forest area [✓]
 5. centre of large city with high-rise bldgs. []
- [* adapted from the
LBL studies -
Lawrence Berkeley
Laboratories]

- (32) House exposure: Second, the close-
in "shielding" or shelter (within
2 or 3 house heights from the
house) can best be described as
1. none: no close-by shelter []
 2. a few scattered obstructions []
 3. some obstructions []
 4. obstructions practically all around [✓]
 5. large obstructions all around house...[]

- (33) House has an active flue(s) yes[✓] no[]
 (i.e. venting the main combustion heating device. Do not count flue from airtight wood stove or condensing or other high efficiency furnace, or from fireplace with damper normally closed)
- (34) House has passive flue(s) yes[] no[✓]
 (incl. fireplace if used often or if damper left open through HS; or any flue normally open from indoors to outdoors)

C. Recollections Indicating Indoor RH, Midwinter, House "As Is"

The householder's recollection of midwinter window condensation fits most closely to which one, or possibly two, of the following descriptions? (Disregard kitchen and bathroom windows and those where heavy curtains, blinds or drapes are drawn at night. Consider only condensation on the indoor surface of double glazing.)

- (a) Almost all the glass is covered "always"... "most days"... Water often runs down on and over sill... The condens. persists into early spring or even later []
- (b) Almost all the glass is covered "often"... "every cold day"... water sometimes runs down on to sill []
- (c) Almost all the glass is covered only "on coldest mornings"... "on windy, cold days"... And/or bottom area of glass is covered "often"... "most mornings" []
- (d) Little condensation in midwinter... bottom area of glass on cold mornings []
- (e) "Almost none"... "bottom edge of glass only on cold mornings" [✓]

Filename: _____

Date: _____

	assumption made	action taken
exposure class:	<u>4</u>	_____
height class:	<u>2 (2.5)</u>	_____
EIA @10 pa:	<u>.112 m²</u>	_____ <i>flue seals + combustion air duct seals</i>
adjustments for flues:	<u>1</u>	_____
number of occupants:	<u>5</u>	_____
dryer vented:	<u>yes</u>	_____
kitchen - bathrm. fan:	<u>no</u>	_____
hobbies - cooking:	<u>—</u>	_____
below grade moisture:	<u>yes but</u>	_____

very cool

*(12-13°C) + fan-vented +
combustion
air duct*

AGW:

How much basement moisture?

It would seem to qualify for at least

$$10 \text{ kg/100 mm/day} = \frac{66}{100} \times 10 = \underline{6.6 \text{ kg/day}}$$

*Apparently about 4 kg/day used for
MRD diagram. yes*

*no -
very
cool
yes*

AIRTIGHTNESS TEST RESULTS
(AS PER CAN/CGSB - 149.10 - M86)

#20 OPEN * *Scania (ottawa)* 8 MAR 89
Ext. Temp. = -12 C Wind Speed = 5 km/h
Envelope Area = 469 m² Volume = 685 m³
Pressure With Fan Sealed - Start: -4 Pa Finish: -4 Pa

PRESS. (Pa)		TI	FLOW (L/S)			RELATIVE
MEAS'D.	ADJ'D.	(C)	MEAS'D.	ADJ'D.	FITTED	ERROR (%)
60.0	64.0	16.6	1263.00	1199.05	1207.49	0.70
55.0	59.0	16.6	1177.00	1117.40	1132.24	1.33
50.0	54.0	16.5	1129.00	1072.02	1055.64	1.53
45.0	49.0	15.0	1034.00	984.37	977.54	0.69
40.0	44.0	15.0	947.00	901.54	897.76	0.42
35.0	39.0	14.9	861.00	819.81	816.05	0.46
30.0	34.0	14.9	775.00	737.93	732.12	0.79
25.0	29.0	14.9	670.00	637.95	645.56	1.19
18.0	22.0	16.8	553.00	524.82	518.84	1.14
15.0	19.0	16.8	470.00	446.05	462.03	3.58

C = 44.99058

n = .7910408

E.L.A. = 1116.82 cm² **

N.L.A. = 2.381 cm²/m²

Q @ 10Pa = 278.08 L/S

Q @ 50Pa = 993.29 L/S

Air Change per Hour @ 50Pa = 5.220

SXX = 5.602919E+12

SXY = 4.432138E+12

SYY = 3.51382E+12


SYX = 11.25465



Correlation Coefficient = .9988869

Relative Standard Error = 2.08%



* Basement door open

** Gas furnace + water heater, fine sealed. Combustion
air sealed +
basement fan
sealed

3. Inland Medium: One-Page MAPP



~~MONDAY~~ ~~16/11/20~~ ~~TUESDAY~~ ~~17/11/20~~ ~~WEDNESDAY~~ ~~18/11/20~~ ~~THURSDAY~~ ~~19/11/20~~ ~~FRIDAY~~ ~~20/11/20~~ ~~SATURDAY~~ ~~21/11/20~~ ~~SUNDAY~~ ~~22/11/20~~



(EMR form)

House 0-20

58910

Contents

Page	Section	Page	Section
1	Occupant Information	5	Comparative Homeowner Information
3	Homeowner Information	6	Energy Consuming Appliances or Activities
4	R-2000 Homeowner Information	8	Air Quality Information

Note: The person being interviewed has been identified throughout this questionnaire as the Occupant. Another person who shares the responsibilities of the household is identified as the Spouse.

FOR OFFICE USE

Occupant Information

600. Occupant Name:

(Surname)

(Initial)

600

Mailing Address:

601. Street:

601

602. City:

602

603. Postal Code:

603

Telephone numbers of occupant & spouse:

Home:

Work:

Work:

(Area Code)

(Number)

Homeowner (If different from the occupant)

Name:

Address:

Phone:

This case
has been taken
on for study
on basement
mould &
means of
isolation
BP

FOR OFFICE USE

604. What type of house is this?

1 - R-2000 Demo

2 - R-2000 ID or repeat 3 - Comparative

604

605. Date the house was occupied:

1985

(MM DD YY)

605

606. Is this the original occupant?

1 - Yes

2 - No

606

2607. Number of occupants over 18 years of age?3

607

3608. Number of occupants under 18 years of age?2

608

2609. How many occupants over 18 years of age remain home during the major portion of the working day? 0

609

0610. How many occupants under 18 years of age remain home during the major portion of the working day? 0

610

0

611. Is the occupant the:

1 - owner

2 - renter

3 - owner/builder

611

2

612. What is the approximate age of the occupant?

1 - 18-30

2 - 31-45

3 - 46-60

4 - over 60

612

2

613. What is the approximate age of the spouse?

-1 N/A

1 - 18-30

2 - 31-45

3 - 46-60

4 - over 60

613

2

614. What are the primary occupations of the occupant and the spouse?

to

615.

614. Occupant 10615. Spouse 15

-1 - N/A

10 - Professional

11 - Manager/Admin.

12 - Technical

13 - Sales

14 - Clerical

15 - Trades

16 - Homemaker

17 - Student

18 - Retired

99 - Other

614

10

615

15

616. What was the occupants previous residence?

1 - an apartment

2 - a row home

3 - a semi-detached home

4 - a detached home

616

1

617. Did the occupants own or rent their previous residence?

-1 - N/A

1 - owned

2 - rented

617

2

THE HOMEOWNER SURVEY

FOR OFFICE USE

618. If the occupant rented their previous residence, how did they pay to for the following utilities?
620.

-1 - N/A 1 - paid directly
2 - Included in rent 98 - don't know

618. Space Heating _____ 618 98

619. Water Heating _____ 619 98

620. Lights and Appliances _____ 620 98

621. Was this house built as a custom home for the present homeowner?

1 - Yes 2 - No 98 - don't know 621 2

Note: A custom home is a home that the homeowner ordered built and had input to the basic design and/or construction techniques.

622. What does the occupant feel will happen to energy prices in the to future?

623. 1 - Increase 2 - remain constant 3 - decrease 98 - don't know

622. over the next 5 years _____ 622 _____

623. over the next 10 years _____ 623 _____

IF THE OCCUPANT RENTS THE RESIDENCE GO TO QUESTION 663.

Homeowner Information

625. For how many years do the occupants expect to own their home?

1 - 5 years or less 2 - 6 to 10 years
3 - 11 to 15 years 4 - more than 15 years
98 - don't know 625 _____

626. What was the purchase price of the home, excluding the price of the land? _____ 626 _____

627. Was the homeowner aware of the R-2000 Program before they purchased their home?
1 - Yes 2 - No 627 _____

628. If the homeowner decided to purchase another home, would they consider the purchase of an R-2000 home?
1 - Yes 2 - No 98 - don't know 628 _____

If the home occupant answered NO to question 628, place the reason in the comment section below.

THE HOMEOWNER SURVEY

FOR OFFICE USE

681. List the features inside the home which contribute to increased energy consumption.

681 _____

685.

- 97 - none
- 21 - well pump
- 22 - sump pump
- 23 - sauna
- 24 - workshop
- 25 - indoor pool

- 26 - whirlpools
- 27 - energy intensive hobbies
- 28 - garbage compactor/shredder
- 29 - central vacuum
- 30 - open windows/doors
- 99 - Other _____

682 _____

683 _____

684 _____

685 24

687. List the features outside the home which contribute to increased energy consumption.

687 97

691.

688 _____

- 97 - none
- 32 - outdoor pool
- 33 - electric gardening tools
- 34 - yard lighting

- 35 - separate workshop
- 36 - heated walk/driveway
- 99 - Other _____

689 _____

690 _____

691 _____

692. Does the occupant use a block heater?

1 - Yes 2 - No

692 2

695. If the occupant uses a vehicle block heater, calculate the total hours per year the block heater is used. Otherwise, enter -1 for Not Applicable.

_____ X _____ X _____ = _____
hrs/day No. of vehicles days/yr total hrs/yr

695 _____

696. Since the home has been occupied, are there areas attached to the home which were not previously heated, and are now heated?

- 97 - none
- 3 - addition
- 99 - Other _____
- 21 - garage
- 54 - sunspace

696 27

THE HOMEOWNER SURVEY

FOR OFFICE USE

Air Quality Information

700. Does the occupant have any concerns regarding the air quality in the home?

1 - Yes 2 - No

700 1

IF THE ANSWER TO QUESTION 700 WAS YES, COMPLETE QUESTIONS 701 TO 724, OTHERWISE GO TO QUESTION 725.

701. Identify any air quality concern(s) by indicating whether or not the following occurs during the summer and/or winter. Do not prompt the occupant.

1 - minor problem
2 - moderate problem

3 - severe problem
97 - no problem

Summer Winter

Moisture/humidity (701-712)

window panes, sills and trim

701 _____ 702 _____

mildew in room ceiling corners

703 _____ 704 _____

sensory perception of moisture

705 _____ 706 _____

warped or swollen doors

707 _____ 708 _____

damp basement floors or walls

709 _____ 710 _____

other: fungus

711 _____ 712 _____

Comments: _____

701 _____

702 _____

703 _____

704 _____

705 _____

706 _____

707 _____

708 _____

709 3

710 2

711 _____

712 1-2?

Odours (713-718)

In the kitchen

713 _____ 714 _____

In the bathroom

715 _____ 716 _____

other: _____

717 _____ 718 _____

Comments: _____

713 _____

714 _____

715 _____

716 _____

717 _____

718 _____

Dry Static Air (719-724)

sensory perception

719 _____ 720 _____

(eg. dry throat)

static electricity

721 _____ 722 _____

other: _____

723 _____ 724 _____

Comments: _____

719 _____

720 _____

721 _____

722 _____

723 _____

724 _____

THE HOMEOWNER SURVEY

FOR OFFICE USE

725. Approximately how many cigarettes are smoked in the home per day?

725 none

726. Are any pipes or cigars smoked in the home?

1 - Yes 2 - No

726 2

727. Approximately how many plants are in the home? _____

727 minimal

728. Approximately how many of these are spider plants? _____

728 none

Note: spider plants have the ability to absorb certain amounts of formaldehyde from the air.

now!

729. List the occupant's hobbies that could effect the air quality in the home?

732.

97 - none
41 - pottery/crafts
42 - wood working
43 - mechanical work

44 - oil painting
45 - beer/wine making
46 - furniture refinishing
99 - other (specify) _____

729 42

730 _____

731 _____

732 _____

735. Prior to moving into the home, were any members of the family sensitive to the following problems? Indicate these below.

740.

(Enter 1 - Yes or 2 - No)

735 1

736 _____

737 _____

738 _____

739 _____

740 _____

	Adults	Children
Allergies	735 <u>1</u>	736 _____
Asthma	737 _____	738 _____
Other: _____	739 _____	740 _____

741. What is the source for water used in this house?

1 - municipal water
2 - homeowner spring or surface well
3 - homeowner well deeper than 25 feet
99 - other

741 1

742. Where does the clothes dryer vent?

-1- N/A 3 - indoors in winter/outdoors in summer
1 - indoors 4 - directly to the HRV
2 - outdoors

742 2

THE HOMEOWNER SURVEY

FOR OFFICE USE.

745. How often does the occupant operate the following equipment?
to

752. -1 - N/A 2 - Intermittantly
1 - continuously 3 - never used

745. humidifier in winter	_____	745	<u>1</u>
746. dehumidifier in summer	_____	746	_____
747. electronic air cleaning equipment	_____	747	_____
748. HRV in the summer	_____	748	_____
749. HRV in the winter	_____	749	_____
750. furnace blower - in winter	_____	750	<u>2</u>
751. furnace blower - in summer	_____	751	_____
752. air conditioning	_____	752	_____

753. Has a manual been provided for the operation and maintenance of the
to ventilation and heating system(s)?

754. -1 - N/A 1 - Yes 2 - No

753. ventilation system	_____	753	<u>2</u>
754. heating system	_____	754	_____

755. Is the occupant aware of the need to perform the following
to mechanical system maintenance?

760. -1 - N/A 1 - Yes 2 - No

755. clean the HRV filters	_____	755	_____
756. clean the HRV core	_____	756	_____
757. check the HRV intake hood	_____	757	_____
758. adjust the humidistat setting	_____	758	<u>1</u>
759. change the furnace filter	_____	759	<u>1</u>
760. clean the electronic air cleaner	_____	760	_____


Note: If the occupant answers no to any of the above questions, impress upon the homeowner the importance of regular equipment maintenance in terms of air quality, equipment longevity and energy savings. Ask them to refer to the appropriate manuals regarding operation and maintenance.

REP
31 MAY 89

APPENDIX 2

THE HOUSE AS RETROFITTED

- Airtightness test
indicating the
tightness of the first
floor/heating system
- Soil gas tests
- Basement air tests
- Fungus sampling: in
soil gases and in
basement and house air



Project: <u>FLOOR LEAKAGE CHARACTERIZATION</u>	By: <u>K. RUEST</u>	Page / of /
Job. No.: <u>58910</u>	Job Title: <u>OTTAWA FUNGUS BASEMENT</u>	Date: <u>MARCH 28/90</u>


	TEST	ELA	
TEST 1	$A_2 + B_2 = 1577.01 \text{ cm}^2$		(basement door open)
TEST 2	$A_2 + C_2 = 1397.12 \text{ cm}^2$		(basement door closed)
TEST 3	$B_2 + C_2 = 825.23 \text{ cm}^2$		(depress. basement to outdoors) (kitchen door open)
			- Makeups duct open -

$$C_2 = \frac{\text{TEST 1} \quad \text{TEST 2} \quad \text{TEST 3}}{(A_2 + C_2) + (B_2 + C_2) - (A_2 + B_2)} \quad 2$$

$$C_2 = \frac{(1397.12) + (825.23) - (1577.01)}{2}$$

$$C_2 = \frac{645.34}{2}$$

$$C_2 = \underline{322.67 \text{ cm}^2} \text{ — FLOOR LEAKAGE "ELA"}$$



Check:

825.23 cm^2 — BASEMENT & FLOOR "ELA"
 $- 322.67 \text{ cm}^2$ — FLOOR LEAKAGE "ELA"
 $B_2 \quad 502.56 \text{ cm}^2$ — BASEMENT LEAKAGE EXCLUDING FLOOR "ELA"

1397.12 cm^2 — FLOOR & ABOVE "ELA"
 $- 322.67 \text{ cm}^2$ — FLOOR LEAKAGE "ELA"
 $A_2 \quad 1074.55 \text{ cm}^2$ — HOUSE LEAKAGE ABOVE BASEMENT "ELA"

$$\begin{array}{r}
 1074.55 \quad A_2 \\
 + 502.56 \quad B_2 \\
 \hline
 1577.11 \quad (A_2 + B_2)
 \end{array}$$

Note: the subscript 2, as in A_2 , refers to the post-tightened period. A was not tightened.

AIRTIGHTNESS TEST RESULTS
(AS PER CAN/CGSB - 149.10 - M86)

A2+B2, WHOLE HOUSE.. FEB.23, 1990
Ext.Temp. = -3.4 C Wind Speed = 15 km/h
Envelope Area = NOT AVAILABLE Volume = ~~1 m^3~~
Pressure With Fan Sealed - Start: 0 Pa Finish: 0 Pa

PRESS.(Pa)		TI (C)	FLOW(L/S)			RELATIVE ERROR(%)
MEAS'D.	ADJ'D.		MEAS'D.	ADJ'D.	FITTED	
60.0	60.0	17.0	1397.00	1346.99	1394.94	3.56
55.0	55.0	17.0	1369.00	1320.00	1311.66	0.63
50.0	50.0	17.6	1282.00	1234.83	1226.13	0.71
45.0	45.0	17.2	1196.00	1152.79	1138.05	1.28
40.0	40.0	17.4	1091.00	1051.22	1047.06	0.40
35.0	35.0	17.2	1005.00	968.69	952.67	1.65
30.0	30.0	17.4	933.00	898.98	854.23	4.98
25.0	25.0	17.9	766.00	737.44	750.85	1.82
20.0	20.0	16.7	651.00	628.02	641.20	2.10
15.0	15.0	17.3	519.00	500.16	523.11	4.59
10.0	10.0	17.7	386.00	371.74	392.66	5.63

C = 77.00329

n = .7075028

E.L.A. = 1577.01 cm²

N.L.A. = NOT AVAILABLE

Q @ 10Pa = 392.66 L/S

Q @ 50Pa = 1226.13 L/S

~~2.14 Change from 1.05 Pa to 0.50 Pa = 2.14 x 1.055~~

SXX= 1.533813E+13

SXY= 1.085177E+13

SYX= 7.742752E+12

SYX= 26.1352

Correlation Coefficient= .9957876

Relative Standard Error = 3.21%

AIRTIGHTNESS TEST RESULTS
(AS PER CAN/CGSB - 149.10 - M86)

A2+C2, FLOOR & ABOVE FEB.23, 1990
Ext.Temp. = -3.4 C Wind Speed = 15 km/h
Envelope Area = NOT AVAILABLE ~~Volume = 1 m³~~
Pressure With Fan Sealed - Start: 0 Pa Finish: 0 Pa

PRESS.(Pa)		TI	FLOW(L/S)			RELATIVE
MEAS'D.	ADJ'D.	(C)	MEAS'D.	ADJ'D.	FITTED	ERROR(%)
60.0	60.0	13.6	1244.00	1206.56	1231.13	2.04
55.0	55.0	16.0	1187.00	1146.49	1157.84	0.99
50.0	50.0	16.3	1139.00	1099.56	1082.56	1.55
45.0	45.0	16.6	1034.00	997.68	1005.02	0.74
40.0	40.0	16.7	957.00	923.22	924.89	0.18
35.0	35.0	16.6	919.00	886.72	841.75	5.07
30.0	30.0	16.7	813.00	784.30	755.03	3.73
25.0	25.0	16.5	708.00	683.25	663.91	2.83
25.0	25.0	15.7	661.00	638.77	663.91	3.94
20.0	20.0	15.9	550.00	531.32	567.22	6.76
15.0	15.0	16.0	452.00	436.57	463.04	6.06

C = 68.55388

n = .7053793

E.L.A. = 1397.12 cm²

N.L.A. = NOT AVAILABLE

Q @ 10Pa = 347.87 L/S

Q @ 50Pa = 1082.56 L/S

~~Air Change per Hour @ 50Pa = 1.9937-200~~

SXX= 8.677981E+12

SXY= 6.121268E+12

SYY= 4.377914E+12

SYX= 27.90397

Correlation Coefficient= .9931124

Relative Standard Error = 4.06%

AIRTIGHTNESS TEST RESULTS
(AS PER CAN/CGSB - 149.10 - M86)

B2+C2, FLOOR & BELOW

FEB.23, 1990

Ext.Temp. = -3.4 C

Wind Speed = 15 km/h

Envelope Area = NOT AVAILABLE

~~Volume = 1 m³~~

Pressure With Fan Sealed - Start: 0 Pa Finish: 0 Pa

PRESS.(Pa)		TI (C)	FLOW(L/S)			RELATIVE ERROR(%)
MEAS'D.	ADJ'D.		MEAS'D.	ADJ'D.	FITTED	
60.0	60.0	11.0	775.00	755.11	780.72	3.39
55.0	55.0	10.9	746.00	726.98	731.71	0.65
50.0	50.0	10.0	718.00	700.80	681.56	2.75
45.0	45.0	10.7	670.00	653.15	630.10	3.53
40.0	40.0	10.8	622.00	606.25	577.17	4.80
35.0	35.0	12.4	505.00	490.83	522.51	6.45
30.0	30.0	11.6	461.00	448.69	465.82	3.82
25.0	25.0	11.3	409.00	398.29	406.66	2.10
20.0	20.0	11.0	348.00	339.07	344.37	1.56
15.0	15.0	11.0	296.00	288.40	277.94	3.63

C = 36.96043

n = .745019

E.L.A. = 825.23 cm²

N.L.A. = NOT AVAILABLE

Q @ 10Pa = 205.47 L/S

Q @ 50Pa = 681.56 L/S

Air Change per Hour @ 50Pa = ~~22453.604~~

SXX= 1.119946E+12


SXY= 8.343813E+11

SYX= 6.34011E+11

SYX= 22.05046

Correlation Coefficient= .9901878

Relative Standard Error = 5.56%



Project: <u>SUMMARY OF RESULTS</u>	<u>IAQ</u>	By: <u>KEN RUEST</u>	Page 1 of 2
Job. No.: <u>58910</u>	Job Title:	Date: <u>SEPT 5/90</u>	Appendix 2

SF6 AIR CHANGE RATE 1.40 AC/Hr

(Bag method)
RCS BIO-TEST (FUNGUS & MOLD RESULTS) *

	FUNGAL & MOLD	
BASEMENT (SOUTH-WEST CORNER)	1 (MOLD)	6 CFU (mold)/m ³
LIVING ROOM	0	0 CFU/m ³ of air
MASTER BEDROOM	0	0 CFU/m ³ of air
BASEMENT (NORTH-WEST CORNER)	0	0 CFU/m ³ of air
WALL HOLE SAMPLING	0	0 CFU/m ³ of air
DRAIN SAMPLING	0	0 CFU/m ³ of air

FLUORISIL SAMPLING **

SAMPLING SITE	WEIGHT OF DEPOSIT mg.	CONCENTRATION mg./m ³	GAS
WALL SAMPLING near grade level	2	0.222	DICAMBA
	0.047	0.005	2,4,5 TP
	0.058	0.006	2,4 D
DRAIN SAMPLING	2	0.222	DICAMBA
	0.058	0.006	2,4,5 TP
	0.047	0.005	2,4 D
BASEMENT AIR	(NO SAMPLE LEFT FOR ANALYSIS SINCE SAMPLING BAG DEFLATED IN LAB)		


RADON SAMPLING

	pCi/L	mWL
BASEMENT	0.6	3
WALL	0.03	0.15
DRAIN	30.42	152.1
(CANADIAN LEVEL	20.00	100)
(EPA LEVEL	4.00	20)

** Fluorisil intended to pick up herbicides. Being re-analysed.

Rsp

* Fungus Sampling and lab procedure not validated - value is suspect Rsp



Project: <u>SUMMARY OF RESULTS</u> <u>IAQ</u>	By: <u>KEN RUEST</u>	Page <u>2</u> of <u>2</u>
Job. No.: <u>50910</u>	Job Title:	Date: <u>SEPT 5/90</u>

Appendix 2

TENAX SAMPLINGSUBSTANCES IDENTIFIED ($\mu\text{g}/\text{m}^3$)
LOCATION

SUBSTANCE	WALL	nr. grade*	DRAIN
ETHYLENE GLYCOL	T		-
O-XYLENE	T		T
M-XYLENE	T		4.0
P-XYLENE	T		T
STYRENE	2.7		T
DICHLOROMETHANE			-
TOLUENE			3.75
1,3,5-DIMETHYLBENZENE			T
DICHLOROBENZENE			T

T = TRACE QUANTITIES $< 1 \mu\text{g}/\text{m}^3$
 - = NONE DETECTED

TEMPERATURE AND RH IN BASEMENT

TEMPERATURE 12.7 °C
 RELATIVE HUMIDITY 46.4%

SOIL GASES PASSIVE RATE OF ENTRY

WALL HOLE 1.2 L/HR. (near grade, in rubblestone)
 DRAIN 0.0 L/HR.

STATIC PRESSURE READINGS

* wall sample: hole in rubblestone wall is just $\frac{1}{2}$ m below grade. Gas probably includes indoor and outdoor air as well as soil gas in this case.