NOTICES TO MARINERS

CANADIAN COAST GUARD

2001

SUMMARY OF (T) AND (P)

IN EFFECT DECEMBER 31, 2000

© Minister of Public Works Government Services Canada 2001 Cat. No. T34-14/2001E Notices to Mariners - 2001 ISBN No. 0-662-27904-2 DFO/5898 **Marine Programs Directorate Aids to Navigation**

Internet: http://www.notmar.com



ANNUAL REPRINT OF NOTICES TO MARINERS OF A TEMPORARY AND PRELIMINARY NOTICES IN FORCE AS OF DECEMBER 31, 2000

Geographical positions refer direct to graduations of the largest scale chart unless otherwise indicated.

Bearings are referred to the True Compass and are reckoned clockwise from 000° (North) to 360°; those relating to lights are from seaward. Visibility of lights is that in clear weather. Depths are referred to the datum of the largest scale chart. Heights are above higher high water large tides except where otherwise indicated.

EXPLANATION OF TEMPORARY AND PRELIMINARY NOTICES

Certain Notices to Mariners appearing in the monthly editions have a (T) or (P) appended to the regular number. These letters indicate that the information contained in the notice is of a temporary or preliminary nature.

TEMPORARY NOTICES (T)

If a temporary change in conditions affecting navigation exists and if the change will be effective for a period of over three months, a (T) notice will be published. Temporary changes which are effective for periods of less than three months will not normally be published. Such information will be broadcast as Notices to Shipping by the Coast Guard base of the area concerned. (T) notices will be cancelled as necessary.

PRELIMINARY NOTICES (P)

- (a) When important changes affecting navigation are to take place in the near future, a Notice to Mariners describing the change will be published so that the mariners will have advanced information on the change. Such notices will be designated (P).
- (b) When a change in conditions affecting navigation has taken place but full information is not available, a (P) notice giving available information will be published. This notice will be followed by a regular notice when complete information becomes available. The regular notice will cancel the (P) notice.
- (c) When changes have taken place which are too complex to describe in a written notice, a (P) notice giving general information will be published. This notice will explain that follow up action will be taken to update charts by publishing patch corrections, new editions or new charts.

ACTION REQUIRED ON RECEIPT TO (T) & (P) NOTICES

It is not customary to make permanent corrections to charts and publications from (T) and (P) notices. On receipt of such notices, the information they contain should be noted on the charts and in the publications affected, in pencil.

CAUTION

Mariners are reminded that charts and publications are not corrected from (T) and (P) notices when purchased from suppliers. Reference should be made to the latest list of charts affected by Temporary and Preliminary Notices published.

GEOGRAPHICAL INDEX OF NOTICES TO MARINERS PRIOR TO 2000

| | | PAGE |
|-----|--|--------------|
| (1) | MISCELLANEOUS | NIL |
| (2) | CANADIAN ARCTIC AND WEST COAST OF GREENLAND | 1 – 6 |
| (3) | HUDSON BAY INCLUDING FOXE CHANNEL, HUDSON STRAIT AND LABRADOR | 7 – 8 |
| (4) | BAY OF FUNDY AND ATLANTIC COAST SOUTH TO 40° N., NOV SCOTIA AND NEWFOUNDLAND | 'A 9 – 27 |
| (5) | GULF AND RIVER ST. LAWRENCE TO MONTRÉAL, INCLUDING PRINCE EDWARD ISLAND AND WEST COAST OF NEWFOUNDLAND AND CAPE BRETON ISLAND | 28 – 43 |
| (6) | ST. LAWRENCE SEAWAY, GREAT LAKES AND THE INLAND WATERS AND RIVERS | 44 – 61 |
| (7) | BRITISH COLUMBIA INCLUDING VANCOUVER ISLAND, QUEEN CHARLOTTE ISLANDS, FRASER RIVER, U.S. WEST COAST SOUTH TO 48° N., AND PUGET SOUND | 62 – 66 |
| | SECTION 1 – 2000 INDEX | |

| (P) | GREAT LAKES - ST. CLAIR RIVER - Lights to be changed | 67 |
|-----|--|---------|
| (T) | LAKE HURON - GEORGIAN BAY - Changes to Aids to Navigation due to Low Water in 2000 | 70 – 73 |
| (P) | MANITOBA - WINNIPEG RIVER - Proposed changes to aids to navigations | 67 – 70 |
| (P) | NEW BRUNSWICK - MIRAMICHI RIVER - Aids to navigation to be changed | 73 – 76 |

INDEX OF (T) & (P) NOTICES PRIOR TO 2000

| Notice # | Page | Notice # | Page | Notice # | Page | Notice # Pa | age |
|--------------------|--------|-----------|-------|--------------|-------|-------------|-------|
| 826(T)/85 | 44 | 299(P)/94 | 31 | 334(P)/97 | 50-52 | 1317(T)/99 | 24 |
| 193(T)/87 | 9 | 359(T)/94 | 15 | 335(P)/97 | 52,53 | 1344(T)/99 | 24,25 |
| 196(T)/87 | 28 | 373(T)/94 | 15 | 361(P)/97 | 53,54 | 1513(P)/99 | 41,42 |
| 292(T)/88 | 7 | 423(P)/94 | 15,16 | 367(P)/97 | 54 | 1722(P)/99 | 60 |
| 367(T)/88 | 44 | 459(P)/94 | 16 | 407(T)/97 | 54 | 1750(P)/99 | 25 |
| 413(T)/88 | 9 | 461(T)/94 | 16 | 450(P)/97 | 54,55 | 1755(P)/99 | 42 |
| 847(P)/89 | 1 | 463(P)/94 | 16 | 531(P)/97 | 55 | 1942(P)/99 | 42 |
| 356(P)/90 | 9 | 583(P)/94 | 31 | 533(P)/97 | 55,56 | 1943(P)/99 | 42,43 |
| 568(T)/90 | 9 | 594(T)/94 | 16 | 103(P)/98 | 56 | 1944(P)/99 | 60 |
| 610(T)/90 | 44 | 612(T)/94 | 31 | 104(P)/98 | 56 | 1945(P)/99 | 63 |
| 769(P)/90 | 28 | 678(T)/94 | 16,17 | 115(P)/98 | 33,34 | 1946(P)/99 | 43 |
| 55(T)/91 | 10 | 717(T)/94 | 17 | 116(P)/98 | 34 | 2100(P)/99 | 43 |
| 150(T)/91 | 44 | 761(T)/94 | 7 | 505(P)/98 | 56,57 | 2106(P)/99 | 25,26 |
| 191(T)/91 | 10 | 798(P)/94 | 31 | 506(T)/98 | 57 | 2107(P)/99 | 26 |
| 380(P)/91 | 45 | 64(T)/95 | 17 | 510(P)/98 | 35 | 2307(P)/99 | 27 |
| 651(T)/91 | 45 | 65(T)/95 | 31,32 | 517(P)/98 | 35 | 2319(T)/99 | 27 |
| 725(T)/91 | 45 | 244(T)/95 | 48 | 518(P)/98 | 21 | 2336(T)/99 | 60,61 |
| 769(T)/91 | 45 | 346(T)/95 | 17 | 535(P)/98 | 21,22 | 2345(P)/99 | 63 |
| 103(T)/92 | 10 | 384(T)/95 | 17 | 723(P)/98 | 57 | 2346(P)/99 | 63,64 |
| 170(T)/92 | 28 | 507(T)/95 | 18 | 765(T)/98 | 22 | 2348(P)/99 | 64,65 |
| 347(T)/92 | 28, 29 | 526(P)/95 | 32 | 768(P)/98 | 22,23 | 2349(P)/99 | 65,66 |
| 433(T)/92 | 29 | 534(T)/95 | 18 | 769(P)/98 | 23 | , , | · |
| 525(T)/92 | 46 | 683(P)/95 | 48 | 771(P)/98 | 35 | | |
| 667(P)/92 | 46 | 733(T)/95 | 62 | 772(P)/98 | 35,36 | | |
| 702(P)/92 | 62 | 736(P)/95 | 48 | 956(P)/98 | 36 | | |
| 782(T)/92 | 10 | 739(P)/95 | 48,49 | 957(P)/98 | 36,37 | | |
| 805(P)/92 | 10-12 | 120(P)/96 | 18,19 | 1109(P)/98 | 58 | | |
| 195(T)/93 | 29 | 141(T)/96 | 19 | 1148(T)/98 | 58 | | |
| 619(T)/93 | 13 | 237(T)/96 | 19 | 1159(P)/98 | 37 | | |
| 636(P)/93 | 30 | 305(P)/96 | 49 | 1510(P)/98 | 2-5 | | |
| 707(T)/93 | 13 | 306(P)/96 | 32 | 1550(P)/98 | 23 | | |
| 737(P)/93 | 13 | 345(P)/96 | 7,8 | 1727(P)/98 | 5,6 | | |
| 804(P)/93 | 7 | 433(T)/96 | 32 | 1746(T)/98 | 37 | | |
| 845(P)/93 | 30 | 434(T)/96 | 32,33 | 1939(T)/98 | 58,59 | | |
| 47(T)/94 | 13 | 444(P)/96 | 19 | 2125(P)/98 | 59 | | |
| 51(P)/94 | 46 | 507(P)/96 | 49 | 2154(P)/98 | 59 | | |
| 53(P)/94 | 46 | 603(T)/96 | 49,50 | 138(T)/99 | 38 | | |
| 75(T)/94 | 14 | 634(P)/96 | 1 | 146(P)/99 | 24 | | |
| 76(T)/94 | 14 | 666(P)/96 | 1 | 153(T)/99 | 6 | | |
| 103(T)/94 | 30 | 687(P)/96 | 8 | 157(T)/99 | 59,60 | | |
| 104(T)/94 | 14 | 738(P)/96 | 2 | 172(T)/99 | 38 | | |
| 105(T)/94 | 14 | 747(P)/96 | 50 | 510(T)/99 | 38 | | |
| 108(T)/94 | 14,15 | 748(T)/96 | 19,20 | 549(T)/99 | 38,39 | | |
| 115(P)/94 | 47 | 751(P)/96 | 2 | 551(P)/99 | 39,40 | | |
| 121(P)/94 | 47 | 814(P)/96 | 62 | 762(T)/99 | 40 | | |
| 162(P)/94 | 47 | 855(P)/96 | 33 | 923(P)/99 | 40,41 | | |
| 163(T)/94 | 7 | 96(P)/97 | 63 | 1101(P)/99 | 41 | | |
| 176(P)/94 | 47 | 221(T)/97 | 33 | 1119(T)/99 | 41 | | |
| 178(P)/94 | 47 | 239(P)/97 | 20 | 1138(P)/99 | 8 | | |
| 170(1 <i>)/3</i> 4 | 71 | 203(1)/31 | 20 | 1 100(1)/33 | U | 1 | |

CHART INDEX NOTICES TO MARINERS - 2000

| | | PAGE |
|----------------------|--|---------------------|
| 1203 1203 | Tadoussac - New Edition - 10-FEB-1995 - NAD 1927 Tadoussac à/to Cap Éternité - New Edition - 10-FEB-1995 - NAD 1927 | 77 77 |
| 1313 1313 1313 | Batiscan au/to Lac Saint-Pierre - New Edition - 27-JUN-1997 - NAD 1983 Port de Bécancour - New Edition - 27-JUN-1997 - NAD1983 Port de Trois-Rivières - New Edition - 27-JUN-1997 - NAD 1983 | 77 - 79 79 80 |
| 1438 | Grindstone Island to/a Carleton Island - New Edition - 06-OCT-1995 - NAD 1983 | 80 |
| 1439 | Carleton Island to/au Charity Shoal - New Edition - 22-FEB-1991 - NAD 1983 | 81 |
| 1515 1515 | Becketts Creek à/to Ottawa - Sheet 2 - New Chart - 24-JUL-1998 - NAD 1983 Continuation B, Lac Leamy Lake - Sheet 2 - New Chart - 24-JUL-1998 - NAD 1983 | 81, 82 82, 83 |
| 2202 | Port Severn to/à Penetang Harbour - Sheet 1 - New Edition - 26-MAR-1999 - NAD 1927 | 83 |
| 2203 | Carling Rock to/à Twin Sisters Island - Sheet 1 - New Edition - 07-OCT-1988 - NAD 1927 | 83 |
| 2205 | Killarney to/à Little Current - New Edition - 18-DEC-1987 - NAD 1927 | 83 |
| 2218 | Penetang Harbour - New chart - 13-APR-1984 - NAD 1927 | 83 |
| 2225 | Approaches to / Approches à Parry Sound - New Edition - 08-MAR-1991 - NAD 1927 | 83 |
| 2241 | Port Severn to/à Christian Island - Sheet 1 - New chart - 30-JUL-1999 - NAD 1983 | 84 |
| L/C 2243 | Bateau Island to/à Byng Inlet - New Edition - 30-AUG-1985 - NAD 1927 | 84 |
| L/C 2244 | Alexander Passage to/à Beaverstone Bay - New Edition - 12-JUN-1987 - NAD 1927 | 84 |
| 2257 | Clapperton Island to/à John Island - Reprint - 07-JUN-1996 - NAD 1927 | 84 |
| 2283 | Owen Sound to/à Giant's Tomb Island - Sheet 1 - New chart - 30-JUL-1999 - NAD 1983 | 85 |
| L/C 2284 | Parry Sound and Approaches/et les approches - New Edition - 27-OCT-1989 - NAD 1927 | 85 |
| 2299 | Clapperton Island to/à Meldrum Bay - Reprint - 30-JUN-1995 - NAD 1927 | 85 |
| L/C 3000 | Juan de Fuca Strait to/à Dixon Entrance - New Edition - 20-JAN-1989 - NAD 1927 | 85,86 |
| L/C 3001 | Vancouver Island/Île de Vancouver Juan De Fuca Strait to/à Queen Charlotte Sound - New Edition - 07-OCT-1994 - NAD 1927 | 87, 88 |
| 3410 | Sooke Inlet to/à Parry Bay - New chart - 24-MAR-1995 - NAD 1983 | 88 |
| 3441 | Haro Strait, Boundary Pass and/et Satellite Channel - New Edition - 06-DEC-1996 - NAD 1927 | 88 |
| 3447 | Nanaimo Harbour and/et Departure Bay - New Chart - 10-DEC-1999 - NAD 1983 | 88 |
| 3459 | Approaches to / Approches à Nanoose Harbour - New Edition - 24-OCT-1997 - NAD 1983 | 88 |
| L/C 3461 | Juan de Fuca Strait, Eastern Portion / Partie Est - New Chart - 06-JAN-1984 - NAD 1927 | 88 - 91 |
| 3481 | Approaches to/Approches à Vancouver Harbour - New Edition - 17-DEC-1993 - NAD 1927 | 91 |

CHART INDEX NOTICES TO MARINERS - 2000

| 3493 | 1983 | 91 |
|--------------|--|------------------|
| 3494 3494 | Second Narrows - New Edition - 18-DEC-1998 - NAD 1983 Vancouver Harbour, Central Portion / Partie Centrale - New Edition - 18-DEC-1998 - NAD 1983 | 91, 92 92, 93 |
| L/C3602 | Approaches to/Approches à Juan de Fuca Strait - New Edition - 24-MAY-1985 - NAD 1927 | 93, 94 |
| 3955 | Porpoise Harbour, Ridley Island and Approaches/et les Approches - New Chart - 15-FEB-1985 - NAD 1927 | 95 |
| 4142 | Evandale to/à Ram Island - Sheet 1 - New Edition - 01-NOV-1996 - NAD 1983 | 95 |
| 4244 | Wedgeport and Vicinity/et les abords - New Chart - 21-FEB-1986 - NAD 1983 | 95 |
| 4266 4266 | Sydney Harbour - New chart - 29-SEP-1989 - NAD 1983 Sydney Wharves/Quais - New chart - 29-SEP-1989 - NAD 1983 | 95 96 |
| L/C 4340 | Grand Manan - New Edition - 12-APR-1991 - NAD 1927 | 96, 97 |
| L/C 4385 | Chebucto Head to/a Betty Island - New Edition - 07-JUN-1996 - NAD 1983 | 97 |
| 4386 | St.Margaret's Bay - New Edition - 24-MAR-1995 - NAD 1927 | 97 |
| 4422 | Cardigan Bay - New Edition - 17-JUN-1994 - NAD 1927 | 97 |
| 4530 | Hamilton Sound, Eastern Portion / Partie est - New Edition - 11-MAR-1983 - NAD 1927 | 97 |
| 4587 | Mortier Bay - New Edition - 21-AUG-1992 - NAD 1927 | 97, 98 |
| 6251 | Red River / Rivière Rouge to/à Gull Harbour - New Edition - 18-JUL-1986 - NAD 1983 | 98 |
| L/C8015 | Funk Island and Approaches/et les approches - New Edition - 16-DEC-1994 - NAD1983 | 98 |

1989

*847(P) NORTHWEST TERRITORIES - LARSEN SOUND - BOOTHIA PENINSULA - Results of surveys.

Chart (Which will be affected) - 7083(1,2)

1. 9 Rep 1986 69°58'40 N 96°28'20" W

2. sandline joining 69 51 38 N 96 11 40 W

69 51 20 N 96 10 40 W 69 50 40 N 96 10 30 W 69 50 55 N 96 11 40 W

and 69 51 38 N 96 11 40 W

NOTE: A new edition of chart 7740 incorporating the above information will be available at a later date.

(AMA8035-10-35) (DFO)

1996

*634(P) NORTHWEST TERRITORIES - ELLESMERE ISLAND - ALEXANDRA FIORD - OFF SKRAELING ISLAND - Result of survey.

Chart (Which will be affected) - 7371(1)

1. Add rock which covers and 78°56'12" N 75°39'11".3 W

uncovers with a drying height of "1 metre 5 decimetres"

NOTE: The above information will be included in a new edition which will be made available at a later date.

(AMA8035-10-35) (DFO-A96-066)

*666(P) WESTERN ARCTIC - GREAT SLAVE LAKE - CURTIS ISLAND - Light to be discontinued.

The Canadian Coast Guard will permanently discontinue Curtis Island light (L.L. 1669) (59°21'50"N 107°41'59"W).

Comments on this action are solicited from mariners and other interested parties and should be directed to the undersigned within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based supporting information on safety, commerce and public benefit.

For dredging contact: Director Waterways Development

5th floor, 200 Kent St. Ottawa, Ontario, K1A 0E6 Telephone:(613) 990-5617 Facsimile:(613) 991-2473

1996

For Marine Aids to Navigation contact:

Supervisor of Navaids Canadian Coast Guard 42037 Mackenzie Highway Hay River, N.W.T., X0E 0R9 Telephone:(403) 874-5550 Facsimile:(403) 874-5508 or Superintendent of Aids to Navigation Canadian Coast Guard Suite 703, 201 North Front Street Sarnia, Ontario, N7T 8B1 Telephone:(519) 383-1859 Facsimile:(519) 383-1995

(AMA8035-10-1) (CCG-A96-049)

*738(P) NORTHWEST TERRITORIES - LAKE ATHABASCA - Range lights to be discontinued.

Chart (Which will be affected) - 6311(Compartment C-D)(Lake Athabasca)(NAD 83)(1)

Range lights

59°15'12" N 106°39'00" W (approx.)

NOTE: The Canadian Coast Guard proposes to permanently discontinue the above-mentioned aids to navigation. Comments on this action are solicited from mariners and other interested parties and should be directed to Superintendent, Aids to Navigation, Canadian Coast Guard, Central region, 201 North Front Street, Suite 703, Sarnia, Ontario, N7T 8B1, Tel. (519) 383-1859, Facs. (519) 383-1995 or Supervisor of Navaids, Canadian Coast Guard, 42037 Mackenzie Highway, Hay River, NWT, X0E 0R9 within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-12) (CCG-A96-050)

*751(P) NORTHWEST TERRITORIES - LAKE ATHABASCA - Range lights to be discontinued.

Chart (Which will be affected) - 6311(Compartment C-D)(Lake Athabasca)(NAD 83)(1)

Range lights

59°16'14" N 105°59'00" W (approx.)

NOTE: The Canadian Coast Guard proposes to permanently discontinue the above-mentioned aids to navigation. Comments on this action are solicited from mariners and other interested parties and should be directed to Superintendent, Aids to Navigation, Canadian Coast Guard, Central region, 201 North Front Street, Suite 703, Sarnia, Ontario, N7T 8B1, Tel. (519) 383-1859, Facs. (519) 383-1995 or Supervisor of Navaids, Canadian Coast Guard, 42037 Mackenzie Highway, Hay River, NWT, X0E 0R9 within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-12) (CCG-A96-051)

1998

*1510(P) NORTHWEST TERRITORIES - SIMPSON STRAIT - RAE STRAIT - Shoal depths.

Charts (Which will be affected) - 7760(NAD 27)(1-48) - 7733(49-53) - 7083(54-60)

1. Replace 6 fathoms 2 feet with 5 fathoms 68°28'39".6 N 96°45'11".8 W

2. Add 5 fathoms 2 feet 68 22 19.8 N 96 12 10.6 W

| | 1998 | |
|-------------|--|-----------------------------|
| 3. | 5 fathoms 2 feet | 68 26 35.4 N 96 45 26.3 W |
| 4. Delete | 21 fathoms | close northwest of (2) |
| 5. | 18 fathoms | close southeast of (2) |
| 6. Add | 5 fathoms 5 feet | 68°25'28".3 N 96°36'02".4 W |
| 7. Replace | 9 fathoms 1 foot with 3 fathoms 5 feet | 68 25 57.2 N 96 28 21.7 W |
| 8. | 7 fathoms 4 feet with 3 fathoms 4 feet | 68 23 06 .6 N 96 26 34.1 W |
| 9. Add | 4 fathoms 4 feet | 68 24 50 N 96 21 33.2 W |
| 10. | 5 fathoms 1 foot | 68 28 12.7 N 96 11 27.1 W |
| 11. | 7 fathoms | 68 29 15.3 N 96 08 23 W |
| 12. | 0 fathom 1 foot | 68 26 24.1 N 95 51 41.3 W |
| 13. | 3 fathoms 1 foot | 68 29 24.6 N 95 46 22.5 W |
| 14. Replace | 6 fathoms 5 feet with 5 fathoms 5 feet | 68 33 43.4 N 95 34 07.7 W |
| 15. Add | 4 fathoms 4 feet | 68 33 24.9 N 95 29 36.3 W |
| 16. Delete | 11 fathoms | close eastward of (15) |
| 17. Add | 7 fathoms 1 foot | 68 35 34 N 95 25 39.3 W |
| 18. | 7 fathoms | 68 35 42.2 N 95 23 47 W |
| 19. Delete | 10 fathoms | close eastward of (18) |
| 20. Add | 6 fathoms | 68 37 43.5 N 95 31 14.3 W |
| 21. | 6 fathoms 2 feet | 68 37 20.8 N 95 24 50.6 W |
| 22. | 6 fathoms 4 feet | 68 37 12.4 N 95 19 25.8 W |
| 23. | 6 fathoms 3 feet | 68 38 15.2 N 95 24 40.1 W |
| 24. Replace | 7 fathoms with 6 fathoms 2 feet | 68 38 26.8 N 95 26 20 W |
| 25. Add | 6 fathoms | 68 38 57.5 N 95 26 17.2 W |
| 26. | 2 fathoms 2 feet | 68 45 33.1 N 9513 06.1 W |
| 27. | 6 fathoms 1 foot | 68 48 31.8 N 95 00 25 W |
| 28. | 5 fathoms 4 feet | 68 49 06 N 94 59 30.7 W |
| 29. | 3 fathoms 3 feet | 68 49 14.3 N 94 58 10.4 W |

| | 1998 | |
|-------------|--|-----------------------------|
| 30. Replace | 9 fathoms 3 feet with 5 fathoms | 68 49 32.9 N 94 57 13.9 W |
| 31. | 11 fathoms with 5 fathoms 3 feet | 68 49 14.8 N 94 52 00.9 W |
| 32. | 5 fathoms 1 foot with 2 fathoms 4 feet | 68°50'20".1 N 94°57'40".4 W |
| 33. Add | 4 fathoms 2 feet | 68 50 25.3 N 94 56 10.6 W |
| 34. Replace | 9 fathoms 4 feet with 5 fathoms 2 feet | 68 50 43 N 94 53 39 W |
| 35. Add | 4 fathoms 4 feet | 68 51 02.8 N 94 50 18.8 W |
| 36. Delete | 16 fathoms | close northeast of (35) |
| 37. Add | 3 fathoms 2 feet | 68 51 26.1 N 94 55 05.7 W |
| 38. | 3 fathoms 3 feet | 68 51 10.4 N 94 57 31.8 W |
| 39. | 6 fathoms | 68 51 32.9 N 94 58 58.7 W |
| 40. Replace | 5 fathoms 4 feet with 3 fathoms 5 feet | 68 51 52.8 N 94 52 10.7 W |
| 41. | 11 fathoms with 4 fathoms 2 feet | 68 52 06.5 N 94 53 41.5 W |
| 42. Add | 3 fathoms 1 foot | 68 5213.5 N 94 55 09.3 W |
| 43. | 4 fathoms | 68 52 34 N 94 52 41.1 W |
| 44. Replace | 8 fathoms 3 feet with 5 fathoms 5 feet | 68 52 53.1 N 94 54 25.5 W |
| 45. Add | 4 fathoms 5 feet | 68 53 10.1 N 94 57 53.9 W |
| 46. | 4 fathoms | 68 53 56.5 N 94 52 58.1 W |
| 47. | 5 fathoms 2 feet | 68 53 49.6 N 94 48 28.1 W |
| 48. Replace | 14 fathoms with 1 fathom 5 feet | 68 54 37.2 N 94 47 01 W |
| 49. Add | 5 fathoms | 68 29 27.5 N 96 43 20 W |
| 50. | 5 fathoms 2 feet | 68 27 26.5 N 96 43 35 W |
| 51. | 3 fathoms 5 feet | 68 26 52 N 96 28 25 W |
| 52. | 5 fathoms 5 feet | 68 25 39 N 96 35 29 W |
| 53. | 3 fathoms 4 feet | 68 23 00 N 96 27 21 W |
| 54. | 5 fathoms 3 feet | 68 48 00 N 94 52 50 W |
| 55. Replace | 13 fathoms with 6 fathoms 4 feet | 68 36 47 N 95 21 18 W |
| | | |

| 1998 | | | |
|-------------|--|-------------------------|--|
| 56. Add | 3 fathoms 1 foot | 68 29 50 N 95 48 30 W | |
| 57. | 0 fathom 1 foot | 68 26 51 N 95 53 20 W | |
| 58. Replace | 9 fathoms 1 foot with 3 fathoms 5 feet | 68 26 53 N 96 28 40 W | |
| 59. | 8 fathoms with 5 fathoms 5 feet | 68°26'15" N 96°35'20" W | |
| 60. Add | 3 fathoms 4 feet | 68 23 35 N 96 26 30 W | |

NOTE: This information will be incorporated in an upcoming new chart and new editions.

(AMA8035-10-35) (DFO-P98-016)

*1727(P) NORTHWEST TERRITORIES - BOOTHIA PENINSULA - JAMES ROSS STRAIT - Shoal depths.

Charts (Which will be affected) - 7760(NAD 27)(1-10) - 7083(11-14)

| 1. Add | 4 fathoms 5 feet | 69°43'20".1 N 95°53'06".3 W |
|-------------|---|-----------------------------|
| 2. Delete | 5 fathoms 3 feet | close westward of (1) |
| 3. Replace | 11 fathoms with 6 fathoms 4 feet | 69 42 48.9 N 95 49 24.2 W |
| 4. | 9 fathoms 5 feet with 5 fathoms 5 feet | 69 42 58.6 N 95 47 59.4 W |
| 5. | 8 fathoms 2 feet with 3 fathoms 5 feet | 69 41 55.2 N 95 45 45.8 W |
| 6. Add | 2 fathoms 4 feet | 69 41 15.4 N 95 43 41.9 W |
| 7. | 2 fathoms 4 feet | 69 40 37.5 N 95 44 10 W |
| 8. | 2 fathoms 3 feet | 69 39 41.8 N 95 42 00.8 W |
| 9. | 3 fathoms | 69 40 07.6 N 95 39 52.7 W |
| 10. | 4 fathoms 3 feet | 69 39 23.8 N 95 37 01.3 W |
| 11. Replace | 5 fathoms 3 feet with 4 fathoms 5 feet | 69 43 23 N 95 50 00 W |
| 12. | 9 fathoms 5 feet with 5 fathoms 5 feet | 69 43 00 N 95 44 25 W |
| 13. | 4 fathoms with 3 fathoms | 69 40 05 N 95 36 00 W |
| 14. Add | 2 fathoms 3 feet | 69 39 38 N 95 38 10 W |

| 1 | q | q | Я |
|---|---|---|---|
| | | | |

NOTE: These informations will be incorporated in an upcoming new edition of chart 7760

(AMA8035-10-35) (DFO-P98-028)

1999

153(T) GRONLAND, WEST COAST - JULIANEHAAB BUGT - Radar transponder beacons temporarily established.

Charts (Temporarily affected) - LC 5001(INT 405)(NAD 27)(1) - LC 7011(2) - 7010(3)

1. Radar transponder beacon 60°43'16" N 46°58'30" W

2. 60 43 30 N 46 56 30 W

3. 60 43 30 N 46 59 30 W

(AMA8035-10-1) (DEN-H98-038)

(3) HUDSON BAY INCLUDING FOXE CHANNEL, HUDSON STRAIT AND LABRADOR

1988

*292(T) LABRADOR COAST- LAKE MELVILLE - GOOSE BAY NARROWS - OFF BRÛLÉ POINT - Shoal reported- Caution.

Chart (Temporarily affected) - 4728

Shoal 53°26'48" N 59°57'24" W (approx.)

(AMA8035-10-30) (TC-N-037)

1993

*804(P) LABRADOR COAST - OFF CAPE HARRIGAN - NANUKTOK (FARMYARD) ISLANDS - Information about depth.

Charts (Which will be affected) - L/C 8047(1) - L/C 4730(2)

1. 11 (Repd 1989) PA 55°52'55".6 N 59°55'27".5 W

R

2. 6 (Repd 1989) PA 55 52 55.6 N 59 55 27.5 W

R

(AMA8035-10-35) (DFO)

1994

*163(T) LABRADOR COAST - EAST OF SOUTH WOLF ISLAND - Scientific subsurface mooring established temporarily.

Charts (Temporarily affected) - 4703 - 5133 - 4732 - L/C 8048 - L/C 4730 - L/C 4700 - L/C 4001(Int. 404) (NAD 27)

Reference: Notice 55(T)/94 cancelled.

Scientific subsurface mooring 53°44'18" N 55°28'30" W

NOTE: Mooring contains current meters 64 m (209.9 ft) below the surface.

(AMA8035-10-32) (TC-N93-127)

*761(T) NEWFOUNDLAND - LABRADOR COAST - LABRADOR SEA - Current meter established temporarily.

Chart (Temporarily affected) - 5001(Int. 405)

Current meter 56°45'12" N 52°27'18" W

NOTE: This mooring consists of a current meter array supported by a subsurface float at a depth of 80 metres below the surface.

(AMA8035-10-32) (TC-N94-092)

1996

^{*345(}P) LABRADOR COAST - MARTIN BAY - Result of survey.

(3) HUDSON BAY INCLUDING FOXE CHANNEL, HUDSON STRAIT AND LABRADOR

1996

Chart (Which will be affected) - 4702(NAD 27)(1,2)

Reference: Notice 428(P)/95 cancelled.

1. Add 2₁ 52°56'18".5 N 55°53'40".5 W

2. rock which covers and 52 56 22.2 N 55 51 15.3 W

uncovers with drying height of

2

NOTE: A chart amendment patch showing the above changes will be available at a later date.

(AMA8035-10-35) (DFO-A96-022)

*687(P) LABRADOR COAST - SOUTH OF FRENCHMAN ISLAND - Result of survey.

Charts (Which will be affected) - 4702(Inset, American Tickle)(NAD 27)(1) - 4702(NAD 27)(2) - 4703(NAD 27)(2)

1. Add depth "0" fathom "5" feet "Rk" 53°13'14".6 N 55°43'57".1 W

2. Replace depth 4 fathoms 1 foot with "0" 53 13 14.6 N 55 43 57.1 W

fathom "5" feet "R"

NOTE: The above information will be included in New Chart 5080, which will be made available at a later date.

(AMA8035-10-35) (DFO-A96-072)

1999

*1138(P) LABRADOR COAST - TURNAVIK ISLANDS TO WHITE BEAR ISLAND - Overlay.

Chart (Which will be affected) - 5046(1)

1. Add overlay 55°20'00" N 59°15'00" W

Mariners are advised that a new route has been surveyed from Turnavik Islands to White Bear Island.

The Canadian Hydrographic Service will provide a mylar overlay depicting these changes. This overlay must be used in conjunction with chart 5046 - Cape Makkovik to Winsor Harbour Island.

Interested parties may obtain a copy of the overlay by contacting:

Canadian Hydrographic Service Scotia-Fundy Region Bedford Institute of Oceanography P.O. Box 1006 Dartmouth, N.S. B2Y 4A2

Tel: 902-426-5051 Fax: 902-426-1893

NOTE: A new edition of chart 5046 will be made available at a later date.

(AMA8035-10-35) (DFO-A99-049)

1987

*193(T) NEWFOUNDLAND, SOUTH COAST - PLACENTIA BAY - MORTIER BAY - OFF SPANISH ROOM POINT - Anchor chains stored temporarily - Caution.

Chart (Temporarily affected) - 4587

Anchor chains

47°10'54" N 55°05'30" W (approx.)

NOTE: Three lengths of anchor chains are being stored and are each marked at one end by an orange buoy. Mariners are requested to use caution when navigating in this area.

(AMA8035-10-10) (TC-N-055)

1988

*413(T) NEWFOUNDLAND, SOUTH COAST - FORTUNE BAY - FORTUNE HARBOUR - FORTUNE BARASWAY - Shoal reported - Caution.

Chart (Temporarily affected) - L/C 4832(Inset, Fortune Harbour)

Shoal

47°04'26" N 55°49'49" W (approx.)

NOTE: Mariners are requested to proceed with caution when navigating in the area.

(AMA8035-10-30) (TC-M-116/86)

1990

*356(P) NEWFOUNDLAND, SOUTH COAST - PLACENTIA BAY - SOUTH OF JUDE ISLAND - Shoal reported.

Charts (Which will be affected) - L/C 4622 - L/C 4624 - L/C 4016

Add

Sunken barge

15 Repd 1990

47°10'15" N 54°47'48" W

NOTE: Additional information will be made available upon completion of a survey investigation.

(AMA8035-10-35) (DFO)

*568(T) NEWFOUNDLAND, SOUTH COAST - ST. MARY'S HARBOUR - GRAVEN BEACH - Sunken barge - Caution.

Charts (Temporarily affected) - 4843(and Inset) - L/C 4817

46°57'52" N 53°31'49" W (approx.)

(AMA8035-10-10) (TC-N-057)

1991

'55(T) NEWFOUNDLAND, EAST COAST - BONAVISTA BAY - NEWMAN SOUND - Wharf under reconstruction - Light discontinued temporarily.

The wharf in 48°34'03" N 53°57'00" W (approx.) is under reconstruction.

The light in 48°34'03" N 53°57'00" W has been temporarily discontinued.

(AMA8035-10-7-2;AMA8035-10-9)

(TC-N-117)

*191(T) NEWFOUNDLAND, EAST COAST - TRINITY BAY - BULL ARM - Current meter established temporarily - Caution.

Chart (Temporarily affected) - L/C 4851

Current meter

47°49'21" N 53°52'37" W

NOTE: The subsurface current meter is marked by three yellow surface buoys, each equipped with a flashing white light and a radar reflector. Mariners are requested to use caution when navigating in the area and to give these buoys a wide berth.

(AMA8035-10-32) (TC-N-011)

1992

*103(T) NEWFOUNDLAND, EAST COAST - CONCEPTION BAY - HARBOUR GRACE - Spires removed temporarily.

Charts (Temporarily affected) - 4849(Plan, Harbour Grace and/et Carbonear)(NAD 83)

Spires

47°41'44" N 53°12'39" W (approx.)

(AMA8035-10-1) (TC-N-163)

*782(T) NEWFOUNDLAND, EAST COAST - CONCEPTION BAY - LONG POND - Information concerning breakwater - Caution.

Charts (Temporarily affected) - 4848(Plan, Long Pond)(NAD 83) - L/C 4847(NAD 83)

Breakwater 47°31'06" N 52°58'45".8 W

NOTE:Armour stone has been placed along the west side of the breakwater. Advertised depths along this area are no longer correct. For further information contact Harbours and Ports Directorate at (709) 772-2288.

(AMA8035-10-30) (TC-N-103)

*805(P) NOVA SCOTIA, SOUTHEAST COAST - ECUM SECUM - Results of survey.

Charts (Which will be affected) - L/C 4234(38-45)(NAD 83) - L/C 4235(35-53)(Inset, Ecum Secum)(1-38) - L/C 4227(35,50-55)(NAD 83)

1. Add 0₉ 44°53'11".7 N 62°11'31".8 W

| 1992 | | | |
|------------|-----------------------|---------------------------|--|
| 2. | 09 | 44 53 48.1 N 62 12 11.5 W | |
| 3. | <u>0</u> 2 | 44 55 39.4 N 62 12 43.7 W | |
| 4. | 12 | 44°55'40".5 N 62°11'04" W | |
| 5. Delete | 62 | close southward of (4) | |
| 6. | PA | 44 55 53 N 62 11 23 W | |
| 7. | Repd 1910 | 44 55 55 N 62 11 15 W | |
| 8. Add | 2 ₆ | 44 53 45.5 N 62 09 19.3 W | |
| 9. | 28 | 44 53 18.3 N 62 09 24.3 W | |
| 10. | 18 | 44 52 51.6 N 62 09 25.9 W | |
| 11. | <u>0</u> 5 | 44 52 56.7 N 62 08 57.9 W | |
| 12. | O_8 | 44 55 31.3 N 62 12 37.2 W | |
| 13. | 44 | 44 55 39.9 N 62 06 12.4 W | |
| 14. | 4 | 44 54 42.2 N 62 07 48.5 W | |
| 15. Delete | e 5 ₆ | close eastward of (14) | |
| 16. Add | <u>1</u> 8 | 44 55 32.8 N 62 08 44.1 W | |
| 17. | 49 | 44 57 00.2 N 62 06 45.1 W | |
| 18. | + | 44 55 57.9 N 62 09 02.2 W | |
| 19. | 14 | 44 55 08.9 N 62 08 59.9 W | |
| 20. | <i>O</i> ₁ | 44 55 41.9 N 62 08 38.5 W | |
| 21. | 16 | 44 55 38.6 N 62 09 18.4 W | |
| 22. | <u>1</u> 2 | 44 55 48 N 62 09 12 W | |
| 23. | 5 | 44 53 34.7 N 62 10 05.9 W | |
| 24. | 84 | 44 53 13.5 N 62 11 08.8 W | |
| 25. | <u>1</u> | 44 55 03.2 N 62 09 35.6 W | |
| 26. | <u>Ø</u> 9 | 44 55 25.2 N 62 12 20.6 W | |
| 27. Delete | e 3 ₇ | close eastward of (26) | |
| 28. Add | <u>0</u> 7 | 44 55 44.1 N 62 08 57 W | |
| 29. | <u>2</u> 1 | 44 55 45.2 N 62 08 37.6 W | |

| 1992 | | | |
|----------------|-------------------------------------|-----------------------------|--|
| 30. | <u>1_3</u> | 44 55 07.7 N 62 09 14 W | |
| 31. | 42 | 44 55 08.1 N 62 08 44.1 W | |
| 32. Delete | 7 ₃ | close northward of (31) | |
| 33. Add | 4 ₃ | 44°56'08".9 N 62°08'52".1 W | |
| 34. | 13 ₉ | 44 52 33.2 N 62 06 57.2 W | |
| 35. Add | 118 | 44 52 40.5 N 62 10 57".7 W | |
| 36. | 07 | 44 53 07.6 N 62 11 37.1 W | |
| 37. | 48 | 44 54 41.8 N 62 12 10.1 W | |
| 38. | 149 | 44 52 41.9 N 62 06 18.1 W | |
| 39. Delete | 21 ₃ | close southward of (38) | |
| 40. Substitute | 2 ₄ for 1 ₉ | 44 57 13.5 N 62 05 39.6 W | |
| 41. Add | 79 | 44 57 26.3 N 62 01 00.8 W | |
| 42. Substitute | 11 ₆ for 8 ₈ | 44 57 31 N 62 04 46.5 W | |
| 43. | 3 ₉ for 2 ₃ | 44 55 36.1 N 62 04 56.1 W | |
| 44. | 4 ₆ for 1 ₅ | 44 54 01.1 N 62 05 07.8 W | |
| 45. | 7 ₆ for 4 ₃ | 44 53 31 N 62 05 18.3 W | |
| 46. Add | 11 | 44 52 26.6 N 62 10 17.7 W | |
| 47. | 79 | 44 54 19.5 N 62 14 29.1 W | |
| 48. | 139 | 44 52 33.2 N 62 06 57.2 W | |
| 49. Delete | 17 ₁ | close northward of (48) | |
| 50. Add | 16 ₃ | 44 52 45.7 N 62 13 19.8 W | |
| 51. | 19 | 44 51 11.4 N 62 10 18.9 W | |
| 52. | 184 | 44 49 58.4 N 62 12 30.7 W | |
| 53. Delete | 26 | close eastward of (52) | |
| 54. | 18 ₃ | close southward of (35) | |
| 55. Substitute | 17 ₁ for 13 ₉ | 44 52 33.2 N 62 06 57.2 W | |

NOTE: New editions of charts L/C 4234 and L/C 4235 and a chart amendment patch for L/C 4227 containing the above information will be available at a later date.

| 1992 | |
|-----------------|-------------|
| (AMA8035-10-35) | (DFO-A-063) |
| 1993 | |

*619(T) NEWFOUNDLAND, SOUTH COAST - FORTUNE BAY - SAGONA ISLAND - Fog signal discontinued temporarily.

Charts (Temporarily affected) - 4830(1) - L/C 4832(NAD 83)(2) - L/C 4016(1)(NAD 27)

Previous Notice 82(T)/92 cancelled.

1. Fog signal 47°22'00" N 55°47'48" W

2. 47 21 59.9 N 55 47 45 W

(AMA8035-10-21) (TC-N-084)

*707(T) OFF NEWFOUNDLAND, EAST COAST - Current meters established temporarily.

Charts (Temporarily affected) - L/C 8010(1)(NAD 27) - L/C 4001(Int. 404)(NAD 27)

1. Current meter 43°06'00" N 49°02'00" W

2. Current meter 42 03 54 N 48 38 00 W

3. 42 57 06 N 48 11 00 W

4. 42 43 00 N 47 23 06 W

NOTE: These moorings come up to 400 meters from the surface with no markings.

(AMA8035-10-21) (TC-N-086)

*737(P) NEWFOUNDLAND, SOUTH COAST - THE BURGEO ISLANDS - GRALEY ROCK - Shoal reported.

Chart (Which will be affected) - 4637

Add 2 Rep (1993) PA 47°34'08" N 57°42'01" W

(AMA8035-10-35) (DFO-A-041)

1994

*47(T) NEWFOUNDLAND, NORTHEAST COAST - Subsurface mooring established temporarily.

Charts (Temporarily affected) - L/C 4520 - L/C 8015(NAD 27)

Subsurface mooring 49°57'10".2 N 52°47'00".6 W

NOTE: The mooring contains current meters with uppermost floats being 139 m (456 ft) from the surface.

(AMA8035-10-32) (TC-N93-126)

1994

*75(T) OFF NEWFOUNDLAND, EAST COAST - Subsurface mooring established temporarily.

Charts (Temporarily affected) - L/C 4017(NAD 27) - L/C 8015(NAD 27)

Subsurface mooring

49°17'14".4 N 51°15'48".6 W

NOTE: This mooring contains a current meter with the uppermost float 255 m (836.4 ft) below the surface.

(AMA8035-10-32) (TC-N93-135)

*76(T) OFF NEWFOUNDLAND, NORTHEAST COAST - Subsurface moorings established temporarily.

Charts (Temporarily affected) - L/C 4520(1) - L/C 4017(NAD 27)(1) - L/C 8014(NAD 27)(1) - L/C 8015 (NAD 83)(1,2) - L/C 8049(2,3)

1. Subsurface mooring

48°49'36" N 52°40'18" W

2.

50 31 45 N 51 03 26.4 W

3.

51 54 17.4 N 51 07 01.2 W

NOTE: The first and second moorings contain current meters with the uppermost floats being 64 m (209.9 ft) from the surface. The third mooring contains a current meter with the uppermost float being 63 m (206.6 ft) from the surface.

(AMA8035-10-32) (TC-N93-125,131,132)

*104(T) NEWFOUNDLAND, EAST COAST - RENEWS HARBOUR - Range lights discontinued temporarily.

Chart (Temporarily affected) - L/C 4844(Inset, Renews Harbour)

(AMA8035-10-7-2) (TC-N93-136)

*105(T) NEWFOUNDLAND, EAST COAST - OFF CAPE RACE - Subsurface mooring established temporarily.

Charts (Temporarily affected) - L/C 4844 - L/C 4817(NAD 27) - L/C 4016(NAD 27) - L/C 8011 - L/C 4047(NAD 27) - L/C 4049(NAD 27)

Subsurface mooring

Range lights

46°38'00" N 52°43'00" W

46°55'50" N 52°57'04" W (approx.)

NOTE: This mooring contains a current meter with the uppermost float 59 m (193.5 ft) below the surface.

(AMA8035-10-32) (TC-N93-119)

*108(T) NEWFOUNDLAND, SOUTH COAST - PLACENTIA BAY APPROACH - Subsurface mooring established temporarily.

Charts (Temporarily affected) - L/C 4016(NAD 27) - L/C 4047(NAD 27)

Subsurface mooring

46°21'12" N 54°52'12" W

1994

NOTE: This mooring contains a current meter with the uppermost float 59 m (193.5 ft) below the surface.

(AMA8035-10-32) (TC-N93-119)

*359(T) NEWFOUNDLAND, EAST COAST - OFF CAPE SPEAR - Subsurface moorings established temporarily.

Charts (Temporarily affected) - L/C 4846(NAD 83)(1,3) - L/C 4016(NAD 27)(2,4) - L/C 4017(NAD 27) (2,4) L/C 8014(NAD 27)(2,4) - L/C 4049(NAD 27)(2,4)

1. Subsurface mooring 47°31'40".8 N 52°35'08".4 W

2. 47 31 40.6 N 52 35 04.9 W

3. 47 30 21.6 N 52 35 03.6 W

4. 47 30 21.4 N 52 35 00.1 W

NOTE:Both moorings contain scientific instruments with uppermost float 19m below the surface.

(AMA8035-10-32) (TC-N93-120)

*373(T) NOVA SCOTIA, SOUTHWEST COAST - YARMOUTH HARBOUR - Information about depths in maintain area.

Chart (Temporarily affected) - 4245(and Inset)(NAD 83)

Previous Notice: 620(T)/92 cancelled.

1. The limiting depth in the turning basin has been reduced to 6.3 metres with the following high spots identified:

| 6.1 metres | 43°49'56".6 N 66°07'30".9 W |
|------------|-----------------------------|
| 6.1 metres | 43 50 00.9 N 66 07 27.6 W |
| 6.2 metres | 43 50 03.5 N 66 07 30.4 W |
| 5.6 metres | 43 50 06.4 N 66 07 24.7 W |
| 6.2 metres | 43 50 07 N 66 07 25.5 W |

2. The limiting depth in the approach channel has been reduced to 6.5 metres with the following spot depths identified:

| 6.3 metres | 43°48'13".4 N 66°08'44".2 W |
|------------|-----------------------------|
| 6.1 metres | 43 48 33.1 N 66 08 39.2 W |
| 6.2 metres | 43 48 43.0 N 66 08 38.8 W |
| 6.2 metres | 43 49 38.5 N 66 07 50.7 W |
| 6.0 metres | 43 49 40.1 N 66 07 49.3 W |

NOTE: The above information is the result of a recent survey. Additional information will be available at a later date.

(AMA8035-10-35) (DFO-A94-017)

*423(P) NEWFOUNDLAND, EAST COAST - BAY DE VERDE - Information about light.

Chart (Which will be affected) - L/C 4850(NAD 83)

1994

Add

light FIR

48°04'58".5 N 52°54'01" W

NOTE: Further information will be available upon completion of survey.

(AMA8035-10-7-2) (TC-N94-053)

*459(P) BAY OF FUNDY - GRAND MANAN - OFF WHITE HEAD ISLAND - Information about depth.

Charts (Which will be affected) - 4342(Plan, Grand Harbour)(1)(NAD 27) - L/C 4340(2)(NAD 27)

1. Add sounding 2

44°38'06" N 66°44'21" W (approx.)

2. sounding 0 fathom 2 feet

NOTE: Further information will be available at a later date.

(AMA8035-10-35) (DFO-A94-021)

*461(T) NOVA SCOTIA, SOUTHEAST COAST - EAST RIVER - Light buoy established temporarily.

Chart (Temporarily affected) - L/C 4235(Inset, Sheet Harbour)(NAD 83)

Green light buoy, FI G, marked XX1

44°55'06" N 62°30'56" W

(AMA8035-10-5-5) (TC-M94-037)

*463(P) NEWFOUNDLAND, SOUTH COAST - WRECK ISLAND - Information about light.

Chart (Which will be affected) - 4635

Add light FI R

47°35'15" N 58°53'57" W

NOTE: Further information will be available upon completion of survey.

(AMA8035-10-7-2) (TC-N94-057)

*594(T) NEWFOUNDLAND, SOUTH COAST - PORT AUX BASQUES AND APPROACHES - Buoys established temporarily.

Charts (Temporarily affected) - 4641 - 4635

Yellow wave rider buoy 47°33'36" N 59°05'42" W

47 34 21 N 59 07 24 W

(AMA8035-10-5-2) (TC-N94-063)

*678(T) NEWFOUNDLAND, EAST COAST - Scientific subsurface mooring established temporarily.

Charts (Temporarily affected) - L/C 4017(NAD 27) - L/C 8015(NAD 27) - L/C 4001(Int. 404)(NAD 27)

Scientific subsurface mooring 49°22'39" N 51°22'12".6 W

NOTE: Mooring is located 30 m (98.4 ft) below the surface.

1994

(AMA8035-10-32) (TC-N94-090)

*717(T) NOVA SCOTIA, SOUTHEAST COAST - EAST RIVER - SHEET HARBOUR - Wreck.

Chart (Temporarily affected) - L/C 4235(Inset, Sheet Harbour)(NAD 83)

Wreck, dangerous to surface navigation 44°55'06" N 62°30'56" W

NOTE:Wreck is being considered for removal at a later date.

(AMA8035-10-35) (DFO-A94-054)

1995

*64(T) NEWFOUNDLAND, EAST COAST - TRINITY BAY - BULL ARM - Pontoons established temporarily.

Chart (Temporarily affected) - LC 4851(NAD 83)

Pontoons 47°49'13".9 N 53°52'17" W

47 49 26.5 N 53 51 59.2 W

47 49 28.8 N 53 52 25.2 W

47 49 13.6 N 53 52 14.9 W

47 49 27.6 N 53 51 59.6 W

47 49 27.8 N 53 52 26.1 W

NOTE: Each of these pontoons are yellow, carries a yellow light and has a fog signal.

(AMA8035-10-1) (TC-N94-124)

*346(T) NOVA SCOTIA, SOUTHEAST COAST - MEDWAY HARBOUR - Light buoy established temporarily.

Chart (Temporarily affected) - 4211(NAD 27)(1)

1. Add green light buoy *Fl G*, marked 44°07'57" N 64°34'42" W

UA65

(AMA8035-10-5-5) (TC-M95-031)

*384(T) NEWFOUNDLAND EAST COAST - TRINITY BAY - BULL ARM - Buoy established temporarily.

Charts (Temporarily affected) - LC 4851(1) - LC 4017(NAD 27)(1)

1. Add yellow waverider light buoy 47°49'00" N 53°51'42" W

(AMA8035-10-5-2) (TC-N95-014)

*507(T) BAY OF FUNDY - BACK BAY - CAILIFF ROCKS - Light buoy relocated temporarily.

1995

Chart (Temporarily affected) - 4124(Plan, Letete Passage, Letang Harbour and/et Blacks Harbour) (NAD 83)(1)

1. Reposition red light buoy SE2 from 45°01'52".8 N 66°52'21".9 W to 45 01 51 N 66 52 18 W

(AMA8035-10-5-7) (TC-M95-052)

*534(T) NOVA SCOTIA, SOUTHWEST COAST - YARMOUTH HARBOUR - Buoys established temporarily.

Chart (Temporarily affected) - 4245(1-10)(and Inset, Yarmouth Wharves/Quais)(1-11)(NAD 83)

Orange mooring buoy
 43°50'10".8 N 66°07'29".4 W
 43 50 12 N 66 07 27.6 W
 43 50 13 N 66 07 28.8 W

4. 43 50 15.6 N 66 07 28.8 W

5. 43 50 15.6 N 66 07 28.2 W

6. 43 50 16.2 N 66 07 28.2 W

7. 43 50 18 N 66 07 28.8 W

8. 43 50 19.8 N 66 07 28.8 W

9. 43 50 21 N 66 07 27.6 W

10. 43 50 21.6 N 66 07 24 W

11. 43 50 18.6 N 66 07 26.4 W

NOTE: Mariners are requested to proceed with caution when navigating in this area.

(AMA8035-10-5-7) (TC-M95-108)

1996

*120(P) NEWFOUNDLAND, SOUTHWEST COAST - BURGEO SHORT REACH - Buoys to be discontinued.

Chart (Which will be affected) - 4637(Inset, Short Reach)(NAD 27)(1)

1. Red spar buoy QG6 47°37'09" N 57°36'00" W

2. Green light buoy QG5 47 3710 N 57 35 33 W

NOTE: The Canadian Coast Guard proposes to permanently discontinue the above mentioned-aids to navigation. Comments on this action are solicited from mariners and other interested parties and should be directed to the Regional Director General, P.O. Box 1300, St. John's, Nfld, A1C 6H8,

1996

Tel: (709) 772-5150 within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-5-2) (TC-N95-091)

*141(T) NOVA SCOTIA, SOUTHEAST COAST - MAHONE BAY - EAST IRONBOUND ISLAND - Light discontinued temporarily.

Chart (Temporarily affected) - 4381(NAD 27)(1)

1. Light 44°26'22" N 64°05'31" W

(AMA8035-10-7-5) (TC-M95-191)

*237(T) NOVA SCOTIA, SOUTHEAST COAST - LAHAVE - CROOKED CHANNEL - Spar buoy repositioned temporarily.

Chart (Temporarily affected) - 4394(NAD 27)(1)

1. Red spar buoy TN56

from 44°13'50".5 N 64°22'32" W to 44 13 49.5 N 64 22 32 W

(AMA8035-10-5-5) (CCG-M96-007)

*444(P) NEWFOUNDLAND, SOUTHEAST COAST - BELLE BAY - ST. JACQUES ISLAND - Fog signal to be discontinued.

Charts (Which will be affected) - LC 4831(NAD 83)(1) - LC 4832(NAD 83)(1) - LC 4016(NAD 27)(1) - 4016R/M - 4832R/M - 76233(4832) - 76234(4832) - 76235(4832) - 76274(4016)

Reference: Notice 616(T)/93 cancelled.

1. Fog signal 47°28'26" N 55°24'23" W

- NOTES: (1) The Canadian Coast Guard proposes to permanently discontinue the above-mentioned aid to navigation. Comments on this action are solicited from mariners and other interested parties and should be directed to the Regional Director General, Canadian Coast Guard, P.O. Box 1300, St. John's, Nfld, A1C 6H8, Telephone (709) 772-5195, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.
 - (2) The above digital data products may also be affected. Contact Nautical Data nternational Inc. (NDI) or your Value Added Remarketers (VAR) for updates.

(AMA8035-10-21) (CCG-N96-013)

*748(T) BAY OF FUNDY - MINAS BASIN - APPROACHES TO HANTSPORT - Results of survey.

Chart (Temporarily affected) - 4140(1-15)

Reference: Notice 464(T)/95 cancelled.

Depth 5 feet
 45°12'47".123 N 64°15'14".35 W
 Depth 4 feet
 45 08 22 37.8 N 64°13'57".541 W
 Depth 7 feet
 45 08 13.971 N 64 13 55.308 W

| | 1996 | |
|--------------|----------------------|-------------------------------|
| 4. | Depth 22 feet | 45 07 54.49 N 64 13 50.093 W |
| 5. | Depth 7 feet | 45 06 33.214 N 64 12 26.587 W |
| 6. | Drying height 7 feet | 45 06 22.962 N 64 12 06.966 W |
| 7. | Drying height 2 feet | 45 06 06.584 N 64 11 54.199 W |
| 8. | Depth 3 feet | 45 06 08.041 N 64 11 46.857 W |
| 9. | Depth 1 foot | 45 05 55.886 N 64 11 38.276 W |
| 10. | Depth 4 feet | 45 05 46.943 N 64 11 25.282 W |
| 11. | Depth 9 feet | 45 05 15.352 N 64 10 39.814 W |
| 12. | Depth 5 feet | 45 04 53.84 N 64 10 14.979 W |
| 13. | Depth 8 feet | 45 04 34.006 N 64 10 15.258 W |
| 14. | Depth 6 feet | 45 04 26.629 N 64 10 07.026 W |
| 15. | Depth 8 feet | 45 04 21.178 N 64 10 07.566 W |
| (AMA8035-10- | 35) | (DFO-A96-076) |

1997

*239(P) NEWFOUNDLAND, SOUTHWEST COAST - ROSE BLANCHE - Spar buoy.

Chart (Which will be affected) - 4635(NAD 27)(1)

1. Add red spar buoy, marked "QD2" 47°36'24" N 58°41'56" W (approx.)

NOTE: Further information will be available when survey is carried out.

(AMA8035-10-5-2) (TC-N95-054)

*291(P) NEWFOUNDLAND, SOUTH COAST - PLACENTIA BAY - Light buoy to be discontinued.

Charts (Which will be affected) - LC 4841(NAD 83)(1) - LC 4622(NAD 27)(2)

1. Red light and whistle buoy PP2 47°14'47".4 N 54°05'38".3 W

2. Red light and whistle buoy PP2 47 14 47.6 N 54 05 41.5 W

NOTE: The Canadian Coast Guard proposes to permanently discontinue the above-mentioned aid to navigation. Comments on this action are solicited from mariners and other interested parties and should be directed to Superintendent Aids to Navigation, Canadian Coast Guard, P.O. Box 5667, St. John's, Newfoundland, A1C 5X1, Tel.: (709) 772-5195, within three months from the

1997

date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-5-2) (CCG-N97-006)

1998

*518(P) NOVA SCOTIA, SOUTHWEST COAST - YARMOUTH SOUND - Buoys to be discontinued.

The Canadian Coast Guard proposes to permanently discontinue the following aids to navigation:

Chart 4245

Yarmouth Sound Middle red spar buoy Y8 (43°48'05".3 N 66°08'36".6 W)

Rams Horn green can buoy Y17 (43°48'43".5 N 66°08'48".8 W)

Little Bunker Island red spar buoy Y20 (43°48'51".3 N 66°08'32".1 W)

Eastern Flats North red spar buoy Y32 (43°49'42" N 66°07'47".4 W)

Doctors Island South Corner green can buoy Y37 (43°50'00" N 66°07'39".2 W)

Doctors Island green spar buoy Y45 (43°50'20".5 N 66°07'25".8 W)

Doctors Island Upper green spar buoy Y47 (43°50'22" N 66°07'20".5 W)

Yarmouth S. Channel Outer green can buoy YA3 (43°49'50".8 N 66°07'33".5 W)

NOTE: Comments on this action are solicited from mariners and other interested parties and should be directed to Senior Navaids Officer, Fisheries and Oceans Canada, Canadian Coast Guard, P.O. Box 700, Saint John, N.B., E2L 4B3, Telephone (506) 636-4703, Facs (506) 636-5635 within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-5-7) (CCG-F97-031)

*535(P) NEWFOUNDLAND, EAST COAST - CONCEPTION BAY - PORT DE GRAVE - Breakwater and lights.

Chart (Which will be affected) - LC 4847(NAD 83)(3,5) - LC 4847(Inset, Port de Grave) (NAD 83)(1,2,4)

| 1. Add | light "FI R" | 47°35'02".5 | 5 N 53°12'44" W |
|--------|--------------------------------|-------------|------------------------|
| 2. Add | light "FI G" | 47 35 03 | N 53 12 47 W |
| 3. | "See WARNING/AVERTISSEMENT" | 47 35 12 | N 53 12 30 W |
| 4. | "See WARNING/AVERTISSEMENT" | 47 35 03 | N 53 12 45 W |
| 5. | Note | 47 40 30 | N 52 46 00 W (approx.) |

1998

WARNING

Extensive harbour construction underway. Extreme caution is to be used when navigating in this area.

AVERTISSEMENT

Des travaux majeurs de construction sont en cours dans le port, d'où la nécessité d'être très prudent en naviguant dans cette zone.

NOTES: 1) Additional information will be available at a later date.

2) Digital data products 4847R/M, 76120(4847) and 76124(4847) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-7-2) (CCG-N98-040, 041)

*765(T) NEWFOUNDLAND, SOUTH COAST - BAY D'ESPOIR AND ROTI BAY - Current meters.

Chart (Temporarily affected) - 4644(NAD 27)(1-5)

| 1. Current meter 2 metres below surface at low water | 47°47'48" N 55°52'36" W |
|--|-------------------------|
| 2. Current meter 6 metres below surface at low water | 47 47 36 N 55 50 06 W |
| 3. Current meter 6 metres below surface at low water | 47 47 12 N 55 51 42 W |
| 4. Current meter 6 metres below surface at low water | 47 46 30 N 55 51 00 W |
| 5. Current meter 6 metres below surface at low water | 47 42 24 N 56 02 18 W |

NOTE: Digital data product 4644R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-1) (CCG-N98-120, 121)

*768(P) NORTHUMBERLAND STRAIT - Fog signals to be discontinued.

The Canadian Coast Guard proposes to permanently discontinue the following fog signals.

Chart 4906

Pointe-Sapin (L.L. 1161.2) (46°57'40".6 N 64°49'50".1 W)

Chart 4911

Point Escuminac (L.L. 1163) (47°04'22".3 N 64°47'52" W)

NOTE: Comments on this action are solicited from mariners and other interested parties and should be directed to Senior Aids to Navigation Officer, Canadian Coast Guard, P.O. Box 1510, Charlottetown, P.E.I., C1A 7N3, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

| 1 | a | a | Ω |
|---|---|---|---|
| | | | |

(AMA8035-10-21)

(CCG-G98-028-030)

*769(P) BAY OF FUNDY - Lights and light buoy to be discontinued.

The Canadian Coast Guard proposes to permanently discontinue the following aids to navigation:

Chart 4011

Fundy Entrance South light & whistle buoy "M" (L.L. 251.8) (44°13'36" N 66°50'12" W)

Chart 4117

Partridge Island (L.L. 100) (45°14'21" N 66°03'13".8 W)

Saint John West (L.L. 113) (45°15'30".4 N 66°03'37".6 W)

NOTE: Comments on this action are solicited from mariners and other interested parties and should be directed to Senior Navaids Officer, Fisheries and Oceans Canada, Canadian Coast Guard, P.O. Box 700, Saint John, N.B., E2L 4B3, Telephone (506) 636-4703, Facs (506) 636-5635 within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-5,10-7-7)

(CCG-F98-002-004)

*1550(P) NEW BRUNSWICK - SAINT-JOHN - MACTAQUAC LAKE - Buoys to be discontinued.

The Canadian Coast Guard proposes to permanently discontinue the following aids to navigation in the Mactaquac Lake:

Chart 4145

Green can buoy MB1 (45°52'49" N 66°58'20" W) Green spar buoy MB3 (45°52'43".5 N 66°58'20" W) Red conical buoy MB4 (45°52'42" N 66°58'22".5 W)

Comments on this action are solicited from mariners and other interested parties and should be directed to the Superintendent, Marine Navigation Services, Canadian Coast Guard - Fundy Zone, P.O. Box 7730, Station A, Saint John, N.B., E2L 4X6, Telephone (506) 636-4703, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-5-7) (CCG-F98-037)

1999

*146(P) NEW BRUNSWICK - GRAND MANAN - Aids to be discontinued.

The Canadian Coast Guard proposes to permanently discontinue the following aids to navigation:

Chart 4124

1999

Seal Cove Breakwater (L.L. 17) (44°39'01".4 N 66°50'17" W)
Seal Cove light and bell buoy XAD (L.L. 13) (44°35'45".3 N 66°51'58".9 W)
Joe's Point red light buoy XA8 (L.L. 18) (44°38'24".3 N 66°48'47".9 W)
Shag Head Breaker red spar buoy XE2 (44°36'03" N 66°49'45".5 W)
Little Wood Island green spar buoy XE3 (44°36'38".2 N 66°49'41" W)
Letete Passage Light and Fog signal (L.L. 71) 45°02'19".8 N 66°53'30".9 W

Chart 4340

Long Point light and Fog signal (L.L. 25) (44°36'49".5 N 66°42'37".6 W) Cow Passage Radar reflector (43°38'59".6 N 66°43'25" W) Gull Cove red can buoy XQ2 (44°38'14" N 66°40'57" W) Connors Cove green can buoy XB1 (44°37'20" N 66°48'19" W)

Chart 4342

North Head Harbour (L.L. 31) (44°45'40".1 N 66°44'56".5 W) Grand Harbour Inner green can buoy XK17 (44°39'50" N 66°45'16" W)

Comments on this action are solicited from mariners and other interested parties and should be directed to the Superintendent, Marine Navigation Services, Canadian Coast Guard - Fundy Zone, P.O. Box 7730, Station A, Saint John, N.B., E2L 4X6, Telephone (506) 636-4703, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-7) (CCG-F98-181-191)

*1317(T) NEWFOUNDLAND, EAST COAST - CONCEPTION BAY - HOLYROOD BAY - Range lights temporarily discontinued.

Charts (Temporarily affected) - 4848(Plan, Holyrood)(NAD 83)(1) - 4848(Inset, Holyrood Marina) (NAD 83)(1) - LC 4847(NAD 83)(1)

1. Range lights 47°23'19".6 N 53°07'39".8 W (approx.)

NOTE: Digital data products 4847R/M, 4848R/M and 76120(4847) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-7-2) (CCG-N99-011)(DFO-A99-053)

*1344(T) NEWFOUNDLAND, SOUTH COAST - GRAND BRUIT HARBOUR - EASTERN ROCK - Light discontinued temporarily.

Charts (Temporarily affected) - 4634(and Inset, Grand Bruit Harbor)(1) - LC 4015(NAD 27)(2)

1. Light 47°39'58" N 58°13'39" W

2. 47 40 12 N 58 13 31 W

NOTE: Digital data products 4015R/M, 4634R/M and 76284(4015) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-7-2) (CCG-N99-013, DFO-A99-058)

1999

*1750(P) NOVA SCOTIA - Lights and buoys to be discontinued.

The Canadian Coast Guard proposes to permanently discontinue the following aids to navigation.

Chart 4244

Abbotts Harbour light and bell buoy A (L.L. 297) (43°38'26" N 65°50'53".5 W).

Abbotts Harbour light (L.L. 296) (43°39'36".9 N 65°49'14".1 W).

Gooseberry Ledge red spar buoy NE14 (43°42'34" N 65°51'58" W).

Camp Island North green spar buoy A17 (43°43'24".3 N 65°50'52" W).

Tusket River fog signal (L.L. 294) (43°42'12".5 N 65°57'08" W).

Chart 4379

Coffin Island light (L.L. 407) (44°02'00".5 N 64°37'44".5 W).

Comments on this action are solicited from mariners and other interested parties and should be directed to the Superintendent, Marine Navigation Services, Canadian Coast Guard - Fundy Zone, P.O. Box 7730, Station A, Saint-John, N.B., E2L 4X6, Telephone: (506) 636-4703, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-7) (CCG-F99-017)

*2106(P) BAY OF FUNDY - SOUTHEAST OF GRAND MANAN - Buoys.

Chart (Which will be affected) - LC 4340(NAD 27)(1-12)

| 1. Delete | fairway light and bell buoy XK | 44°35'17" N 66°41'21".5 W |
|---------------|--|--|
| 2. Add | red and white fairway light buoy Mo(A), BELL, marked XKA | 44 35 07 N 66 40 48 W |
| 3. Amend | XK10 to read XK6 against red conical buoy | 44 37 47.4 N 66 45 12 W |
| 4. Delete | green light and whistle buoy XK1 | 44 32 36 N 66 39 30 W |
| 5. Add | green light buoy FI G, WHIS, marked X1 | 44 32 45 N 66 39 00 W |
| 6. Reposition | red conical buoy XM2 from t | m 44 36 56 N 66 43 37.5 W o 44 36 43 N 66 43 24 W |
| 7. Delete | green light and bell buoy XK11 | 44 38 18 N 66 45 56 W |
| 8. Add | green light buoy Q G, BELL, marked XK7 | 44 38 18 N 66 45 56 W |
| 9. Replace | green light buoy XK5 with green light FI G, BELL, marked XK3 | 44 35 50 N 66 42 41.5 W |

| | 1999 |) | | |
|-------|--|----------|-------------|------------|
| 10. / | st cardinal light buoy Q(3)10s, ELL, BYB, marked XK | 44 | 4 33 46 N | 66 39 42 W |
| 11. | K6 to read XK2 against red con loy | nical 44 | 4 35 52 N | 66 41 53 W |
| 12. | d conical buoy XK8 with red lig | ght 44 | 4 37 00.2 N | 66 44 32 W |

NOTE: (1) Digital data products 4340R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(2) The above information will be included in the next edition of chart 4340, which will be made available at a later date.

(AMA8035-10-5-7)

(CCG-F99-080-082,085,086,093-095,102, DFO-A99-091)

*2107(P) BAY OF FUNDY - EAST OF GRAND MANAN AND WHITE HEAD ISLAND - Buoys.

Chart (Which will be affected) - LC 4340(NAD 27)(1-7)

| 1. Reposition | red spar buoy XP6 | from to | | 66°41'50" W 66 42 08 W |
|---------------|--|------------|----------------------------|---------------------------|
| 2. | green can buoy XP7 | from to | 44 40 44.5 N 44 40 49 N | 66 42 36 W 66 42 36 W |
| 3. Delete | green can buoy XU1 | | 44 42 44 N | 66 42 12 W |
| 4. Add | east cardinal spar buoy BYB, | | 44 42 44 N | 66 42 12 W |
| 5. Delete | red conical buoy XT2 | | 44 41 58 N | 66 42 24 W |
| 6. Add | south cardinal spar buoy YB, marked XT | | 44 41 57 N | 66 42 24 W |
| 7. Delete | red conical buoy XQ2 | | 44 38 14 N | 66 40 55 W |

NOTE: (1) Digital data products 4340R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(2) The above information will be included in the next edition of chart 4340, which will be made available at a later date.

(AMA8035-10-5-7)

(CCG-F99-083,084,097,098,105, DFO-A99-090

*2307(P) BAY OF FUNDY - GRAND MANAN - GRAND HARBOUR AND OFF WOOD ISLAND - Buoys.

Chart (Which will be affected) - LC 4340(NAD 27)(1-4)

| 1. Replace | green spar buoy XK15 with green light buoy FI G, marked XK11 | 44°39'27". | 5 N 66°45'13" W |
|------------|--|------------|-----------------|
| 2. Amend | XK13 to read XK9 against green spar buoy | 44 39 09 | N 66 45 23 W |

| | 1999 | | |
|------------|--|----------|-----------------|
| 3. Replace | green spar buoy XV5 with north cardinal spar buoy, marked XV | 44 44 24 | N 66 43 57".5 W |
| 4. Delete | green spar buoy XB1 | 44 37 21 | N 66 48 19 W |

NOTE: (1) Digital data products 4340R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(2) The above information will be included in the new edition of chart L/C 4340, which will be made available at a later date.

(AMA8035-10-5-7)

(CCG-F99-104, (DFO-A99-104

*2319(T) NORTHUMBERLAND STRAIT - PUGWASH HARBOUR - Buoy established temporarily.

Chart (Temporarily affected) - 4498(Inset, Pugwash Harbour)(NAD 27)(1)

1. Add yellow cautionary buoy 45°50'51".8 N 63°39'53".7 W

NOTE: Digital data products 4498R/M and 76184(4498) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-5-6) (CCG-G99-077, DFO-A99-103)

(5) GULF AND RIVER ST. LAWRENCE TO MONTRÉAL, INCLUDING PRINCE EDWARD ISLAND AND WEST COASTS OF NEWFOUNDLAND AND CAPE BRETON ISLAND.

1987

*196(T) QUÉBEC - RIVIÈRE RICHELIEU - CUSTOMS WHARF - Shoal reported.

Chart (Temporarily affected) - 1351(Sheet 4)(1)(and Inset, Quai des Douanes/Customs Wharf)(2)

1. Shoal 45°01'22" N 73°20'55" W (approx.)

2. Shoal 121° 289.6 m (950 ft) from Dou Triangulation Point (45°01'27".31 N

73°21'07".16 W)

(AMA8035-10-30) (TC-L-006)

1990

*769(P) GULF OF ST. LAWRENCE, NORTH SHORE - OFF ROCHER DE LA GARDE - Information about depth.

Chart (Which will be affected) - 4456

Add 0₅ 50°10'58" N 63°08'04" W

(AMA8035-10-35) (DFO)

1992

*170(T) ST. LAWRENCE RIVER - QUÉBEC HARBOUR TO TROIS-RIVIÈRES HARBOUR - DESCHAILLONS-SUR-SAINT-LAURENT - Wharf damaged - Docking prohibited - Caution.

Chart (Temporarily affected) - 1314(NAD 27)

Wharf 46°33'39".7 N 72°06'23".9 W (approx.)

(AMA8035-10-9) (TC-L-142)

*347(T) NEWFOUNDLAND, WEST COAST - STEPHENVILLE ENTRANCE CHANNEL AND TURNING BASIN - Information about shoaling.

Mariners are advised that shoaling has occurred on the northwest side of the dredged channel at the entrance to Port Harmon at approximately 48°30'23".2 N 58°32'31".8 W. The area measures approximately 150 metres long by 20 to 30 metres wide and has depths from 9.8 to 9.3 metres.

Some high spots have also been identified in the turning basin as follows:

- 8.6 metres at 48°31'47".5 N 58°31'39" W
- 8.7 metres at 48°31'39".1 N 58°31'33".9 W
- 8.9 metres at 48°31'46".6 N 58°31'38" W
- 9.1 metres at 48°31'33".2 N 58°31'41".8 W
- 9.1 metres at 48°31'30".9 N 58°31'43".4 W
- 9.0 metres at 48°31'39".3 N 58°31'34".1 W

(5) GULF AND RIVER ST. LAWRENCE TO MONTRÉAL, INCLUDING PRINCE EDWARD ISLAND AND WEST COASTS OF NEWFOUNDLAND AND CAPE BRETON ISLAND.

1992

NOTE:For further information contact the Harbour and Ports Directorate of the Canadian Coast Guard at (709) 772-5154.

(AMA8035-10-30) (TC-N-027)

*433(T) GULF OF ST. LAWRENCE, NORTH SHORE - ÎLES MINGAN - HAVRE SAINT-CHARLES - Information about reported sandbank.

Chart (Temporarily affected) - 4456

Add sandbank 50°13'00" N 63°20'00" W (approx.)

NOTE: The sandbank at Havre Saint-Charles has been reported to be extended by approximately 0.2 miles southward. Mariners are warned to exercise caution in this area.

(AMA8035-10-35) (DFO)

1993

*195(T) GULF OF ST. LAWRENCE - ÎLES DE LA MADELEINE - CHENAL DU HAVRE DE LA GRANDE ENTRÉE - Information about depths.

Chart (Temporarily affected) - 4954(1,2)(NAD 83)(and Inset, Quai Mines Seleine)(3-12)(NAD 83)

| 1. Add | 69 | 47°36'21" N 61°33'11".4 W |
|--------|----------------|-----------------------------|
| 2. | 6 | 47 34 59.1 N 61 32 26.2 W |
| 3. | 56 | 47 36 38.4 N 61 33 35.2 W |
| 4. | 6 | 47 36 38.1 N 61 33 29.3 W |
| 5. | 63 | 47 36 37.2 N 61 33 22.2 W |
| 6. | 69 | 47 36 34.7 N 61 33 17.2 W |
| 7. Add | 64 | 47°36'32".5 N 61°33'13".7 W |
| 8. | 7 | 47 36 28.1 N 61 33 14 W |
| 9. | 5 ₇ | 47 36 25.2 N 61 33 22.1 W |
| 10. | 7 | 47 36 29.6 N 61 33 27.2 W |
| 11. | 5 | 47°36'30".2 N 61°33'29".7 W |
| 12. | 7 | 47 36 26.8 N 61 33 25.8 W |

(AMA8035-10-35) (DFO-Q-121)

(5) GULF AND RIVER ST. LAWRENCE TO MONTRÉAL, INCLUDING PRINCE EDWARD ISLAND AND WEST COASTS OF NEWFOUNDLAND AND CAPE BRETON ISLAND.

1993

*636(P) QUÉBEC - RIVIÈRE RICHELIEU - BASSIN DE CHAMBLY - Anemometer tower.

Chart (Which will be affected) -1351(Sheet 1)(NAD 27)

Add tower Tr

45°27'51 » N 73°16'08 » W

NOTE: Additional information will be available at a later date.

(AMA8035-10-35; AMA8035-10-1)

(DFO-Q-068; TC-L-053)

(DFO-A93-049)

*845(P) GULF OF ST. LAWRENCE - RINCE EDWARD ISLAND, SOUTH SIDE - CHARLOTTETOWN HARBOUR - Light established.

Chart (Which will be affected) - 4460(NAD 27)

Add

light Iso G

46°13'51".2 N 63°07'17".7 W

NOTE: More information will be available when surveys are completed.

(AMA8035-10-7-6) (TC-M-235)

1994

*103(T) GULF OF ST. LAWRENCE - CHALEUR BAY - RESTIGOUCHE RIVER - DALHOUSIE - Results of survey.

Chart (Temporarily affected) - 4426(Inset)(NAD 27)

Previous Notice 352(T)/93 cancelled.

(AMA8035-10-35)

| Add | 28 | 48°04'21".2 N 66°22'56".2 W |
|-----|----|-----------------------------|
| Add | 28 | 48 04 22.4 N 66 22 39.3 W |
| | 27 | 48 04 22.4 N 66 22 36.4 W |
| | 28 | 48 04 22.8 N 66 22 34.5 W |
| | 25 | 48 04 21.8 N 66 22 32.7 W |
| | 27 | 48 04 22.6 N 66 22 31.4 W |
| | 26 | 48 04 21.7 N 66 22 29.2 W |
| | 29 | 48 04 22.5 N 66 22 27 W |
| | 28 | 48°04'14".5 N 66°21'45".5 W |
| | 27 | 48 04 13.9 N 66 21 34.4 W |
| | 28 | 48 04 15 N 66 21 33.1 W |

30

1994

*299(P) STRAIT OF BELLE ISLE - GREEN ISLAND BROOK - Light established.

Chart (Which will be affected) - L/C 4020(NAD 27)

Add light FIR4 s 10 ft

51°24'00" N 56°31'14" W (approx.)

NOTE: Further information will be available upon completion of survey.

(AMA8035-10-7-2) (TC-N93-134)

*583(P) CAPE BRETON ISLAND, WEST COAST - PLEASANT BAY - Light.

Charts (Which will be affected) - L/C 4464(NAD 27) - L/C 4022(NAD 27)

Amend FI 6 s 40 ft 15 M to read

46°49'57" N 60°47'51" W

FI 6 s 30 ft 15 M

NOTE: Further information will be available upon completion of survey.

(AMA8035-10-7-5) (TC-M94-063)

*612(T) GULF OF ST. LAWRENCE, SOUTH SHORE - CARIBOU HARBOUR - Results of survey.

Chart (Temporarily affected) - 4483(NAD 27)

Previous Notice 422(T)/90 cancelled.

Depth 12 feet 45°44'40".3 N 62°41'02".7 W

NOTE: Additional information will be made available at a later date.

(AMA8035-10-35) (DFO-A94-046)

*798(P) GULF OF ST. LAWRENCE - CHALEUR BAY - ANSE-BLEUE - Range lights to be discontinued.

Chart (Which will be affected) - L/C 4486(NAD 27)

Delete range lights 47°49'55".3 N 65°04'50".1 W (approx.)

NOTE: The Canadian Coast Guard proposes to permanently discontinue the above-mentioned aids to navigation. Comments on this action are solicited from mariners and other interested parties and should be directed to the Canadian Coast Guard Base, P.O. Box 1270, Charlottetown, P.E.I., C1A 7M8, Telephone: (902) 566-7936 within three months of the date of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-6) (TC-M94-090, 092)

1995

*65(T) ST. LAWRENCE RIVER - CAP-DE-LA-MADELEINE - Wharf partially closed.

Chart (Temporarily affected) - 1313(and Inset, Port de Trois-Rivières)(NAD 83)

Wharf 46°22'00" N 72°29'45" W

1995

NOTE: The eastern side of Cap-de-la-Madeleine wharf is closed to navigation due to damage to this section of the wharf.

(AMA8035-10-35) (DFO-Q94-123)

*526(P) GULF OF ST. LAWRENCE - PICTOU HARBOUR - Light and breakwater.

Chart (Which will be affected) - 4437(and Inset)(NAD 27)(1,2)

1. Add light Q G Priv 45°40'27".6 N 62°42'41".7 W

2. floating breakwater joigning 45 40 27.2 N 62 42 44.8 W and 45 40 27.6 N 62 42 41.7 W

NOTE:A chart amendment patch showing the marina and the light referred to above will be available at a later date.

(AMA8035-10-7-6) (TC-M94-165)

1996

*306(P) GULF OF ST. LAWRENCE - CHALEUR BAY - JACQUET RIVER - Light to be discontinued.

Chart (Which will be affected) - LC 4486(NAD 27)(1)

1. Light 47°55'25".1 N 66°01'58".6 W

NOTE: The Canadian Coast Guard proposes to permanently discontinue the above mentioned-aid to navigation. Comments on this action are solicited from mariners and other interested parties and should be directed to Canadian Coast Guard Base, P.O. Box 1270, Charlottetown, P.E.I., C1A 7M8, Telephone (902) 566-7936 within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-6) (CCG-M96-009)

*433(T) QUÉBEC - RIVIÈRE RICHELIEU - CHENAL ÎLE AUX NOIX - Shoal reported.

Chart (Temporarily affected) - 1351(Sheet 3)(NAD 27)(1)

45°06'52" N 73°16'29" W (approx.)

NOTE:Mariners are requested to proceed with caution when navigating in this area. Additional information will be made available at a later date.

(AMA8035-10-35) (DFO-Q95-118; TC-L95-211)

*434(T) CHALEUR BAY - GRANDE RIVIÈRE - Shoal reported.

1. 1 metre 5 decimetres

Chart (Temporarily affected) - 4921(Plan, Grande Rivière)(NAD 27)(1) - 79065(4921)

1. Shoal 48°23'43".6 N 64°30'04".8 W (approx.)

1996

- NOTE: (1) New information affect your R/M and/or your ENC product. Contact Nautical Date International Inc. (NDI) or your Value Added Remarketers (VAR) for updates.
 - (2) Mariners are requested to proceed with caution when navigating in this area. Additional information will be made available at a later date.

(AMA8035-10-35)

(DFO-Q95-129; TC-L95-213)

*855(P) GULF OF ST. LAWRENCE - MIRAMICHI RIVER - BLACK RIVER - Pier.

Chart (Which will be affected) - 4912(NAD 83)(1)

1. Pier

47°02'06" N 65°12'41" W (approx.)

NOTE: It has been reported that the three bridge piers currently charted as being visible at High Water are in fact covered, and that the centre pier at 47°02'06"N 65°12'41"W approx., is covered at Low Water (Chart Datum). Caution should be exercised when navigating in this area. Additional information will be made available at a later date.

(AMA8035-10-35)

(DFO-A96-110)

1997

*221(T) ST. LAWRENCE RIVER - UPSTREAM FROM SOREL - Aids obstructed - Caution.

The above information affects charts: 1310, 1350, 1351, 1409, 1410, 1510 and 1511.

The range daymarks or reference lights located in the secondary channels of the following sectors may be obstructed until further notice.

- Îles de Boucherville (Southern channel)
- Chenal de Lavaltrie
- Lac Saint-Louis
- Rivière Richelieu
- Lac des Deux Montagnes
- Rivière des Outaquais

(AMA8035-10-10) (TC-L95-209)

1998

*115(P) GULF OF ST. LAWRENCE - ÎLES DE LA MADELEINE - GRANDE ENTRÉE - Sector light.

Chart (Which will be affected) - 4954(NAD 83)(1-7)

1. Delete 47°35'46".4 N 61°32'44".2 W sector light

2. Add sector light "F RWG 13m" "Priv" 47 36 29.5 N 61 32 23 W

> The light is visible over an arc of 005°. Red from 015°30' to 017°32'; Al RW from 017°32' to 017°50'; white from 017°50' to 018°10'; Al GW from 018°10' to 018°28'; green from

018°28' to 020°30'.

| 1998 | | |
|--------|----------------|-----------------------------|
| 3. | legend "G" | 47°33'28".2 N 61°33'56".2 W |
| 4. | legend "W" | 47 33 27.1 N 61 33 50.8 W |
| 5. | legend "R" | 47 33 26 N 61 33 45.4 W |
| 6. | legend "Al GW" | 47 33 20.3 N 61 33 55.5 W |
| 7. Add | legend "AI RW" | 47 33 18.5 N 61 33 53.3 W |

NOTE: (1) A chart amendment patch showing the above changes will be available at a later date.

(2) Digital data products 4954R/M and 79084(4954) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-7-9)

(CCG-L97-101A, 101, DFO-Q97-129)

*116(P) GULF OF ST. LAWRENCE - ÎLES DE LA MADELEINE - Shoal depths.

Chart (Which will be affected) - 4954(NAD 83)(1-6) - 4954(Inset, Quai/Wharf Mines Seleine)(NAD 83) (6-12)

| 1. Add | 6 metres 6 decimetres | 47°32'25".9 N 61°34'21".9 W |
|------------|--|-----------------------------|
| 2. | 2 metres 4 decimetres | 47 33 33.9 N 61 33 51.8 W |
| 3. | 6 metres 4 decimetres | 47 34 37.6 N 61 32 43 W |
| 4. | 4 metres 3 decimetres | 47 34 58 N 61 32 20.6 W |
| 5. Replace | 6 metres 5 decimetres with 5 metres 8 decimetres | 47 36 09.4 N 61 32 22.7 W |
| 6. Add | 3 metres 3 decimetres | 47 36 32.3 N 61 33 29.9 W |
| 7. | 5 metres 9 decimetres | 47 36 38.4 N 61 33 34.5 W |
| 8. | 5 metres 3 decimetres | 47 36 37.9 N 61 33 21.2 W |
| 9. Replace | 3 metres 6 decimetres with 3 metres 2 decimetres | 47 36 30.4 N 61 33 30.5 W |
| 10. Add | 6 metres 5 decimetres | 47 36 28.4 N 61 33 28.7 W |
| 11. | 6 metres | 47 36 32.3 N 61 33 12.6 W |
| 12. | 6 metres 6 decimetres | 47 36 28 N 61 33 13.4 W |

NOTE: (1) A chart amendment patch showing the above changes will be available at a later date.

Digital data products 4954R/M, 79084(4954) and 79085(4954) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) DFO-Q97-152)

1998

*510(P) QUÉBEC - RIVIÈRE RICHELIEU - ÎLE GOYER - Rocks.

Chart (Which will be affected) - 1351(Sheet 1)(Bassin de Chambly à/to Île Sainte-Thérèse) (NAD 27)(1,2)

1. Delete rock with drying height 1 metre 45°28'32".8 N 73°16'28" W

2. rock with drying height 1 metre 45 28 31 N 73 16 30 W

NOTES: (1) Digital data product 1351R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(2) Additional information will be made available at a later date.

(AMA8035-10-35) (DFO-Q98-016)

*517(P) QUÉBEC - RIVIÈRES RICHELIEU, DES PRAIRIES, DES OUTAOUAIS - Vertical clearances under cables - Caution.

It is possible that, after the ice storm, the vertical clearances under the cables are lower than those indicated on marine charts. Also, new cables might have been installed and not be indicated on marine charts.

Mariners are requested to use caution when using the following charts: 1350, 1351, 1509, 1510 and 1511.

NOTE: Additional information will be available at a later date.

(AMA8035-10-35) (DFO-Q98-024)

*771(P) CAPE BRETON ISLAND - ENRAGÉE POINT AND BEACH POINT. - Fog signal and light to be discontinued.

The Canadian Coast Guard proposes to permanently discontinue the following aids to navigation:

Chart 4449

Enragée Point Fog signal (L.L. 867) (46°38'58".2 N 61°01'37".8 W)

Chart 4277

Beach Point light (L.L. 845) (46°17'24".5 N 60°32'32".7 W)

NOTE: Comments on this action are solicited from mariners and other interested parties. Comments should be directed to Senior Aids to Navigation Officer, Canadian Coast Guard, P.O. Box 1510, Charlottetown, P.E.I., C1A 7N3 within three months from the date of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-6; AMA8035-10-21)

(CCG-G97-162,G98-014)

*772(P) CHALEUR BAY - MISCOU ISLAND - Fog signal to be discontinued.

The Canadian Coast Guard proposes to permanently discontinue the following fog signal.

Chart 4486

Miscou Island (L.L. 1264.7) (48°00'34" N 64°29'38" W)

1998

NOTE: Comments on this action are solicited from mariners and other interested parties and should be directed to Senior Aids to Navigation Officer, Canadian Coast Guard, P.O. Box 1510, Charlottetown, P.E.I., C1A 7N3 within three months from the date of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-21) (CCG-G98-031)

*956(P) ST. LAWRENCE RIVER - THOUSAND ISLANDS, BROCKVILLE TO KINGSTON - Buoys and light

As a result of a recent Levels of Service review, the Canadian Coast Guard proposes to conduct the following changes to aids to navigation - Thousand Islands, Brockville to Kingston.

Chart 1438

Discontinue red spar buoy H30/2 (44°18'07" N 76°07'43" W)

Discontinue red spar buoy H30/4 (44°18'01".5 N 76°07'58" W)

Discontinue red spar buoy JD2 (44°19'28" N 76°09'33" W)

Discontinue red spar buoy J6 (44°19'29".5 N 76°08'48" W)

Charts 1437 and 1438

Discontinue green spar buoy H29 (44°17'56".5 N 76°07'04 W)

Charts 1436 and 1437

Upgrade Grenadier Island light structure to increase daytime visibility (44°22'58" N 75°54'19" W) (L.L. 361)

Chart 1436

Discontinue green spar buoy U15 (44°24'58".5 N 75°52'58" W)

Establish red spar buoy marked "U16" (44°24'59" N 75°53'03" W).

Comments on this action are solicited from mariners and other interested parties and should be directed to Mr. Steven D. Lear, Supervisor, Marine Aids Program, Canadian Coast Guard, P.O. Box 1000, Prescott, Ontario, K0E 1T0, Tel.: (613) 925-2865 ext. 215, Facs: (613) 925-5540, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-5-14; AMA8035-10-7-14)

(CCG-B98-001; DFO-C98-087)

*957(P) ST. LAWRENCE RIVER - KINGSTON HARBOUR AND APPROACHES - Aids to navigation.

As a result of a recent Levels of Service review, the Canadian Coast Guard proposes to conduct the following changes to aids to navigation - Kingston Harbour and Approaches.

Chart 1438

Relocate Wolfe Island Cut green spar buoy PV3 from 44°14'09" N $\,$ 78°10'49" W to 44°14'14" N $\,$ 76°10'52".5 W

Discontinue Wolfe Island Cut red spar buoy PV4 (44°14'11".5 N 78°10'43" W)

Discontinue Wolfe Island Cut green light buoy PV5 (L.L. 376) (44°14'27" N 76°11'05" W)

1998

Chart 1439

Discontinue Knapp Point light (L.L. 396) (44°13'56" N 76°23'51".9 W)

Charts 1439 and 2017

Discontinue green spar buoy H45 (44°12'51" N 76°25'57".5 W)

Downsize red light buoy KH2 (L.L. 405.6) (44°13'25" N 76°28'17".5 W)

Relocate Snake Island green light buoy K5 (L.L. 415) from 44°11'48" N 76°33'01" W to 44°11'59" N 76°32'34" W

Discontinue green spar buoy KE1 (44°11'14" N 76°29'19" W)

Discontinue red spar buoy KE2 (44°11'05" N 76°29'28" W)

Discontinue red spar buoy KS2 (44°11'04" N 76°32'05".5 W)

Downsize Nine Mile Point light (L.L. 419) from a 17 NM light to a 13 NM light (44°09'05".2 N 76°33'21" W)

Comments on this action are solicited from mariners and other interested parties and should be directed to Mr. Steven D. Lear, Supervisor, Marine Aids Program, Canadian Coast Guard, P.O. Box 1000, Prescott, Ontario, K0E 1T0, Telephone (613) 925-2865 ext. 215, Facs: (613) 925-5540 within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-1) (CCG-B98-002)

*1159(P) GULF OF ST. LAWRENCE - MIRAMICHI BAY AND RIVER - Range lights to be discontinued.

The Canadian Coast Guard proposes to permanently discontinue St. Andrews Bank range lights (47°04'14".6 N 65°25'08" W approx.)(L.L. 1208.8 and 1208.9).

Comments on this action are solicited from mariners and other interested parties and should be directed to Bev Cleaveland, Canadian Coast Guard, P.O. Box 1236, Charlottetown, P.E.I., C1A 7M8, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-6) (CCG-G98-049)

*1746(T) RIVIÈRE DES MILLES-ÎLES - LAVAL - Shoal.

Chart (Temporarily affected) - 1509(Compartment E-F)(NAD 83)(1)

1. Shoal 0.7 metre

45°42'01" N 73°31'49" W (approx.)

- NOTE: (1) A shoal has been reported between buoys MC-9 and MC-10. Further informations will be available at a later date.
 - (2) Digital data product 1509R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-Q98-108)

1999

*138(T) GULF OF ST. LAWRENCE - PRINCE EDWARD ISLAND - ST. PETER'S BAY - Range lights temporarily discontinued.

Chart (Temporarily affected) - 4425(Plan, St. Peters Bay)(NAD 27)(1) - 4425(Inset, Entrance to/Entrée à St. Peters Bay)(NAD 27)(1)

1. Range lights

46°26'17".4 N 62°44'16".5 W (approx.)

NOTE: Digital data products 4425R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-7-6)

(CCG-G98-098, 099, DFO-A98-125)

172(T) UNITED STATES, EAST COAST - CAPE COD BAY - Light temporarily replaced.

Chart (Temporarily affected) - LC 4003(NAD 27)(1)

1. FI(3) 14M to read FI(3) W R 10M & 6M

42°00'00" N 70°36'06" W

NOTE: Digital data products 4003R/M and 76140(4003) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(MS-W98-041)

*510(T) ST. LAWRENCE RIVER - BAIE VERTE - Light discontinued temporarily.

Chart (Temporarily affected) - LC 1236(Inset, Baie Verte)(NAD 83)(1)

Reference: Notice 2330(T)/98 cancelled.

1. Light

48°44'17".1 N 69°02'54".6 W

NOTE:

- (1) Experimental reflective light panels have been installed on light structure (LL 1737) at the end of Baie Verte breakwater. The upper portion is painted white and the lower portion is red. The light is discontinued until further notice. Mariners are invited to forward their comments to: Aids to Navigation Office, 101 boul. Champlain, Québec, Québec G1K 7Y7
- (2) There was an error in the coordinates shown in Notice 2330(T)/98.
- (3) Digital data products 1236R/M and 79039(1236) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-7-9)

(CCG-L99-004)(DFO-Q99-014)

*549(T) GULF OF ST. LAWRENCE - ÎLE D'ANTICOSTI - Scientific equipment established temporarily.

Chart (Temporarily affected) - LC 4025(NAD 27)(1)

1. Add obstruction with a depth known of 19 fathoms

48°52'33".3 N 61°00'32".8 W

1999

NOTE: (1) It is anticipated that the above scientific equipment will be removed by mid-August 1999.

(2) Digital data products 4025R/M and 79043(4025) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-Q99-018)

*551(P) GULF OF ST. LAWRENCE - CHALEUR BAY - CHANDLER - Shoal depths.

Chart (Which will be affected) - 4921(Inset, Quai/Wharf Chandler)(NAD 83)(1-24)

| 1. Replace | 6 metres 6 decimetres with 6 metres 3 decimetres | 48°20'36".8 N 64°39'30".9 W |
|-------------|---|-----------------------------|
| 2. | 7 metres 6 decimetres with 7 metres 1 decimetre | 48 20 35.7 N 64 39 27.7 W |
| 3. | 8 metres 7 decimetres with 8 metres 4 decimetres | 48 20 33.2 N 64 39 28.1 W |
| 4. | 8 metres with 7 metres 5 decimetres | 48 20 34.7 N 64 39 32.4 W |
| 5. Delete | 9 metres 5 decimetres | 48°20'32".9 N 64°39'34".6 W |
| 6. Replace | 8 metres 8 decimetres with 8 metres 2 decimetres | 48 20 31.6 N 64 39 38.5 W |
| 7. | 9 metres 3 decimetres with 8 metres 8 decimetres | 48 20 28.3 N 64 39 39.8 W |
| 8. Add | 8 metres 1 decimetre | 48 20 28.8 N 64 39 29.4 W |
| 9. Delete | 9 metres 5 decimetres | 48 20 25.3 N 64 39 37.9 W |
| 10. Add | 9 metres 1 decimetre | 48°20'25".3 N 64°39'38".8 W |
| 11. | 8 metres 3 decimetres | 48 20 24.6 N 64 39 37.1 W |
| 12. Delete | 10 metres 7 decimetres | 48 20 23.6 N 64 39 34.1 W |
| 13. Add | 10 metres 4 decimetres | 48 20 23.2 N 64 39 33 W |
| 14. Replace | 11 metres 5 decimetres with 11 metres 1 decimetre | 48 20 22.1 N 64 39 29.9 W |
| 15. | 11 metres with 10 metres 5 decimetres | 48 20 24.9 N 64 39 29.1 W |
| 16. Add | 10 metres | 48 20 27.1 N 64 39 27.8 W |
| 17. Replace | 10 metres 2 decimetres with 9 metres 9 decimetres | 48 20 29.2 N 64 39 26.6 W |
| 18. | 10 metres 6 decimetres with 10 metres | 48 20 30.5 N 64 39 22.3 W |

| 1999 | | | | |
|------|-------------|--|-------------------------|----------------------|
| | | 2 decimetres | | |
| | | | | |
| | 19. | 11 metres 3 decimetres with 11 metres | 48 20 26.3 | N 64 39 25.7 W |
| | 20. | 12 metres 1 decimetre with 11 metres 8 decimetres | 48 20 27.8 | N 64 39 21.7 W |
| | 21. | 12 metres 6 decimetres with 12 metres 3 decimetres | 48 20 27.8 | N 64 39 15.9 W |
| | 22. | 12 metres 2 decimetres with 11 metres 9 decimetres | 48 20 22.8 | N 64 39 24.8 W |
| | 23. | 12 metres 7 decimetres with 12 metres 3 decimetres | 48 20 24.4 | N 64 39 20.6 W |
| | 24. Amend | legend 9.8m (1991) to read 9,0m (1999) | 48 20 30.1 (approx.) | N 64 39 32.7 W |
| | NOTE: (4) A | short amondment notab abouting the above abongs | انبير مطالنير | able at a later data |

NOTE: (1) A chart amendment patch showing the above changes will be available at a later date.

(2) Digital data products 4921R/M and 79072(4921) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-Q99-019)

*762(T) GULF OF ST. LAWRENCE - PRINCE EDWARD ISLAND - SUMMERSIDE HARBOUR - Depths.

Chart (Temporarily affected) - 4459(Inset, Summerside Harbour)(NAD 27)(1,2)

1. 21 feet 46°23'12".2 N 63°47'30".3 W

2. 21 feet 46 22 55.8 N 63 48 47.6 W

NOTE: (1) The above information is the result of a recent survey. Additional information will be available at a later date.

(2) Digital data products 4459R/M, 76181(4459) and 76182(4459) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-A99-027)

*923(P) QUÉBEC - ÎLES DE LA MADELEINE - CAP-AUX-MEULES - Shoal depths.

Chart (Which will be affected) - 4956(NAD 83)(1-6)

| 1. Replace | 5 metres 2 decimetres with 4 metres 7 decimetres | 47°22'48".4 N 61°51'21".6 W |
|------------|--|-----------------------------|
| 2. Add | 4 metres 5 decimetres | 47 22 48.8 N 61 51 17.5 W |
| 3. | 4 metres 5 decimetres | 47 22 47.5 N 61 51 18.3 W |
| 4. | 5 metres | 47 22 45.8 N 61 51 18.3 W |

| | 1999 | |
|----|-----------------------|---------------------------|
| 5. | 4 metres 8 decimetres | 47 22 45.1 N 61 51 20.7 W |
| 6. | 4 metres 6 decimetres | 47 22 46.8 N 61 51 22.3 W |
| | | |

NOTE: (1) A new edition incorporating the above-mentioned changes will be available at a later date.

(2) Digital data products 4956R/M and 79046(4956) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-Q99-044)

*1101(P) QUÉBEC - LAKE MEMPHREMAGOG - SUNKEN ISLAND - Shoal depth.

Chart (Which will be affected) - 1361(Compartment B-C)(1)

, , , , ,

1. Replace 10 feet to 1 foot 45°02'51" N 72°16'42" W

NOTE: Additional information will be made available at a later date.

(AMA8035-10-35) (DFO-Q99-052)

*1119(T) ST. LAWRENCE RIVER - RIVIÈRE-DU-LOUP - Shoal depth.

Chart (Temporarily affected) - LC 1234(Inset, Pointe de la Rivière du Loup)(NAD 83)(1)

1. Add 4 metres 7 decimetres 47°50′52″.5 N 69°34′15″.6 W

NOTE: (1) Additional information will be made available at a later date.

(2) Digital data products 1234R/M and 79031(1234) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-Q99-058)

*1316(T) CHALEUR BAY - LOWER AND MIDDLE CARAQUET - Lights temporarily discontinued.

Charts (Temporarily affected) - LC 4913(NAD 83)(1,2) - 4920(Plan, Middle Caraquet)(NAD 83)(2) - 4920(Plan, Bas-Caraquet)(NAD 83)(1)

1. Light 47°48'39".4 N 64°51'22".3 W

2. Light 47 48 14.7 N 64 52 23.8 W

NOTE: Digital data products 4913R/M, 4920R/M, 76265(4920), 76266(4920) and 76275(4913) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-7-6) (CCG-G99-024,025)(DFO-A99-052)

*1513(P) ST. LAWRENCE RIVER - SAINTE-PÉTRONILLE - Obstruction.

Chart (Which will be affected) - 1317(Continuation A)(NAD 83)(1)

Reference: Notice 119(P)/99 cancelled.

1. Add obstruction and legend Obstn 46°50'42" N 71°06'54" W

1999

NOTE: (1) Digital data products 1317R/M and 79082(1317) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(2) Additional information will be made available at a later date.

(AMA8035-10-35) (DFO-H99-094)

*1755(P) GULF OF ST. LAWRENCE - Light and buoys to be discontinued.

The Canadian Coast Guard proposes to permanently discontinue the following aids to navigation:

Chart: 4437

Town Point light (L.L. 906.5) (44°40'26".6 N 62°42'14".8 W) Loudon Beach red conical buoy SJ10 (45°41'21" N 62°40'10" W)

Chart: 4497

Brule red spar buoy UC2 (45°45'18" N 63°09'49" W)
Brule Harbour green spar buoy UC3 (45°45'09" N 63°10'12" W)
Brule red spar buoy UC4 (45°45'15" N 63°10'18" W)

Comments on this action are solicited from mariners and other interested parties and should be directed to Bev Cleaveland, Canadian Coast Guard Base, P.O. Box 1236, Charlottetown, PEI., C1A 7M8, Telephone (902) 566-7936, within three months from the date of publication of this notice. Any objections raised must state the facts on which which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-5-6; 7-6)

(CCG-G99-028, 029, 39-41)

*1942(P) CAPE BRETON ISLAND - ISLE MADAME - PETIT DE GRAT - Light to be discontinued.

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Chart: 4308

Petit De Grat light (L.L. 715) (45°29'44".8 N 60°57'45".8 W).

Comments on this action are solicited from mariners and other interested parties and should be directed to Bev Cleaveland, Canadian Coast Guard Base, P.O. Box 1236, Charlottetown, PEI., C1A 7M8, Telephone (902) 566-7936, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-6) (CCG-G99-048)

*1943(P) CAPE BRETON ISLAND - PORT MORIEN - Fog signal to be discontinued.

The Canadian Coast Guard proposes to permanently discontinue Port Morien fog signal.

Chart: 4375

Port Morien fog signal (L.L. 768) (46°07'51".5 N 59°52'15".5 W).

1999

Comments on this action are solicited from mariners and other interested parties and should be directed to Bev Cleaveland, Canadian Coast Guard Base, P.O. Box 1236, Charlottetown, PEI., C1A 7M8, Telephone (902) 566-7936, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-6) (CCG-G99-049)

*1946(P) QUÉBEC - LAC DES DEUX MONTAGNES - SENNEVILLE - Buoys and shoals.

Chart 1510

Buoys H-1 to H-8 were moved slightly northwestward of their charted position to avoid two dangerous rocky zones located between buoys H3 and H7. It is recommended that mariners stay well inside the channel limits.

Note: Additional information will be available at a later date.

(AMA8035-10-5-9) (DFO-Q99-088A)

*2100(P) QUÉBEC - ÎLES DE LA MADELEINE - CAP-AUX-MEULES - Shoal depths.

Chart (Which will be affected) - 4956(NAD 83)(1-3)

| 1. Add | 6 metres 3 decimetres | 47°22'30".5 N 61°51'07".6 W | |
|-----------|--|-----------------------------|--|
| 2. | 5 metres 7 decimetres | 47 22 26 N 61 51 03.6 W | |
| 3. | 5 metres 9 decimetres | 47 22 23.5 N 61 51 01.6 W | |
| NOTE: (1) | New infrastructures including a wharf, a breakwater and a dauphin have been constructed in Havre de Cap-aux-Meules. A new edition incorporating the above-mentioned changes will be available at a later date. | | |
| (2) | Digital data products 4956R/M and 79046(4956) ma Data International Inc. (NDI) or your local Value Add | • | |

(AMA8035-10-35) (DFO-Q99-093)

1985

*826(T) ONTARIO - LAKE SIMCOE - COOK'S BAY - MASKINONGÉ (JERSEY) RIVER ENTRANCE - Light established temporarily.

Chart (Temporarily affected) - 2028(Sheet 1)

Light FR 44°13'29" N 79°28'18" W (approx.)

(AMA8035-10-7-13) (TC)

1988

*367(T) LAKE HURON - GEORGIAN BAY - MIDLAND BAY - TIFFIN BASIN - WYE RIVER APPROACH - Shoal reported.

Chart (Temporarily affected) - 2222 - 2202(Sheet 1)

Shoal from 44°44'47".5 N 79°51'23" W to 44 44 46 N 79 51 14.5 W

(AMA8035-10-30) (TC-C-238)

1990

*610(T) MANITOBA - RED RIVER LOCKPORT - ST. ANDREWS LOCK - Bascule lift non-operational - Caution.

Chart (Temporarily affected) - 6242(Sheet 1)(and Inset)

Bascule lift 50°05'03" N 96°56'26".5 W

NOTE:Mariners are advised that due to inspection and repair work, the lift span of the St. Andrews Lock and dam will be non-operational until further notice.

(AMA8035-10-16) (TC-C-044)

1991

*150(T) QUÉBEC - RIVIÈRE DES PRAIRIES - Booms established temporarily - Caution.

Temporary booms, marked by yellow lighted barrel buoys FI Y, in the following areas :

- 1. At approximately 1.6 km (1 mile) east of Jacques-Bizard bridge linking Sainte-Geneviève and Île Bizard.
- 2. At approximately 366 m (1,200 ft) west of Lachapelle bridge linking Cartierville and Chomedey and obstructing the entire river.

NOTE: Mariners are requested to use extreme caution when navigating in the area.

(AMA8035-10-10) (TC-L-065)

1991

*380(P) LAKE HURON - NORTH CHANNEL - EAST OF ARNOLD ROCK - Shoal reported.

Charts (Which will be affected) - 2268(Plan, Boyd Island to/à Spanish River) - 2257 - 2299

Add 6 Repd 1990

46°07'07 ».5 N 82°20'10 ».5 W

(approx.)

NOTE: Further information will be available upon completion of survey.

(AMA8035-10-35) (DFO)

*651(T) ONTARIO - TRENT-SEVERN WATERWAY - RICE LAKE - SOUTH OF BIRDSALLS POINT - Light buoy established temporarily.

Chart (Temporarily affected) - 2022(Sheet 1 and Sheet 2)(NAD 27)

Yellow light buoy FI Y with radar reflector

44°15'28 » N 78°03'42 » W

(AMA8035-10-5-14) (TC)

*725(T) LAKE ERIE - PORT STANLEY - Information about depths.

Chart (Temporarily affected) - 2181(Plan, Port Stanley)(NAD 27)

A recent survey indicates the following minimum depths exist in the following areas:

Area/Zone B 19 ft

in title block

Area/Zone C 17 ft

Area/Zone D 13 ft

Area/Zone E 15 ft

(AMA8035-10-35) (DFO)

*769(T) LAKE HURON - GODERICH HARBOUR - Results of a survey.

Chart (Temporarily affected) - 2291 (Inset, Goderich Harbour)

Add 26 43°44'46 ».6 N 81°43'55 » W

25 43 44 46 N 81 43 52.2 W

26 43 44 44.5 N 81 43 51.4 W

13 43 44 42.6 N 81 43 49.2 W

NOTE: Depths less than dredged area.

(AMA8035-10-35) (DFO)

1992

*525(T) ONTARIO - TRENT-SEVERN WATERWAY - OTONABEE RIVER - LAKEFIELD - Pier under reconstruction - Caution.

Chart (Temporarily affected) - 2023(Sheet 1 and Inset, Lakefield Lock/Écluse 26)(and Sheet 2 and Inset, Lakefield Lock/Écluse 26)

Reconstruction

44°25'10" N 78°16'11".5 W (approx.)

NOTE:Mariners are requested to exercise extreme caution when navigating in the area because of construction equipment obstructing the navigation channel and the possibility of diving operations in progress.

(AMA8035-10-25) (TC)

*667(P) ONTARIO - LAKE OF THE WOODS - OFF KENORA - Spar buoy to be discontinued.

Chart (Which will be affected) - 6218(NAD 27)

Green spar buoy 1

49°45'37".5 N 94°29'27" W

NOTE:The Canadian Coast Guard proposes to permanently discontinue the above-mentioned aid to navigation. Comments on this action are solicited from mariners and other interested parties and should be directed to the Sub-District Manager, Canadian Coast Guard, P.O. Box 649, Kenora, Ontario, P9N 3X6, Telephone: (807) 468-6441, Fax (807) 468-6973 within three months of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-5-13) (TC-C-017)

1994

*51(P) LAKE SUPERIOR - PATTERSON ISLAND - LAWRENCE BAY - Information about shoal.

Chart (Which will be affected) - 2304

Add 3/4 Rep (1992)

48°39'12" N 87°01'47" W

(AMA8035-10-35) (DFO-C93-101)

*53(P) LAKE HURON - NORTH CHANNEL - WHALESBACK CHANNEL - BEARDROP HARBOUR - Shoal reported.

Charts (Which will be affected) - 2268(Plan, Whalesback Channel)(NAD 27) - 2259(NAD 27) - 2299 (NAD 27)

Add 4 Repd 1990

46°09'34".7 N 82°38'06" W (approx.)

NOTE: Further information will be available at a later date.

(AMA8035-10-35) (DFO-C93-109)

1994

*115(P) LAKE HURON - GEORGIAN BAY - RED ROCK POINT - Fog signal to be discontinued.

Charts (Which will be affected) - L/C 2245(NAD 27) - L/C 2201(NAD 27) - 2204(Sheet 4)(NAD 27) - 2205(NAD 27)

Fog signal 45°58'05".2 N 81°29'20".3 W

(AMA8035-10-21) (TC-C93-095)

*121(P) LAKE ERIE - PORT DOVER - Fog signal to be discontinued.

Charts (Which will be affected) - 2181(Plan, Port Dover)(NAD 27)(1) - L/C 2110(NAD 83)(2)

1. Fog signal 42°46'51".7 N 80°12'06".7 W

2. Fog signal 42°46'51".9 N 80°12'06".1 W

(AMA8035-10-21) (TC-C93-095)

*162(P) LAKE ERIE - PELEE ISLAND - Information about fish haven.

Chart (Which will be affected) - L/C 2123(NAD 27)

Add Obstn (1) 41°45'25" N 82°41'25" W (approx.)

NOTE: Further information will be available upon completion of survey.

(AMA8035-10-35) (DFO-C93-112)

*176(P) LAKE HURON - BAYFIELD - Fog signal to be discontinued.

Charts (Which will be affected) - L/C 2228(NAD 83) - L/C 2200(NAD 27) - 2260(NAD 27) - 2261

Fog signal 43°34'10".1 N 81°42'33" W

(AMA8035-10-21) (TC-C93-095)

*178(P) LAKE HURON - KINCARDINE - Fog signal to be discontinued.

Charts (Which will be affected) - 2291(Inset, Kincardine) - L/C 2228(NAD 83) - L/C 2200(NAD 27) - 2261

Fog signal 44°10'42" N 81°38'38" W

(AMA8035-10-21) (TC-C93-095)

*179(P) LAKE HURON - SAUGEEN RIVER - Fog signal to be discontinued.

Chart (Which will be affected) - 2292(and Inset)

Fog signal 44°30'06" N 81°22'33" W

(AMA8035-10-21) (TC-C93-095)

1995

*244(T) LAKE ERIE - PORT BURWELL - Light changed temporarily.

Charts (Temporarily affected) - 2181(Plan, Port Burwell)(NAD 27)(1) - LC 2121(NAD 27)(2)

Reference: Notices 1159(T)/89 and 472(P)/94 cancelled.

1. Amend FR to read FY

012° 850 m (2788 ft) from breakwater light (42°37'56" N 80°48'34" W approx.)

2. 42°38'24" N 80°48'26".5 W

NOTE: Recent soundings indicate there is no water when reduced to chart datum very near the harbour entrance. Mariners who do not have detailed local knowledge of the channel entrance conditions should not attempt to navigate into this harbour.

(AMA8035-10-7-14) (TC-C95-028)

*683(P) LAKE ONTARIO - TORONTO HARBOUR - TORONTO HARBOUR AQUATIC PARK - Light and Racon to be discontinued.

Charts (Which will be affected) - 2085(NAD 27)(1) - 2086(NAD 83)(2) - LC 2077(NAD 83)(2)

1. Light and Racon

43°36'48" N 79°20'36" W

2.

43 36 48.2 N 79 20 35.3 W

NOTE: The Canadian Coast Guard proposes to permanently discontinue the above-mentioned aids to navigation. Comments on this action are solicited from mariners and other interested parties and should be directed to Supervisor of Aids operations, Canadian Coast Guard, P.O. Box 1000, 401 King Street West, Prescott, Ontario, K0E 1T0, Telephone (613) 925-2865, Facs: (613) 925-5540 within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-14) (TC-C95-100)

*736(P) LAKE HURON - SAUGEEN RIVER - Light.

Chart (Which will be affected) - 2292(and Inset)(1)

1. Add light FI R

44°33'04" N 81°22'33" W

NOTE: Further information will be available upon completion of survey.

(AMA8035-10-7-13) (TC-C95-080)

*739(P) LAKE ONTARIO - TORONTO HARBOUR - WESTERN GAP - Range lights to be discontinued.

Charts (Which will be affected) - 2085(NAD 27)(1) - LC 2077(NAD 83)(1) - 2086(NAD 83)(1)

1. Range lights 43°37'46".2 N 79°24'09".7 W (approx.)

1995

NOTE: The Canadian Coast Guard proposes to permanently discontinue Toronto Harbour Western Gap range. Comments on this action are solicited from mariners and other interested parties and should be directed to the Supervisor of Aids Operations, Canadian Coast Guard, P.O. Box 1000, 401 King Street West, Prescott, Ontario, K0E 1T0, Telephone: (613) 925-2865; Facs: (613) 925-5540 within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-12) (TC-C95-099)

1996

*305(P) GREAT LAKES - DETROIT RIVER - AMHERSTBURG - Fog signal to be discontinued.

This information is applicable to US chart 14853.

The Canadian Coast Guard proposes to permanently discontinue the fog signal in Livingstone Channel Upper Entrance. Comments on this action are solicited from mariners and other interested parties and should be directed to the District Manager, P.O. Box 1000, 401 King Street West, Prescott, Ontario, K0E 1T0, Telephone: (613) 925-2865, Facs: (613) 925-5540, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-21) (CCG -C96-021)

*507(P) GREAT LAKES - DETROIT RIVER - Light to be changed.

Chart (Which will be affected) - LC 2123(NAD 27)(1)

1. FI G 10s, D33 to read "Iso G 4s", marked "D33"

42°02'24" N 83°08'03" W

NOTE: The Canadian Coast Guard proposes to permanently reduce intensity, change characteristics from FI G to Iso G 4 sec. and remove floodlighting from the above-mentioned aid to navigation. Comments on this action are solicited from mariners and other interested parties and should be directed to the Supervisor, Navaids, Canadian Coast Guard, P.O. Box 1000, 401 King Street West., Prescott, Ontario, K0E 1T0, Telephone (613) 925-2865, Facs: (613) 925-5540 within three months of the date of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-14) (CCG-B96-020)

*603(T) LAKE ONTARIO - BURLINGTON CANAL ENTRANCE - Light buoy established temporarily.

Charts (Temporarily affected) - 2067(NAD 27)(1) - 2086NAD 83)(2) - LC 2077(NAD 83)(2) - **2067R/M** - **2086R/M** - **73003(2067)** - **73091(2077)**

Reference: Notice 236(T)/96 cancelled.

1. Red light buoy "Q R", marked "MB2"

43°18'07".7 N 79°47'23".3 W

2. Red light buoy "Q R", marked "MB2"

43°18'07".9 N 79°47'22".6 W

1996

NOTE: The above digital data products may also be affected. Contact Nautical Data International Inc. (NDI) or your Value Added Remarketers (VAR) for updates.

(AMA8035-10-5-14) (CCG-P96-035)

*747(P) LAKE ONTARIO - BAY OF QUINTE - Result of survey.

Chart (Which will be affected) - 2021(Sheet 2)(Trenton to/à Glen Ross)(NAD 27)(1-5)

| 1. | Breakwater | | | 77°31'29".5 W 77 31 29.9 W |
|----|-----------------------|------------|---|-------------------------------|
| 2. | light "Fl Or", "Priv" | 44 06 13 | N | 77 31 29.5 W |
| 3. | light "Fl Or", "Priv" | 44 06 14.8 | N | 77 31 30 W |
| 4. | light "Fl Or", "Priv" | 44 06 16.9 | N | 77 31 29 W |
| 5. | light "Fl G", "Priv" | 44 06 17 | N | 77 31 29.9 W |

NOTE: Additional information will be made available at a later date. Digital data products 2069R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-C96-031)

1997

*334(P) LAKE HURON - GEORGIAN BAY - GIANTS TOMB ISLAND TO LONE ROCK - Depths.

Chart (Which will be affected) - 2289(1-33)

| 1. Add | depth "2 1/4" fathoms | 44°57'34" N 79°58'24" W |
|--------|-----------------------|---------------------------|
| 2. | depth "3/4" fathom | 44 57 23 N 79 58 41.5 W |
| 3. | depth "3/4" fathom | 44 57 19.5 N 79 59 10 W |
| 4. | depth "1 1/2" fathoms | 44 57 27.5 N 79 59 25 W |
| 5. | depth "7 1/2" fathoms | 44 56 40 N 80 02 20 W |
| 6. | depth "9 1/2" fathoms | 44 57 04 N 80 03 04 W |
| 7. Add | depth "4 1/2" fathoms | 44 57 13 N 80 01 17 W |
| 8. | depth "4 1/4" fathoms | 44 57 15.5 N 80 01 40 W |
| 9. | depth "3 1/2" fathoms | 44 57 47.5 N 80 01 24.5 W |
| 10. | depth "5 1/2" fathoms | 44 58 10 N 80 02 22 W |
| 11. | depth "1 1/2" fathoms | 44 57 54 N 79 59 59 W |
| 12. | depth "3 1/4" fathoms | 44 57 52.5 N 79 59 40 W |
| | | |

| | 1997 | | | |
|-----|-----------------------|------------|---|------------|
| | | | | |
| 13. | depth "2" fathoms | 44 58 08 | Ν | 79 59 38 W |
| 14. | depth "1 1/2" fathoms | 44 58 10 | Ν | 79 59 20 W |
| 15. | depth "4 3/4" fathoms | 44 58 09 | Ν | 80 00 36 W |
| 16. | depth "3 1/2" fathoms | 44 58 13.5 | N | 80 01 48 W |
| 17. | depth "4 1/2" fathoms | 44 58 28 | N | 80 01 49 W |
| 18. | depth "1 1/2" fathoms | 44 58 14 | N | 80 00 17 W |
| 19. | depth "2" fathoms | 44 58 25 | N | 80 00 10 W |
| 20. | depth "1 1/4" fathoms | 44 59 35 | N | 80 00 05 W |
| 21. | depth "3 1/4" fathoms | 44 58 44 | N | 79 59 50 W |
| 22. | depth "3 1/2" fathoms | 44 58 52 | N | 80 01 10 W |
| 23. | depth "2" fathoms | 44 58 55 | N | 80 00 28 W |
| 24. | depth "3 1/4" fathoms | 44 58 59 | N | 80 00 15 W |
| 25. | depth "1 1/2" fathoms | 44 59 09 | N | 80 00 36 W |
| 26. | depth "2" fathoms | 44 59 12 | N | 80 01 28 W |
| 27. | depth "1 1/4" fathoms | 44 59 15 | N | 80 00 05 W |
| 28. | depth "1" fathom | 44 59 33 | N | 80 01 34 W |
| 29. | depth "3" fathoms | 44 59 44 | N | 80 00 50 W |
| 30. | depth "1 3/4" fathoms | 45 00 06 | N | 80 01 25 W |
| 31. | depth "1 1/2" fathoms | 45 00 23 | N | 80 02 59 W |
| 32. | depth "1 1/2" fathoms | 45 00 47 | N | 80 01 49 W |
| 33. | depth "1 1/4" fathoms | 45 00 52 | N | 80 02 14 W |
| | | | | |

NOTE: (1) Recent hydrographic surveys show significant changes to charted depths. The most critical soundings are listed above.

Mariners should exercise extreme caution while navigating in the area bounded by:

45°02'00" N 80°04'00" W 44 54 00 N 80 04 00 W 44 54 00 N 79 56 00 W 45 02 00 N 80 00 00 W

The surveys that are now in progress will be fully applied to the new edition scheduled or release in 1999.

1997

(NDI) or your local Value Added Remarketers (VAR) for updates.

Digital data products 73047(2289) may also be affected. Contact Nautical Data International Inc.

(AMA8035-10-35) (DFO-D97-003)

*335(P) LAKE HURON - GEORGIAN BAY - GIANTS TOMB ISLAND TO LONE ROCK - Depths.

Chart (Which will be affected) - 2289 (1-39)

(2)

| 1. Add | depth "4 1/4" fathoms | 44°54'09" N 79°57'26" W |
|---------|-----------------------|-------------------------|
| 2. | depth "3 ¾" fathoms | 44 54 23 N 79 57 49 W |
| 3. | depth "4 1/2" fathoms | 44 54 27 N 79 58 00 W |
| 4. | depth "4 1/2" fathoms | 44 54 35 N 79 58 02 W |
| 5. | depth "3 ¾" fathoms | 44 55 03 N 79 58 13 W |
| 6. | depth "3 ½" fathoms | 44 55 07 N 79 58 33 W |
| 7. | depth "3 ½" fathoms | 44 55 09 N 79 58 06 W |
| 8. | depth "4" fathoms | 44 55 11 N 79 57 48 W |
| 9. | depth "1 ½" fathoms | 44 55 29 N 79 57 20 W |
| 10. | depth "1 ½" fathoms | 44 55 36 N 79 57 33 W |
| 11. | depth "1 1/4" fathoms | 44 55 38 N 79 57 58 W |
| 12. | depth "1 ½" fathoms | 44 55 35 N 79 58 12 W |
| 13 | depth "2" fathoms | 44 55 57 N 79 57 19 W |
| 14. | depth "1 ½" fathoms | 44 55 53 N 79 57 39 W |
| 15. | depth "1 1/2" fathoms | 44 55 51 N 79 58 25 W |
| 16. | depth "1/2" fathom | 44 55 48 N 79 58 53 W |
| 17. | depth "4 1/4" fathoms | 44 56 02 N 79 59 35 W |
| 18. | depth "2 1/2" fathoms | 44 56 18 N 79 58 20 W |
| 19. | depth "2 1/2" fathoms | 44 56 20 N 79 59 01 W |
| 20. | depth "1 1/4" fathoms | 44 56 27 N 79 58 58 W |
| 21. Add | depth "2" fathoms | 44 56 36 N 79 57 43 W |
| 22. | depth "1/2" fathom | 44 56 37 N 79 59 09 W |
| 23. | depth "3 ½" fathoms | 44 56 39 N 79 59 46 W |
| 24. | depth "1" fathom | 44 56 42 N 79 57 38 W |

| 1997 | | | |
|------|-----------------------|-------------------------|--|
| 25. | depth "3/4" fathom | 44 56 44 N 79 58 51 W | |
| 26. | depth "1 ½" fathoms | 44 56 48 N 79 57 52 W | |
| 27. | depth "2 1/2" fathoms | 44 56 48 N 79 58 13 W | |
| 28. | depth "2 1/4" fathoms | 44 56 53 N 79 58 00 W | |
| 29. | depth "2 1/2" fathoms | 44 56 56 N 79 58 06 W | |
| 30. | depth "2 1/4" fathoms | 44°56'55" N 79°58'20" W | |
| 31. | depth "2 1/4" fathoms | 44 57 03 N 79 57 52 W | |
| 32. | depth "2" fathoms | 44 57 03 N 79 58 14 W | |
| 33. | depth "2" fathoms | 44 56 52 N 79 58 45 W | |
| 34. | depth "1" fathom | 44 56 53 N 79 59 11 W | |
| 35. | depth "3 1/2" fathoms | 44 56 50 N 79 59 29 W | |
| 36. | depth "3 ¾" fathoms | 44 56 56 N 79 59 36 W | |
| 37. | depth "2 ¾" fathoms | 44 57 05 N 79 59 17 W | |
| 38. | depth "1 1/2" fathoms | 44 57 08 N 79 59 39 W | |
| 39. | depth "2 1/2" fathoms | 44 57 05 N 80 00 25 W | |
| | | | |

NOTE: (1) Recent hydrographic surveys show significant changes to charted depths. The most critical soundings are listed above.

Mariners should exercise extreme caution while navigating in the area bounded by:

45°02'00" N 80°04'00" W 44°54'00" N 80°04'00" W 44°54'00" N 79°56'00" W 45°02'00" N 80°00'00" W

The surveys that are now in progress will be fully applied to the new edition scheduled for release in the 1999.

(2) Digital data products 73047(2289) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-C97-004)

*361(P) LAKE HURON - ST JOSEPH CHANNEL - RICHARDS LANDING - Breakwater.

Chart (Which will be affected) - 2250(Inset, Richards Landing)(NAD 27)(2) - 2250(NAD 27)(1)

| 1. Add | Breakwater | joining 4 | 46°17'43".2 N | 84°02'13" W (approx.) |
|--------|------------|-----------|---------------|------------------------|
| | | • | 46 17 44 N | 84 02 13.5 W (approx.) |
| | | • | 46 17 44.1 N | 84 02 19 W (approx.) |
| | | and 4 | 46 17 43.5 N | 84 02 20.2 W (approx.) |
| 2. | Breakwater | joining 4 | 46 17 43.2 N | 84 02 13.1 W (approx.) |
| | | | 46 17 44 N | 84 02 13.5 W (approx.) |
| | | and 4 | 46 17 44.1 N | 84 02 16 W (approx.) |

1997

NOTE: (1) This breakwater extends from the Northwest corner of the existing dock, approximately 26m North then 160m West. This breakwater cannot be fully shown on the existing inset of Richards Landing. Caution is to be used while navigating in this area. Additional information will be made available at a later date.

(2) Digital data products 2250R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-C97-027)

*367(P) LAKE ERIE - POINTE AUX PINS - Light to be changed.

Charts (Which will be affected) - LC 2122(NAD 27)(2) - LC 2100(NAD 27)(1)

1. F R to read "FI R" 42°15'33".6 N 81°50'54".7 W

2. F R 13m 6M to read "FI R 4s 13m 6M"

NOTE: (1) The Canadian Coast Guard proposes to permanently reduce the intensity and change the characteristics of the above-mentioned aid to navigation. Comments on this action are solicited from mariners and other interested parties and should be directed to Mr. Steven D. Lear, Supervisor, NAVAIDS, Canadian Coast Guard, P.O. Box 1000, 401 King Street West, Prescott, Ontario, K0E 1T0, Telephone (613) 925-2865, Facs: (613) 925-5540 within three months of the date of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(2) Digital data products 2100R/M, 2122R/M, 73090(2122) and 73094(2100) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

42 15 33.6 N 81 50 54.7 W

(AMA8035-10-7-14) (CCG-B96-056)

*407(T) QUÉBEC - LAC DES DEUX MONTAGNES - ANSE DE VAUDREUIL - Shoal reported.

Chart (Temporarily affected) - 1510(Sheet 1)(Compartment A-B)(NAD 27)(1)

1. Shoal between 45°25'36" N 74°02'00" W (approx.) and 45 26 24 N 74 02 00 W (approx.)

NOTE: Mariners are requested to proceed with caution when navigating in this area. Additional information will be made available at a later date.

(AMA8035-10-35) (DFO-Q97-076)

*450(P) LAKE SUPERIOR - NIPIGON BAY - JACKFISH BAY, SIMPSON ISLAND, MACINNES POINT - Lights to be discontinued.

Charts (Which will be affected) - 2305(1) - 2303(1,2) - 2312(NAD 27)(2,3) - 2304(4)

1. Light 48°47'22" N 86°58'54" W
2. 48 50 27 N 87 41 26 W
3. 48 55 44 N 87 55 42 W
4. 48 47 17 N 86 58 54 W

1997

- NOTE: (1) The Canadian Coast Guard proposes to permanently discontinue the above-mentioned aids to navigation. Comments on these actions are solicited from mariners and other interested parties and should be directed to the Supervisor, Marine Aids Program, Canadian Coast Guard, P.O. Box 310, 28 Waubeek St., Parry Sound, Ontario P2A 2X4, Telephone (705) 746-2196, Facs: (705) 746-6953 within three months of the date of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.
 - (2) Digital data products 2303R/M, 2304R/M, 2312R/M, 73062(2312), 73066(2303), 73067(2304) and 73120(2312) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-7-13)

(CCG-D97-018,DFO-C97-052)

*531(P) QUÉBEC - OTTAWA RIVER - DESJARDINSVILLE - Light.

Chart (Which will be affected) - 1553(Sheet 1)(Inset, Desjardinsville)(NAD 27)(1) - 1553(Sheet 1)(NAD 27)(2)

1. Add light "FI R" 166°30' 850 ft from NE corner of the building

2. light "FI R" 45°50'42".2 N 77°06'53".4 W

NOTE: The light is located on a new breakwater. Additional information will be made available at a later date.

(AMA8035-10-7-14)

(CCG-B97-018;DFO-C97-077)

*533(P) LAKE HURON - GEORGIAN BAY - COGNASHENE BY PASS - THE WHALESBACK - Buoys.

Chart (Which will be affected) - 2289(1-18)

| 1. Delete | green spar buoy MA7 | | 44°55'05" | Ν | 79°55'20" W |
|---------------|--------------------------------|------------|----------------------|-----|--------------------------|
| 2. Add | red spar buoy marked "MA4" | | 44 55 06 | N | 79 55 20 W |
| 3. Reposition | green spar buoy MA5 | from to | 44 54 33 44 54 26 | | 79 56 31 W 79 56 27 W |
| 4. | red spar buoy MA6 | from to | 44 54 26 44 54 33 | | 79 56 27 W 79 56 31 W |
| 5. Add | red spar buoy marked "MG4" | | 44 54 21 | N | 79 56 09 W |
| 6. | green spar buoy marked "MG5" | | 44 54 13 | N | 79 56 10 W |
| 7. | red spar buoy marked "MG6" | | 44 55 03 | N | 79 56 01 W |
| 8. Add | green spar buoy marked "MG7" | | 44 55 42 | N | 79 56 40.5 W |
| 9. | red spar buoy marked "MG8" | | 44 55 45 | N | 79 56 39 W |
| 10. | green spar buoy marked "MG9" | | 44 56 00 | N | 79 56 57 W |
| 11. | green spar buoy marked "MG9/1" | | 44 56 13.6 | S N | 79 56 56.5 W |
| 12. | red spar buoy marked "MG10" | | 44 56 20 | N | 79 56 51 W |

| | 1997 | |
|------------------|---|--|
| | | |
| 13. | green spar buoy marked "MG11" | 44 56 22 N 79 56 59 W |
| 14. | north cardinal buoy "BY" marked "MG" | 44 56 52 N 79 56 47 W |
| 15. | green spar buoy marked "C113" | 44 56 56 N 79 57 02.5 W |
| 16. | red spar buoy marked "GB2" | 44 54 47.5 N 79 58 02 W |
| 17. | green spar buoy marked "GB3" | 44 55 47 N 79 58 15.5 W |
| 18. | red spar buoy marked "GB4" | 44 55 48 N 79 58 10 W |
| NOTE: (1) (2) | Additional information will be available at a la Digital data products 73047(2289) may also be lnc. (NDI) or your local Value Added Remarks | pe affected. Contact Nautical Data International |
| (AMA8035-10 |)-35) | (DFO-C97-063) |

(AMA8035-10-35) (DFO-C97-063)

1998

*103(P) LAKE SUPERIOR - Fog signals to be privatized.

Reference: Notice 480(P)/96.

The Canadian Coast Guard proposes to privatize the fog signals at Michipicoten Harbour (L.L. 1093) (47°56'33" N 84°54'27" W) (Chart 2315) and Thunder Bay Main (L.L. 1152) (48°25'58" N 89°11'45" W) (Chart 2314).

Comments on this action are solicited from mariners and other interested parties and should be directed to: Supervisor, Marine Aids Program, Canadian Coast Guard, 28 Waubeek St., Box 310, Parry Sound, Ontario, P2A 2X4, Tel.: (705) 746-2196, Fax.: (705) 746-6953, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-21) (CCG-D97-015)

*104(P) LAKE ERIE - PORT COLBORNE - Front range light to be discontinued.

The Canadian Coast Guard intends to permanently discontinue Port Colborne Entrance front range light (L.L. 560.6) (42°52'40".9 N 79°14'52".3 W) prior to the start of the 1998 navigation season.

Comments on this action are solicited from mariners and the public within 3 months of the date of this notice and should be directed to Mr. Steven D. Lear Supervisor, Marine Aids Program, Canadian Coast Guard, P.O. Box 1000, Prescott, Ontario K0E 1T0, Tel. (613) 925-2865 ext. 215, Facs. (613) 925-5540, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-14) (CCG-B97-049)

*505(P) LAKE ERIE - PELEE PASSAGE - Buoys to be relocated and discontinued.

Chart (Which will be affected) - LC 2123(NAD 27)(1,2)

1998

1. Reposition red light buoy E10 from 41°52'35" N 82°36'06" W

to 41 53 09 N 82 38 44 W

2. Delete red spar buoy E12 41 53 09 N 82 38 44 W

NOTES: (1) The Canadian Coast Guard proposes to permanently relocate and discontinue the abovementioned aids to navigation. Comments on this action are solicited from mariners and the public within 3 months of the date of this notice and should be directed to: Supervisor, Marine Aids Program, Canadian Coast Guard, P.O. Box 1000, Prescott, Ont., K0E 1T0, Tel: (613) 925-2865, ext. 215, Facs: (613) 925-5540. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(2) Digital data products 2123R/M and 73089(2123) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-5-14)

1. Construction

(CCG-B97-052; DFO-C98-003)

43°37'54" N 79°28'17" W (approx.)

*506(T) LAKE ONTARIO - HUMBER RIVER ENTRANCE - Construction.

Charts (Temporarily affected) - LC 2077(NAD 83)(1) - 2086(NAD 83)(1)

NOTES:(1) The demolition of an existing structure and the erection of a new structure at the mouth of the Humber River in Lake Ontario began December 17, 1997. Work will continue 24 hours a day, 7 days a week for approximately 1 year. Cofferdams have

been erected on the East and West shorelines.

(2) Digital data products 2077R/M, 2086R/M, 73048(2086) and 73091(2077) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-C98-

005)

*723(P) ONTARIO - KENORA - Amendments to the aids to navigation level of service - 1998.

Mariners are advised that, at the beginning of the 1998 navigation season, the Canadian Coast Guard intends to permanently discontinue the aids to navigation service on Pellican Lake, Abram Lake, Minnitaki Lake, Red Lake, Lost Lake, Dinorwic Lake and Wabigoon Lake.

Interested parties may seek to take over responsibility for the operation and maintenance of all, or some, of these aids to navigation. This would require signing a memorandum of understanding transferring ownership and responsibility for the equipment.

Requests for information with regard to this notice should be directed to the Canadian Coast Guard. You may contact any one of the following:

R.E. Childerhose Supervisor Marine Aids Program P.O. Box 310, Parry Sound, Ont. P2A 2X4

Telephone: (705) 746-2196, ext. 238

Al Dion Superintendent Marine Aids Program 201 N. Front Street, Sarnia, Ont. N7T 8B1

Telephone: (519) 383-1859

1998

(AMA8035-10-7-13) (CCG-D97-028)

*1109(P) LAKE ONTARIO - PRESQU'ÎLE BAY - Buoys and range lights.

As a result of a recent Levels of Service review, the Canadian Coast Guard proposes to conduct the following changes to aids to navigation - Lake Ontario, Presqu'Île Bay.

Chart 2021 (Sheet 1)

Discontinue light buoy P (L.L. 491.8) (43°59'57" N 77°39'48" W).

Relocate green spar buoy MP23 from 44°00'22" N 77°40'52" W to 44°00'22" N 77°40'57" W.

Discontinue green spar buoy MP11 (44°01'21" N 77°42'18".3 W).

Discontinue green spar buoy MP19 (44°00'42" N 77°41'54" W).

Discontinue green spar buoy MP15 (44°01'04" N 77°42'40" W).

Relocate green spar buoy MP9 from 44°01'27" N 77°42'05".7 W to 44°01'28".5 N 77°42'03" W.

Relocate red spar buoy MP12 from 44°01'18" N 77°42'28".5 W to 44°01'19" N 77°42'18" W.

Relocate green spar buoy MP13 from 44°01'13" N 77°42'33" W to 44°01'21" N 77°42'12" W.

Relocate green spar buoy MP17 from 44°00'54" N 77°42'34" W to 44°00'56" N 77°41'55" W

Discontinue red spar buoy MP14 (44°01'01" N 77°42'59.5" W).

Establish East Cardinal spar buoy, marked MP (44°01'02" N 77°42'57" W).

Discontinue Brighton range lights (L.L. 487 and 488) (44°01'07" N 77°43'17" W).

Replace red spar buoy MP24 with a lighted red spar buoy FI R marked MP24 (44°00'12" N 77°40'37".5 W)

Replace green spar buoy MP21 with a lighted green spar buoy FI G marked MP21 (44°00'25" N 77°41'11" W).

Comments on this action are solicited from mariners and other interested parties and should be directed to Mr. Steven D. Lear, Supervisor, Marine Aids Program, Canadian Coast Guard, P.O. Box 1000, Prescott, Ontario, K0E 1T0, Tel.: (613) 925-2865 ext. 215, Facs: (613) 925-5540, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-5-14) (CCG-B98-015)

*1148(T) LAKE HURON - GEORGIAN BAY - COLPOY'S BAY - Barge.

Chart (Temporarily affected) - LC 2282(NAD 83)(1)

1. Barge 44°48'48" N 81°03'00" W

NOTE: (1) The barge is equipped on all corners with white lights. Mariners can contact barge/VD9768 via VHF CH16.

(2) Digital data products 2282R/M, 73076(2282), 73077(2282), 73078(2282) and 73079(2282) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-C98-108)

*1939(T) ONTARIO - LOST LAKE - Lights discontinued temporarily.

The following lights have been temporarily discontinued.

Bear Narrows (L.L. 1526) (50°24'30" N 92°00'00" W)

Omega Point (L.L. 1527) (50°17'30" N 92°01'00" W)

1998

McLean Narrows (L.L. 1528) (50°22'00" N 92°04'00" W)

Pauli Island (L.L. 1528.2) (50°23'50" N 92°07'00 "W)

Deception Bay (L.L. 1528.4) (50°11'20" N 92°57'30" W)

Manitou Rapids (L.L. 1528.6) (50°13'20" N 92°05'00" W)

Devil's Elbow (L.L. 1529) (50°13'30" N 92°06'00" W)

Canoe River (L.L. 1530) (50°18'20" N 92°13'20" W)

Eagle Island (L.L. 1531) (50°19'30" N 92°20'30" W)

Broken Stick Island (L.L. 1532) (50°19'00" N 92°23'50" W)

(AMA8035-10-7-13) (CCG-D98-015)

*2125(P) QUÉBEC - OTTAWA RIVER - CARILLON - Shoal depth.

1. Replace

Chart (Which will be affected) - 1510(Sheet 1)(NAD 27)(1) - 1510(Sheet 1)(Inset, Carillon)(NAD 27)(2)

1. Replace 19 feet with 3 feet 45°33'53" N 74°22'31" W

2. 19 feet with 3 feet 043°00' 257 metres (843 feet) from

lower left corner of inset

45°33'56".6 N 74°25'44".6 W

NOTE: (1) Additional information will be made available at a later date.

(2) Digital data product 1510R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-Q98-126)

*2154(P) QUÉBEC - OTTAWA RIVER - LAC DOLLARD-DES-ORMEAUX - Dangerous underwater rock.

Chart (Which will be affected) - 1514(Compartment A-B)(Carillon à/to Papineauville)(NAD 83)(1)

dangerous underwater rock with a depth of 0 metre 9 decimetres

2 metres 7 decimetres with a

NOTE: Additional information will be made available at a later date.

(AMA8035-10-35) (DFO-Q98-125)

1999

*157(T) QUÉBEC - OTTAWA RIVER - LAC DES DEUX MONTAGNES - POINTE-CALUMET - Shoal.

Chart (Temporarily affected) - 1510(Sheet 2)(Compartment B-C)(Baie de Vaudreuil à/to Laval) (NAD 27)(1)

1. Shoal 45°29'40" N 73°57'08" W (approx.)

1999

NOTE: (1) A shoal exist in the channel between buoys HD74 and CAL. Additional information will be made available at a later date.

(2) Digital data products 1510R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-Q98-141)

*1722(P) LAKE ONTARIO - WICKLOW BEACH - Light.

Chart (Which will be affected) - 2059(NAD 83)(1)

1. Add light F Y Priv

43°58'27".6 N 77°57'30".7 W

NOTE: (1) The light is located on a breakwater. Additional information about the breakwater will be available at a later date.

(2) Digital data products 2059R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-C99-095)

*1944(P) LAKE HURON - NORTH CHANNEL - CLAPPERTON ISLAND - Buoy.

Chart (Which will be affected) - 2299(NAD 27)(1)

1. Replace green light buoy J71 with green spar

46°02'00" N 82°11'10" W

buoy, marked J71

NOTE: (1) This notice will be incorporated in the next New Edition of chart 2299.

(2) Digital data products 2299R/M and 73059(2299) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-C99-134)

*2336(T) LAKE HURON - GEORGIAN BAY - BATEAU ISLAND TO BYNG INLET - Depths.

Chart (Temporarily affected) - LC 2243(NAD 27)(1-14)

| 1. Add | 17 | 45°24'11" N 80°34'46".9" W |
|-----------|----|----------------------------|
| 2. | 7 | 45 22 54.8 N 80 30 42.7 W |
| 3. | 25 | 45 25 11.2 N 80 29 25.9 W |
| 4. | 1 | 45 25 40.8 N 80 28 15.6 W |
| 5. | 8 | 45 25 28.8 N 80 25 51 W |
| 6. Delete | 28 | 45 25 26.8 N 80 25 51 W |
| 7. Add | 16 | 45 24 15 N 80 25 12.3 W |
| 8. | 19 | 45 23 55.9 N 80 24 56.9 W |
| 9. | 9 | 45 25 13.1 N 80 23 44.6 W |

| 1999 | | |
|------------|----|---------------------------|
| 10. | 7 | 45 25 05 N 80 23 30 W |
| 11. | 24 | 45 24 50.6 N 80 23 44.6 W |
| 12. | 4 | 45 23 19.7 N 80 22 14.2 W |
| 13. | 26 | 45 25 26.4 N 80 29 19.2 W |
| 14. Delete | 34 | 45 25 27.2 N 80 29 12.1 W |

NOTE: Digital data products 2243R/M and 73053(2243) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-C99-164)

1992

*702(P) BRITISH COLUMBIA - SHUSWAP LAKE - SALMON ARM - Range lights established.

Chart (Which will be affected) - 3053(Compartment B-C)(Continuation A)(NAD 27)

Add range lights

Front - Iso Y 50°42'33" N 119°16'58" W

Rear - Iso Y 151° 120 m (394 ft) from front light

NOTE: Exact position will be available upon completion of survey.

(AMA8035-10-7-16; 8010-1894)

(TC-V-052,053)

1995

*733(T) BRITISH COLUMBIA - DIXON ENTRANCE - ROSE SPIT - Racon temporarily relocated.

Chart (Temporarily affected) - LC 3802(NAD 27)(1)

1. Racon from 54°11'12 ».5 N 131°38'43 » W to 54 11 07 N 131 38 52 W

(AMA8035-10-18-6) (TC-P95-005)

1996

*814(P) VANCOUVER ISLAND, WEST COAST - APPROACHES TO ESPERANZA INLET - Shoal depths.

Charts (Which will be affected) - 3682(NAD 27)(1-6)

| 1. Replace | 3 3/4 fathoms with "1 fathom" | 49°52'51".1 N 127°11'10".2 W |
|------------|---------------------------------|------------------------------|
| 2. | 3 1/2 fathoms with "1/4 fathom" | 49 51 16.7 N 127 07 36.5 W |
| 3. Add | "4 fathoms" | 49°50'11".7 N 127°06'36".2 W |
| 4. | "2 1/4 fathoms" | 49 50 46.1 N 127 04 21.5 W |
| 5. | "3 1/4 fathoms" | 49 51 01.3 N 127 05 09.9 W |
| 6. | "2 1/2 fathoms" | 49 51 25.9 N 127 04 31.8 W |

NOTE:

- (1) Digital data products 3682R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.
- (2) New charts incorporating this information will be available at a later date.

(AMA8035-10-35) (DFO-P96-058)

1997

*96(P) VANCOUVER ISLAND, WEST COAST - KYUQUOT SOUND - ENTRANCE TO FAIR HARBOUR - Shoal reported.

Chart (Which will be affected) - 3623(NAD 27)(1)

1. Depth "1 fathom 1 foot"

50 04 27 N 127 09 15.6 W (approx.)

NOTE: (1) Digital data products 3623R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(2) Additional information will be made available upon completion of survey.

(AMA8035-10-35) (DFO-P96-065)

1999

*1945(P) BRITISH COLUMBIA - KYUQUOT SOUND - ENTRANCE TO FAIR HARBOUR - Rocks.

Charts (Which will be affected) - 3682(NAD 27)(1,2) - 3623(NAD 27)(1,3)

1. Add dangerous underwater rock 50°04'37" N 127°09'10".5 W

2. Add dangerous underwater rock 50 04 40.9 N 127 09 21.8 W

3. dangerous underwater rock 50 04 41 N 127 09 21.7 W

NOTE: (1) Additional information will be available upon completion of survey.

(2) Digital data products 3623R/M, 3682R/M and 70291(3623) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-P99-046)

*2345(P) BRITISH COLUMBIA - WEST OF QUEEN CHARLOTTE ISLANDS - Submarine cable.

Chart (Which will be affected) - LC 3002(NAD 27)(1)

1. Add submarine cable joining 50°45'00" N 131°36'05".8 W

51 00 00 N 132 00 00 W

and 53 30 00 N 134 00 00 W

NOTE: (1) This information will be incorporated in the next printing of chart L/C 3002.

Digital data products 3002R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-P99-053)

*2346(P) UNITED STATES, WEST COAST - JUAN DE FUCA STRAIT - WEST OF VANCOUVER ISLAND AND QUEEN CHARLOTTE ISLANDS - Submarine cable.

Chart (Which will be affected) - LC 3000(NAD 27)(1)

1999

| 1. A | Add submarine cable | joining | 47°51'54" N 122°19'55".8 W |
|------|---------------------|---------|----------------------------|
| | | | 47 52 04.2 N 122 20 49.8 W |
| | | | 47 50 38.4 N 122 25 03 W |
| | | | 47 51 13.8 N 122 27 51.6 W |
| | | | 47 55 13.8 N 122 28 37.8 W |
| | | | 47 56 42 N 122 31 00.6 W |
| | | | 47 57 18.6 N 122 34 36 W |
| | | | 48 01 52.2 N 122 37 49.2 W |
| | | | 48 06 40.8 N 122 39 34.2 W |
| | | | 48 11 46.8 N 122 47 00 W |
| | | | 48 12 09 N 122 51 54 W |
| | | | 48 14 39 N 122 59 31.2 W |
| | | | 48 11 31.2 N 123 16 00 W |
| | | | 48 10 54 N 123 25 25.2 W |
| | | | 48 11 48 N 123 35 30 W |
| | | | 48 13 18 N 123 36 24 W |
| | | | 48 16 48 N 124 00 00 W |
| | | | 48 22 13.2 N 124 21 21.6 W |
| | | | 48 26 15.6 N 124 32 00 W |
| | | | 48 28 02.4 N 124 40 24 W |
| | | | 48 28 12 N 124 44 00 W |
| | | | 48 25 28.8 N 125 00 00 W |
| | | | 48 27 16.2 N 125 05 27.6 W |
| | | | 48 26 51.6 N 125 08 14.4 W |
| | | | 48 24 28.8 N 125 11 45.6 W |
| | | | 48 19 16.8 N 125 24 00 W |
| | | | 48 18 06 N 125 30 00 W |
| | | | 48 10 57.6 N 125 51 38.4 W |
| | | | 48 06 18 N 125 59 28.2 W |
| | | | 48 03 00 N 126 11 12 W |
| | | | 48 03 01.8 N 126 50 00 W |
| | | | 48 08 37.2 N 127 05 04.2 W |
| | | | 49 05 00 N 129 00 00 W |
| | | | 51 00 00 N 132 00 00 W |
| | | | 53 30 00 N 134 00 00 W |
| | | | E4 E0 00 NI 40E 04 04 0 NI |

- NOTE: (1) This information will be incorporated in the next printing of chart L/C 3000.
 - (2) Digital data products 3000R/M may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

and 54 50 00 N 135 31 31.2 W

(AMA8035-10-35) (DFO-P99-054)

*2348(P) UNITED STATES, WEST COAST - APPROACHES TO JUAN DE FUCA STRAIT - Submarine cable.

Chart (Which will be affected) - LC 3602(NAD 27)(1)

1000

| | 1' | 999 | |
|--------|-----------------|---------|------------------------------|
| 1. Add | submarine cable | joining | 48°27'28".6 N 124°37'35".1 W |
| | | | 48 28 03.2 N 124 40 18.9 W |
| | | | 48 28 12.8 N 124 43 54. 9 W |
| | | | 48 26 08 N 124 55 54.9 W |
| | | | 48 25 36.8 N 124 57 54.9 W |
| | | | 48 25 29.6 N 124 59 54.9 W |
| | | | 48 25 34.4 N 125 00 48.9 W |
| | | | 48 25 56 N 125 01 54.9 W |
| | | | 48 27 08 N 125 04 39.9 W |
| | | | 48 27 17.6 N 125 06 14.1 W |
| | | | 48 26 52.4 N 125 08 09.3 W |
| | | | 48 25 57.2 N 125 09 46.5 W |
| | | | 48 24 29.6 N 125 11 40.5 W |
| | | | 48 19 17.6 N 125 23 54.9 W |
| | | | 48 18 06.8 N 125 29 54.9 W |
| | | | 48 14 12.8 N 125 42 54.9 W |
| | | | 48 10 58.4 N 125 51 33.3 W |
| | | | 48 06 18.8 N 125 59 23.1 W |
| | | | 48 06 00.8 N 125 01 18.9 W |
| | | | 48 04 54.8 N 126 03 18.9 W |
| | | | 48 03 00.8 N 126 11 06.9 W |
| | | and | 48 03 01.8 N 126 22 59 W |
| | | ana | 10 00 01.0 14 120 22 00 W |

NOTE: (1) This information will be incorporated in the next printing of chart L/C 3602.

Digital data products 3602R/M and 70203(3602) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates. This information will be incorporated in the new edition of this chart.

(AWA8035-10-35) (DFO-P99-057)

*2349(P) UNITED STATES, WEST COAST - PUGET SOUND - JUAN DE FUCA STRAIT - Submarine cable.

Chart (Which will be affected) - LC 3461(NAD 27)(1)

1. Add submarine cable joining 47°57'42" N 122°34'57".1 W 47 57 55.3 N 122 35 12.1 W 48 01 52.9 N 122 37 44.5 W 48 06 16.9 N 122 39 09.7 W 48 06 41.5 N 122 39 29.5 W 48 08 16.9 N 122 41 36.7 W 49 09 44.5 N 122 44 13.3 W 48 10 38.5 N 122 44 52.3 W 48 11 39.1 N 122 46 29.5 W 48 11 57.1 N 122 47 59.5 W 48 12 09.7 N 122 51 49.3 W 48 12 51.1 N 122 54 50.5 W 48 14 18.7 N 122 57 39.1 W 48 14 37 N 122 58 31.5 W 48 14 37.3 N 123 00 24.1 W 48 11 31.9 N 123 15 55.3 W 48 11 06.7 N 123 22 55.3 W 48 10 54.7 N 123 24 24.7 W 48 10 54.7 N 123 25 20.5 W

48 11 13.3 N 123 27 31.9 W

| 1999 | |
|------|----------------------------|
| | 48 11 24.7 N 123 34 25.3 W |
| | 48 11 48.7 N 123 35 25.3 W |
| | 48 13 18.7 N 123 36 19.3 W |
| | 48 13 36 7 N 123 37 07 3 W |

and 48 14 47.3 N 123 45 30 W

NOTE: (1) This information will be incorporated in the next printing of chart L/C 3461.

(2) Digital data products 3461R/M and 70141(3461) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-P99-058)

SECTION 1 – 2000

EDITION 03/2000

(P) GREAT LAKES - ST. CLAIR RIVER - Lights to be changed.

This information is applicable to U.S. Chart 14863.

The Canadian Coast Guard proposes to permanently change the characteristic of the following lights:

Courtright (L.L. 753) (42°48'23" N 82°28'43" W) from F Y to Iso Y 4 s.

Stokes Point Wharf (L.L. 749) (42°44'05" N 82°28'44".2 W) from F R to Iso R 4 s.

Comments on this action are solicited from mariners and other interested parties and should be directed to Mr. Steven D. Lear, Supervisor, Marine Aids Program, Canadian Coast Guard, P.O. Box 1000, 401 King Street W., Prescott, Ontario, K0E 1T0, Telephone (613) 925-2865 Ext. 215, Faxs: (613) 925-5540, within three months from the date of publication of this notice. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(AMA8035-10-7-14) (CCG-B99-061)

EDITION 04/2000

(P) MANITOBA - WINNIPEG RIVER - Proposed changes to aids to navigations.

| Aid I.D. # | | | | Proposed | | Latitud | е | L | _ongitu | de |
|------------|---------------|--|-------------------------------------|-----------|------|---------|------|------|---------|------|
| L.L.# | Chart(s) | Name/Location | Action | Aid I.D.# | Deg. | Min. | Sec. | Deg. | Min. | Sec. |
| Q2 | 6286 | Roughrock Lake | Status Quo | | 50 | 05 | 12 | 094 | 48 | 37 |
| Q3 | 6286 | Roughrock Lake | Status Quo | | 50 | 05 | 59 | 094 | 47 | 18 |
| Q4 | 6286 | Roughrock Lake | Status Quo | | 50 | 05 | 53 | 094 | 47 | 18 |
| Q6 | 6286 | Roughrock Lake | Status Quo | | 50 | 06 | 05 | 094 | 46 | 35 |
| Q8 | 6286 | Roughrock Lake | Status Quo | | 50 | 06 | 02 | 094 | 45 | 33 |
| Q11 | 6286 | Roughrock Lake | Status Quo | | 50 | 05 | 24 | 094 | 45 | 19 |
| Bn | 6286 | Little Sand Lake | Numbered | DB-Q12 | 50 | 04 | 04 | 094 | 43 | 57 |
| Q14 | 6286 | Little Sand Lake | Status Quo | | 50 | 02 | 38 | 094 | 42 | 13 |
| Q16 | 6286 | Little Sand Lake | Status Quo | | 50 | 02 | 20 | 094 | 42 | 02 |
| Q18 | 6286 | Little Sand Lake | Status Quo | | 50 | 02 | 04 | 094 | 42 | 21 |
| Q21 | 6286 | Little Sand Lake | Status Quo | | 50 | 01 | 19 | 094 | 42 | 20 |
| Bn | 6286 | Little Sand Lake-S of Cummings Island | Replaced with Port Bn & numbered | DB-Q23 | 50 | 01 | 05 | 094 | 41 | 59 |
| Q24 | 6286 | Little Sand Lake-S of Wilcox Island | Status Quo | | 50 | 00 | 43 | 094 | 41 | 26 |
| Bn | 6286 | NW of Minaki | Status Quo | DB-Q | 49 | 59 | 56 | 094 | 41 | 05 |
| QH4 | 6286 | Pistol Lake | Status Quo | | 50 | 00 | 33 | 094 | 42 | 42 |
| QH6 | 6286 | Pistol Lake | Status Quo | | 50 | 00 | 30 | 094 | 42 | 49 |
| QH7 | 6286 | Pistol Lake | Status Quo | | 50 | 00 | 09 | 094 | 42 | 36 |
| Q29 | 6286 | N of Minaki | Discontinued | | 50 | 00 | 02 | 094 | 40 | 32 |
| Q31 | 6286 | N of Minaki | Discontinued | | 49 | 59 | 56 | 094 | 40 | 22 |
| QJ4 | 6286, 6287 | N of Minaki | Discontinued | | 49 | 59 | 41 | 094 | 40 | 36 |
| QJ6 | 6286, 6287 | N of Minaki | Discontinued | | 49 | 59 | 45 | 094 | 40 | 21 |

SECTION 1 - 2000

| Aid I.D. # | | | | Proposed | | Latitud | е | L | ongitue | de |
|------------|---------------|--|---|-----------|------|---------|------|------|---------|------|
| L.L.# | Chart(s) | Name/Location | Action | Aid I.D.# | Deg. | Min. | Sec. | Deg. | Min. | Sec. |
| Bn | 6286, 6287 | N of Minaki | Numbered | DB-Q32 | 49 | 59 | 44 | 094 | 40 | 14 |
| Q36 | 6286 | E of Minaki | Status Quo | | 49 | 59 | 06 | 094 | 39 | 13 |
| QA6 | 6286 | Roughrock Lake | Status Quo | | 50 | 06 | 03 | 094 | 48 | 38 |
| QA8 | 6286 | Roughrock Lake | Status Quo | | 50 | 05 | 47 | 094 | 48 | 03 |
| QE1 | 6286 | Roughrock Lake | Status Quo | | 50 | 06 | 55 | 094 | 47 | 80 |
| QE3 | 6286 | Roughrock Lake | Status Quo | | 50 | 06 | 44 | 094 | 47 | 04 |
| QC2 | 6286 | Roughrock Lake | Discontinued | | 50 | 07 | 10 | 094 | 47 | 19 |
| QC8 | 6286 | Roughrock Lake | Discontinued | | 50 | 06 | 48 | 094 | 45 | 42 |
| QD3 | 6286 | Roughrock Lake | Status Quo | | 50 | 06 | 16 | 094 | 44 | 47 |
| Bn | 6286 | Roughrock Lake | Numbered | DB-QD1 | 50 | 06 | 22 | 94 | 44 | 17 |
| X2 | 6286 | Little Sand Lake | Renumbered | QQ2 | 50 | 04 | 26 | 094 | 39 | 35 |
| QE4 | 6286 | Little Sand Lake-E of Chapmans Island | Discontinued | | 50 | 01 | 49 | 094 | 41 | 59 |
| QE6 | 6286 | Little Sand Lake-E of Chapmans Island | Discontinued | | 50 | 01 | 45 | 094 | 42 | 02 |
| QE | 6286 | Little Sand Lake-E of Chapmans Island | Discontinued | | 50 | 01 | 30 | 094 | 41 | 55 |
| QD | 6286 | Little Sand Lake | Replace with green buoy, Renumbered & reposition to | QN1 | 50 | 02 | 20 | 094 | 41 | 09 |
| QD2 | 6286 | Little Sand Lake | Renumbered | QN2 | 50 | 02 | 12 | 094 | 41 | 04 |
| QX | 6286 | Little Sand Lake | Replace with green buoy & Renumbered | QN3 | 50 | 02 | 09 | 094 | 40 | 56 |
| QW2 | 6286 | Little Sand Lake-S of Harbour Island | Discontinued | | 50 | 02 | 18 | 094 | 40 | 21 |
| X46 | 6286 | Little Sand Lake-S of Octo Island | Renumbered | QM12 | 50 | 01 | 14 | 094 | 40 | 27 |
| Bn | 6286 | Little Sand Lake-S of Harbour Island | Numbered | DB-QM8 | 50 | 02 | 28 | 094 | 39 | 42 |
| X41 | 6286 | Little Sand Lake-S of Harbour Island | Renumbered | QM9 | 50 | 02 | 36 | 094 | 39 | 18 |
| Bn | 6286 | Moores Point | Numbered | DB-QM7 | 50 | 04 | 00 | 094 | 38 | 48 |
| X36 | 6286, 6287 | Little Sand Lake-E of Harbour Island | Renumbered | QX6 | 50 | 04 | 13 | 094 | 39 | 00 |
| X34 | 6286 | Little Sand Lake-E of Harbour Island | Renumbered | QM6 | 50 | 04 | 35 | 094 | 38 | 27 |
| Bn | 6286 | Little Sand Lake-E of Harbour Island | Numbered | DB-QM5 | 50 | 04 | 49 | 094 | 37 | 52 |
| XC | 6286 | Sand Lake-S of Deer Island | buoy & Renumbered | QM4 | 50 | 05 | 22 | 094 | 37 | 20 |
| Red Buoy | 6286 | Pickerel Island | Numbered | QM2 | 50 | 06 | 12 | 094 | 36 | 11 |
| XJ3 | 6286 | NE of Harbour Island | Renumbered | QJ3 | 50 | 04 | 51 | 094 | 39 | 10 |
| X8 | 6286 | N of Harbour Island | Renumbered | QJ2 | 50 | 05 | 19 | 094 | 39 | 15 |
| WC5 | 6286, 6287 | Gun Lake | Discontinued | | 49 | 57 | 54 | 094 | 39 | 33 |
| WC6 | 6286, 6287 | S of Big Island | Discontinued | | 49 | 57 | 01 | 094 | 39 | 43 |
| W11 | 6286, 6287 | W of Big Island | Renumbered | QW11 | 49 | 57 | 08 | 094 | 40 | 32 |
| W15 | 6287 | Gun Lake | Renumbered | QW15 | 49 | 56 | 10 | 094 | 40 | 48 |
| W21 | 6287 | NW of Throat Rapids | Renumbered | QW21 | 49 | 55 | 52 | 094 | 39 | 03 |
| W25 | 6287 | N of Throat Rapids | Renumbered | QW25 | 49 | 54 | 36 | 094 | 38 | 17 |
| W26 | 6287 | S of Throat Rapids | Renumbered | QW26 | 49 | 53 | 38 | 094 | 37 | 49 |
| W37 | 6287 | SE of Myrtle Rapids Narrows | Renumbered | QW37 | 49 | 52 | 46 | 094 | 35 | 28 |

SECTION 1 - 2000

| Aid I.D. # | | | | Proposed | | Latitud | e | L | ongitue | de |
|------------|----------|-----------------------------|------------------------------------|-----------|------|---------|------|------|---------|------|
| L.L.# | Chart(s) | Name/Location | Action | Aid I.D.# | Deg. | Min. | Sec. | Deg. | Min. | Sec. |
| W38 | 6287 | SE of Myrtle Rapids Narrows | Renumbered | QW38 | 49 | 52 | 47 | 094 | 35 | 47 |
| W41 | 6287 | SE of Myrtle Rapids Narrows | Renumbered | QW41 | 49 | 52 | 27 | 094 | 35 | 03 |
| QH | 6287 | Tunnel Bay | Replaced with Isolated Danger buoy | QH | 49 | 58 | 14 | 094 | 36 | 44 |
| Q46 | 6287 | S End of the Big Stretch | Status Quo | | 49 | 56 | 00 | 094 | 34 | 20 |
| Q50 | 6287 | Black Stugeon River | Status Quo | | 49 | 54 | 54 | 094 | 32 | 58 |
| Bn | 6287 | Black Stugeon River | Numbered | DB-QS2 | 49 | 54 | 40 | 094 | 32 | 39 |
| QS4 | 6287 | Black Stugeon River | Status Quo | | 49 | 54 | 42 | 094 | 32 | 36 |
| Q56 | | E of The Little Dalles | Status Quo | | 49 | 52 | 25 | 094 | 33 | 23 |
| Q58 | 6287 | E of The Little Dalles | Status Quo | | 49 | 52 | 20 | 094 | 33 | 32 |
| Q59 | 6287 | E of The Little Dalles | Status Quo | | 49 | 52 | 15 | 094 | 33 | 27 |
| Bn | 6287 | The Little Dalles | Status Quo | DB-Q60 | 49 | 52 | 13 | 094 | 34 | 04 |
| Q64 | 6287 | SW of The Little Dalles | Status Quo | | 49 | 51 | 59 | 094 | 34 | 30 |
| Bn | 6287 | E of Boudreau Island | Status Quo | DB-Q66 | 49 | 51 | 07 | 094 | 34 | 44 |
| Bn | 6287 | The Powderpuff | Status Quo | DB-Q68 | 49 | 50 | 23 | 094 | 34 | 55 |
| Q69 | 6287 | W of Laurensons Island | Status Quo | | 49 | 50 | 19 | 094 | 34 | 51 |
| Q70 | 6287 | SW of Laurensons Island | Status Quo | | 49 | 50 | 06 | 094 | 34 | 50 |
| Q73 | 6287 | W of Fiddlers Island | Status Quo | | 49 | 49 | 29 | 094 | 34 | 14 |
| QK4 | 6287 | E of Laurensons Island | Status Quo | | 49 | 50 | 35 | 094 | 33 | 09 |
| QK8 | 6287 | N of Fiddlers Island | Status Quo | | 49 | 49 | 41 | 094 | 33 | 12 |
| QK10 | 6287 | N of Fiddlers Island | Status Quo | | 49 | 49 | 31 | 094 | 33 | 17 |
| Q76 | 6287 | N of Dufresne Island | Status Quo | | 49 | 48 | 58 | 094 | 32 | 42 |
| Q78 | 6287 | N of Dufresne Island | Status Quo | | 49 | 48 | 57 | 094 | 32 | 12 |
| Q80 | 6287 | N of Dufresne Island | Discontinued | | 49 | 48 | 52 | 094 | 31 | 54 |
| Q81 | 6287 | N of Dufresne Island | Discontinued | | 49 | 49 | 00 | 094 | 31 | 47 |
| Q83 | 6287 | N of Dufresne Island | Status Quo | | 49 | 48 | 48 | 094 | 31 | 33 |
| Q89 | 6287 | N of Dufresne Island | Status Quo | | 49 | 48 | 37 | 094 | 31 | 28 |
| Bn | 6287 | N of Dufresne Island | Numbered | DB-Q91 | 49 | 48 | 23 | 094 | 31 | 34 |
| Bn | 6287 | N of Dufresne Island | Numbered | DB-Q92 | 49 | 48 | 19 | 094 | 31 | 41 |
| Bn | 6287 | N of Dufresne Island | Numbered | DB-Q93 | 49 | 48 | 03 | 094 | 31 | 38 |
| Bn | 6287 | N of Dufresne Island | Numbered | DB-QU2 | 49 | 48 | 35 | 094 | 31 | 46 |
| QU6 | 6287 | NE of Dufresne Island | Status Quo | | 49 | 48 | 21 | 094 | 30 | 28 |
| QN4 | 6287 | NE of Dufresne Island | Status Quo | | 49 | 48 | 02 | 094 | 31 | 20 |
| Bn | 6287 | NE of Dufresne Island | Numbered | DB-QN1 | 49 | 48 | 01 | 094 | 31 | 18 |
| Bn | 6287 | E of Dufresne Island | Numbered | DB-Q94 | 49 | 47 | 34 | 094 | 31 | 06 |
| Bn | 6287 | Millers Rapids | Numbered | DB-QS2 | 49 | 47 | 27 | 094 | 30 | 34 |
| Bn | 6287 | Millers Rapids | Numbered | DB-QP1 | 49 | 47 | 11 | 094 | 30 | 47 |
| QP5 | 6287 | Millers Rapids | Status Quo | | 49 | 47 | 21 | 094 | 30 | 24 |
| Q95 | 6287 | Jay Island | Discontinued | | 49 | 46 | 56 | 094 | 31 | 02 |
| Day Range | 6287 | Jay Island | Discontinued | | 49 | 47 | 01 | 094 | 31 | 01 |
| Day Range | 6287 | Jay Island | Discontinued | | 49 | 47 | 01 | 094 | 31 | 01 |
| Day Range | 6287 | Jay Island | Discontinued | | 49 | 46 | 40 | 094 | 31 | 04 |
| Day Range | 6287 | Jay Island | Discontinued | | 49 | 46 | 40 | 094 | 31 | 04 |
| QQ3 | 6287 | NE of Keewaytin | Status Quo | | 49 | 46 | 16 | 094 | 32 | 27 |
| Bn | 6287 | NW of Boat Lift | Numbered | DB-Q97 | 49 | 45 | 57 | 094 | 33 | 40 |
| Q99 | 6287 | NW of Boat Lift | Status Quo | | 49 | 45 | 55 | 094 | 33 | 37 |
| QX2 | 6287 | Darlington Bay | Status Quo | | 49 | 45 | 52 | 094 | 33 | 57 |
| Bn | 6287 | W of Dufresne Island | Numbered | DB-QT3 | 49 | 48 | 30 | 094 | 33 | 52 |

SECTION 1 – 2000

| Aid I.D. # | | | | Proposed | I | Latitude |) | L | .ongitud | le |
|------------|----------|----------------------|------------|-----------|------|----------|------|------|----------|------|
| L.L.# | Chart(s) | Name/Location | Action | Aid I.D.# | Deg. | Min. | Sec. | Deg. | Min. | Sec. |
| QT8 | 6287 | W of Dufresne Island | Status Quo | | 49 | 47 | 38 | 094 | 33 | 47 |
| Bn | 6287 | Palmerston Channel | Numbered | DB-QT10 | 49 | 47 | 08 | 094 | 33 | 01 |

The Canadian Coast Guard proposes to make the following changes to the aids to navigation in Winnipeg River. Changes are a result of a review of the entire aids to navigation system and as per the Aids Modernization Program and Initiatives. Mariners are requested to comment on changes. Changes are scheduled to take effect for the start of the 2001 navigation season. Dates may change to accommodate changes being made to the appropriate charts. Contact the Supervisor, Marine Aids Program, 28 Waubeek St., Parry Sound, Ontario P2A 1B9

EDITION 07/2000

(T) LAKE HURON - GEORGIAN BAY - Changes to Aids to Navigation due to Low Water in 2000.

| Chart | Name/Location | Change | Reason | Channel Conditions - At Datum | | Latitu | ıde | dec | I | Longi | tude | dec | NS |
|-------|------------------------------|---------------------|--|-------------------------------------|----|--------|------|-----|-----|-------|------|-----|-------|
| 2202 | Potato Island Channel | Information Buoy | Add white information buoy to warn of Low Water conditions | Depths of 5' - 5.5' | 44 | 47 | 10.2 | .17 | 079 | 44 | 1.2 | .02 | C790 |
| 2202 | Potato Island Channel | Information Buoy | Add white information buoy to warn of Low Water conditions | Depths of 5' - 5.5' | 44 | 47 | 35.4 | .59 | 079 | 47 | 55.8 | .93 | C790 |
| 2202 | Roberts Island | MK2/2 | Add to mark 1.8m shoal | | 44 | 50 | 39.6 | .66 | 079 | 50 | 24.6 | .41 | C626 |
| 2202 | Minnicognashene | MH2/2 | Add red spar buoy to mark shoaling | Depths of 6' but channel narrowed | 44 | 53 | 18.6 | .31 | 079 | 54 | 04.8 | .08 | C690 |
| 2202 | Minnicognashene | MH5/1 | Add green spar buoy to mark shoaling | Depths of 6' but channel narrowed | 44 | 53 | 42.6 | .71 | 079 | 54 | 11.4 | .19 | C691 |
| 2202 | Minnicognashene | MH4/2 | Add red spar buoy to mark shoaling | | 44 | 53 | 24 | .4 | 079 | 54 | 05 | .08 | C1553 |
| 2202 | Minnicognashene | MH3/1 | Add green spar buoy to mark shoaling | | 44 | 53 | 25 | .41 | 079 | | 06 | .1 | C1527 |
| 2202 | Quarry Island | C52/2 | Add to mark 1m shoal | Depths of 4' reported | 44 | 49 | 09 | .15 | 079 | 47 | 43 | .72 | C1668 |
| 2202 | Quarry Island | Information Buoy | Add white information buoy to warn of Low Water conditions | Depths of 4' reported | 44 | 48 | 55.8 | .93 | 079 | 47 | 52.2 | .87 | C789 |
| 2202 | Quarry Island | Information Buoy | Add white information buoy to warn of Low Water conditions | Depths of 4' reported | 44 | 50 | 54 | .9 | 079 | 49 | 03.6 | .06 | C789 |
| 2202 | Twelve Mile Bay | C152 | Add red spar to mark shoaling created by low water | | 45 | 05 | 38.4 | .64 | 080 | 05 | 52.2 | .87 | C700 |
| 2202 | Bears Head | CP2 | Add red spar to mark shoaling created by low water | | 45 | 13 | 25.8 | .43 | 080 | 10 | 57 | .95 | C707 |
| 2202 | Bears Head | CP2/2 | Buoy CP2 renumbered CP2/2 | | 45 | 13 | 28 | .46 | 080 | 11 | 12 | .2 | C706 |
| 2202 | Long Sault - Ellsmere Is | CP18 | Add red spar buoy to mark shoaling created by low water | | 45 | 14 | 21.6 | .36 | 080 | 12 | 06.6 | .11 | C708 |
| 2202 | Long Sault - Glencairn Is | CP32 | Add red spar buoy to mark shoaling created by low water | | 45 | 15 | 07.8 | .13 | 080 | 12 | 37.2 | .62 | C709 |

SECTION 1 - 2000

| Chart | Name/Location | Change | Reason | Channel Conditions - At Datum | | Latitu | ıde | dec | ı | _ongi | tude | dec | NS |
|-------|-------------------------------------|---------------------|---|--|----------|--------|-------|------|-----|-------|--------|------|------|
| 2202 | Honey Harbour/Big Dog Channel | Information buoy | Add white information buoy to warn of Low Water conditions | Depths of 4' reported | 44 | 52 | 15.6 | .26 | 079 | 49 | 48 | .8 | C922 |
| 2202 | Honey Harbour/Big Dog Channel | Information buoy | Add white information buoy to warn of Low Water conditions | Depths of 4' reported | 44 | 52 | 22.8 | .38 | 079 | 50 | 37.2 | .62 | C922 |
| 2202 | Big Dog Channel | MN10/2 | Add red spar buoy to mark shoaling | Depths of 4' reported - Channel narrowed | 44 | 52 | 18 | .3 | 079 | 50 | 28 | .46 | C982 |
| 2203 | Huckleberry Island | PK1 | Spar buoy | Marks rock ledge on edge of channel | 45 | 23 | 41 | .68 | 080 | 07 | 59.5 | .992 | C837 |
| 2203 | Pointe au Baril | AE4/2 | Add red spar buoy to mark shoaling created by low water | | 45 34 06 | | .1 | 080 | 28 | 06 | .1 | C733 | |
| 2203 | Nares - Hangdog | AQ1 | New Channel - Provides alternate route around Shoal Narrows | New Channel - Minimum depths of 7' | 45 | 34 | 05.14 | .086 | 080 | 31 | 21.743 | .362 | C973 |
| 2203 | Nares - Hangdog | AQ | New Channel - Provides alternate route around Shoal Narrows | New Channel - Minimum depths of 7' | 45 | 34 | 09.64 | .161 | 080 | 31 | 23.561 | .393 | C973 |
| 2203 | Nares - Hangdog | AQ3 | New Channel - Provides alternate route around Shoal Narrows | New Channel - Minimum depths of 7' | 45 | 34 | 19.26 | .321 | 080 | 31 | 32.109 | .535 | C973 |
| 2203 | Nares - Hangdog | AQ4 | New Channel - Provides alternate route around Shoal Narrows | New Channel - Minimum depths of 7' | 45 | 34 | 23.64 | .374 | 080 | 31 | 34.529 | .575 | C973 |
| 2203 | Nares - Hangdog | AQ5 | New Channel - Provides alternate route around Shoal Narrows | New Channel - Minimum depths of | | 34 | 37.56 | .626 | 080 | 31 | 43.75 | .729 | C973 |
| 2203 | Nares - Hangdog | AQ6 | New Channel - Provides alternate route around Shoal Narrows | New Channel - Minimum depths of 7' | 45 | 34 | 34.94 | .582 | 080 | 31 | 41.872 | .698 | C973 |
| 2203 | Nares - Hangdog | AQ8 | New Channel - Provides alternate route around Shoal Narrows | New Channel - Minimum depths of 7' | 45 | 34 | 53.35 | .889 | 080 | 31 | 50.763 | .846 | C973 |
| 2203 | Hangdog | A75/1 | Add green spar buoy to mark shoaling created by low water | | 45 | 35 | 21.5 | .358 | 080 | 32 | 00 | 0 | C744 |
| 2203 | Hangdog | A76 | Add red spar buoy to mark shoaling created by low water | | 45 | 35 | 22 | .366 | 080 | 31 | 59 | .983 | C744 |
| 2203 | Hangdog | A75/3 | Add green spar buoy to mark shoaling created by low water | | 45 | 35 | 24 | .4 | 080 | 32 | 00 | 0 | C744 |
| 2203 | Shoal Narrows | New Buoys | Channel depth maintained but channel narrowed considerably | | | | | | | | | | |
| 2203 | Norgate - Gereaux Is | AN1 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 41 | 25.6 | .42 | 080 | 39 | 4.8 | 0.8 | C972 |
| 2203 | Norgate - Gereaux Is | AN2 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 41 | 38.20 | 0.64 | 080 | 39 | 28 | 0.47 | |
| 2203 | Norgate - Gereaux Is | AN3 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 41 | 36.4 | 0.61 | 080 | 39 | 29.1 | 0.49 | |
| 2203 | Norgate - Gereaux Is | AN4 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 41 | 45.6 | 0.76 | 080 | 39 | 44.1 | 0.74 | |
| 2203 | Norgate - Gereaux Is | AN5 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 41 | 43.8 | 0.73 | 080 | 39 | 46.1 | 0.77 | |

SECTION 1 – 2000

| Chart | Name/Location | Change | Reason | Channel Conditions - At Datum | | Latitu | ıde | dec | I | Longi | tude | dec | NS |
|-------|------------------------------------|---------------------|--|---|----|--------|-------|------|-----|-------|-------|------|-------|
| 2203 | Norgate - Gereaux Is | AN6 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 41 | 56.2 | 0.94 | 080 | 40 | 07.9 | 0.13 | |
| 2203 | Norgate - Gereaux Is | AN7 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 41 | 54.5 | 0.91 | 080 | 40 | 09.9 | 0.17 | |
| 2203 | Norgate - Gereaux Is | AN8 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 42 | 08 | 0.13 | 080 | 40 | 34.5 | 0.58 | |
| 2203 | Norgate - Gereaux Is | AN9 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 42 | 06.7 | 0.11 | 080 | 40 | 36.4 | 0.61 | |
| 2203 | Norgate - Gereaux Is | AN10 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 42 | 27 | 0.45 | 080 | 40 | 35.1 | 0.59 | |
| 2203 | Norgate - Gereaux Is | AN11 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 42 | 29.6 | 0.49 | 080 | 40 | 35.5 | 0.59 | |
| 2203 | Norgate - Gereaux Is | AN14 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 42 | 41.5 | 0.69 | 080 | 40 | 34 | 0.57 | |
| 2203 | Norgate - Gereaux Is | AN15 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 42 | 48.6 | 0.81 | 080 | 40 | 34.1 | 0.57 | |
| 2203 | Norgate - Gereaux Is | AN17 | Provides alternate route outside of Norgate Rock | New Channel - Minimum depths of 7' | 45 | 43 | 04.2 | 0.07 | 080 | 40 | 32.7 | 0.55 | |
| 2203 | Milo Reef | A45 | Add green 2' spar buoy to provide alternate route around Franklin Island | New Channel - Minimum depths of 18' | 45 | 26 | 3.24 | .054 | 080 | 24 | 8.28 | .138 | C510 |
| 2204 | Beaverstone Bay | Information buoy | Add white information buoy to warn of low water conditions | | 45 | 59 | 37 | .62 | 081 | 09 | 32.5 | .54 | C1136 |
| 2204 | Beaverstone Bay | Information buoy | Add white information buoy to warn of low water conditions | | 46 | 00 | 37 | .62 | 081 | 09 | 32.5 | .54 | C1136 |
| 2225 | Young Rock | PP4 | Add red 2' spar buoy to provide alternate route around Franklin Island | New Channel - Minimum depths of 18' | 45 | 22 | 35.4 | .590 | 080 | 23 | 4.5 | .075 | C510 |
| 2225 | Cook Reef | PP5 | Add green 2' spar buoy to provide alternate route around Franklin Island | New Channel - Minimum depths of 18' | 45 | 22 | 28.74 | .479 | 080 | 23 | 22.8 | .380 | C510 |
| 2284 | Corisande Rock | PP8 | Add red 2' spar buoy to provide alternate route around Franklin Island | New Channel - Minimum depths of 18' | 45 | 24 | 19.8 | .330 | 080 | 24 | 3.12 | .052 | C510 |
| 2241 | Spain Rock | GB6 | Changed to west cardinal, lighted and renumbered MC | Extends outside channel to Lone Rock | 44 | 59 | 38 | .63 | 080 | 05 | 02 | .03 | C526 |
| 2284 | Lone Rock - SW Fryingpan Is | CS2 | Changed to west cardinal, lighted and renumbered MCS | Lone Rock buoy now lighted | 45 | 09 | 15.42 | .257 | 080 | 13 | 45.84 | .764 | C582 |
| 2245 | Scarecrow Island – Killarney area | DE2 | Lighted buoy provides outside route bypassing Beaverstone Bay | | 45 | 53 | 48 | .8 | 081 | 23 | 02 | .033 | C869 |
| 2205 | Cash Flow Rock – Killarney | Add Shorelight | Add FIR Shorelight and change lighted buoy EA2 to unlit | | 45 | 58 | 02.5 | .041 | 081 | 33 | 56 | .933 | C799 |
| 2203 | Gereaux Island | A146/2 | Spar Buoy | Channel depth maintained but narrowed | 45 | 44 | 42 | .7 | 080 | 39 | 22.5 | .375 | C874 |

SECTION 1 – 2000

| Chart | Name/Location | Change | Reason | Channel Conditions - At Datum | L | .atitu | de | dec | L | _ongit | ude | dec | NS |
|-------|---------------|--------|--|---------------------------------------|----|--------|------|-----|-----|--------|-----|------|------|
| 2283 | Thornbury | _ | Marks boulder that rolled into channel | Channel depth maintained but narrowed | 44 | 33 | 59.8 | .99 | 080 | 27 | 0.5 | .008 | C801 |

EDITION 12/2000

(P) NEW BRUNSWICK - MIRAMICHI RIVER - Aids to navigation to be changed.

The Canadian Coast Guard proposes to make the following changes to the aids to navigation in Miramichi River, N.B.

MIRAMICHI - NOV. 2000

| Aid Id | Aid Name | LL # | Chart # | L | atitud | le | L | _ongitu | de | Proposed Changes |
|-----------|-----------------------------------|---------|---------|-----|--------|-------|-----|------------|-------|--|
| | | | | Deg | Min | Sec | Deg | <u>Min</u> | Sec | |
| M2 | Miramichi Bar Light and Bell | 1170 | 4911 | 47 | 5 | 51.9 | 64 | 56 | 30 | Downgrade to lighted buoy M2, LL1170. |
| M4 | Miramichi Outer Bar Light Buoy | 1171 | 4911 | 47 | 5 | 55 | 64 | 56 | 54 | Change to lighted spar M4, LL1171. |
| M5 | Miramichi Outer Bar Light Buoy | 1171.3 | 4911 | 47 | 5 | 56 | 64 | 57 | 3.5 | Permanently discontinue. |
| M6 | Miramichi Bar Light Buoy | 1171.5 | 4911 | 47 | 6 | 14.8 | 64 | 57 | 30 | Permanently discontinue. |
| M7 | The Lump Light Buoy | 1172 | 4911 | 47 | 6 | 23.41 | 64 | 57 | 53.32 | Change to lighted spar & renumber to M5, LL1172. |
| M7/5 | The Lump Spar Buoy | 6176 | 4911 | 47 | 6 | 32.2 | 64 | 58 | 10.7 | Permanently discontinue. |
| M8 | The Lump Light Buoy | 1172.5 | 4911 | 47 | 6 | 36.5 | 64 | 58 | 15.2 | Change to lighted spar & renumber to M6, LL1172.5. |
| M10 | The Swashway Light Buoy | 1173 | 4911 | 47 | 6 | 43.6 | 64 | 58 | 27.4 | Change to lighted spar M10, LL1173. |
| M10.2 | Swashway Light Buoy | 1173.01 | 4911 | 47 | 6 | 48.6 | 64 | 58 | 30.9 | Change to lighted spar & renumber to M12, LL1173.01. |
| M11 | Ship Channel Light Buoy | 1173.1 | 4911 | 47 | 6 | 43.5 | 64 | 58 | 33.1 | Permanently discontinue. |
| M12 | Ship Channel Light Buoy | 1173.2 | 4911 | 47 | 7 | 6 | 64 | 58 | 42.5 | Permanently discontinue. |
| M13 | Ship Channel Light Buoy | 1173.3 | 4911 | 47 | 7 | 47.3 | 64 | 59 | 20.65 | Change to lighted spar M13, LL1173.3. |
| M14 | Miramichi Bar Light Buoy | 1173.5 | 4911 | 47 | 7 | 49.8 | 64 | 59 | 16 | Change to lighted spar M14, LL1173.5. |
| M15 | Split Shoal Light Buoy | 1173.8 | 4911 | 47 | 8 | 29.35 | 65 | 0 | 23.63 | Change to lighted spar M15, LL1173.8. |
| M17 | Miramichi Bar Light Buoy | 1179 | 4911 | 47 | 8 | 40.9 | 65 | 1 | 2 | Change to lighted spar M17, LL1179. |
| M19 | Spit Shoal Inner Light Buoy | 1180 | 4911 | 47 | 8 | 37.3 | 65 | 1 | 43 | Permanently discontinue. |
| M21 | Miramichi Bar Light Buoy | 1180.5 | 4911 | 47 | 8 | 37.5 | 65 | 2 | 51 | Change to lighted spar & renumber to M19, LL1180.5. |
| M23 | Horseshoe Bar Light Buoy | 1181 | 4911 | 47 | 8 | 32 | 65 | 3 | 19 | Change to lighted spar & renumber to M21, LL1181. |
| M24 | Horseshoe Bar Light Buoy | 1182 | 4911 | 47 | 8 | 29.1 | 65 | 3 | 28.9 | Change to lighted spar & renumber to M22, LL1182. |

SECTION 1 - 2000

| Aid Id | Aid Name | <u>LL#</u> | Chart # | l | Latitud | de | L | _ongitu | de | Proposed Changes |
|-----------|---|------------|---------|----|---------|------|----|---------|------|---|
| | Horseshoe Bar Red Spar | 6182.1 | 4911 | 47 | 8 | 17 | 65 | 3 | 47.3 | Permanently discontinue. |
| M26 | Horseshoe Bar Light Buoy | 1183 | 4911 | 47 | 8 | 3.8 | 65 | 4 | 5.3 | Permanently discontinue. |
| M26.2 | Horseshoe Bar Red Spar | 6183.1 | 4911 | 47 | 7 | 51.2 | 65 | 4 | 23.9 | Permanently discontinue. |
| M27 | Horseshoe Bar Light Buoy | 1184 | 4911 | 47 | 7 | 38.9 | 65 | 4 | 34.5 | Permanently discontinue. |
| M28 | Horseshoe Bar Light Buoy | 1184.5 | 4911 | 47 | 7 | 39 | 65 | 4 | 42.5 | Change to lighted spar & renumber to M24, LL1184.5. |
| M29 | Horseshoe Bar Light Buoy | 1185 | 4911 | 47 | 7 | 27.4 | 65 | 5 | 5.5 | Permanently discontinue. |
| M30 | Horseshoe Bar Light Buoy | 1186 | 4911 | 47 | 7 | 19.8 | 65 | 5 | 37 | Change to lighted spar & renumber to M26, LL1186. |
| M31 | Horseshoe Bar Light Buoy | 1186.5 | 4911 | 47 | 7 | 15 | 65 | 5 | 43.5 | Permanently discontinue. |
| M34 | Grand Dune Flats Light Buoy | 1188 | 4911 | 47 | 7 | 18.8 | 65 | 5 | 52.8 | Change to lighted spar & renumber to M28, LL1188. |
| M36 | Grand Dune Channel East Light Buoy | 1189 | 4912 | 47 | 7 | 30 | 65 | 7 | 13 | Permanently discontinue. |
| M37 | Grand Dune Middle Channel Light Buoy | 1189.1 | 4912 | 47 | 7 | 42.8 | 65 | 8 | 54.3 | Permanently discontinue. |
| M38 | Grand Dune Channel Middle Light Buoy | 1189.2 | 4912 | 47 | 7 | 44.9 | 65 | 8 | 54.7 | Change to lighted spar & renumber to M30, LL1189.2. |
| M40 | Grand Dune Channel West Light Buoy | 1189.4 | 4912 | 47 | 8 | 1.6 | 65 | 10 | 49.2 | Permanently discontinue. |
| M41 | Grand Dune Range Turning Light Buoy | 1195 | 4912 | 47 | 8 | 8.9 | 65 | 11 | 53 | Change to lighted spar & renumber to M31, LL1195. |
| M42 | Grand Dune Spar | 6189.5 | 4912 | 47 | 8 | 11.5 | 65 | 12 | 2.3 | Permanently discontinue. |
| M42/6 | Grand Dune Spar | 6189.6 | 4912 | 47 | 8 | 5.4 | 65 | 12 | 21.4 | Permanently discontinue. |
| M43 | Grand Dune Range Turning Light Buoy | 1195.5 | 4912 | 47 | 8 | 3.7 | 65 | 12 | 19.2 | Change to lighted spar & renumber to M33, LL1195.5. |
| M44 | Grand Dune Flats North Light Buoy | 1198 | 4912 | 47 | 7 | 47 | 65 | 12 | 48 | Change to lighted spar & renumber to M34, LL1198. |
| M45 | Grand Dune Flats South Light Buoy | 1198.3 | 4912 | 47 | 7 | 17.4 | 65 | 13 | 29 | Change to lighted spar & renumber to M35, LL1198.3. |
| M46 | Robichaud Spit Light Buoy | 1198.6 | 4912 | 47 | 6 | 52.9 | 65 | 14 | 12.9 | Change to lighted spar & renumber to M36, LL1198.6. |
| M47 | Robichaud Spit Miramichi Light Buoy | 1198.65 | 4912 | 47 | 6 | 49.8 | 65 | 14 | 10.2 | Permanently discontinue. |
| M48 | Oak Channel Spar Buoy | 6198.75 | 4912 | 47 | 6 | 46 | 65 | 14 | 48.5 | Permanently discontinue. |
| M49 | Oak Channel Light Buoy | 1198.7 | 4912 | 47 | 6 | 41.2 | 65 | 15 | 7 | Permanently discontinue. |
| M50 | Oak Channel Spar Buoy | 6198.95 | 4912 | 47 | 6 | 33.9 | 65 | 16 | 7.6 | Permanently discontinue. |
| M51 | The Willows Light Buoy | 1199 | 4912 | 47 | 6 | 31 | 65 | 16 | 4.8 | Change to lighted spar & renumber to M37, LL1199. |
| M52 | Oak Channel Spar | 6199.1 | 4912 | 47 | 5 | 47 | 65 | 17 | 12.7 | Permanently discontinue. |
| M53 | Oak Channel Light Buoy | 1202 | 4912 | 47 | 5 | 45.6 | 65 | 17 | 9.3 | Change to lighted spar & renumber to M39, LL1202. |
| M54 | Oak Channel Light Buoy | 1203 | 4912 | 47 | 5 | 3.1 | 65 | 17 | 45.5 | Change to lighted spar & renumber to M40, LL1203. |

SECTION 1 - 2000

| Aid Id | Aid Name | <u>LL #</u> | Chart # | | Latitu | de | L | _ongitu | de | Proposed Changes |
|-----------|--------------------------------------|-------------|---------|----|--------|------|----|---------|------|--|
| | Oak Channel Light Buoy | 1203.1 | 4912 | 47 | 4 | 56.7 | 65 | 18 | 1.2 | Change to lighted spar & renumber to M44, LL1203.1. |
| M55 | Oak Channel Spar | 6203.1 | 4912 | 47 | 5 | 1.8 | 65 | 17 | 38.8 | Permanently discontinue. |
| M56 | Sheldrake Channel East Light Buoy | 1206 | 4912 | 47 | 4 | 44.8 | 65 | 18 | 51 | Change to lighted spar & renumber to M46, LL1206. |
| M57 | Sheldrake Channel Spar | 6206.1 | 4912 | 47 | 4 | 40.9 | 65 | 18 | 50.6 | Permanently discontinue. |
| M58 | Sheldrake Channel Light Buoy | 1206.5 | 4912 | 47 | 4 | 48.1 | 65 | 19 | 45.7 | Permanently discontinue. |
| M58.2 | Sheldrake Channel Spar | 6206.3 | 4912 | 47 | 4 | 55.4 | 65 | 20 | 59.9 | Permanently discontinue. |
| M59 | Sheldrake Channel Spar | 6206.4 | 4912 | 47 | 4 | 51.4 | 65 | 20 | 38.5 | Permanently discontinue. |
| M59.3 | Sheldrake Channel Spar | 6206.5 | 4912 | 47 | 4 | 55.8 | 65 | 21 | 20.7 | Change to lighted spar & renumber to M47, LL1208.91. |
| M60 | Sheldrake Channel Spar | 6206.6 | 4912 | 47 | 4 | 59.9 | 65 | 21 | 47.8 | Permanently discontinue. |
| M61 | Sheldrake Channel Light Buoy | 1209 | 4912 | 47 | 4 | 57.8 | 65 | 21 | 48 | Change to lighted spar & renumber to M51, LL1209. |
| M62 | Sheldrake Channel Spar | 6209.1 | 4912 | 47 | 4 | 51.2 | 65 | 22 | 44.8 | Permanently discontinue. |
| M65 | Gordon Point Light Buoy | 1210 | 4912 | 47 | 4 | 41.4 | 65 | 23 | 27.6 | Change to lighted spar & renumber to M53, LL1210. |
| M67 | Leggett Shoal Light Buoy | 1211 | 4912 | 47 | 4 | 28.1 | 65 | 24 | 13.2 | Change to lighted spar & renumber to M55, LL1211. |
| M68 | Leggett Shoal Light Buoy | 1212 | 4912 | 47 | 3 | 56.2 | 65 | 25 | 4.5 | Change to lighted spar & renumber to M56, LL1212. |
| M71 | Millbank Light Buoy | 1213 | 4912 | 47 | 3 | 27.4 | 65 | 27 | 3 | Change to lighted spar & renumber to M57, LL1213. |
| M73 | Millbank Channel Light Buoy | 1214 | 4912 | 47 | 3 | 16.9 | 65 | 27 | 27.4 | Change to lighted spar & renumber to M59, LL1214. |
| M75 | Middle Island Light Buoy | 1215 | 4912 | 47 | 2 | 59.9 | 65 | 27 | 48 | Change to lighted spar & renumber to M61, LL1215. |
| M76 | Chatham Wharf Scow Buoy | 1215.2 | 4912 | 47 | 2 | 13.3 | 65 | 28 | 7 | Change to lighted spar & renumber to M62, LL1215.2. |
| M78 | Chatham Wharf Red Spar | 6215.3 | 4912 | 47 | 1 | 50.2 | 65 | 28 | 28.2 | Permanently discontinue. |
| M84 | Wright Bank Light Buoy | 1216 | 4912 | 47 | 1 | 11.5 | 65 | 29 | 31.5 | Change to lighted spar & renumber to M64, LL1216. |
| M88 | Wright Bank Light Buoy | 1216.5 | 4912 | 47 | 0 | 58 | 65 | 30 | 56.5 | Change to lighted spar & renumber to M66, LL1216.5. |
| M90 | Wright Bank Light Buoy | 1217 | 4912 | 47 | 0 | 53.6 | 65 | 31 | 46.7 | Change to lighted spar & renumber to M68, LL1217. |
| M91 | Wright Bank Light Buoy | 1220 | 4912 | 47 | 0 | 53.4 | 65 | 32 | 33.8 | Change to lighted spar & renumber to M69, LL1220. |
| M95 | Newcastle North Light Buoy | 1222 | 4912 | 47 | 0 | 29.8 | 65 | 33 | 33.3 | Change to lighted spar & renumber to M71, LL1222. |
| M97 | Newcastle North Light Buoy | 1223 | 4912 | 47 | 0 | 16.1 | 65 | 33 | 39.5 | Change to lighted spar & renumber to M73, LL1223. |

SECTION 1 - 2000

| Aid Id | Aid Name | <u>LL #</u> | Chart # | | Latituc | le | L | .ongitu | de | Proposed Changes |
|-----------|-----------------|-------------|---------|----|---------|-----|----|---------|------|---|
| M99 | Newcastle Wharf | 6223.1 | 4912 | 47 | 0 | 3.2 | 65 | 33 | 28.7 | Change to lighted spar & renumber to M75, LL1224. |

NOTE: Comments on this action are solicited from mariners and other interested parties. Comments should be directed to Bev Cleaveland, Canadian Coast Guard Base, P.O. Box 1236, Charlottetown, PEI, C1A 7M8 within three months from the date of this Notice. Any objections raised should state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

SECTION 2 - 2000

1203 - Tadoussac - New Edition - 10-FEB-1995 - NAD 1927

| 2E | FFF | 20 | \sim |
|----|-----|----|--------|
| | | | |

(P)Amend FI 6s 12m 9M to read FI 6s 12m 8M 77°30′, 953 m from southwest

corner of margin

46°26'47.4"N 072°16'04.6"W 46°26'41.3"N 072°16'16.3"W 46°26'36.5"N 072°16'29.0"W 46°26'32.0"N 072°16'45.4"W and 46°26'29.1"N 072°17'02.3"W

1203 - Tadoussac à/to Cap Éternité - New Edition - 10-FEB-1995 - NAD 1927 25-FEB-2000.

| (P)Amend | FI 10s 20m 20M to read FI 10s 20m 16M | 48°04'10.1"N | 069°33'08.7"W |
|----------|---|--------------|---------------|
| (P)Amend | FI 21/2s 25m 20M to read FI 21/2s 25m 18M | 48°06'09.7"N | 069°36'03.3"W |
| (P)Amend | F 26m to read F 28m 22M | 48°07'04.0"N | 069°43'02.3"W |
| (P)Amend | F G 25m to read F G 28m 7M | 48°07'04.0"N | 069°43'02.3"W |
| (P)Amend | F 40m to read F 42m 22M | 48°07'04.8"N | 069°43'02.8"W |
| (P)Amend | FI 6s 12m 9M to read FI 6s 12m 8M | 48°08'07.4"N | 069°43'01.2"W |

1313 - Batiscan au/to Lac Saint-Pierre - New Edition - 27-JUN-1997 - NAD 1983 28-APR-2000.

| (P)Amend | legend 11 m to read "11,3 m" | | 46°14'52.0"N | 072°44'17.0"W |
|-----------|--|-----------|--------------|---------------|
| | A new chart edition incorporating the above changes will be available at | a later d | ate. | |
| (P)Amend | legend 11 m to read "11,3 m" | | 46°15'49.0"N | 072°40'18.0"W |
| | A new chart edition incorporating the above changes will be available at | a later d | ate. | |
| (P)Amend | legend 11 m to read "11,3 m" | | 46°18'35.0"N | 072°33'31.0"W |
| | A new chart edition incorporating the above changes will be available at | a later d | ate. | |
| (P)Amend | legend 11 m to read "11,3 m" | | 46°21'21.0"N | 072°30'18.0"W |
| | A new chart edition incorporating the above changes will be available at | a later d | ate. | |
| (P)Amend | legend 11 m to read "11,3 m" | | 46°22'47.0"N | 072°27'07.0"W |
| | A new chart edition incorporating the above changes will be available at | a later d | ate. | |
| (P)Amend | legend 11 m to read "11,3 m" | | 46°24'07.0"N | 072°23'56.0"W |
| | A new chart edition incorporating the above changes will be available at | a later d | ate. | |
| (P)Amend | legend 11 m to read "11,3 m" | | 46°26'19.0"N | 072°18'44.0"W |
| | A new chart edition incorporating the above changes will be available at | a later d | ate. | |
| (P)Delete | dredged area limit | joining | 46°28'21.3"N | 072°14'42.0"W |
| | | | 46°27'39.1"N | 072°15'16.0"W |
| | | | 46°27'06.3"N | 072°15'43.5"W |
| | | | 46°26'47.4"N | 072°16'04.6"W |
| | | | 46°26'36.5"N | 072°16'29.0"W |
| | | and | 46°26'29.1"N | 072°17'02.3"W |
| | A new chart edition incorporating the above changes will be available at | a later d | ate. | |
| (P)Add | dredged area limit | joining | 46°28'21.3"N | 072°14'42.0"W |
| | | | 46°27'17.3"N | 072°15'31.1"W |

SECTION 2 - 2000

1313 - Batiscan au/to Lac Saint-Pierre - New Edition - 27-JUN-1997 - NAD 1983

| - Batiscan au/to | o Lac Saint-Pierre - New Edition - 27-JUN-1997 - NAD | 1983 | |
|------------------|---|--|-------|
| | A new chart edition incorporating the above changes v | rill be available at a later date. | |
| (P)Add | dredged area limit | between 46°29'06.1"N 072°14'21.2 | 2"W |
| | | and 46°29'03.7"N 072°14'10.3 | 3"W |
| | A new chart edition incorporating the above changes v | ill be available at a later date. | |
| (P)Delete | dredged area limit | between 46°19'33.7"N 072°32'53.8 | 3"W |
| | | and 46°21'06.2"N 072°30'45.9 | 9"W |
| | A new chart edition incorporating the above changes v | rill be available at a later date. | |
| (P)Add | dredged area limit | joining 46°19'33.5"N 072°32'53.6 | 3"W |
| | | 46°20'12.5"N 072°31'49.2 | 2"W |
| | | 46°21'03.9"N 072°30'40.2 | 2"W |
| | | and 46°21'25.0"N 072°30'16.9 | 9"W |
| | A new chart edition incorporating the above changes v | ill be available at a later date. | |
| (P)Delete | dredged area limit | joining 46°22'11.7"N 072°29'20.5 | 5"W |
| | | 46°22'08.8"N 072°29'28.7 | 7"W |
| | | and 46°22'01.0"N 072°29'37.3 | 3"W |
| | A new chart edition incorporating the above changes v | ill be available at a later date. | |
| (P)Add | dredged area limit | between 46°22'11.7"N 072°29'20.5 | 5"W |
| | | and 46°22'01.0"N 072°29'37.3 | 3"W |
| | A new chart edition incorporating the above changes v | ill be available at a later date. | |
| (P)Delete | dredged area limit | joining 46°22'35.5"N 072°27'37.6 | 3"W |
| | | 46°22'24.0"N 072°28'21.4 | 1"W |
| | | 46°22'13.5"N 072°28'50.7 | 7"W |
| | | 46°22'00.0"N 072°29'18.1 | 1"W |
| | | and 46°21'43.7"N 072°29'42.1 | 1"W |
| | A new chart edition incorporating the above changes v | rill be available at a later date. | |
| (P)Add | dredged area limit | joining 46°22'35.5"N 072°27'37.6 | 3"W |
| | | 46°22'29.1"N 072°28'04.1 | 1"W |
| | | 46°22'24.0"N 072°28'21.4 | 1"W |
| | | 46°22'19.1"N 072°28'36.2 | |
| | | 46°22'13.5"N 072°28'50.7 | |
| | | 46°22'07.0"N 072°29'04.9 | |
| | | 46°22'00.0"N 072°29'18.1 | |
| | | 46°21'52.3"N 072°29'30.3 and 46°21'43.7"N 072°29'42.1 | |
| | A new chart edition incorporating the above changes v | | . •• |
| (P)Delete | dredged area limit | joining 46°26'14.9"N 072°20'20.8 | R"\// |
| (i)Delete | aroagoa aroa iiriit | joining 40 20 14.3 N 0/2 20 20.0 | , vv |

46°26'01.7"N 072°21'12.1"W

46°26'13.7"N 072°20'37.4"W

and 46°25'53.0"N 072°21'23.8"W

A new chart edition incorporating the above changes will be available at a later date.

SECTION 2 - 2000

| 1313 - Batiscan au/to Lac Saint-Pierre - New Edition - 27-JUN-1997 - NAD 1983 |
|---|
|---|

(P)Delete dredged area limit joining 46°26'08.4"N 072°20'00.7"W

46°26'02.6"N 072°20'32.9"W 46°25'52.5"N 072°21'02.0"W

and 46°25'38.2"N 072°21'28.0"W

A new chart edition incorporating the above changes will be available at a later date.

(P)Add dredge area limit joining 46°26'14.9"N 072°20'20.8"W

46°26'12.9"N 072°20'38.4"W 46°26'01.7"N 072°21'10.7"W

and 46°25'53.0"N 072°21'23.8"W

A new chart edition incorporating the above changes will be available at a later date.

(P)Add dredged area limit joining 46°26'08.4"N 072°20'00.7"W

46°26'02.6"N 072°20'32.9"W 46°26'02.6"N 072°20'32.9"W 46°25'58.0"N 072°20'48.1"W

46°25'52.5"N 072°21'02.0"W 46°25'46.0"N 072°21'15.3"W

and 46°25'38.2"N 072°21'28.0"W

A new chart edition incorporating the above changes will be available at a later date.

(P)Delete dredged area limit joining 46°22'58.3"N 072°25'50.1"W

46°22'52.7"N 072°25'59.7"W

and 46°22'50.6"N 072°26'11.8"W

A new chart edition incorporating the above changes will be available at a later date.

(P)Add dredged area limit joining 46°22'58.3"N 072°25'50.1"W

46°22'53.4"N 072°26'00.4"W

and 46°22'50.6"N 072°26'11.8"W

A new chart edition incorporating the above changes will be available at a later date.

1313 - Port de Bécancour - New Edition - 27-JUN-1997 - NAD1983

28-APR-2000.

(P)Amend legend 11 m to read "11,3 m" 46°24'36.0"N 072°23'12.0"W

A new chart edition incorporating the above changes will be available at a later date.

(P)Delete dredged area limit between 46°25'42.0"N 072°21'21.2"W

and 46°25'38.2"N 072°21'28.0"W

A new chart edition incorporating the above changes will be available at a later date.

(P)Add dredged area limit between 46°25'42.0"N 072°21'22.1"W

and 46°25'38.2"N 072°21'28.0"W

A new chart edition incorporating the above changes will be available at a later date.

SECTION 2 - 2000

1313 - Port de Trois-Rivières - New Edition - 27-JUN-1997 - NAD 1983

28-APR-2000.

(P)Amend legend 11 m to read "11,3 m" 46°21'16.0"N 072°30'21.0"W

A new chart edition incorporating the above changes will be available at a later date.

(P)Delete dredged area limit between 46°19'33.7"N 072°32'53.8"W

and 46°21'06.2"N 072°30'45.9"W

A new chart edition incorporating the above changes will be available at a later date.

(P)Add dredged area limit joining 46°19'33.5"N 072°32'53.6"W

46°20'12.5"N 072°31'49.2"W 46°21'03.9"N 072°30'40.2"W

and 46°21'25.0"N 072°30'16.9"W

A new chart edition incorporating the above changes will be available at a later date.

(P)Delete legend "11 m" 46°20'42.0"N 072°31'14.0"W

A new chart edition incorporating the above changes will be available at a later date.

(P)Delete dredged area limit joining 46°22'11.7"N 072°29'20.5"W

46°22'08.8"N 072°29'28.7"W and 46°22'01.0"N 072°29'37.3"W

A new chart edition incorporating the above changes will be available at a later date.

(P)Add dredged area limit between 46°22'11.7"N 072°29'20.5"W

and 46°22'01.0"N 072°29'37.3"W

A new chart edition incorporating the above changes will be available at a later date.

(P)Delete dredged area limit between 46°22'00.0"N 072°29'18.0"W

and 46°21'43.7"N 072°29'42.1"W

A new chart edition incorporating the above changes will be available at a later date.

(P)Add dredged area limit joining 46°22'00.0"N 072°29'18.0"W

46°21'52.3"N 072°29'30.3"W

and 46°21'43.7"N 072°29'42.1"W

1438 - Grindstone Island to/a Carleton Island - New Edition - 06-OCT-1995 - NAD 1983

12-MAY-2000.

(P)Delete light 44°11'39.0"N 076°19'42.5"W

A chart amendment patch incorporating the above information will be available at a later date.

(P)Add sector light FRWG, red from 260°30' to 262°; alternating 44°11'39.0"N 076°19'42.5"W

red/white from 262° to 262°15'; white from 262°15' to 263° 45'; alternating green/white from 263°45' to 264°; green from 264° to

265°30'

A chart amendment patch incorporating the above information will be available at a later date.

20-OCT-2000. LNM/D. (2304-1999)

(P)Delete green, port hand, spar buoy, marked J5/1 44°19'27.0"N 076°07'42.0"W

1439 - Carleton Island to/au Charity Shoal - New Edition - 22-FEB-1991 - NAD 1983

12-MAY-2000.

SECTION 2 - 2000

| (P)Delete | light | 44°11'39.0"N | 076°19'42.5"W |
|-----------|---|--------------|---------------|
| | A New Edition incorporating the above information will be available at a later date | э. | |
| (P)Add | sector light FRWG, red from 260°30' to 262°; alternating red/white from 262° to 262°15'; white from 262°15' to 263° 45'; alternating green/white from 263°45' to 264°; green from 264° to 265°30' | 44°11'39.0"N | 076°19'42.5"W |
| | A New Edition incorporating the above information will be available at a later date | Э. | |

| 01-DEC-2000 | | LNM/D. (1100-1 |
|-------------|---|-------------------------|
| (P)Delete | 4 metres 9 decimetres | 45°27'13.0"N 075°41'35. |
| | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| (P)Replace | 3 metres 4 decimetres by 2 metres 5 decimetres | 45°27'08.2"N 075°41'41. |
| | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| (P)Replace | 2 metres 1 decimetre by 1 metre 6 decimetres | 45°27'10.6"N 075°41'39. |
| | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| (P)Replace | 2 metres 7 decimetres by 1 metre 9 decimetres | 45°27'13.3"N 075°41'46. |
| | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| (P)Replace | 5 metres 5 decimetres by 4 metres 6 decimetres | 45°27'14.5"N 075°41'43. |
| | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| (P)Replace | 4 metres by 3 metres 5 decimetres | 45°27'17.8"N 075°41'35. |
| | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| (P)Replace | 6 metres 7 decimetres by 5 metres 5 decimetres | 45°27'18.0"N 075°41'47 |
| | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| (P)Add | 4 metres 3 decimetres | 45°27'12.0"N 075°41'35. |
| | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| (P)Add | 2 metres 9 decimetres | 45°27'17.5"N 075°41'52 |
| | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| (P)Add | 0 metre 3 decimetres | 45°27'20.5"N 075°42'01 |
| | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| (P)Add | drying height of 0 metre 4 decimetres | 45°27'22.2"N 075°43'10. |
| | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| (P)Replace | 1 metre 2 decimetres by 0 metre 3 decimetres | 45°27'11.1"N 075°43'17 |
| | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| (P)Replace | 3 metres 4 decimetres by 2 metres 7 decimetres | 45°27'08.3"N 075°43'13. |

SECTION 2 – 2000

| 1515 - | Becketts Creel | k à/to Ottawa - Sheet 2 - New Chart - 24-JUL-1998 - NAD 1983 | |
|--------|----------------|---|----------------------------|
| | | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| | (P)Delete | 3 metres | 45°27'04.4"N 075°43'13.5"W |
| | | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| | (P)Add | 0 metre 6 decimetres | 45°26'58.4"N 075°43'12.6"W |
| | | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| | (P)Add | 1 metre | 45°27'05.5"N 075°43'14.3"W |
| | | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| | (P)Replace | 3 metres 4 decimetres with 1 metre 8 decimetres | 45°27'14.8"N 075°41'49.0"W |
| | | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| 1515 - | Continuation E | 3, Lac Leamy Lake - Sheet 2 - New Chart - 24-JUL-1998 - NAD 1983 | |
| | 01-DEC-2000. | | LNM/D. (1100-1999) |
| | (P)Add | drying height of 0 metre 4 decimetres | 45°27'22.2"N 075°43'10.7"W |
| | | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| | (P)Replace | 1 metre 2 decimetres by 0 metre 3 decimetres | 45°27'11.1"N 075°43'17.4"W |
| | | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| | (P)Replace | 1 metre 2 decimetres by 0 metre 3 decimetres | 45°27'10.3"N 075°43'25.7"W |
| | | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| | (P)Replace | 3 metres 4 decimetres by 2 metres 7 decimetres | 45°27'08.3"N 075°43'13.4"W |
| | | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| | (P)Replace | 5 metres 5 decimetres by 0 metres 8 decimetres | 45°27'00.6"N 075°43'35.2"W |
| | | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| | (P)Delete | 3 metres | 45°27'04.7"N 075°43'14.0"W |
| | | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| | (P)Add | 0 metre 8 decimetres | 45°26'56.7"N 075°43'24.7"W |
| | | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| | (P)Add | 0 metre 6 decimetres | 45°26'58.4"N 075°43'12.6"W |
| | | A chart patch incorporating the above-mentioned change will be available at a later date. | |
| | (P)Add | 0 metre 2 decimetres | 45°26'54.3"N 075°43'22.7"W |

SECTION 2 – 2000

1515 - Continuation B, Lac Leamy Lake - Sheet 2 - New Chart - 24-JUL-1998 - NAD 1983

A chart patch incorporating the above-mentioned change will be

available at a later date.

(P)Add 1 metre 45°27'05.5"N 075°43'14.3"W

A chart patch incorporating the above-mentioned change will be

available at a later date.

2202 - Port Severn to/à Penetang Harbour - Sheet 1 - New Edition - 26-MAR-1999 - NAD 1927

28-APR-2000.

 (P)Add
 crib with known depth of "2ft"
 44°46'12.0"N
 079°56'37.0"W

 (P)Add
 crib with known depth of "1ft"
 44°46'15.5"N
 079°56'55.0"W

2203 - Carling Rock to/à Twin Sisters Island - Sheet 1 - New Edition - 07-OCT-1988 - NAD 1927

23-JUN-2000.

(T)Add green port hand spar buoy, marked A45 45°26'03.2"N 080°24'08.3"W

2205 - Killarney to/à Little Current - New Edition - 18-DEC-1987 - NAD 1927

12-MAY-2000.

(P)Delete light "FI" 45°55'35.0"N 081°36'43.0"W

A New Edition incorporating the above information will be available at a later date.

(P)Add light "FI" 45°55'41.5"N 081°36'08.0"W

A New Edition incorporating the above information will be available at a later date.

16-JUN-2000.

(P)Delete light 45°58'48.0"N 081°30'55.0"W

A new edition of this chart incorporating the above information will

be available at a later date.

2218 - Penetang Harbour - New chart - 13-APR-1984 - NAD 1927

28-APR-2000.

 (P)Add
 crib with known depth of "0.6m"
 44°46'12.0"N
 079°56'37.0"W

 (P)Add
 crib with known depth of "0.3m"
 44°46'15.5"N
 079°56'55.0"W

2225 - Approaches to / Approches à Parry Sound - New Edition - 08-MAR-1991 - NAD 1927

16-JUN-2000.

(T)Add green, port hand, spar buoy, marked PP5 45°22'28.7"N 080°23'22.8"W

23-JUN-2000.

(T)Add red starboard hand spar buoy, marked PP4 45°22'35.4"N 080°23'40.5"W

SECTION 2 – 2000

| 28-APR-20 | 00. | | |
|-----------------------------|--|---------------|---------------|
| (P)Add | crib with known depth of "0.6m" | 44°46'13.0"N | 079°56'35.0" |
| (P)Add | crib with known depth of "0.3m" | 44°46'17.5"N | 079°56'55.0"\ |
| 243 - Bateau I 07-APR-20 | sland to/à Byng Inlet - New Edition - 30-AUG-1985 - NAD 1927 00. | | |
| (T)Add | depth of 16ft | 45°24'27.2"N | 080°28'30.1" |
| 16-JUN-20 | 00. | | |
| (T)Add | green, port hand, spar buoy, marked PP5 | 45°22'29.0"N | 080°23'23.0" |
| 23-JUN-20 | 00. | | |
| (T)Add | red starboard hand spar buoy, marked PP4 | 45°22'36.0"N | 080°23'42.0"' |
| (T)Add | red starboard hand spar buoy, marked PP8 | 45°24'19.8"N | 080°24'03.1"\ |
| (P)Delete | red starboard hand spar buoy, marked H4 | 45°44'12.0"N | 080°43'05.0" |
| | A New Edition incorporating the above information will be available at a later date. | | |
| (P)Delete | red starboard hand spar buoy, marked H14 | 45°44'33.0"N | 080°40'38.5" |
| | A New Edition incorporating the above information will be available at a later date. | | |
| (P)Delete | red starboard hand conical buoy, marked H20 | 45°44'55.0"N | 080°39'29.0" |
| | A New Edition incorporating the above information will be available at a later date. | | |
| 244 - Alexano 02-JUN-20 | der Passage to/à Beaverstone Bay - New Edition - 12-JUN-1987 - NAD 1927 | | |
| (P)Delete | daybeacon | 45°54'15 0"N | 081°08'40.0" |
| (P)Add | light "FI 7.5s 46ft" | | 081°08'42.0" |
| 23-JUN-200 | | 40 04 10.0 IV | 001 00 42.0 |
| (P)Delete | red starboard hand spar buoy, marked H4 | 45°44`12 0"N | 080°43`05.0" |
| (1)201010 | A New Edition incorporating the above information will be available at a later date. | 10 11 12.0 14 | 000 10 00.0 |
| (P)Delete | red starboard hand spar buoy, marked H14 | 45°44`34.0"N | 080°40`38.5' |
| | A New Edition incorporating the above information will be available at a later date. | | |
| (P)Delete | red starboard hand conical buoy, marked H20 | 45°44`55.0"N | 080°39`29.0 |
| | A New Edition incorporating the above information will be available at a later date. | | |
| | Island to/à John Island - Reprint - 07-JUN-1996 - NAD 1927 | | |
| 07-JAN-20 | 00 | | |
| (P)Delete | light | 46°00'00.0"N | |

2283 - Owen Sound to/à Giant's Tomb Island - Sheet 1 - New chart - 30-JUL-1999 - NAD 1983 31-MAR-2000.

SECTION 2 – 2000

(P)Amend legend Measured Distance/Base de vitesse 1852m 145°-325° to read Measured Distance/ Base de Vitesse 1853m 145°45'-325°45' 44°49'03.0"N 080°12'42.0"W

NOTE: This information will be included in the next edition of chart

2283.

L/C2284 - Parry Sound and Approaches/et les approches - New Edition - 27-OCT-1989 - NAD 1927

16-JUN-2000.

(T)Add green, port hand, spar buoy, marked PP5 45°22'28.5"N 080°23'21.2"W

23-JUN-2000.

(T)Add red starboard hand spar buoy, marked PP4 45°22'36.0"N 080°23'42.0"W
(T)Add red starboard hand spar buoy, marked PP8 45°24'19.8"N 080°24'03.1"W

2299 - Clapperton Island to/à Meldrum Bay - Reprint - 30-JUN-1995 - NAD 1927

07-JAN-2000

(P)Delete light 46°00'00.0"N 082°14'59.0"W

L/C3000 - Juan de Fuca Strait to/à Dixon Entrance - New Edition - 20-JAN-1989 - NAD 1927 28-APR-2000.

| (P)Add | submarine cable | joining 48°26'27.6"N | 124°41'44.5"W |
|--------|-----------------|----------------------|---------------|
|--------|-----------------|----------------------|---------------|

48°26'48.5"N 124°49'04.3"W 48°23'39.4"N 124°58'33.2"W 48°24'03.2"N 125°04'51.7"W 48°22'43.6"N 125°15'07.6"W 48°22'39.2"N 125°17'43.0"W 48°21'31.5"N 125°21'24.2"W 48°21'05.9"N 125°24'40.5"W 48°21'11.9"N 125°27'32.0"W 48°19'22.2"N 125°41'28.9"W 48°17'56.3"N 125°48'17.0"W 48°15'52.7"N 126°03'06.0"W 48°16'12.3"N 126°06'28.9"W 48°14'53.9"N 126°12'16.2"W 48°12'38.3"N 126°28'58.0"W 48°07'57.5"N 126°55'35.9"W 48°08'30.9"N 127°05'00.0"W 48°45'48.9"N 128°57'11.2"W

48°51'09.0"N 129°16'43.4"W 48°56'19.1"N 129°30'18.8"W 49°10'15.7"N 130°33'45.5"W 49°16'19.0"N 130°41'48.7"W

SECTION 2 - 2000

L/C3000 - Juan de Fuca Strait to/à Dixon Entrance - New Edition - 20-JAN-1989 - NAD 1927

| | 49°19'27.0"N | 130°49'00.9"W |
|-----|--------------|---------------|
| | 49°23'53.0"N | 131°11'32.4"W |
| | 49°30'38.5"N | 131°29'47.3"W |
| | 49°38'00.1"N | 131°59'59.8"W |
| | 49°49'24.0"N | 132°52'15.6"W |
| | 49°53'51.1"N | 133°18'59.9"W |
| | 49°57'40.6"N | 133°25'00.0"W |
| | 50°00'55.3"N | 133°42'18.6"W |
| | 50°07'30.2"N | 134°09'59.8"W |
| | 50°24'27.6"N | 135°52'37.0"W |
| | 50°35'50.8"N | 136°52'24.0"W |
| and | 50°51'27.7"N | 139°00'00.0"W |

03-NOV-2000. LNM/D. (2360-1999)

(P)Add submarine cable joining 4

joining 48°25'23.6"N 124°38'59.9"W 48°26'26.8"N 124°49'14.8"W 48°23'50.7"N 124°56'28.3"W 48°22'46.2"N 125°03'18.9"W 48°22'37.4"N 125°09'16.4"W 48°21'08.9"N 125°21'10.8"W 48°19'24.1"N 125°31'36.2"W 48°18'46.9"N 125°32'42.3"W 48°17'49.3"N 125°39'51.2"W 48°18'02.4"N 125°41'00.0"W 48°16'12.3"N 125°51'00.5"W 48°15'20.2"N 125°53'36.3"W 48°10'55.5"N 126°00'53.1"W 48°06'11.5"N 126°04'15.4"W 48°00'00.0"N 126°04'15.4"W 47°49'43.7"N 126°06'24.4"W 47°45'33.5"N 126°03'51.2"W 47°35'02.4"N 126°05'00.6"W 47°27'00.2"N 126°10'03.1"W 47°21'59.7"N 126°11'33.5"W

and 46°20'00.0"N 126°15'03.0"W

L/C3001 - Vancouver Island/Île de Vancouver Juan De Fuca Strait to/à Queen Charlotte Sound - New Edition - 07-OCT-1994 - NAD 1927

28-APR-2000.

(P)Add submarine cable joining 47°59'00.0"N 122°34'33.4"W

SECTION 2 - 2000

L/C3001 - Vancouver Island/Île de Vancouver Juan De Fuca Strait to/à Queen Charlotte Sound - New Edition - 07-OCT-1994 - NAD 1927

| 48°01' | 55.0"N | 122°37'03.6"W |
|---------|--------|---------------|
| 48°07'0 | 02.0"N | 122°38'24.9"W |
| 48°09'(| 01.2"N | 122°41'00.7"W |
| 48°12'(| 09.8"N | 122°46'11.7"W |
| 48°12'2 | 20.3"N | 122°47'53.3"W |
| 48°15'(| 03.2"N | 122°53'40.8"W |
| 48°14' | 57.2"N | 122°59'07.8"W |
| 48°15'(| 09.3"N | 123°02'22.0"W |
| 48°14' | 18.0"N | 123°07'17.3"W |
| 48°12'2 | 20.3"N | 123°15'17.9"W |
| 48°12'(| 08.2"N | 123°17'28.9"W |
| 48°10' | 54.4"N | 123°19'26.2"W |
| 48°10'2 | 21.2"N | 123°22'35.6"W |
| 48°10'2 | 22.6"N | 123°26'36.7"W |
| 48°10' | 56.0"N | 123°28'42.9"W |
| 48°12'(| 03.7"N | 123°30'38.1"W |
| 48°11' | 56.3"N | 123°35'40.3"W |
| 48°12' | 32.4"N | 123°37'21.9"W |
| 48°13' | 58.4"N | 123°49'55.4"W |
| 48°16' | 34.9"N | 124°08'23.3"W |
| 48°19'2 | 23.5"N | 124°17'19.1"W |
| 48°23'2 | 22.7"N | 124°31'10.2"W |
| 48°26'2 | 27.6"N | 124°41'44.5"W |
| 48°26'4 | 48.5"N | 124°49'04.3"W |
| 48°23'3 | 39.4"N | 124°58'33.2"W |
| 48°24'(| 03.2"N | 125°04'51.7"W |
| 48°22'4 | 43.6"N | 125°15'07.6"W |
| 48°22'3 | 39.2"N | 125°17'43.0"W |
| 48°21' | 31.5"N | 125°21'24.2"W |
| 48°21'(| 05.9"N | 125°24'40.5"W |
| 48°21' | 11.9"N | 125°27'32.0"W |
| 48°19'2 | 22.2"N | 125°41'28.9"W |
| 48°17' | 56.3"N | 125°48'17.0"W |
| 48°15' | 52.7"N | 126°03'06.0"W |
| 48°16' | 12.3"N | 126°06'28.9"W |
| 48°14' | 53.9"N | 126°12'16.2"W |
| 48°12' | 38.3"N | 126°28'58.0"W |
| 48°07' | 57.5"N | 126°55'35.9"W |
| 48°08' | 30.9"N | 127°05'00.0"W |
| | | |

SECTION 2 – 2000

L/C3001 - Vancouver Island/Île de Vancouver Juan De Fuca Strait to/à Queen Charlotte Sound - New Edition - 07-OCT-1994 - NAD 1927

48°45'48.9"N 128°57'11.2"W

48°51'09.0"N 129°16'43.4"W

48°56'19.1"N 129°30'18.8"W

and 49°04'28.1"N 130°07'00.0"W

3410 - Sooke Inlet to/à Parry Bay - New chart - 24-MAR-1995 - NAD 1983 31-MAR-2000.

(P)Amend measured distance with bearing 027 1/2°-207 1/2°-1852m to read

48°22'05.0"N 123°29'35.0"W

027°41'-207°41'-1849m

This information will be included in the next edition of chart 3410.

3441 - Haro Strait, Boundary Pass and/et Satellite Channel - New Edition - 06-DEC-1996 - NAD 1927 31-MAR-2000.

(P)Amend measured distance with bearing 143°-323°-1845m to read 142°48'-

48°37'24.0"N 123°20'54.0"W

49°11'12.0"N 123°56'00.0"W

322°48'-1838m

This information will be incorporated in the next edition of chart 3441.

3447 - Nanaimo Harbour and/et Departure Bay - New Chart - 10-DEC-1999 - NAD 1983

15-SEP-2000.

(P)Add

CAUTION: Extensive changes to anchorage prohibited buoys and

speed restriction buoys have occurred in Nanaimo Harbour.
ATTENTION: Des changements importants aux bouées de mouillage interdite et aux bouées de restriction de vitesse sont

survenus dans Nanaimo Harbour.

A chart amendment patch incorporating this information will be

available at a later date.

3459 - Approaches to / Approches à Nanoose Harbour - New Edition - 24-OCT-1997 - NAD 1983

17-MAR-2000.

(T)Delete yellow cautionary buoy "NAVY"

49°17'07.0"N 124°03'47.5"W

L/C3461 - Juan de Fuca Strait, Eastern Portion / Partie Est - New Chart - 06-JAN-1984 - NAD 1927 28-APR-2000.

(P)Add submarine cable joining 47°59'02.3"N 122°34'30.0"W

48°01'11.9"N 122°36'06.8"W 48°01'51.4"N 122°36'53.3"W 48°02'50.0"N 122°37'20.0"W 48°05'06.6"N 122°37'49.4"W 48°06'35.5"N 122°38'20.8"W

48°00'28.4"N 122°35'42.2"W

48°08'11.1"N 122°39'34.7"W

48°08'32.6"N 122°40'02.7"W

SECTION 2 - 2000

L/C3461 - Juan de Fuca Strait, Eastern Portion / Partie Est - New Chart - 06-JAN-1984 - NAD 1927

20-OCT-2000. (P)Add su

submarine cable

| D 1921 | | |
|---------|--------------|----------------|
| | 48°09'18.4"N | 122°41'33.6"W |
| | 48°10'17.4"N | 122°42'59.7"W |
| | 48°12'05.2"N | 122°46'00.9"W |
| | 48°12'18.0"N | 122°46'45.3"W |
| | 48°12'17.6"N | 122°47'20.9"W |
| | 48°12'36.3"N | 122°48'28.5"W |
| | 48°14'32.8"N | 122°52'19.6"W |
| | 48°15'02.9"N | 122°53'51.9"W |
| | 48°15'07.9"N | 122°55'51.5"W |
| | 48°14'57.4"N | 122°58'50.6"W |
| | 48°15'12.0"N | 123°01'49.0"W |
| | 48°14'18.6"N | 123°07'14.5"W |
| | 48°12'23.0"N | 123°15'00.7"W |
| | 48°12'14.8"N | 123°16'44.6"W |
| | 48°11'51.9"N | 123°17'50.2"W |
| | 48°11'00.7"N | 123°19'05.4"W |
| | 48°10'29.2"N | 123°21'07.1"W |
| | 48°10'21.9"N | 123°22'44.9"W |
| | 48°10'21.4"N | 123°26'05.8"W |
| | 48°10'39.7"N | 123°27'53.9"W |
| | 48°11'06.2"N | 123°28'51.3"W |
| | 48°11'37.7"N | 123°29'22.7"W |
| | 48°11'55.1"N | 123°30'13.3"W |
| | 48°12'07.5"N | 123°32'25.9"W |
| | 48°11'56.5"N | 123°35'38.7"W |
| | 48°12'26.2"N | 123°37'07.6"W |
| | 48°12'49.0"N | 123°39'23.0"W |
| and | 48°13'30.2"N | 123°45'30.0"W |
| | LNM/ | D. 15-SEP-2000 |
| joining | 47°58'02.9"N | 122°34'30.0"W |
| | 48°00'02.5"N | 122°36'07.9"W |
| | 48°00'20.9"N | 122°36'34.1"W |
| | 48°00'30.6"N | 122°37'06.8"W |
| | 48°00'58.7"N | 122°37'40.2"W |
| | 48°01'49.7"N | 122°38'16.2"W |
| | 48°03'00.8"N | 122°38'37.8"W |
| | 48°04'00.5"N | 122°38'46.3"W |
| | 48°05'24.8"N | 122°39'13.2"W |
| | 48°06'58.6"N | 122°40'23.9"W |
| | 48°08'01.3"N | 122°41'43.8"W |
| | | |

89

SECTION 2 - 2000

L/C3461 - Juan de Fuca Strait, Eastern Portion / Partie Est - New Chart - 06-JAN-1984 - NAD 1927

| 48°08'37.7"N | 122°42'55.2"W |
|--------------|--|
| 48°09'51.7"N | 122°44'55.7"W |
| 48°11'33.8"N | 122°47'55.7"W |
| 48°13'09.2"N | 122°50'38.1"W |
| 48°13'39.9"N | 122°51'12.2"W |
| 48°14'18.8"N | 122°52'24.9"W |
| 48°14'50.3"N | 122°54'00.4"W |
| 48°14'55.1"N | 122°54'55.5"W |
| 48°14'44.2"N | 122°56'55.3"W |
| 48°14'43.3"N | 122°58'17.8"W |
| 48°14'55.9"N | 123°00'55.6"W |
| 48°14'56.4"N | 123°02'13.5"W |
| 48°14'13.1"N | 123°06'32.2"W |
| 48°12'09.2"N | 123°14'55.7"W |
| 48°11'57.9"N | 123°16'40.5"W |
| 48°11'41.2"N | 123°17'37.5"W |
| 48°11'00.9"N | 123°18'33.1"W |
| 48°10'40.4"N | 123°19'20.3"W |
| 48°10'17.6"N | 123°21'01.1"W |
| 48°10'09.3"N | 123°22'23.0"W |
| 48°10'09.7"N | 123°26'14.7"W |
| 48°10'29.0"N | 123°28'02.8"W |
| 48°10'52.2"N | 123°29'03.1"W |
| 48°11'05.8"N | 123°29'24.0"W |
| 48°11'25.9"N | 123°29'41.7"W |
| 48°11'35.1"N | 123°29'56.7"W |
| 48°11'46.9"N | 123°30'41.3"W |
| 48°11'43.4"N | 123°34'44.2"W |
| 48°11'47.8"N | 123°35'49.7"W |
| 48°11'54.8"N | 123°36'30.9"W |
| 48°12'14.9"N | 123°37'12.2"W |
| 48°12'38.1"N | 123°39'30.3"W |
| 48°12'43.4"N | 123°40'58.8"W |
| 48°13'14.9"N | 123°45'30.0"W |
| | 48°09'51.7"N 48°11'33.8"N 48°13'39.9"N 48°14'18.8"N 48°14'55.1"N 48°14'455.1"N 48°14'455.9"N 48°14'55.9"N 48°14'55.9"N 48°11'37.9"N 48°11'41.2"N 48°11'41.2"N 48°11'41.2"N 48°11'41.2"N 48°10'09.2"N 48°10'40.4"N 48°10'17.6"N 48°10'17.6"N 48°10'29.0"N 48°10'29.0"N 48°10'52.2"N 48°11'55.8"N 48°11'35.1"N 48°11'35.1"N 48°11'35.1"N 48°11'43.4"N 48°11'47.8"N 48°11'47.8"N 48°11'47.8"N 48°12'14.9"N 48°12'14.9"N 48°12'14.9"N 48°12'38.1"N |

This information will be incorporated in the next New Edition.

3481 - Approaches to/Approches à Vancouver Harbour - New Edition - 17-DEC-1993 - NAD 1927 31-MAR-2000.

(P)Amend measured distance with bearing 090°-270°-1852m to read 89°46′-269°46′-1853m

49°17'47.0"N 123°13'48.0"W

SECTION 2 – 2000

This information will be included in the next edition of chart 3481.

3493 - Vancouver Harbour, Western Portion / Partie Ouest - New Edition - 18-DEC-1998 - NAD 1983

3494

| | | ,, | | - | |
|------------|--------------|---|------|--------------|----------------|
| | 18-AUG-2000. | | | LNM/E | D. 24-MAR-2000 |
| | (P)Amend | "F R" to read "F G" | | 49°17'41.0"N | 123°01'28.5"W |
| | | A patch incorporating this change will be issued at a later date. | | | |
| | (P)Amend | "F Y" to read "F" | | 49°17'42.5"N | 123°01'35.2"W |
| | | A patch incorporating this change will be issued at a later date. | | | |
| | (P)Amend | "F G" to read "F" | | 49°17'42.5"N | 123°01'34.0"W |
| | | A patch incorporating this change will be issued at a later date. | | | |
| | (P)Add | light "F" | | 49°17'40.9"N | 123°01'34.1"W |
| | | A patch incorporating this change will be issued at a later date. | | | |
| | (P)Add | light "F" | | 49°17'39.0"N | 123°01'35.1"W |
| | | A patch incorporating this change will be issued at a later date. | | | |
| | (P)Add | light "F" | | 49°17'39.0"N | 123°01'34.0"W |
| | | A patch incorporating this change will be issued at a later date. | | | |
| | 08-SEP-200 | 0. | | LNM/[| D. 24-MAR-2000 |
| | (P)Amend | "F R" to read "F G" | | 49°17'41.0"N | 123°01'27.9"W |
| | | A patch incorporating this change will be available at a later date | | | |
| | (P)Amend | "F G" to read "F R" | | 49°17'40.9"N | 123°01'27.9"W |
| | | A patch incorporating this change will be available at a later date | | | |
| | (P)Amend | "F G" to read "F R" | | 49°17'40.9"N | 123°01'28.5"W |
| | | A patch incorporating this change will be available at a later date | | | |
| ļ - | Second Narr | ows - New Edition - 18-DEC-1998 - NAD 1983 | | | |
| | 18-AUG-200 | | | LNM/ | D. 07-JUL-2000 |
| | (P)Amend | "F R" to read "F G" | | 49°17'41.0"N | 123°01'28.5"W |
| | | A patch incorporating these changes will be issued at a later date. | | | |
| | (P)Repositio | n light | from | 49°17'42.5"N | 123°01'34.9"W |
| | | | to | 49°17'42.5"N | 123°01'35.2"W |
| | | A patch incorporating these changes will be issued at a later date. | | | |
| | (P)Amend | "F Y" to read "F" | | 49°17'42.5"N | 123°01'35.2"W |
| | | A patch incorporating these changes will be issued at a later date. | | | |
| | (P)Repositio | n light | from | 49°17'42.5"N | 123°01'34.2"W |
| | | | to | 49°17'42.5"N | 123°01'34.0"W |
| | | A patch incorporating these changes will be issued at a later date. | | | |
| | (P)Amend | "F G" to read "F" | | 49°17'42.5"N | 123°01'34.0"W |
| | | A patch incorporating these changes will be issued at a later date. | | | |
| | (P)Add | light "F" | | 49°17'40.9"N | 123°01'34.1"W |
| | | A patch incorporating these changes will be issued at a later date. | | | |
| | (P)Add | light "F" | | 49°17'39.0"N | 123°01'35.1"W |
| | | | | | |

SECTION 2 - 2000

3494

| | 18-AUG-2000. | | LNM | D. 07-JUL-2000 |
|-----|--------------|---|--------------|----------------|
| | | A patch incorporating these changes will be issued at a later date. | | |
| | (P)Add | light "F" | 49°17'39.0"N | 123°01'34.0"W |
| | | A patch incorporating these changes will be issued at a later date. | | |
| | 08-SEP-2000. | | LNM | D. 07-JUL-2000 |
| | (P)Amend | "F R" to read "F G" | 49°17'41.0"N | 123°01'27.9"W |
| | | A patch incorporating this change will be available at a later date | | |
| | (P)Amend | "F G" to read "F R" | 49°17'40.9"N | 123°01'27.9"W |
| | | A patch incorporating this change will be available at a later date | | |
| | (P)Amend | "F G" to read "F R" | 49°17'40.9"N | 123°01'28.5"W |
| | | A patch incorporating this change will be available at a later date | | |
| 4 - | Vancouver Ha | bour, Central Portion / Partie Centrale - New Edition - 18-DEC-1998 - NAD | 1983 | |
| | 18-AUG-2000 | | LNM | D. 07-JUL-2000 |
| | (P)Amend | "F R" to read "F G" | 49°17'41.0"N | 123°01'28.5"W |
| | | A patch incorporating these changes will be issued at a later date. | | |
| | (P)Amend | "F Y" to read "F" | 49°17'42.5"N | 123°01'35.2"W |
| | | A patch incorporating these changes will be issued at a later date. | | |
| | (P)Amend | "F G" to read "F" | 49°17'42.5"N | 123°01'34.0"W |
| | | A patch incorporating these changes will be issued at a later date. | | |
| | (P)Add | light "F" | 49°17'40.9"N | 123°01'34.1"W |
| | | A patch incorporating these changes will be issued at a later date. | | |
| | (P)Add | light "F" | 49°17'39.0"N | 123°01'35.1"W |
| | | A patch incorporating these changes will be issued at a later date. | | |
| | (P)Add | light "F" | 49°17'39.0"N | 123°01'34.0"W |
| | | A patch incorporating these changes will be issued at a later date. | | |
| | 08-SEP-2000. | | LNM | D. 07-JUL-2000 |
| | (P)Amend | "F R" to read "F G" | 49°17'41.0"N | 123°01'27.9"W |
| | . , | A patch incorporating this change will be available at a later date | | |
| | (P)Amend | "F G" to read "F R" | 49°17'40.9"N | 123°01'27.9"W |
| | • | A patch incorporating this change will be available at a later date | | |
| | (P)Amend | "F G" to read "F R" | 49°17'40.9"N | 123°01'28.5"W |
| | • | A patch incorporating this change will be available at a later date | | |
| | | | | |

L/C3602 - Approaches to/Approches à Juan de Fuca Strait - New Edition - 24-MAY-1985 - NAD 1927 28-APR-2000.

(P)Add submarine cable joining 48°25'18.7"N 124°37'30.0"W

48°26'19.5"N 124°41'11.6"W

SECTION 2 - 2000

L/C3602 - Approaches to/Approches à Juan de Fuca Strait - New Edition - 24-MAY-1985 - NAD 1927

| | 48°26'29.5"N | 124°42'12.7"W |
|-----|--------------|---------------|
| | 48°26'47.4"N | 124°48'24.6"W |
| | 48°26'36.8"N | 124°49'58.3"W |
| | 48°24'00.7"N | 124°57'14.6"W |
| | 48°23'39.0"N | 124°58'56.9"W |
| | 48°23'36.8"N | 125°00'20.6"W |
| | 48°24'01.3"N | 125°03'34.9"W |
| | 48°24'00.2"N | 125°05'47.2"W |
| | 48°22'42.8"N | 125°14'59.1"W |
| | 48°22'44.5"N | 125°16'26.3"W |
| | 48°22'34.5"N | 125°17'54.3"W |
| | 48°21'35.3"N | 125°21'15.2"W |
| | 48°21'08.6"N | 125°24'28.7"W |
| | 48°21'13.1"N | 125°27'31.3"W |
| | 48°19'25.0"N | 125°41'15.0"W |
| | 48°18'01.2"N | 125°47'50.7"W |
| | 48°15'54.6"N | 126°02'59.0"W |
| | 48°16'13.9"N | 126°06'22.6"W |
| | 48°14'52.5"N | 126°12'15.6"W |
| | 48°12'33.1"N | 126°29'47.3"W |
| and | 48°11'54.0"N | 126°33'12.0"W |
| | | |

17-NOV-2000. LNM/D. (903-1999)

(P)Add submarine cable joining 48°25'01.2"N 124°37'30

joining 48°25'01.2"N 124°37'30.0"W 48°25'24.3"N 124°38'55.4"W 48°26'30.8"N 124°48'19.7"W 48°26'27.6"N 124°49'10.0"W 48°25'39.2"N 124°51'51.0"W 48°25'18.8"N 124°52'46.6"W 48°24'48.1"N 124°53'45.8"W 48°24'09.1"N 124°55'20.2"W 48°23'51.4"N 124°56'23.3"W 48°23'03.3"N 125°00'20.0"W 48°22'47.1"N 125°03'14.2"W 48°22'56.1"N 125°05'35.4"W 48°22'38.3"N 125°09'11.3"W 48°21'24.9"N 125°17'19.2"W 48°21'19.0"N 125°18'24.9"W 48°21'20.8"N 125°19'53.9"W

SECTION 2 - 2000

L/C3602 - Approaches to/Approches à Juan de Fuca Strait - New Edition - 24-MAY-1985 - NAD 1927

48°21'09.8"N 125°21'05.8"W 48°20'19.1"N 125°24'29.3"W 48°19'48.3"N 125°27'55.2"W 48°19'49.7"N 125°29'26.8"W 48°19'36.7"N 125°30'55.0"W 48°19'25.0"N 125°31'31.2"W 48°18'58.2"N 125°32'08.4"W 48°18'47.9"N 125°32'37.6"W 48°17'47.9"N 125°39'16.2"W 48°17'50.2"N 125°39'46.6"W 48°18'02.1"N 125°40'22.7"W 48°18'03.0"N 125°40'55.0"W 48°17'45.3"N 125°42'54.8"W 48°17'01.0"N 125°45'53.8"W 48°16'13.0"N 125°50'55.4"W 48°15'20.8"N 125°53'31.6"W 48°10'56.4"N 126°00'47.9"W 48°06'12.4"N 126°04'10.1"W and 48°00'00.0"N 126°04'10.4"W

This information will be added on the next New Edition.

3955 - Porpoise Harbour, Ridley Island and Approaches/et les Approches - New Chart - 15-FEB-1985 - NAD 1927

| 15-SEP-2000 | | LNM/D. 05-MAY-200 | 0 |
|-------------|---|------------------------------------|---|
| (P)Add | outfall | between 54°13'39.3"N 130°17'38.4"N | ٧ |
| | | and 54°13'36.5"N 130°17'50.2"V | ٧ |
| | This information will be incorporated in the next New Edition. | | |
| (P)Add | pipe sign | 54°13'39.3"N 130°17'38.4"N | ٧ |
| | This information will be incorporated in the next New Edition. | | |
| (P)Add | pipe sign | 54°13'34.6"N 130°18'02.5"N | ٧ |
| | This information will be incorporated in the next New Edition. | | |
| (P)Add | outfall | between 54°13'12.4"N 130°17'26.3"N | ٧ |
| | | and 54°13'10.4"N 130°17'34.1"N | ٧ |
| | This information will be incorporated in the next New Edition. | | |
| (P)Add | pipe sign | 54°13'12.5"N 130°17'26.0"N | ٧ |
| | This information will be incorporated in the next New Edition. | | |
| (P)Add | CAUTION: Extensive changes have occurred in the area of Port Edward. ATTENTION: Des changements importants sont survenus dans la zone de Port Edward. | 54°13'42.0"N 130°17'26.0"\ | V |
| | This information will be incorporated in the next New Edition. | | |

SECTION 2 – 2000

4142 - Evandale to/à Ram Island - Sheet 1 - New Edition - 01-NOV-1996 - NAD 1983

13-OCT-2000. LNM/D. 26-MAY-2000 (T)Add green port hand spar buoy, marked H11/5 45°50'06.3"N 066°11'16.6"W (T)Add red light, starboard hand spar buoy FI R, marked H10 45°50'04.8"N 066°11'05.1"W (T)Add green port hand spar buoy, marked H11 45°50'03.9"N 066°11'07.1"W 27-OCT-2000. LNM/D. 26-MAY-2000 (T)Add red light, starboard hand spar buoy FIR, marked H12/6 45°50'07.1"N 066°11'14.6"W

4244 - Wedgeport and Vicinity/et les abords - New Chart - 21-FEB-1986 - NAD 1983

11-AUG-2000. LNM/D. 14-APR-2000

(T)Add yellow and black south cardinal spar buoy, marked ND 43°40'48.0"N 065°54'00.0"W

Temporary replacement of radar reflector with south cardinal buoy.

(T)Delete radar refelector 43°41'00.5"N 065°54'03.0"W

Temporary replacement of radar reflector with south cardinal buoy.

4266 - Sydney Harbour - New chart - 29-SEP-1989 - NAD 1983

12-MAY-2000.

(T)Add yellow cautionary spar buoy 46°08'10.0"N 060°11'53.0"W

Buoy temporarily established

SECTION 2 - 2000

4266 - Sydney Wharves/Quais - New chart - 29-SEP-1989 - NAD 1983 12-MAY-2000.

(P)Delete

| | (T)Add | yellow cautionary spar buoy | 46°08'10.0"N | 060°11'53.0"W |
|-------|----------------|--|--------------|-----------------|
| | | Buoy temporarily established | | |
| | | | | |
| L/C43 | 40 - Grand Man | an - New Edition - 12-APR-1991 - NAD 1927 | | |
| | 24-MAR-2000 | | | |
| | (P)Amend | FR to read "FI R(2)" | 44°55'07.6"N | 066°58'02.9"W |
| | | NOTE: The above information will be included in the new edition of chart 4340, which will be made available at a later date. | | |
| | 16-JUN-2000. | | | |
| | (P)Add | south cardinal can buoy yellow and black, marked XE | 44°35'54.4"N | 066°50'23.0"W |
| | | A new edition of this chart incorporating the above information will be available at a later date. | | |
| | (P)Add | green light and bell, port hand pillar buoy FI G, marked XA3 | 44°36'10.4"N | 066°52'23.0"W |
| | | A new edition of this chart incorporating the above information will be available at a later date. | | |
| | (P)Add | red light, starboard hand spar buoy FI R, marked XA8 | 44°38'24.6"N | 066°48'50.3"W |
| | | A new edition of this chart incorporating the above information will be available at a later date. | | |
| | (P)Amend | FI G 4s 44ft to read, FI G 12s 44ft 5M | 44°36'09.4"N | 066°48'27.6"W |
| | | A new edition of this chart incorporating the above information will be available at a later date. | | |
| | (P)Amend | FI 10s 156ft 20M to read, FI 10s 156ft 16M | 44°36'02.3"N | 066°54'21.8"W |
| | | A new edition of this chart incorporating the above information will be available at a later date. | | |
| | (P)Delete | red and white, fairway, pillar, light and bell buoy Mo (A), marked XAD | 44°35'45.0"N | 066°52'01.8"W |
| | | A new edition of this chart incorporating the above information will be available at a later date. | | |
| | (P)Delete | green port hand, can buoy, marked XE1 | 44°35'55.0"N | I 066°50'20.5"W |
| | | A new edition of this chart incorporating the above information will be available at a later date. | | |
| | (P)Delete | red starboard hand, spar buoy, marked XE2 | 44°36'03.9"N | l 066°49'46.5"W |
| | | A new edition of this chart incorporating the above information will be available at a later date. | | |
| | (P)Delete | green port hand, can buoy, marked XA3 | 44°36'14.5"N | I 066°52'23.0"W |
| | | A new edition of this chart incorporating the above information will be available at a later date. | | |
| | (P)Delete | green port hand, spar buoy, marked XE3 | 44°36'37.5"N | I 066°49'42.0"W |
| | | A new edition of this chart incorporating the above information will be available at a later date. | | |
| | | | | |

44°38'24.0"N 066°48'51.5"W

red light starboard hand pillar buoy FI R, marked XA8

SECTION 2 – 2000

L/C4340 - Grand Manan - New Edition - 12-APR-1991 - NAD 1927

A new edition of this chart incorporating the above information

will be available at a later date.

(P)Delete light F R 44°39'01.0"N 066°50'19.5"W

A new edition of this chart incorporating the above information

will be available at a later date.

11-AUG-2000. LNM/D. (2132-1999)

(P)Amend FI R to read FI G 44°43'24.0"N 066°43'36.0"W

This change will be incorporated in the next new edition of this

chart which will be available at a later date.

L/C4385 - Chebucto Head to/a Betty Island - New Edition - 07-JUN-1996 - NAD 1983

31-MAR-2000.

(P)Amend measured distance with bearing 154°20′-334°20′ 6078ft to read 44°31′24.0"N 063°30′37.0"W

154°20'-334°20' 6118ft

NOTE: This information will be incorporated in the next edition

of chart 4385.

4386 - St.Margaret's Bay - New Edition - 24-MAR-1995 - NAD 1927

31-MAR-2000.

(P)Amend legend Measured Distance 6088 feet 154°20'-334°20' to read 44°32'48.0"N 063°59'42.0"W

Measured Distance 6087 feet 154°20'-334°20'

NOTE: This information will be included in the next edition of

chart 4386.

4422 - Cardigan Bay - New Edition - 17-JUN-1994 - NAD 1927

31-MAR-2000.

(P)Amend legend Measured Distance 6080 feet 149°-329' to read 46°07'39.0"N 062°24'32.0"W Measured Distance 6299 feet 146°59'-326°59'

NOTE: This information will be included in the next edition of

NOTE: This information will be included in the next edition of

chart 4422.

4530 - Hamilton Sound, Eastern Portion / Partie est - New Edition - 11-MAR-1983 - NAD 1927

21-APR-2000.

(P)Add dolphin 49°34'16.7"N 054°18'04.9"W

New edition of chart 4530 to be published at a later date.

(P)Add light "FI R" 49°34'16.7"N 054°18'04.9"W

New edition of chart 4530 to be published at a later date.

4587 - Mortier Bay - New Edition - 21-AUG-1992 - NAD 1927

31-MAR-2000.

(P)Amend measured distance with bearing 007°18'-187°18' 6079 47°10'00.0"N 055°04'57.0"W

Feet/Pieds to read 007°14'-187°14' 6079 Feet/Pieds

NOTE: This information will be incorporated in the next

edition of chart 4587.

SECTION 2 – 2000

6251 - Red River / Rivière Rouge to/à Gull Harbour - New Edition - 18-JUL-1986 - NAD 1983

23-JUN-2000.

(P)Reposition black and yellow, north cardinal spar buoy, marked DP from 50°34'24.0"N 096°37'24.0"W

to 50°34'20.5"N 096°37'29.2"W

A New Edition incorporating the above information will be

available at a later date.

(P)Amend legend DP to read GNC 50°34'20.5"N 096°37'29.2"W

A New Edition incorporating the above information will be

available at a later date.

(P)Reposition yellow and black, south cardinal spar buoy, marked DJ from 50°33'49.0"N 096°37'24.0"W

to 50°33'52.4"N 096°37'29.2"W

A New Edition incorporating the above information will be

available at a later date.

(P)Amend legend DJ to read GSC 50°33`52.4"N 096°37`29.2"W

A New Edition incorporating the above information will be

available at a later date.

L/C8015 - Funk Island and Approaches/et les approches - New Edition - 16-DEC-1994 - NAD1983

23-JUN-2000.

(P)Amend Chart/Carte 4562 to read, "Chart/Carte 4854" 48°52'00.0"N 053°10'30.0"W

A New Edition incorporating the above information will be

available at a later date.

SUMMARY OF (T) & (P) NOTICES 2001

| CHARTS | ACTION DATE | CHARTS | ACTION DATE | CHARTS | ACTION DATE |
|--------|-------------|--------|-------------|--------|-------------|
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |