

# WESTERN EDITION OF NOTICES TO MARINERS

Published monthly by the

# CANADIAN COAST GUARD

**NOTICES** 

1300 to 1353

# **CONTENTS**

		Page
SEC. I	Safety and General Information	1 - 6
SEC. II	Chart Corrections	7 - 8
SEC. III	Radio Aids to Marine Navigation Corrections	NIL
	Sailing Directions and Small Craft Guide Corrections	9 - 17
SEC. V	Light List Corrections	19

Marine Navigation Services Directorate Marine Aids

# **RECYCLED PAPER**

Internet: http://www.notmar.com

#### **ADVISORY**

# NOTICES TO SHIPPING (WRITTEN AND BROADCAST)

The Canadian Coast Guard is implementing a number of changes to the aids to navigation system in Canada.

These changes are advertised as Notices to Shipping (Broadcast and Written) by the Canadian Coast Guard and are followed up with Notices to Mariners, then charts are updated by hand correction, reprints or new editions.

The publication of Notices to Mariners and chart revisions are being delayed by the volume of changes that are taking place.

Mariners are advised that all relevant Written Notices to Shipping should be kept until superseded by Notices to Mariners or through revised charts issued by the Canadian Hydrographic Service.

Written Notices to Shipping are published weekly and are available from local Canadian Coast Guard Offices.

The Canadian Hydrographic Service is reviewing the impact of these changes with the Canadian Coast Guard and together we are preparing an action plan on the issuing of chart revisions.

For further information contact your local Canadian Coast Guard office.

#### Newfoundland

#### Maritimes

St. John's MCTS Centre Phone: (709) 772-2083

Fax: (709) 772-6285

Maritimes Regional Operations Centre Toll Free in Maritimes 1-800-565-1633

Phone: (902) 426-6030 (902) 426-6334

http://www.mar.dfo.mpo.gc.ca/cg/ops/roc.htm Website E-Mail: ROCWeb@mar.dfo-mpo.gc.ca

#### Laurentienne

#### Central & Arctic

Québec MCTS Centre Phone: (418) 648-5410

(418) 648-7244

E-Mail: XLAUSCTM@dfo-mpo.gc.ca

Sarnia MCTS Centre

Toll Free in Ontario 1-800-265-0237

Phone: (519) 337-6360 Fax: (519) 337-2498

### **Pacific**

Vancouver Regional Marine Information Centre

Phone: (604) 666-6011 Fax: (604) 666-8453

#### **EXPLANATORY NOTES**

**Geographical positions** refer directly to the graduations of the largest scale Canadian Hydrographic chart unless otherwise indicated.

**Bearings** refer to the true compass and are measured clockwise from 000° (North) clockwise to 359°; those relating to lights are from seaward.

Visibility of lights is that in clear weather.

**Depths** - The units used for soundings (metres, fathoms or feet) are stated in the title of each chart.

Elevations are normally given above Higher High Water, Large Tides unless otherwise indicated.

**Original Canadian Information** - A star (\*) adjacent to the Notice number indicates that this notice is based on original Canadian information.

**Distances** may be calculated as follows:

```
1 nautical mile = 1 852 metres (6,076.1 feet)
1 statute mile = 1 609.3 metres (5,280 feet)
1 metre = 3.28 feet
```

**Temporary & Preliminary Notices** are indicated by a (T) or a (P) after the Notice number. Nautical charts and publications are not hand amended for Temporary (T) and Preliminary (P) Notices to Mariners Listings of Charts Affected by Temporary and Preliminary Notices to Mariners are revised and promulgated quarterly, in Section I. Reference should be made to the latest published listing and to the monthly editions of Notices to Mariners published subsequently.

Please note that, in addition to the temporary and preliminary changes normally advertised as (T) and (P) Notices, there are a significant number of permanent changes to navigational aids that have been advertised as Preliminary Notices to Mariners while charts are being updated forew editions.

Marine Information Report & Suggestion Sheet - Mariners are requested to notify the responsible authorities when new or suspected dangers to navigation are discovered, changes observed in aids to navigation or corrections to publications are seen to be necessary. Such communications can be made using the Marine Information Report & Suggestion Sheet inserted on the last page of each monthly edition of Notices to Mariners.

**Monthly edition of Notices to Mariners** - *Notices to Mariners* are issued free of charge on a monthly basis. Mariners now have a choice between specific *Regional* issue(s) they wish to receive. Requests to be placed on or removed from the mailing list should be made by using the form inserted on pagex of each monthly edition. Notification of changes to the mailing addresses, regional issues and/or number of copies required should also be transmitted by means of this form.

**Canadian Nautical Charts & Publications** - A source list of *Canadian Nautical Charts & publications* is published in *Notice No. 14* of the current *Annual Edition of Notices to Mariners.* The source supply and the prices effective at the time of printing are listed. This list is periodically updated in the monthly edition of *Notices to Mariners.* 

NOTE: Cette publication est aussi disponible en français.

# **DGPS INITAL OPERATIONAL SERVICE**

The Canadian Coast Guard (CCG) announces that the Differential Global Positioning Service (DGPS) Initial Operational Service (IOS) is available for positioning and navigation.

IOS means the service will provide a DGPS broadcast using the type 9 RTCM message for pseudorange corrections at a data transmission rate of 200 baud. Refer to Radio Aids to Marine Navigation (RAMN) for estimated advertised coverage for each differential station.

Although the service is IOS, users may experience service interruptions without advance notice. Further, CCG advises that IOS DGPS broadcasts should not be used under any circumstances where a sudden system failure or inaccuracy could constitute a safety hazard. Following a one year verification period, the DGPS service will be declared as being a Full Operational Service (FOS).

Users are also advised that differential corrections are based on the NAD 83 datum position of the reference station antenna and positions obtained using DGPS should be referenced to this coordinate system only. DGPS receivers must be set to the WGS 84 datum in order to obtain optimum positioning accuracy.

Table of Stage 1 DGPS Reference Stations							
Station Name	ld Nos of Ref. Stations	DGPS Station ID	Georgr. Pos. Latitude Longitude	Frequency [khz]	Bits/sec.		
Alert Bay BC	300,301	909	50 35 N 126 55 W	309	200		
Amphitrite Pt BC	302,303	908	48 55 N 125 32 W	315	200		
Cardinal ON	308,309	919	44 47 N 75 25 W	306	200		
St. Jean Richelieu QUÉ	312,313	929	45 19 N 73 18 W	296	200		
Lauzon QUÉ	316,317	927	46 48 N 71 09 W	309	200		
Partridge Island NB	326,327	939	45 14 N 66 03 W	295	200		
Pt. Escuminac NB	332,333	936	47 04 N 64 47 W	319	200		
Fox Island NS	336,337	934	45 19 N 61 04 W	307	200		
Cape Race NFLD	338,339	940	46 39 N 53 04 W	315	200		
Cape Ray NFLD	340,341	942	47 34 N 59 09 W	290	200		

# **DGPS USER ALERT**

Currently, ten Phase 1 DGPS stations are providing Initial Operational Service (IOS) which was declared by Regional Notices to Mariners issued in September 1996. Another eight DGPS stations will be installed in 1997. Extensive validation of operational performance is being conducted throughout 1997. Full Operational Service (FOS) will follow after successful validation.

The Canadian Coast Guard has recently received reports of DGPS receivers apparently ignoring the broadcast alarm which should signal the immediate discontinuation of a particular satellite correction. Reports indicate that some user equipment does not properly recognize this "do-not-use" correction flag and as a result erroneously processes it as a correction. This can result in position errors as large as 15 kilometers while the receiver is in DGPS mode. DGPS users are advised that they should contact the manufacturer of their equipment immediately to determine if they require a receiver upgrade.

Apart from this, no major difficulties with DGPS implementation have been experienced to date nor are any expected in the future.

#### DISCREPANCY REPORT FOR DGPS USERS.

The Canadian Coast Guard is currently implementing the Differential Global Positioning System in Canada. In August 1996, 10 DGPS stations were announced as providing an Initial Operational Service (IOS). Eight (8) additional DGPS stations will be implemented in the fall of 1997.

Following a service validation period, it is expected that the DGPS service will be announced as providing a Full Operational Service (FOS) in December 1997. The fully operational DGPS service is expected to meet the advertised Levels of Service standards and all service guarantees will be provided with FOS.

Throughout the service validation period, the Coast Guard will be conducting numerous tests of the differential service. To assist the Coast Guard in this validation testing, mariners are requested to complete the attached anomoly report. Please take note of any DGPS service anomalies you experience and forward the completed form to the Director Marine Aids, Fisheries and Oceans Canada, 200 Kent Street, Station 5130, Ottawa, ON, K1A 0E6.

# DGPS station anomaly report / Rapport d'anomalie des stations DGPS

With the purpose of constantly evaluating the quality of the DGPS service offered, the Canadian Coast Guard is providing the mariner with the following anomaly report. This report will allow us to get well-supported information concerning the anomaly and thus, will facilitate the identification of the origin of the problem. Please fill accordingly each section of this report and forward it by the suggested ways. You will find a legend at the end of this document.

Avec le souci d'évaluer constamment la qualité du service DGPS offert, la Garde côtière met à la disposition du navigateur le présent rapport d'anomalie. Ce rapport servira à bien documenter l'anomalie et, de ce fait, facilitera l'identification ou la recherche de la source du problème. Nous vous prions de bien remplir chaque section de ce rapport et de l'acheminer de la façon suggérée. Vous trouverez une légende à la fin de ce document.

User informations / Renseignemer sur l'usager	nts		
Vessel name / Nom du navire:	Destinati	on:	
Vessel position at the beginning of the	anomaly /	J	
Position du navire au début de l'anoma	alie:		
Vessel position at the end of the anom			
	e <u>:</u>		
Anomaly report / Rapport d'anomalie			
Date and time of the anomaly / Date e	t heure de l'anomalie:	Duration / Durée:	
Number of satellites tracked on GPS re	eceiver / Nombre de satellites reçu par le	<u> </u>	
DGPS site using / Station DGPS utilise	ée: Freq.:kHz SS:	dB SNR:	dB
DOP Geometry / Géométrie DOP :			
User receiver operates correctly with o			
	il normalement à l'utilisation d'autres static	ons DGPS?: Yes/O <u>ui</u>	
_No / Non			
Comments / Commentaires:			
Doint of contact / Doronno recourse	Nome/Nome		
Point of contact / Personne-ressource	e: Name/ Nom: Phone / Téléphone :		
	Thorie / Telephone .		
Weather conditions /			
Conditions météo	Winds / Vents: Direction:	Speed / Vitessse:	KTS
Conditions meteo	Temp. °C:	Opeed / Vitessse	N.M.
	Sea State / État de la mer :	vi3	IN.IVI.
	Bearing and range to electrical storm		
	Direction et distance de l'orage :		
	Time of the storm / Heure de l'orage:		UTC
	o o ,		
Essential informations on user equi	pment to fill / Renseignements indispe	nsables sur l'équipement	à
remplir:	,		
· •			
User equipment informations / Rens	seignements sur		
l'équipement	g		
- oquipomoni			
GPS receiver / Récepteur GPS: Make	e / Fabriquant	Model:	
	ır DGPS: Make / Fabriquant <u>:</u>	Model:	
Gyro interface with GPS / Gyro intégré	avec le GPS? Yes / Oui :	No / Non :	
DGPS interfaced with an ECDIS / DGF	e avec le GPS? Yes / Oui : PS intégré dans un SVCEI? Yes / Oui:	No / Non :	
If yes, please fill below / Si oui, S.V.P.	compléter ci-dessous:		

ECDIS / SVCEI: Make / Fabriquant:	Model:	
Radar image interfaced / Image radar intégrée?: Yes / Oui:		No / Non:
Gyro interfaced with ECDIS / Gyro intégré avec SVCEI? Yes / Oui:	No / Non:	
Permanent installation or in evaluation / Installation permanente ou en évaluati	ion :	

# This report can be sent the following ways / Ce rapport peut être acheminé selon les façons suivantes:

1) Fax / Par télécopieur : 613-998-8428 attention AWAD.

2) Mail / Par la poste: Director Marine Aids

Fisheries and Oceans Canada 200 Kent Street, Station 5130

Ottawa, ON K1A 0E6.

# Canadä

Legend/ Légende

**Position**: Position can be provided by latitude, longitude, bearing and distance, location

of a buoy, etc.

La position peut être donnée en latitude, longitude, relèvement et distance,

emplacement de bouée, etc.

KTS : Wind speed in knots / Vitesse du vent en noeuds.N.M. : Visibility in Nautical Miles / Visibilité en milles nautiques.

**N.M.** : Visibility in Nautical Miles / Visibilite en milles nautiques **Freq. kHz** : Frequency in kilohertz / Fréquence en kilohertz .

SS : Signal strength in decibel / Force de signal en décibel.

SNR : Signal to noise ratio in decibel / Rapport signal-bruit **a** décibel .

**DOP** (dilution of precision): Measure of the geometrical «strength» of the GPS satellite configuration.

The DOP is measured on a scale of 1 to 10 / Mesure de la «force » géométrique de la configuration satellite. Le DOP est mesuré sur une échelle

de 1 à 10

**SVCEI / ECDIS**: Electronic Chart Display and Information System / Système de Visualisation de

Cartes Electroniques et d'Information .

# **IMPORTANT NOTICE TO USERS**

# The Canadian Coast Guard Marine Aids Modernization Program

- The Canadian Coast Guard is initiating an aids to navigation modernization program which takes advantage of
  modern technology and will result in a more equitable, safe, cost-effective and environmentally friendly service
  across Canada. Low maintenance buoys, solar power, the elimination of diesel power and the application of
  national provision and design standards, will be used to realize these objectives.
- In consultation with local users, aids to navigation which are redundant, exceed the national standards or should not be publicly funded, will be downsized, privatized or discontinued.
- Regional plans as well as detailed Notices to Shipping and Notices to Mariners will be issued and distributed in
  the usual manner in advance of all changes to aids to navigation. All users are encouraged to participate in
  local consultations and to monitor these Notices. It will be every user's responsibility to adapt to the changes
  and to take the appropriate measures.

# 1. Redundant Aids to Navigation

Many conventional aids to navigation were established for commercial mariners who now use radar. As a result these users no longer require as many landfall shore lights, large lighted buoys and fog signals and support their discontinuance.

However, before these commercially redundant marine aids are removed, the Coast Guard is assessing, where required, the local needs of small craft operators and redesigning the old commercial aids to meet these needs within national provision policies and design standards.

Coast Guard policy does not provide for the retention of fog horns for pleasure craft, due to the high cost to provide such a service across Canada. However, where practical and where there is local support, the existing redundant fog horns are being transferred to local authorities at no cost.

The conversion of lightstations to solar power allows major economic and environmental benefits by allowing removal of fuel tanks and diesel generators. Although this eliminates the need for many structures, the Coast Guard will protect all heritage lightstations through continued operation or transfer to provincial, municipal or other authorities for local use.

#### 2. Aids to Navigation Standards

In consultation with local users, all aids to navigation systems across Canada are under review. National system design standards will be used to assess these systems. Systems that do not meet these standards will be upgraded; those systems that exceed them will be downsized.

Adjustments in some channels will result in an increase or a decrease in the number of buoys and/or the conversion of some lighted buoys to unlighted buoys displaying reflective material.

# 3. Private Aids to Navigation

Although Coast Guard policy does not provide for the establishment of aids to navigation in inadequately charted waters, or where the traffic volume does not justify the cost of the system, some have been established in the past. These aids to navigation will be transferred to local authorities no cost, with Coast Guard retaining design and regulatory authority under the Private Buoy Regulations

# **NEW INITIATIVES**

The Canadian Coast Guard is also introducing a new differential correction service to augment the satellite-based Global Positioning System (GPS), with 18 transmitting stations fully operational in 1998.

This Differential Global Positioning System (DGPS), will improve the accuracy and integrity of GPS and will enable mariners who are equipped with the appropriate receivers to identify their precise position in most major southern Canadian waters, including the Great Lakes and the St. Lawrence River.

The use of DGPS in conjunction with Electronic Chart Display and Information Systems (ECDIS), will greatly improve navigation accuracy. The expanding use of this new technology is expected to increase marine safety and thus provide greater environmental protection to Canadian waters. It is also believed that implementation of DGPS will allow further adjustment to conventional aids in the future.

All mariners and shipowners are encouraged to equip their vessels with GPS receivers which have the capability to receive the Differential signals, particularly where there is frequent risk of reduced visibility.

The Canadian Coast Guard believes that the availability of GPS, particularly when augmented by the Differential service, will make Loran C obsolete. Consultations are underway to assess the impact of discontinuing Loran C in Canada.

### **CENTRAL & ARCTIC REGION**

The Canadian Coast Guard is planning to further modernize its marine aids to navigation service. Changes will include adjusting all service levels to national standards between 1997 and the year 2000 and reducing some conventional aids services based on the availability of the Global Positioning System, Differential Global Positioning System (DGPS) and the Electronic Chart Display Information System (ECDIS). The new electronic systems will supplement the remaining conventional aids system, permitting continued maintenance of a safe service at lower cost

Implementation of the following changes will begin within Coast Guard Central and Arctic region on A <u>pril</u> 1, 1997.

# **MEASURES**

- 1) Upgrading DGPS sites at Cardinal and Wiarton to Initial Operating Service to provide, with the United States Coast Guard, to provide complete coverage of the Great Lakes/St. Lawrence Seaway by December 1997.
- 2) Removal or divestiture of 700 floating and fixed aids to navigation in the Athabasca River System.
- 3) Removal of approximately 20 floating aids in the Western Arctic in Simpson Strait, Cambridge Bay, Gjoa Haven and Spence Bay.
- 4) Privatization of 30 buoys in the Napanee River and approximately 120 fixed and floating aids to navigation in Northern Ontario due to uncharted or inadequately charted waters.
- 5) Removal or divestiture of approximately 30 reference or wharf-lights in conjunction with Small Craft Harbours, or Ports and Harbours Canada initiatives.
- 6) Conversion of approximately 20 lighted buoys to unlighted buoys in pleasure craft channels.
- 7) Removal of 50 floating aids to navigation in commercial channels.
- 8) Divestiture of 1 light house and associated property.
- 9) Removal or transfer of 14 fog horns on Lake Superior.
- 10) Removal or downsizing of 31 large lighted floating aids to navigation on the Great Lakes.

Over the next year, more detailed information concerning each of these proposed changes will be provided in each region or geographic area by Notices to Shipping and Notices to Mariners, allowing users time to comment prior to finalizing planned changes. Further Notices to Shipping and Notices to Mariners will also be issued at the time of all changes.

Mariners and representatives of user groups wishing to provide comments or recommendations on this or any subsequent notice may write to:

Superintendent Marine Aids Program Central and Arctic Region 201 Front Street North, Suite 703 Sarnia, Ontario, N7T 8B1 Telephone (519)383-1816 Facsimile (519)383-1995

# **MONTHLY EDITION OF NOTICES TO MARINERS**

# **MAILING LIST CHANGES**

Director General, Marine Navigation Services Directorate, Canadian Coast Guard, Department of Fisheries and Oceans, Ottawa, Ontario, K1A 0E6

Ottawa, Ontario K1A 0E6	Fisheries and Oceans, 0,	
	- (613) 990-3037 - (613) 998-8428	
Please indicate	which edition you would like to receive.	
EASTERN EDI Central areas)	ITION (will be comprised of Arctic, Newfoundland, Maritimes, Gulf & River St. Lawrence an	d
WESTERN ED	PITION (will be comprised of Arctic and Pacific areas)	
ADD	AMEND REMOVE NO. OF COPIES	
		7
	OLD ADDRESS	
NAME		
STREET	APT	
CITY	POSTAL CODE	
PROVINCE	COUNTRY	
	NEW ADDRESS	
NAME		
STREET	APT	
CITY	POSTAL CODE	
PROVINCE	COUNTRY	
		-

ID number above address on label .....

or

Attach complete address label to this sheet

# INDEX PAGE

NATIONAL		
ERRATUM - Correction to Notice to Mariners 1162/98 - Chart 3651	1352	6
CANADA - List of charts affected by (T) and (P) notices in effect June 26, 1998.	1346	3,4
- Notice to Shipowners and Operators of Canadian Safety Convention Ships.	1334	1,2
- Summary of (T) and (P) Notices in effect June 26, 1998	1345	2,3
- Information about CHS chart dealers		1 4-6
ARCTIC		
HUDSON BAY- DAWSON INLET TO MARBLE ISLAND - Rocks	1310	7
PACIFIC		
BRITISH COLUMBIA- BAYNES SOUND - CAPE LAZO - Light - Buoys	1302	8 7 7
UNITED STATES, WEST COAST- ADMIRALTY INLET - OFF POINT	1319	7
WILSON - Buoy - JUAN DE FUCA STRAIT - OFF PORT ANGELES- Buoy	1301	8

NOTICES 1305 AND 1350 ARE NOT PUBLISHED

# NUMERICAL INDEX OF CANADIAN CHARTS AFFECTED

Chart No.	Notice #	Page	Chart No.	Notice #	Page	Chart No.	Notice #	Page
3313	1319 7	7						
3457	1351 1	l						
_C 3461	1301 8 1319 7							
3490	1302 7 1308 7							
_C 3513	1313 8	3						
3527	1313 8	3						
3544	1351 1	I						
3601	1319 7	7						
C 3606	1301 8	3						
3729	1351 1	I						
3745	1351 1	I						
3785	1351 1	I						
8894	1351 1	I						
3927	1351 1	I						
3932	1351 1	I						
963	1351 1	I						
397	1310 7	7						
398	1310 7	7						

# \*1351 CANADIAN HYDROGRAPHIC SERVICE - Charts.

CHART	TITLE & CONTENTS	SCALE	DATED	CAT#	PRICE
1. New Edition	ons.				
	British Columbia/Colombie-Britannique				
3729	Dean Channel - Southern Portion/Partie Sud and/et Burke Channel	1:75 000	June 5/98	2	\$20.00
3745	Gardner Canal	1:73 050	June 12/98	2	20.00
3894	Selwyn Inlet to Lawn Point	1:73 026	June 12/98	2	20.00
3927	Bonilla Island to/à Edye Passage	1:77 800	May 29/98	2	20.00
2. Reprints.					
	British Columbia/Colombie-Britannique				
3457	Nanaimo Harbour and/et Departure Bay	1:8 000	May 1/98	2	20.00
3544	Johnstone Strait - Race Passage and/et Current Passage	1:25 000	June 5/98	2	20.00
3785	Namu Harbour to Dryad Point	1:40 533	June 12/98	2	20.00
3932	Rivers Inlet	1:40 000	June 12/98	2	20.00
3963	Work Channel	1:40 000	June 12/98	2	20.00

I

(AMA8035-10-35) (DFO-H98-065)

# \*1334 CANADA - Notice to Shipowners and Operators of Canadian Safety Convention Ships.

Shipowners and operators of Canadian Safety Convention ships are reminded that under SOLAS Chapter IV, and the Canadian Ship Station Radio Regulations section 11, their ships will have to be fully fitted for the GMDSS and have on board suitably trained and certified officers for the GMDSS by February 1, 1999. To ensure compliance, SOLAS radio certificates issued in 1998 to ships not already in compliance with the GMDSS will not be valid after January 31, 1999. For this reason, these certicates are being endorsed to expire on this date.

In addition, owing to an expected heavy demand for GMDSS equipment and training courses, shipowners and operators are advised to take early action in making the necessary arrangements to become GMDSS compliant.

Questions on this notice may be directed to:

Allen Williams Marine Safety Tower C, Place de Ville 330 Sparks Street Ottawa, K1A 0N8

Telephone: (613) 991-2061 Facsimile: (613) 993-8196 E-mail: williaa@tc.gc.ca Procedures for arranging a radio inspection, and a list of Canadian Coast Guard ship radio inspection contacts can be found in a correction to the Radio Aids to Marine Navigation published in Notices to Mariners Edn #10/97.

(AMA8035-10-1) (CCG-H98-035)

I

\*1345

# SUMMARY OF TEMPORARY AND PRELIMINARY NOTICES IN EFFECT JUNE 26, 1998

(Revised and promulgated quarterly) Reference: Notice 757/98 cancelled.

NOTICE	CHART	LOC	CALITY AND SUBJECT			
		(1)	MISCELLANEOUS			
342(P)/97			Canada - Loran-C lattices on nautical charts.			
633(T)/97			Canada - Safety of offshore exploration and exploitation vessels.			
		(2)	CANADIAN ARCTIC AND WEST COAST OF GREENLAND			
847(P)/89	7740, 7083		Northwest Territories - Larsen Sound - Boothia Peninsula - Results of surveys.			
634(P)/96	7371		Northwest Territories - Ellesmere Island - Alexandra Fiord - Off Skraeling Island -Result of survey.			
658(P)/96			Northwest Territories - Hay River - Lights and light buoys to be discontinued.			
666(P)/96			Western Arctic - Great Slave Lake - Curtis Island - Light to be discontinued.			
738(P)/96	6311		Northwest Territories - Lake Athabasca - Range lights to be discontinued.			
751(P)/96	6311		Northwest Territories - Lake Athabasca - Range lights to be discontinued.			
222(P)/97			Northwest Territories - Simpson Strait - Spar buoys to be discontinued.			
223(P)/97			Northwest Territories - McClintock Bay - Spar buoys to be discontinued.			
233(P)/97			Northwest Territories - Spence Bay - Spar buoys to be discontinued.			
328(P)/98			Northwest Territories - Fort Chipewyan to Fort McMurray - Changes to the buoyage system - 1998.			
		(3)	BRITISH COLUMBIA INCLUDING VANCOUVER ISLAND, QUEEN CHARLOTTE ISLANDS, FRASER RIVER, U.S. WEST COAST SOUTH TO 48°N., AND PUGET SOUND			
967(T)/85	3441, L/C 3462, 3313		Vancouver Island - Saanich Inlet - Off Coal Point and Squally Reach - Moorings established temporarily.			
516(P)/92			British Columbia - Strait of Georgia - Lund - Daymark to be discontinued.			

EDN # 07/98

575(T)/92	3313, 3441	Vancouver Island - Saanich Inlet - Patricia Bay - Sub-surface acoustic target established.
702(P)/92	3053	British Columbia - Shuswap Lake - Salmon Arm - Range lights established.
784(P)/92	3540, 3312	Vancouver Island - Discovery Passage - Campbell River - Information about fuel barge.
454(T)/93	3490	British Columbia - Fraser River - Sturgeon Bank - Cautionary light buoy established temporarily.
651(T)/93	3419	Juan de Fuca Strait - Esquimalt Harbour - Off Yew Point - ODAS/SADO buoy established temporarily.
669(T)/93	3958, 3964	British Columbia - Prince Rupert Harbour - Current meters established temporarily.
684(T)/93	L/C 3602, L/C 3001, L/C 3000	Off Vancouver Island - Subsurface mooring established temporarily.
279(T)/94	L/C 3000	Off Vancouver Island - Subsurface moorings established temporarily.
301(T)/94	3680, 3623, L/C 3604, L/C 3001, L/C 3000	Off Vancouver Island - Scientific subsurface mooring established temporarily.
303(T)/94	L/C 3604, L/C 3001, L/C 3000	Off Vancouver Island - Scientific subsurface mooring established temporarily.
733(T)/95	LC 3802	British Columbia - Dixon Entrance - Rose Spit - Racon temporarily relocated.
715(P)/96		Pacific Ocean - Strait of Juan de Fuca - Fog signal, daybeacon and light to be discontinued.
814(P)/96	3682, 3663, 3662	Vancouver Island, West Coast - Approaches to Esperanza Inlert - Shoal depths.
96(P)/97	3682, 3623	Vancouver Island, West Coast - Kyuquot Sound - Entrance to Fair Harbour - Shoal reported.
327(P)/97		British Columbia - Changes to the buoyage system - 1997.
474(P)/97		British Columbia - Fraser River - Changes to the buoyage system - 1997.
516(P)/97	3662	Vancouver Island, West Coast - Approaches to Esperanza Inlet - Shoal depth.
693(P)/97	3728	British Columbia - Milbanke Sound - Bardswell Group - Results of survey.
694(P)/97	3711	British Columbia - Milbanke Sound - Bardswell Group - Wurtele Island - Results of survey.
695(P)/97	3787	British Columbia - Milbanke Sound - Bardswell Group - Results of survey.

I

528(P)/98 3442

British Columbia - Gulf Islands - Samuel Island - Off Ralph Grey Point - Chart amendment.

(AMA8035-10-1) (CCG-H98-036)

\* 1346

# LIST OF CHARTS AFFECTED BY (T) AND (P) NOTICES IN EFFECT JUNE 26, 1998

I

(Revised and promulgated quarterly) (Reference: Notice 756/98 cancelled)

CHARTS	(T) and (P) NOTICES
L/C 3000 L/C 3001 3053 3312 3313 3419 3441 3442 L/C 3462 3490 3540 L/C 3602 L/C 3604 3623 3662 3663 3680 3682 3711 3728 3787 LC 3802 3958 3964 6311 7083 7371 7740	684(T)/93, 279(T)/94, 301(T)/94, 303(T)/94 684(T)/93, 301(T)/94, 303(T)/94 702(P)/92 784(P)/92 967(T)/85, 572(T)/92 651(T)/93 967(T)/85, 575(T)/92 528(P)/98 967(T)/85 454(T)/93 784(P)/92 684(T)/93 301(T)/94, 303(T)/94 301(T)/94, 96(P)/97 814(P)/96, 516(P)/97 814(P)/96, 96(P)/97 694(P)/97 693(P)/97 733(T)/95 669(T)/93 669(T)/93 738(P)/96, 751(P)/96 847(P)/89 847(P)/89
(AMA8035-10-1)	(CCG-H98-037)

# \*1336 CANADIAN HYDROGRAPHIC SERVICE - Information about CHS chart dealers.

# 1 - NEWLY APPOINTED CHART DEALERS

Atelier Guy Malouin Enr. 2965 Bas de la Rivière Nicolet (Québec)

J3T 1E4

Tel: (819) 293-5916 Fax: (819) 293-6333 KP's Fibreglasing & Marine Supplies 559 Main Street, P.O. Box 172 Burin Bay Arm, Newfoundland A0E 1G0

Tel: (709) 891-2229 Fax: (709) 891-2229 Boathouse

8245 Taschereau, #18A Brossard, Québec

J4Y 1A4

Tel: (514) 445-9033

Fax: (514) 445-9211

Crate Marine Sales Limited 290 The Queensway South

Keswick, Ontario

L4P 2B3

Tel: (905) 476-4552 Fax: (905) 476-6308 Email: sales@crates.com Web: www.crates.com

Bellingham Chart Printers 7 Parks Bay Drive, Shaw Island

P.O. Box 1728

Friday Harbor, WA 98250, U.S.A.

Tel: (360)468-3900, (800)643-3900

Fax: (360)468-3939 Web: www.tidesend.com Email: sales@tidesend.com

**Hudson Bay Port Company** 

P.O. Box 217 Churchill, Manitoba

**R0B 0E0** 

Tel: (204) 675-8823 Fax: (204) 675-2550

Mains'L Marine

Main Highway, P.O. Box 1169 Manuels, Newfoundland

A1W 1N6

Tel: (709) 781-0228 Fax: (709) 781-1021 Heritage Foundation for Terra Nova National Park Glovertown, Newfoundland

A0G 2L0

I

Tel: (709) 533-2884

(709) 533-2801, ext. 145

Fax: (709) 533-2706

Vandervoort Hardware Vandervoort Holdings Ltd. 77 Princess Street, P.O. Box 160 Kingston,Ontario

K7L 4V8

Tel: (613) 548-7783 Fax: (613) 547-5150

Dépanneur Roger Jones Enr. 1066, boul. Dr. Camille Marcoux

C.P. 268

Lourdes-de-Blanc-Sablon, Québec

G0G 1W0

Tel: (418) 461-2010 Fax: (418) 461-2362

Brown's Marina Ltd. 7719 County Road, #42

Elgin, Ontario K0G 1E0

Tel: (613) 272-5466 Fax: (613) 272-3450

Oxford-Basics 495 Dundas Street Woodstock, Ontario

N4S 1C3

Tel: (519) 539-9725 Fax: (519) 539-0248

# 2 - DEALER ADDRESS CHANGE

# **OLD ADDRESS**

Armchair Sailor Books & Charts 546 Highway 98 E. P.O. Box 698 Destin, FL 32540 U.S.A.

Tel: (904) 837-1577 Fax: (904) 837-1579

# **NEW ADDRESS**

The Kayak Experience 600 Highway 98 E. P.O. Box 698 Destin, FL 32540

U.S.A.

Tel: (850) 837-1577 Fax: (850) 837-1579 City of Belleville Parks & Recreation Dept.

116 Pinnacle Street Belleville, Ontario

K8N 3A4

Tel: (613) 966-4632 Fax: (613) 967-2043

The Map Store Old Town Plaza 505 Stillwater Avenue Old Town, ME 04468

U.S.A.

Tel: (207) 827-4511

Hilton Beach Marina, Village of Hilton Beach 1 Marks Street, Box 25 Hilton Beach, Ontario

P0R 1G0

Tel: (705) 246-2291, 246-2242

Fax: (705) 246-2913

Safe Navigation 820 Long Beach Blvd.

Long Beach, CA 90813, U.S.A. Tel: (562) 590-8744, (800)723-3628

Fax: (562) 491-0073

 ${\bf Email: safenav@internetMCI.com}$ 

City of Belleville

Parks & Recreation Dept.

169 Front Street Belleville, Ontario

K8N 2Y8

**Physical location** 84 River Road Corbyville, Ontario

K0K 1V0

Tel: (613) 966-4632 Fax: (613) 967-3207

Email: parksrec@city.belleville.on.ca
Web: www.city.belleville.on.ca

The Map Store R.R. #1, Box 182A Old Town, ME 04468

U.S.A.

Tel: (207) 827-4511

Hilton Beach Marina, Village of Hilton Beach

3130 Marks Street, Box 25 Hilton Beach, Ontario

P0R 1G0

Tel: (705) 246-2291, 246-2242

Fax: (705) 246-2913

Email: Hilton\_Beach@hotmail.com

Web: www.geocities.com/athens/delphi/1245

Safe Navigation 454 Pacific Avenue

Long Beach, CA 90802, U.S.A. Tel: (562) 590-8744, (800)723-3628

Fax: (562) 491-0073

Email: safenav@internetMCI.com

#### 3 - THE FOLLOWING ARE NO LONGER AUTHORIZED CHS CHART DEALERS

Baker Marine P.O. Box 99, Rice Lake Gore's Landing, Ontario

K0K 2E0

Tel: (416) 342-5664

Dawson's Marina Limited 294 The Queensway South

Keswick, Ontario

L4P 2B5

Tel: (905) 476-4321 Fax: (905) 476-5039

McGarr Marine

1204 St. Laurent Street West

Longueuil, Québec

J4K 1E4

Tel: (514) 677-8966 Fax: (514) 677-8681 Madawaska Marine Ltd. 210 Riverview Drive Arnprior, Ontario

K7S 3S6

Tel: (613) 623-2228 Fax: (613) 623-7173

Sea's Chandlery & Service

24 Apple Street Brockville, Ontario

K6V 4X8

Tel: (613) 498-2564 Fax: (613) 498-2487

T.S.O. Marine

114 Mississaga Street East

P.O. Box 2112 Orillia, Ontario L3V 6R9

I EDN # 07/98

M.M.O.S. Inc. 1210 Union Avenue Montréal, Québec H3B 3C4

Tel: (514) 866-1146 Fax: (514) 876-7852

(AMA8035-10-35) (DFO-H98-062)

# \*1352 ERRATUM - Correction to Notice to Mariners 1162/98 - Chart 3651.

The date for the last New Edition of chart 3651 should read "April 9, 1993".

(AMA8035-10-35) (DFO-H98-066)

# \*1310 HUDSON BAY - DAWSON INLET TO MARBLE ISLAND - Rocks.

Charts (Last correction) - 5397(1-3)(1127/98) - 5398(4)(1121/98)

1. Add rock awash 61°58'12".7 N 92°37'30".3 W

2. Add rock with drying height of 1 61 58 32.7 N 92 25 05.6 W

foot

3. Replace 1 fathom, 2 feet with rock with 62 13 58.7 N 91 49 02.1 W

known depth of 1 fathom

4. Add rock awash 61 58 12.7 N 92 37 30.3 W

(AMA8035-10-35) (DFO-C98-109)

# \*1319 UNITED STATES, WEST COAST - ADMIRALTY INLET - OFF POINTWILSON - Buoy.

Charts (Last correction) - 3313(Sheet 1)(Vancouver Island)(NAD 83)(2) - LC 3461(NAD 27)(1)(1301/98) - 3601(NAD 83)(2)

1. Reposition	red light buoy 6		48°09'09" N 1 48 09 11.7 N 1	122°45'47".5 W 122 45 33.3 W
2. Reposition	red light buoy	_	48 09 08 N 48 09 11 N	

NOTE: Digital data products 3461R/M, 70113(3601) and 70141(3461) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-P98-021)

# \*1302 BRITISH COLUMBIA - FRASER RIVER - GARRY POINT - Light.

Chart (Last correction) - 3490(Compartment A-B)(NAD 83)(1)(1116/98)

1. Delete light Fl 49°07'27".7 N 123°11'48".8 W

NOTE: Digital data products 3490R/M, 70015(3490) and 70128(3490) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-P98-015)

\*1308 BRITISH COLUMBIA - FRASER RIVER - STEVESTON BEND - Buoy.

II EDN# 07/98

Chart (Last correction) - 3490(Compartment A-B)(NAD 83)(1)(1302/98)

1. red light buoy S8 from 49°07'41" N 123°14'30" W Reposition to 49 07 38 N 123 14 35 W

NOTE: Digital data products 3490R/M, 70015(3490) and 70128(3490) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-5-16)

(CCG-P98-019, DFO-P98-020)

# \*1301 UNITED STATES, WEST COAST - JUAN DE FUCA STRAIT - OFF PORT ANGELES - Buoy.

Charts (Last correction) - LC 3461(NAD 27)(1)(620/97) - LC 3606(NAD 27)(1)(522/97)

1. Add red light buoy "FI R", marked 48°09'48".7 N 123°28'19".2 W "4"

NOTE: Digital data products 3461R/M, 3606R/M, 70141(3461) and 70144(3606) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-35) (DFO-P98-018)

# \*1313 BRITISH COLUMBIA - BAYNES SOUND - CAPE LAZO - Light - Buoys.

Charts (Last correction) - 3527(NAD 27)(1-4)(74/96) - LC 3513(NAD 27)(1-4)(697/97)

1. Delete	light	49°42'24".5 N	124°51'41".5 W
2. Delete	east cardinal buoy PK	49 42 45 N	124 50 52 W
3. Add	east cardinal light buoy, "Q(3) 10 s", "BYB", marked "PB"	49 42 42.5 N	124 50 24 W
4. Replace	east cardinal spar buoy PJ with an east cardinal can buoy "BYB" marked "PJ"	49 41 32 N	124 49 38 W

NOTE: Digital data products 3513R/M, 3527R/M, 70016(3513) and 70218(3527) may also be affected. Contact Nautical Data International Inc. (NDI) or your local Value Added Remarketers (VAR) for updates.

(AMA8035-10-7-16; 5-16)

(CCG-P98-016-018, DFO-P98-019)

# SAILING DIRECTIONS AND SMALL CRAFT GUIDE CORRECTIONS

Arctic Canada, Volume 3, Fifth Edition, 1994 —

Page 78 - Paragraph 298, line 2 - After 'advised.'

Insert: **Note**. – Supplements for *Charts 7780 and 7781*, which include data from the 1994 and 1997 surveys, are available from the Canadian Hydrographic Service.

(P23/98)

Page 88 - Paragraph 388, line 3 After 'required.'

Insert: **Note**. – A supplement for *Chart 7781*, which includes data from the 1994 and 1997 surveys, is available from the Canadian Hydrographic Service.

(P23/98)

Page 105 — Before paragraph 249 -After 7731

Add: 7784

(P22/98)

Page 108 - Delete paragraph 64

Replace by: 64 **Shoals.** – A depth of 30 feet (9.1 m) lies 3 miles east of Peffer River. Two shoals (one reported 1981) with 32 feet (9.4 m) over them lie 4.5 miles ESE of James Ross Point. A depth of 35 feet (10.7 m) lies 3 miles SSW of James Ross Point. Depths of 23 and 22 feet (7 and 6.7 m) lie 1.8 miles SE and 5.5 miles SSE, respectively, of James Ross Point.

(P21/98)

Page 111 – Paragraph 114, line 5 – After "islands."

Insert: A depth of 1 foot (0.3 m) lies 1.25 miles SW and a 19 foot (5.8 m) depth is 1.25 miles NE of the west Hovgaard Island.

(P21/98)

Page 112 - Paragraph 134, line 4

Delete: 6 miles Replace by: 7 miles

(P21/98)

Page 112 – Paragraph 139, line 5

Delete: 5 miles Replace by: 7 miles

(P21/98)

Page 123 — Before paragraph 1 - After 7830

Add: 7784

(P22/98)

# SAILING DIRECTIONS AND SMALL CRAFT GUIDE CORRECTIONS

Page 123 — Paragraph 2, line 1

Delete: Victoria Strait and

(P22/98)

Page 123 — Before paragraph 7

Delete: Chart 7083 Replace by: Chart 7784

(P22/98)

Page 123 — Delete paragraph 7.

(P22/98)

Page 123 — Paragraph 12, lines 1 to 3 Delete: "The only" to end of paragraph

Replace by: Inside the magenta pecked lines the soundings are from the 1993/94 survey and are more complete than the surrounding areas.

(P22/98)

Page 126 — Top of left column

Delete: Chart 7083 Replace by: Chart 7784

(P22/98)

Page 126 — After paragraph 25

Insert: Chart 7083

(P22/98)

Page 126 — Before paragraph 31

Insert: Chart 7784

(P22/98)

Page 126 — Before paragraph 39

Insert: Chart 7083

(P22/98)

British Columbia, Volume 1, Fifteenth Edition, 1990 —

Page 122 – Delete paragraph 84

Replace by: 84 **Light**. – International Boundary light A (U.S. 19969), on the International Boundary, is shown at an elevation of 7.6 m (25 ft) from a concrete structure.

(P22/98)

# SAILING DIRECTIONS AND SMALL CRAFT GUIDE CORRECTIONS

Page 244 – Paragraph 258, line 6 - After "mud." Insert: A drying rock is close offshore in the NW part of the inner cove.

(P24/98)

British Columbia, Volume 2, Twelfth Edition, 1991 —

Page 213 – After paragraph 500

Insert: 500.1 A mooring buoy is about 0.5 mile north of Island Point.

(P21/98)

Page 231 — Paragraph 281, line 1 Delete: 16 to 17 fathoms (29 to 31 m) Replace by: 82 to 89 feet (25 to 27 m)

(P20/98)

Page 231 — Paragraph 282, line 9

Delete: 4 feet (1.2 m) Replace by: 7 feet (2 m)

(P20/98)

Page 231 — Paragraph 282, line 10

Delete: 7 feet (2.1 m)

(P20/98)

Page 231 — Paragraph 285, line 3

Delete: 8 feet (2.4 m) Replace by: 7 feet (2 m)

(P20/98)

Page 232 — Paragraph 285 line 9

Delete (0.2 m) Replace by: (0.3 m)

(P20/98)

Page 232 — Paragraph 292, line 2

Delete: 39 feet (11.9 m) Replace by: 38 feet (11.7 m)

(P20/98)

Page 232 — Paragraph 293, line 6

Delete: (4 m)

Replace by: (3.9 m)

(P20/98)

# SAILING DIRECTIONS AND SMALL CRAFT GUIDE CORRECTIONS

Page 232 — Paragraph 293, line 8

Delete: (4.3 m) Replace by: (4.2 m)

(P20/98)

Page 232 — Paragraph 295, line 2

Delete: 41 feet (12.5 m) Replace by: 42 feet (12.8 m)

(P20/98)

Page 232 — Paragraph 295, line 4

Delete: (16.5 and 18.3 m) Replace by: (16.8 and 19.2 m)

(P20/98)

Page 234 — Paragraph 309, line 6

Delete: 15 fathoms (27.4 m) Replace by: 84 feet (25.7 m)

(P20/98)

Page 234 — Paragraph 312, line 4

Delete: 1,450 feet (439 m) Replace by: 1,368 feet (417 m)

(P20/98)

Page 234 — Paragraph 314, lines 3 to 5

Delete: "From ... extremity."

Replace by: Two islets lie close-off the west side of the bay.

(P20/98)

Page 234 — Paragraph 322, line 1

Delete: 16 fathoms (29 m) Replace by: 88 feet (26.8 m)

(P20/98)

Page 234 — Paragraph 327, line 1

Delete: uncharted

(P20/98)

Small Craft Guide, British Columbia Volume 2, Eighth Edition 1990

Page 33 – Delete paragraph 53

Replace by: 53 **Light**. – International Boundary light A *(U.S. 19969)*, on the International Boundary, is shown at an elevation of 7.6 m (25 ft) from a concrete structure.

(P22/98)

# SAILING DIRECTIONS AND SMALL CRAFT GUIDE CORRECTIONS

Page 149 – Paragraph 216, line 5 – After "mud." Insert: A drying rock is close offshore in the NW part of the inner cove.

(P24/98)

V EDN # 07/98

						<u> </u>			12	$\mathbf{D}\mathbf{N} \pi \mathbf{U} \mathbf{U} \mathbf{U} \mathbf{U}$
No.	Name	Position  Latitude N. Longitude W.	Cha	Light aracteri	stics	Focal Height in m. above water	Nomi- nal Range	Description  Height in meters above ground	Rema  Fog Sig	-
<u>Pacific</u>	<u>2</u>									
189.7	Ediz Hook light buoy 4 (U.S.)	48 09 48.7 123 28 19.2	FI	R	<b>4</b> s			Red, marked "4".		Chart:3461 1301/98
321.5	Light buoy S8	On S. side of channel. 49 07 38 123 14 35	FI	R	4s			Red, marked "S8".	Year round.	Chart:3490 1308/98
334	Garry Point								Delete from List.	Chart:3490 1302/98
507 G5548	Cape Lazo								Delete from List.	Chart:3527 1313/98
507.5	Cape Lazo - East Cardinal light buoy	49 42 42.5 124 50 24	Q(3)	W	10s			Black, yellow and black, marked "PB".		Chart:3527 1313/98

# CANADIAN COAST GUARD MARINE INFORMATION REPORT AND SUGGESTION SHEET

Navigating Officer or Observer:	Captain:
Ship (or address)	
If Merchant Vessel add Line or Company with Head Office address:	
General locality: Subject:	
Subject:  Approx. position:  Chart No. used to plot:  Publications affected: (Quote Volume and page)  * Full details (Attach additional sheets as necessary)  Time (UTC)  Date	
INSTRUCTIONS:	
Mariners are requested to notify the responsible authorities when new discovered, changes are observed in aids to navigation, or corrections to p	
* In the case of new or suspected dangers to navigation, it is important that future investigations. Items of interest include heights, depths, physical destinated used to position the item. It is helpful to mark details on chart, a Canadian Hydrographic Service.	scription, type of bottom and equipment
Reports should be made to the nearest Marine Communications and confirmed in writing to:	Traffic Services Centre and should be
Director General, Marine Navigation Services Directorate, Canadian Coast Guard, Department of Fisheries and Oceans, Ottawa, Ontario, K1A 0E6	In the case of information concerning navigational aids or the List of Lights, Buoys and Fog Signals.
OR	
Dominion Hydrographer, Canadian Hydrographic Service, Department of Fisheries and Oceans, Ottawa, Ontario, K1A 0E6	In the case of new or suspected dangers to navigation, or where corrections to "Sailing Directions" appear to be necessary.