

Fisheries and Oceans Canada

Canadian Coast Guard Pêches et Océans Canada

Garde côtière canadienne

NOTICES TO MARINERS PUBLICATION EASTERN EDITION

MONTHLY EDITION N^o 08 29th August, 2014



Safety First, Service Always

Published monthly by the CANADIAN COAST GUARD www.notmar.gc.ca/subscribe

CONTENTS

Page

Section 1	Safety and General Information	1 - 7
Section 2	Chart Corrections	
Section 3	Radio Aids to Marine Navigation Corrections	N/A
Section 4	Sailing Directions and Small Craft Guide Corrections	
Section 5	List of Lights, Buoys and Fog Signals Corrections	22 - 23

Canadian Coast Guard Programs Aids to Navigation and Waterways



EXPLANATORY NOTES

Geographical positions refer directly to the graduations of the largest scale Canadian Hydrographic chart unless otherwise indicated.

Bearings refer to the true compass and are measured clockwise from 000° (North) clockwise to 359°; those relating to lights are from seaward.

Visibility of lights is that in clear weather.

Depths - The units used for soundings (metres, fathoms or feet) are stated in the title of each chart.

Elevations are normally given above Higher High Water, Large Tides unless otherwise indicated.

Distances may be calculated as follows:

1 nautical mile	= 1 852 metres (6,076.1 feet)
1 statute mile	= 1 609.3 metres (5,280 feet)
1 metre	= 3.28 feet

Temporary & Preliminary Notices are indicated by a (T) or a (P) in the section 1. Please note that Nautical charts are not amended by the Canadian Hydrographic Service for Temporary (T) and Preliminary (P) Notices. It is recommended that mariners chart these corrections in pencil. Listing of charts affected by Temporary and Preliminary Notices are revised and promulgated quarterly in Section 1 of the Monthly Edition.

Please note that, in addition to the temporary and preliminary changes normally advertised as (T) and (P) Notices, there are a few permanent changes to navigational aids that have been advertised as Preliminary Notices to Mariners while charts are being updated for new editions.

Marine Information Report & Suggestion Sheet - Mariners are requested to notify the responsible authorities when new or suspected dangers to navigation are discovered, changes observed in aids to navigation or corrections to publications are seen to be necessary. Such communications can be made using the *Marine Information Report & Suggestion Sheet* inserted on the last page of each monthly edition of *Notices to Mariners*.

Canadian Hydrographic Service – Information Published in Section 2 Notices to Mariners - Mariners are advised that only the most critical changes that directly affect safety to navigation are issued in Chart Corrections - Section 2. This limitation is required to ensure that charts remain as clear and easy to read as possible. As a result, mariners may see minor discrepancies of a non-critical nature between information in official publications. For example, a small change in the nominal range or height of a light may not result in the production of a chart correction, in *Notices to Mariners*, but may result in a *List of Light, Buoys and Fog Signals* correction.

In case of discrepancy between information provided on CHS charts related to aids to navigation, and the List of Light publication, the latter shall be deemed as containing the most up to date information

Canadian Nautical Charts & Publications - A source list of *Canadian Nautical Charts & Publications is published in Notice No.* 14 of the *Notices to Mariners Annual Edition April 2012.* The source supply and the prices effective at the time of printing are listed. For current chart edition dates refer to the following website:

www.chs-shc.gc.ca/charts-cartes/paper-papier/index-eng.asp

NOTE: Cette publication est aussi disponible en français.

CHART CORRECTIONS - SECTION 2

Corrections to nautical charts will be listed in numeric order by chart number. Each chart correction listed applies only to that particular chart. Related charts, if any, will have their own specific correction listed separately.

Users should also refer to CHS Chart 1 Symbols, Abbreviations Terms for additional information pertaining to the correction of charts.

The illustration below describes the elements that will comprise a typical Section 2 chart corection:

Weekly	Chart Number C	Chart Title Cap Etern	Charts latest new edition (ité à/to Saint-Fulgence – N		Horizontal Char ition – 20-MAY-94			
chart correction	_6-Aug-1999						LNM/E) 23-Jul-1999
date	Add	light FI G				48°26'	'36.4"N	70°53'08.6"W
		(See Char	t No 1 P24)		(F2007-	-107) LL (700) DFO	(6829264-01)
	Chart a	iction C	Chart No 1 reference no.	cco	G reference no.	List of light	no.	CHS reference no.

The last correction number is identified with the LNM/D or Last <u>N</u>otice to <u>M</u>ariners Number / <u>D</u>ate. This number is expressed in either old notice number format (ex.: 594/99) or in day-month-year format which is the date known as the weekly chart correction date shown in the above diagram as item (8).

MONTHLY EDITION OF NOTICES TO MARINERS.

WEB ACCESS.

We are offering a feature where subscribers to our on-line service are able to receive the complete electronic monthly edition of our Notices to Mariners. We are encouraging our clients to visit the

www.notmar.gc.ca/subscribe website to subscribe for this service.

Users wishing to receive information updates for their charts can do so by setting up a "User Profile" on the following web page

www.notmar.gc.ca/search/mycharts-eng.php?czoxOToibnRtPXN0ZXBfb25IJmxhbmc9ZSI7

This feature permits users to register the nautical charts they currently have in their possession.

Registrants are then automatically notified by e-mail when a Notice to Mariners is published concerning these charts.

ADVISORY NOTICES TO SHIPPING (WRITTEN AND BROADCAST).

The Canadian Coast Guard is implementing a number of changes to the aids to navigation system in Canada. These changes are advertised as Notices to Shipping (Broadcast and Written) by the Canadian Coast Guard and are followed up with Notices to Mariners, then charts are updated by hand correction, reprints or new editions.

Mariners are advised that all relevant Written Notices to Shipping should be kept until superseded by Notices to Mariners or through revised charts issued by the Canadian Hydrographic Service.

The Canadian Hydrographic Service is reviewing the impact of these changes with the Canadian Coast Guard and together are preparing an action plan on the issuing of chart revisions.

For further information contact your local Regional Notices to Shipping (Notships) issuing authorities.

Newfoundland

*Fisheries and Oceans Canada Canadian Coast Guard Port aux Basques MCTS Centre 49 Stadium Road P.O. Box 99 PORT AUX BASQUES, NL A0M 1C0 Telephone : (709) 695-2168 Facsimile : (709) 695-7784 Email :<u>notshippax@dfo-mpo.gc.ca</u> Website: <u>http://www.ccg-gcc.gc.ca/e0030407</u>

<u>Québec</u>

* Fisheries and Oceans Canada Canadian Coast Guard Les Escoumins MCTS Centre 5 Otis street, LES ESCOUMINS, QC G0T 1K0 Telephone: (418) 233-2308 Facsimile: (418) 233-3299 Website: www.marinfo.gc.ca/; http://www.marinfo.gc.ca/en/avisecrits/index.asp Website: www.ccg-cc.gc.ca/eng/CCG/Notship_Home

Maritimes

* Fisheries and Oceans Canada Canadian Coast Guard Sydney MCTS Centre 1190 Westmount Road SYDNEY, N.S, B1R 2J6 Telephone: (902) 564-7751 or 1-800-686-8676 Facsimile: (902) 564-2446 Email: <u>notshipssyd@mar.dfo-mpo.gc.ca</u> Website: <u>http://www.ccg-gcc.gc.ca/e0030406</u>

Central & Arctic

* Fisheries and Oceans Canada Canadian Coast Guard Marine Communications and Traffic Services Notices to Shipping Series "C" 401 King Street West PRESCOTT, ON K0E 1T0 Telephone (613) 925-0666 or 1-800 265 0237 Facsimile: (613) 925-4519 Email: <u>NotshipC&A@DFO-MPO.GC.CA</u> Website: www.ccg-cc.gc.ca/eng/CCG/Notship Home

* Fisheries and Oceans Canada Canadian Coast Guard Iqaluit MCTS Centre Notices to Shipping Series "A" and Series "H" P.O. Box 189 IQALUIT NU X0A 0H0 Telephone: (867) 979-5269 Facsimile: (867) 979-4264 Email: <u>IQANORDREG@INNAV.GC.CA</u> Website: www.ccq-cc.qc.ca/eng/CCG/Notship Home

* Services provided in English and French.

INDEX.

CANADIAN HYDROGRAPHIC SERVICE - ANNOUNCEMENT REGARDING CANADIAN HYDROGRAPHIC SERVICE CHART PATCHES
CANADIAN HYDROGRAPHIC SERVICE - CUMULATIVE CHART CORRECTIONS1
CANADIAN HYDROGRAPHIC SERVICE - CURRENT CHART EDITION DATES.
CANADIAN HYDROGRAPHIC SERVICE - PRINT ON DEMAND CHARTS - CARE AND USE1
CANADIAN HYDROGRAPHIC SERVICE - TRANSPORT CANADA NAVIGATION SAFETY – ECDIS
CONSOLIDATION OF MARINE COMMUNICATIONS AND TRAFFIC SERVICES (MCTS) CENTRES.
CANADIAN COAST GUARD PUBLICATION - RADIO AIDS TO MARINE NAVIGATION (ATLANTIC, ST. LAWRENCE, GREAT LAKES, LAKE WINNIPEG AND ARCTIC) PUBLICATION – 2014 - THE COMMERCIAL PUBLIC CORRESPONDENCE SERVICE
ERRATUM: REFERENCE NOTICE 710(P)/2014 AND NOTICE 711(P)/20142
*801 SAGUENAY-ST. LAWRENCE MARINE PARK AND SURROUNDING WATERS - WHALE PROTECTION
*802 CANADIAN HYDROGRAPHIC SERVICE - NAUTICAL CHARTS4
*804 CANADIAN HYDROGRAPHIC SERVICE - RASTER DIGITAL CHARTS (BSB V4)5
*805 CANADIAN HYDROGRAPHIC SERVICE – SAILING DIRECTIONS – CEN 307 — NORTH CHANNEL OF LAKE HURON, FIRST EDITION, 2000 IS NOW AVAILABLE AS PRINT-ON-DEMAND (POD) PRODUCT
*806 TRANSPORT CANADA - SHIP SAFETY BULLETIN5
*807 CANADIAN COAST GUARD PUBLICATIONS - NEW EDITION OF RADIO AIDS TO MARINE NAVIGATION (ATLANTIC, ST. LAWRENCE, GREAT LAKES, LAKE WINNIPEG AND ARCTIC) – 2014
(ATLANTIC, ST. LAWRENCE, GREAT LAKES, LAKE WINNIPEG AND ARCTIC) – 20146
(ATLANTIC, ST. LAWRENCE, GREAT LAKES, LAKE WINNIPEG AND ARCTIC) – 2014
 (ATLANTIC, ST. LAWRENCE, GREAT LAKES, LAKE WINNIPEG AND ARCTIC) – 2014

NUMERICAL INDEX OF CANADIAN CHARTS AFFECTED.					
Chart No.	Page	Chart No.	Page	Chart No.	Page
1311	8	4911	19		
1312	8	4913	19		
1313	9,10	5051	4		
1314	10,12	5452	19		
2250	12,13	7220	19		
2283	13,14	7750	20		
3939	4				
4026	4, 14				
4114	14				
4115	14				
4118	14				
4237	15				
4241	6				
4266	6,15				
4275	4				
4277	15				
4335	15				
4367	16				
4385	16				
4466	16,17				
4530	7				
4825	17				
4846	17				
4847	18				
4848	18				
4857	7,18				

SECTION 1 SAFETY AND GENERAL INFORMATION

CANADIAN HYDROGRAPHIC SERVICE - ANNOUNCEMENT REGARDING CANADIAN HYDROGRAPHIC SERVICE CHART PATCHES.

Colour Web Patches are free to the mariner, and given the quality of many printers, should reproduce well. They will be available in real time all around the world.

CHS welcomes your feedback on this service at chsinfo@dfo-mpo.gc.ca

CANADIAN HYDROGRAPHIC SERVICE - CUMULATIVE CHART CORRECTIONS.

The cumulative Notices to Mariners corrections for charts can now be accessed at www.notmar.gc.ca/search/notmar-eng.php.

CANADIAN HYDROGRAPHIC SERVICE - CURRENT CHART EDITION DATES.

CHART EDITIONS

The three terms described below are used to indicate the publication status of Canadian charts.

NEW CHART - "NEWCHT"

The first publication of a Canadian chart embracing an area not previously charted to the scale shown, or embracing an area different from any existing Canadian chart.

NEW EDITION - "NEWEDT".

A new issue of an existing chart containing amendments essential to navigation in addition to those issued in Notices to Mariners and making existing editions obsolete.

REPRINTS.

A new issue of the current edition of a chart incorporating no amendments of navigational significance other than those previously promulgated in Notices to Mariners. It may also contain amendments from other sources provided they are not essential to navigation. Previous printings of the current edition remain in force.

The current chart edition dates can be accessed at www.chs-shc.gc.ca/charts-cartes/paper-papier/index-eng.asp

CANADIAN HYDROGRAPHIC SERVICE - PRINT ON DEMAND CHARTS - CARE AND USE.

Background.

By providing nautical charts to the public, the goal of the Canadian Hydrographic Service (CHS) is to provide services for safe navigation in a fiscally responsible manner. As a result, CHS continues to expand its portfolio of nautical paper charts that are printed using Print On Demand (POD) technology. These charts are easily recognized by their whiter paper and the coloured logo of the Canadian Hydrographic Service. This new technology enables CHS to print charts in a more efficient manner while enhancing chart content through being able to quickly add new and important information. POD technology provides customers with up-to-date charts without the historical hand-drawn corrections or glued-on patches. Additionally, this technology eliminates out-of-stock situations which arise with the traditional printing and warehousing methods. In the event of a national emergency, CHS can respond to the appropriate authorities with best available information very quickly.

Care of Your POD Chart.

CHS encourages its customers to handle the POD charts more carefully than the traditional lithographic charts. When plotting information on POD charts, use HB pencils and apply limited pressure. Testing has suggested that an Indian gum eraser is more effective than alternatives when used on the product. This eraser is also suitable for charts printed using lithographic processes.

SECTION 1 SAFETY AND GENERAL INFORMATION

CANADIAN HYDROGRAPHIC SERVICE - TRANSPORT CANADA NAVIGATION SAFETY – ECDIS.

Mariners are advised that ECDIS may not display some isolated shoal depths when operating in "base or standard display" mode. Route planning and monitoring alarms for these shoal depths may not always be activated. To ensure safe navigation and to confirm that a planned route is clear of such dangers, mariners should visually inspect the planned route and any deviations from it using ECDIS configured to display "all data". The automated voyage planning check function should not be solely relied upon.

CONSOLIDATION OF MARINE COMMUNICATIONS AND TRAFFIC SERVICES (MCTS) CENTRES.

The Canadian Coast Guard is consolidating and modernizing its Marine Communications and Traffic Services. These changes will result in a configuration of 12 MCTS Centres strategically located across the country. Information pertaining to consolidation will be advertised to clients by all available means.

Atlantic Region

St. John's MCTS will close; services will be provided remotely by Placentia MCTS Saint John (Fundy) MCTS will close; services will be provided remotely by Halifax MCTS St. Anthony MCTS will close; services will be provided remotely by Labrador (Goose Bay) MCTS

Central & Arctic Region

Montreal MCTS will close; services will be provided remotely by Quebec MCTS Thunder Bay MCTS will close; services will be provided remotely by Sarnia MCTS Rivière-au-Renard MCTS will close; services will be provided remotely by Les Escoumins MCTS

There will be no reduction in the MCTS level of service provided to clients. Mariners should be aware that, as a result of consolidation, contact information, weather and other pertinent marine broadcast schedules may change. These changes will be advertised in RAMN, as they become available.

Mariners should check NOTMAR PART 3 on a monthly basis for updates.

CANADIAN COAST GUARD PUBLICATION - RADIO AIDS TO MARINE NAVIGATION (ATLANTIC, ST. LAWRENCE, GREAT LAKES, LAKE WINNIPEG AND ARCTIC) PUBLICATION – 2014 - THE COMMERCIAL PUBLIC CORRESPONDENCE SERVICE.

Part I – Page 2 of 10 ADVANCE NOTICES

1.8 The Commercial Public Correspondence Service

Effective January 1, 2014, the following changes to the Canadian Coast Guard commercial public correspondence service, provided through select Marine Communications and Traffic Services centres, will be in effect: All <u>long distance ship-shore calls</u> will be administered through the regular telephone service provider as a <u>collect call</u>. Individuals intending to place <u>shore-ship calls</u> will be required to direct-dial the appropriate MCTS centre. MCTS centres providing a commercial public correspondence service are identified in RAMN, Part 2.

ERRATUM: REFERENCE NOTICE 710(P)/2014 AND NOTICE 711(P)/2014

AMEND Position: LL 202 (44° 47' 17.1"N 65° 45' 34.6"W) TO READ Position: LL 202 (44° 41' 17.1"N 65° 45' 34.6"W)

SECTION 1 SAFETY AND GENERAL INFORMATION

*801 SAGUENAY-ST. LAWRENCE MARINE PARK AND SURROUNDING WATERS - WHALE PROTECTION

The waters in and around the Saguenay-St. Lawrence Marine Park are well known for their resident threatened beluga population and the wide diversity of whales that migrate there to feed, particularly between April and November.

REGULATORY PROTECTION MEASURES

All whale species that are found in the St. Lawrence are protected under the *Marine Mammal Regulations*, pursuant to the *Fisheries Act*. Within the boundaries of the Marine Park, specific measures are set out in the *Marine Activities in the Saguenay–St. Lawrence Marine Park Regulations*, pursuant to the *Act Establishing the Saguenay–St. Lawrence Marine Park Regulations*, pursuant to the Marine Park must immediately be reported to a park warden at 1-866-508-9888. For collisions that occur outside the Marine Park or for any situation involving a marine mammal that is dead or in trouble, contact the emergency network at 1-877-722-5346 or on channel 16. (see section 5C of the Annual Edition of the Notices to Mariners – April 2014 to March 2015).

VOLUNTARY PROTECTION MEASURES

Provisional measures in effect from May 1 to October 31, 2014


These measures apply to merchant vessels and cruise ships between Pointe à Boisvert and Cap de la Tête au Chien to prevent collisions with whales (see link below to view map). These measures should only be taken when they will not jeopardize navigational safety.

Caution area (yellow area): To reduce the risk of collisions with whales that can be present anywhere in this area, heightened vigilance is critical for navigators. Posting a lookout is recommended in order to increase the chances of seeing the whales and thus taking necessary measures to avoid them. If bypassing the whales is not possible, slow down and wait for the animals to move away to a distance greater than 400 meters (0.215 nautical miles) before resuming original speed. It is more difficult to see the animals at night therefore increased caution is recommended. **Slow down to 10 knots area (red area):** To reduce the risk of collisions with whales in this feeding area, it is recommended that vessels slow down to a maximum speed through the water of 10 knots and post a lookout. It is further recommended to remain in the Laurentian Channel to the north of île Rouge to minimize the impact of noise in a sensitive area south of this island, which is highly frequented by herds of beluga whales composed of females and young.

Area to be avoided (hatched red area): To reduce noise and the risk of collisions with whales, vessels should avoid transiting through this area which is highly frequented by blue whales, an endangered species. If the area cannot be avoided, slow down to a maximum speed through the water of 10 knots.

See attached map:

SECTION 1 SAFETY AND GENERAL INFORMATION



*802 CANADIAN HYDROGRAPHIC SERVICE - NAUTICAL CHARTS

CHARTS	MAIN TITLE	SCALE	PUBLISHED	CAT#	PRICE
New Editions					
3939	Fisher Channel to/à Seaforth Channel and/et Dean Channel	1:40000	01-AUG-2014	2	20.00
4026	Havre Saint-Pierre et/and Cap des Rosiers à/to Pointe des Monts	1:300000	23-MAY-2014	1	20.00
4275	St. Peters Bay	1:20000	28-MAR-2014	1	20.00
5051	Nunaksuk Island to/à Calf Cow and/et Bull Islands	1:60000	25-APR-2014	1	20.00

SECTION 1 SAFETY AND GENERAL INFORMATION

*803 CANADIAN HYDROGRAPHIC SERVICE - ELECTRONIC NAVIGATIONAL CHARTS

NEW PRODUCTS	
S-57 ENC NUMBER	CHART TITLE
CA376691	Cape George to/à Pictou
CA576692	Ballantynes Cove Wharf/Quai
CA576693	Cribbons Point Wharf/Quai
CA576694	Arisaig Wharf/Quai
CA576695	Lismore Wharf/Quai
WITHDRAWN PRODUCTS	
CA573309	Parry Sound Harbour
CA573310	Rose Island Channel

*804 CANADIAN HYDROGRAPHIC SERVICE - RASTER DIGITAL CHARTS (BSB V4)

CHARTS	MAIN TITLE	SCALE	PUBLISHED
New Charts			
R/M1201	Saint-Fulgence à/to Saguenay	1:15000	07-FEB-2014
R/M1360	Lac Memphrémagog	1:30000	23-MAY-2014
R/M4404	Cape George to/à Pictou	1:75888	28-FEB-2014
New Editions			
R/M2250	Bruce Mines to/à Sugar Island	1:25000	28-FEB-2014
R/M3936	Fitz Hugh Sound to/à Lama Passage	1:40000	21-MAR-2014
R/M4025	Cap Whittle à/to Havre-Saint-Pierre et/and Île d'Anticosti	1:300000	28-MAR-2014
R/M4266	Sydney Harbour	1:20000	28-FEB-2014
R/M4275	St. Peters Bay	1:20000	28-MAR-2014
R/M5051	Nunaksuk Island to/à Calf Cow and/et Bull Islands	1:60000	25-APR-2014
R/M7950	Jones Sound,Norwegian Bay and Queens Channel	1:500000	21-JUN-2013

*805 CANADIAN HYDROGRAPHIC SERVICE – SAILING DIRECTIONS – CEN 307 — NORTH CHANNEL OF LAKE HURON, FIRST EDITION, 2000 IS NOW AVAILABLE AS PRINT-ON-DEMAND (POD) PRODUCT.

The Sailing Directions booklet is now available as Print-on-Demand (POD) product. POD booklets are updated through Notices to Mariners to the date of printing. For instance, the POD version of CEN 307 now incorporates some 148 Notices to Mariners issued since 2000, which previously had to be manually added to the book. The Canadian Hydrographic Service (CHS) is converting all of its Sailing Directions to the POD format in response to requests received through our Level of Service initiative. Contact an authorized CHS dealer to purchase a new copy.

Please note that despite the new look, the content remains the same except that the Notices to Mariners have been incorporated up to the date of printing.

*806 TRANSPORT CANADA - SHIP SAFETY BULLETIN

An updated **Ship Safety Bulletin** has recently been posted to the Transport Canada website at <u>www.tc.gc.ca/ssb-bsn/</u>. To go online to view or download this bulletin, please click on the link below:

• <u>SSB#04/2014</u> – GME 406 MHz EPIRB Product Safety Recall (Amendment 2014-08-08) RDIMS#9175301

Note: Sign yourself up for <u>e-Bulletin</u> to receive an e-mail notice each time a new Ship Safety Bulletin is published on our Website.

Contact us at marinesafety-securitemaritime@tc.gc.ca or 1-855-859-3123 (Toll Free).

SECTION 1 SAFETY AND GENERAL INFORMATION

*807 CANADIAN COAST GUARD PUBLICATIONS - NEW EDITION OF RADIO AIDS TO MARINE NAVIGATION (ATLANTIC, ST. LAWRENCE, GREAT LAKES, LAKE WINNIPEG AND ARCTIC) – 2014.

The 2014 edition of the *Radio Aids to Marine Navigation (Atlantic, St. Lawrence, Great Lakes, Lake Winnipeg and Arctic)* is now available for download, free of charge, on the *Marine Communications and Traffic Services MCTS* website: <u>http://www.ccg-gcc.gc.ca/Marine-Communications/Home</u>

Paper copies of the publication are no longer sold.

Amendments to this publication are advertised by radio broadcast (Notices to Shipping) and/or in Section 3 of the monthly edition of Notices to Mariners <u>www.notmar.gc.ca</u>

The 2014 edition has been revised to July 25, 2014 and supersedes the 2013 edition.

*808 SYDNEY HARBOUR – LIGHT BUOY DISCONTINUED.

Reference: Notice 608(P)/2012 is now cancelled. (Chart 4266)

809 SYDNEY HARBOUR – LIGHT BUOY DISCONTINUED

Reference: Notice 609(P)/2012 is now cancelled. (Chart 4266)

(G2014063)

(G2014062)

*810(P) LOCKEPORT TO/À CAPE SABLE - FOG SIGNAL TO BE DISCONTINUED.

Reference Chart: 4241

The Canadian Coast Guard proposes to permanently discontinue the following Aid to navigation:

Baccaro Point Fog Signal LL 336 (43° 26' 59"N 65° 28' 15"W).

Comments on this action are solicited from mariners and other interested parties. Comments should be directed to the following within three months from the date of this notice:

A\Regional Superintendent, Aids to Navigation & Waterways, Canadian Coast Guard, PO Box 5667, St. John's, NL, A1C 5X1

Telephone: 709-772-5195, Email: <u>Renee.Pope@dfo-mpo.gc.ca</u>

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(F2014-025)

SECTION 1 SAFETY AND GENERAL INFORMATION

*811(P) HAMILTON SOUND, EASTERN PORTION / PARTIE EST - FOG SIGNAL TO BE DISCONTINUED.

Reference Chart: 4530

The Canadian Coast Guard proposes to permanently discontinue the following Aid to navigation:

Peckford Island Fog Signal LL 395 (49° 31' 49.6"N 53° 51' 04.8"W).

Comments on this action are solicited from mariners and other interested parties. Comments should be directed to the following within three months from the date of this notice:

A\Regional Superintendent, Aids to Navigation & Waterways, Canadian Coast Guard, PO Box 5667, St. John's, NL, A1C 5X1

Telephone: 709-772-5195, Email: <u>Renee.Pope@dfo-mpo.gc.ca</u>

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(N2014-039)

*812(P) INDIAN BAY TO/À WADHAM ISLANDS - FOG SIGNAL TO BE DISCONTINUED.

Reference Chart: 4857

The Canadian Coast Guard proposes to permanently discontinue the following Aid to navigation:

Cabot Islands Fog Signal LL 406 (49° 10' 28.1"N 53° 22' 03.3"W).

Comments on this action are solicited from mariners and other interested parties. Comments should be directed to the following within three months from the date of this notice:

A\Regional Superintendent, Aids to Navigation & Waterways, Canadian Coast Guard, PO Box 5667, St. John's, NL, A1C 5X1

Telephone: 709-772-5195, Email: <u>Renee.Pope@dfo-mpo.gc.ca</u>

Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

(N2014-040)

SECTION 2 CHART CORRECTIONS

1311 - Sorel- 08-AUG-2014	Tracy à/to Varennes - New Edition - 19-SEP-2013 - NAD 1983 I	LNM/D. 18-JUL-2014
Delete	depth of 4 metres 6 decimetres (See Chart No. 1, I10)	46°04′07.9″N 073°05′19.6″W
	This notice affects Electronic Navigational Chart: CA479129	DFO(6408908-04)
Add	depth of 3 metres 5 decimetres (See Chart No. 1, I10)	46°04′09.4″N 073°05′18.8″W
	This notice affects Electronic Navigational Chart: CA479129	DFO(6408908-05)
	aint-Pierre - New Edition - 24-MAY-2013 - NAD 1983	
08-AUG-2014 Replace	yellow cautionary lighted spar buoy FI Y, marked LAC with yellow cautionary lighted pillar buoy FI Y, marked LAC	LNM/D. 18-JUL-2014 46°16′03.1″N 072°41′43.4″W
	(See Chart No. 1, Qm, Q23) This notice affects Electronic Navigational Chart: CA479129	
	(Q2014	019) LL(2123.5) DFO(6408901-01)
Replace	wreck Wk with known depth of 2 metres 4 decimetres with wreck Wk with known depth of 2 metres 3 decimetres (See Chart No. 1, K26)	46°04'16.8"N 073°04'43.5"W
	This notice affects Electronic Navigational Chart: CA479129	DFO(6408908-01)
Delete	depth of 0 metres 7 decimetres (See Chart No. 1, I10)	46°04'12.4"N 073°04'25.6"W
	This notice affects Electronic Navigational Chart: CA479129	DFO(6408908-02)
Add	wreck Wk with known depth of 0 metres 8 decimetres (See Chart No. 1, K26)	46°04'12.0"N 073°04'25.6"W
	This notice affects Electronic Navigational Chart: CA479129	DFO(6408908-03)
Delete	depth of 4 metres 6 decimetres (See Chart No. 1, I10)	46°04′07.9″N 073°05′19.6″W
	This notice affects Electronic Navigational Chart: CA479129	DFO(6408908-04)
Add	depth of 3 metres 5 decimetres (See Chart No. 1, I10)	46°04′09.4″N 073°05′18.8″W
	This notice affects Electronic Navigational Chart: CA479129	DFO(6408908-05)

SECTION 2 CHART CORRECTIONS

1313 - Batiso 22-AUG-2014	an au/to Lac Saint-Pierre - New Edition - 07-JUN-2013 - NAD 1983	LNM/D. 08-AUG-2014
Amend	vertical clearance of 32 metres, to read 3 metres 2 decimetres (See Chart No. 1, D20)	46°21′16.5″N 072°26′19.8″W
		DFO(6408946-07)
Amend	vertical clearance of 41 metres, to read 4 metres 1 decimetre (See Chart No. 1, D20)	46°23'01.4"N 072°20'15.5"W
		DFO(6408946-08)
Amend	vertical clearance of 43 metres, to read 4 metres 3 decimetres (See Chart No. 1, D20)	46°27′08.4″N 072°17′02.1″W
		DFO(6408946-09)
Amend	vertical clearance of 87 metres, to read 8 metres 7 decimetres (See Chart No. 1, D20)	46°27′00.4″N 072°16′49.0″W
		DFO(6408946-10)
Amend	vertical clearance of 85 metres, to read 8 metres 5 decimetres (See Chart No. 1, D20)	46°26′20.2″N 072°13′25.7″W
		DFO(6408946-11)
08-AUG-2014 Replace	yellow cautionary lighted spar buoy FI Y, marked LAC with yellow cautiona lighted pillar buoy FI Y, marked LAC (See Chart No. 1, Qm, Q23)	LNM/D. 27-DEC-2013 ry 46°16'03.1"N 072°41'43.4"W
	This notice affects Electronic Navigational Chart: CA479129	014019) LL(2123.5) DFO(6408901-01)
	e Trois-Rivières - New Edition - 07-JUN-2013 - NAD 1983	
29-AUG-2014 Delete	depth of 9 metres 5 decimetres	LNM/D. 22-AUG-2014 46°20'41.5"N 072°31'53.8"W
Delete	(See Chart No. 1, I10)	
	This notice affects Electronic Navigational Chart: CA579015	DFO(6408944-16)
Add	depth of 8 metres 8 decimetres (See Chart No. 1, I10)	46°20'41.2"N 072°31'54.2"W
	This notice affects Electronic Navigational Chart: CA579015	DFO(6408944-17)
Amend	10,8 m (2010) to read 10,4 m (2013) (See Chart No. 1, I22)	46°20'03.5"N 072°32'35.0"W
	This notice affects Electronic Navigational Chart: CA579015	
		DFO(6408944-18)
22-AUG-2014		LNM/D. 08-AUG-2014
Amend	vertical clearance of 35 metres, to read 3 metres 5 decimetres (See Chart No. 1, D20)	46°21′46.6″N 072°31′54.4″W
		DFO(6408946-01)

SECTION 2 CHART CORRECTIONS

Amend	vertical clearance of 38 metres, to read 3 metres 8 decimetres (See Chart No. 1, D20)	46°21′35.5″N 072°32′08.8″W
		DFO(6408946-02)
Amend	vertical clearance of 17 metres, to read 1 metre 7 decimetres (See Chart No. 1, D20)	46°21′29.3″N 072°31′29.8″W
		DFO(6408946-03)
Amend	vertical clearance of 72 metres, to read 7 metres 2 decimetres (See Chart No. 1, D20)	46°21′26.5″N 072°31′26.6″W
		DFO(6408946-04)
Amend	vertical clearance of 37 metres to read 3 metres 7 decimetres (See Chart No. 1, D20)	46°21′24.1″N 072°31′36.2″W
		DFO(6408946-05)
Amend	vertical clearance of 65 metres, to read 6 metres 5 decimetres (See Chart No. 1, D20)	46°21′14.1″N 072°31′29.2″W
		DFO(6408946-06)
1314 - Donnac	ona à/to Batiscan - New Edition - 21-JUN-2013 - NAD 1983	
29-AUG-2014	ona ano Baliscan - New Eulion - 21-3011-2013 - 1460 1903	LNM/D. 22-AUG-2014
Reposition	green port hand lighted pillar buoy Q G, marked Q61 (See Chart No. 1, Qg, Q23)	from 46°40'40.1"N 071°51'05.4"W
		to 46°40'37.5"N 071°50'58.2"W
	This notice affects Electronic Navigational Chart: CA479017	(Q2014031) LL(1993) DFO(6408930-01)
Reposition	green port hand lighted pillar buoy Q G, marked Q65 (See Chart No. 1, Qg, Q23)	from 46°40′07.9″N 071°53′02.1″W
	(to 46°40′23.7″N 071°52′44.3″W
	This notice affects Electronic Navigational Chart: CA479017	
		(Q2014032) LL(1999.5) DFO(6408931-01)
Reposition	green port hand lighted spar buoy FI G, marked Q63 (See Chart No. 1, Qg, Q24)	from 46°40'32.4"N 071°52'27.1"W
		to 46°40'40.6"N 071°51'40.2"W
	This notice affects Electronic Navigational Chart: CA479017	(Q2014033) LL(1994) DFO(6408932-01)
Add	depth of 7 metres 1 decimetre (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA479017	46°35′22.5″N 072°00′48.9″W
		DFO(6408944-01)
Delete	depth of 13 metres 4 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA479017	46°34′53.6″N 072°02′00.3″W
	This house alrests Electronic Navigational Chart. OA475017	DFO(6408944-02)
Add	depth of 12 metres 6 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA479017	46°34′53.6″N 072°02′00.3″W
		DFO(6408944-03)

SECTION 2 CHART CORRECTIONS

Add	depth of 9 metres 1 decimetre (See Chart No. 1, I10)	46°34′48.0″N 072°02′15.1″W
	This notice affects Electronic Navigational Chart: CA479017	
		DFO(6408944-04)
Delete	depth of 6 metres 6 decimetres (See Chart No. 1, I10)	46°34'44.3"N 072°02'13.0"W
	This notice affects Electronic Navigational Chart: CA479017	
		DFO(6408944-05)
Add	depth of 6 metres 3 decimetres (See Chart No. 1, I10)	46°34'44.3"N 072°02'13.0"W
	This notice affects Electronic Navigational Chart: CA479017	
		DFO(6408944-06)
Add	depth of 6 metres 5 decimetres (See Chart No. 1, I10)	46°33'49.8″N 072°06'17.4″W
	This notice affects Electronic Navigational Chart: CA479017, CA579142	
		DFO(6408944-07)
Delete	depth of 3 metres 8 decimetres (See Chart No. 1, I10)	46°33′58.3″N 072°06′46.3″W
	This notice affects Electronic Navigational Chart: CA479017	
۸dd	depth of 2 metros 4 desimptres	<i>DFO(6408944-08)</i> 46°33′58.3″N 072°06′46.3″W
Add	depth of 3 metres 4 decimetres (See Chart No. 1, I10)	40 33 56.3 N 072 00 40.3 W
	This notice affects Electronic Navigational Chart: CA479017	
		DFO(6408944-09)
Delete	depth of 13 metres 5 decimetres (See Chart No. 1, I10)	46°33'18.1"N 072°08'51.3"W
	This notice affects Electronic Navigational Chart: CA479017	DFO(6408944-10)
Add	depth of 12 metres 7 decimetres	46°33'19.3"N 072°08'48.2"W
Auu	(See Chart No. 1, I10)	40 33 19.3 10 072 00 40.2 10
	This notice affects Electronic Navigational Chart: CA479017	
		DFO(6408944-11)
Add	depth of 7 metres 6 decimetres (See Chart No. 1, I10)	46°33'05.4"N 072°09'11.2"W
	This notice affects Electronic Navigational Chart: CA479017	DF0(6408944-12)
Add	depth of 4 metres 1 decimetre	46°32′10.7″N 072°10′40.0″W
Auu	(See Chart No. 1, I10)	40 32 10.7 10 072 10 40.0 W
	This notice affects Electronic Navigational Chart: CA479017	
Dalat		DFO(6408944-13)
Delete	depth of 5 metres 9 decimetres (See Chart No. 1, I10)	46°31′41.0″N 072°11′46.1″W
	This notice affects Electronic Navigational Chart: CA479017	
		DFO(6408944-14)

DFO(6408944-14)

SECTION 2 CHART CORRECTIONS

Add	depth of 5 metres 7 decimetres (See Chart No. 1, I10)	46°31′40.4″N 072°11′47.3″W
	This notice affects Electronic Navigational Chart: CA479017	
	-	DFO(6408944-15)
22-AUG-2014		LNM/D. 04-JUL-2014
Amend	vertical clearance of 85 metres, to read 8 metres 5 decimetres (See Chart No. 1, D20)	46°26'20.2"N 072°13'25.7"W
		DFO(6408946-11)
Amend	vertical clearance of 55 metres, to read 5 metres 5 decimetres (See Chart No. 1, D20)	46°31′08.0″N 072°14′41.1″W
		DFO(6408946-12)
Amend	vertical clearance of 58 metres, to read 5 metres 8 decimetres	46°31′25.6″N 072°15′12.8″W
	(See Chart No. 1, D20)	DFO(6408946-13)
Amend	vertical clearance of 37 metres to read 3 metres 7 decimetres (See Chart No. 1, D20)	46°34'18.3"N 072°12'35.1"W
		DFO(6408946-14)
Amend	vertical clearance of 58 metres, to read 5 metres 8 decimetres (See Chart No. 1, D20)	46°34′29.2″N 072°12′34.9″W
		DFO(6408946-15)
Amend	vertical clearance of 45 metres, to read 4 metres 5 decimetres (See Chart No. 1, D20)	46°34'17.0"N 071°59'33.4"W
		DFO(6408946-16)
Amend	vertical clearance of 58 metres, to read 5 metres 8 decimetres (See Chart No. 1, D20)	46°34'28.6"N 071°59'35.6"W
		DFO(6408946-17)
Amend	vertical clearance of 76 metres to read 7 metres 6 decimetres (See Chart No. 1, D20)	46°41′28.6″N 071°52′57.9″W
		DFO(6408946-18)
Amend	vertical clearance of 49 metres, to read 4 metres 9 decimetres (See Chart No. 1, D20)	46°41′33.1″N 071°52′41.7″W
		DFO(6408946-19)
Amend	vertical clearance of 52 metres, to read 5 metres 2 decimetres (See Chart No. 1, D20)	46°33′33.2″N 072°11′09.9″W
		DFO(6408946-20)
2250 - Bruce 29-AUG-2014	Mines to/à Sugar Island - New Edition - 28-FEB-2014 - World Geodetic Syst	em 1984
Amend	vertical clearance of 5.5 metres, to read 5 metres 5 decimetres	46°14′56.0″N 084°06′35.3″W
,	(See Chart No. 1, D20)	
	Note: The decimal point of vertical clearance of 5.5 meters is too small and incorrectly placed on New Edition 28-Feb-2014	
		DFO(6603996-01)
Amend	vertical clearance of 7.6 metres, to read 7 metres 6 decimetres (See Chart No. 1, D20)	46°18′04.1″N 084°00′44.1″W
	Note: The decimal point of vertical clearance of 7.6 meters is too small and incorrectly placed on New Edition 28-Feb-2014	
		DFO(6603996-02)

SECTION 2 CHART CORRECTIONS

Amend	vertical clearance of 8.8 metres, to read 8 metres 8 decimetres (See Chart No. 1, D20) Note: The decimal point of vertical clearance of 8.8 meters is too small and incorrectly placed on New Edition 28-Feb-2014	46°17′56.6″N 084°00′35.5″W
		DFO(6603996-03)
Amend	vertical clearance of 2.6 metres, to read 2 metres 6 decimetres (See Chart No. 1, D20)	46°17′53.7″N 083°57′33.1″W
	Note: The decimal point of vertical clearance of 2.6 meters is too small and incorrectly placed on New Edition 28-Feb-2014	DFO(6603996-04)
2250 - Twyni 29-AUG-2014	ng Island Bridge - New Edition - 28-FEB-2014 - World Geodetic System 1984 ¹	
Amend	vertical clearance of 5.2 metres, to read 5 metres 2 decimetres	46°19'13.1"N 083°59'55.0"W
	(See Chart No. 1, D20) Note: The decimal point of vertical clearance of 5.2 meters is too small and incorrectly placed on New Edition 28-Feb-2014	
		DFO(6603996-05)
Amend	vertical clearance of 3.5 metres, to read 3 metres 5 decimetres (See Chart No. 1, D20) Note: The decimal point of vertical clearance of 3.5 meters is too small and	46°18'41.5″N 083°59'15.3″W
	incorrectly placed on New Edition 28-Feb-2014	DFO(6603996-06)
Amend	vertical clearance of 7.7 metres, to read 7 metres 7 decimetres (See Chart No. 1, D20) Note: The decimal point of vertical clearance of 7.7 meters is too small and	46°18′39.0″N 083°59′21.2″W
	incorrectly placed on New Edition 28-Feb-2014	DFO(6603996-07)
2283 - Collin 29-AUG-2014	gwood - New Edition - 31-AUG-2012 - World Geodetic System 1984	LNM/D. 14-FEB-2014
Amend	vertical clearance of 28 metres, to read 2 metres 8 decimetres (See Chart No. 1, D20)	44°30'14.3"N 080°13'37.0"W
		DFO(6603994-04)
Amend	vertical clearance of 25 metres, to read 2 metres 5 decimetres (See Chart No. 1, D20)	44°30'14.2"N 080°13'29.4"W
		DFO(6603994-05)
2283 - Meafo 29-AUG-2014	rd - New Edition - 31-AUG-2012 - World Geodetic System 1984	LNM/D. 14-FEB-2014
Amend	vertical clearance of 36 metres, to read 3 metres 6 decimetres (See Chart No. 1, D20)	44°36′21.4″N 080°35′28.4″W
		DFO(6603994-06)
Amend	vertical clearance of 39 metres, to read 3 metres 9 decimetres (See Chart No. 1, D20)	44°36′26.8″N 080°35′19.4″W
		DFO(6603994-07)

SECTION 2 CHART CORRECTIONS

	Sound Harbour - New Edition - 31-AUG-2012 - World Geodetic Syste	
29-AUG-2014 Amend	vertical clearance of 33 metres, to read 3 metres 3 decimetres (See Chart No. 1, D20)	LNM/D. 14-FEB-2014 44°34′02.0″N 080°56′40.6″W
		DFO(6603994-03)
2283 - Owen S	Sound to/à Giant's Tomb Island - New Edition - 31-AUG-2012 - World	d Geodetic System 1984
29-AUG-2014 Amend	vertical clearance of 34 metres, to read 3 metres 4 decimetres (See Chart No. 1, D20)	LNM/D. 14-FEB-2014 44°29′20.5″N 080°03′08.5″W
		DFO(6603994-01)
Amend	vertical clearance of 35 metres, to read 3 metres 5 decimetres (See Chart No. 1, D20)	44°31′28.3″N 080°00′42.1″W
		DFO(6603994-02)
4026 - Havre \$ 22-AUG-2014	Saint-Pierre et/and Cap des Rosiers à/to Pointe des Monts - New Ed	ition - 23-MAY-2014 - NAD 1983
Amend	vertical clearance of 31 metres, to read 3 metres 1 decimetre (See Chart No. 1, D20)	49°44′45.9″N 067°10′58.9″W
		DFO(6408955-01)
Amend	vertical clearance of 67 metres, to read 6 metres 7 decimetres (See Chart No. 1, D20)	50°18′20.6″N 064°19′51.2″W
		DFO(6408955-02)
	bello Island - New Edition - 29-SEP-2006 - NAD 1983	
15-AUG-2014 Amend	FR to read LFIR against light (See Chart No. 1, P1)	LNM/D. 31-AUG-2012 44°57′50.0″N 067°00′29.9″W
	This notice affects Electronic Navigational Chart: CA476035	
		(F2014024) LL(48) DFO(6306794-01)
4115 - Passan 15-AUG-2014	naquoddy Bay and/et St. Croix River - New Edition - 24-FEB-2012 - \	Norld Geodetic System 1984 LNM/D. 04-OCT-2013
Amend	FR to read LFIR against light (See Chart No. 1, P1)	44°57′50.0″N 067°00′29.4″W
	This notice affects Electronic Navigational Chart: CA476035	
		(F2014024) LL(48) DFO(6306794-01)
	assage - New Edition - 13-NOV-1998 - NAD 1983	
01-AUG-2014 Amend	vertical clearance of 43 metres, to read 39 metres (See Chart No. 1, D20)	LNM/D. 20-JUN-2014 44°23′28.8″N 066°12′11.0″W
	This notice affects Electronic Navigational Chart: CA476028	
		DFO(6306764-02)
	ys Bay - New Edition - 13-NOV-1998 - NAD 1983	
01-AUG-2014		LNM/D. 20-JUN-2014
Delete	abandoned lighthouse with legend Lt Ho/Phare Aband	44°19′54.9″N 066°07′32.3″W
	This notice affects Electronic Navigational Chart: CA376024	
		DFO(6306764-01)

SECTION 2 CHART CORRECTIONS

	ches to/Approches au Halifax Harbour - New Edition - 02-JUN-200	
15-AUG-2014 Delete	pilot boarding station (See Chart No. 1, T1.1)	LNM/D. 10-JAN-2014 44°31′24.0″N 063°30′21.7″W
	This notice affects Electronic Navigational Chart: CA476009	DFO(6306785-01)
		, , , , , , , , , , , , , , , , , , ,
Add	pilot boarding station (See Chart No. 1, T1.1)	44°30′24.0″N 063°29′30.0″W
	This notice affects Electronic Navigational Chart: CA476009	DFO(6306785-02)
4266 - Sydney 15-AUG-2014	Harbour - New Edition - 28-FEB-2014 - NAD 1983	
Delete	red and white fairway lighted pillar buoy Mo(A), marked SC (See Chart No. 1, Qh)	46°14′37.5″N 060°11′21.0″W
	This notice affects Electronic Navigational Chart: CA376093, CA576	
		(G2014062) LL(777) DFO(6306795-01)
Delete	green port hand lighted pillar buoy QG, marked S7 (See Chart No. 1, Qg)	46°12'14.2"N 060°13'21.2"W
	This notice affects Electronic Navigational Chart: CA576095	
		(G2014063) LL(778.2) DFO(6306795-02)
4277 - Entranc 01-AUG-2014	e to/Entrée à Great Bras D'Or - New Edition - 17-APR-1998 - NAD	1983 LNM/D. 18-APR-2014
Delete	pile with legend piles/pieus (See Chart No. 1, F22)	46°16′33.6″N 060°25′57.0″W
	This notice affects Electronic Navigational Chart: CA476063, CA57	6064
		DFO(6306755-01)
	ras D'Or, St. Andrews Channel and/et St. Anns Bay - New Edition	- 17-APR-1998 - NAD 1983
01-AUG-2014 Delete	pile with legend piles/pieus	LNM/D. 18-APR-2014 46°16′33.6″N 060°25′57.0″W
Delete	(See Chart No. 1, F22)	40 10 33.0 10 000 23 37.0 W
	This notice affects Electronic Navigational Chart: CA476063, CA57	6064 DFO(6306755-01)
4335 - Guvsbo	rough Harbour - New Edition - 04-JAN-2008 - NAD 1983	
15-AUG-2014 Reposition	red starboard hand conical lighted buoy FIR, marked CQ2	LNM/D. 18-JUL-2014 from 45°22'33.2″N 061°29'13.3″W
	(See Chart No. 1, Qf)	to 45°22′29.1″N 061°29′06.6″W (G2014064) LL(683.1) DFO(6306797-01)
4335 - Strait of	Canso and Approaches/et les approches - New Edition - 04-JAN	-2008 - NAD 1983
15-AUG-2014		LNM/D. 18-JUL-2014
Reposition	red starboard hand conical lighted buoy FIR, marked CQ2 (See Chart No. 1, Qf)	from 45°22'33.2"N 061°29'13.3"W
		to 45°22′29.1″N 061°29′06.6″W (G2014064) LL(683.1) DFO(6306797-01)

SECTION 2 CHART CORRECTIONS

4367 - Flint Isla 15-AUG-2014	and to/à Cape Smokey - New Edition - 03-APR-2003 - NAD 1983	LNM/D. 18-OCT-2013
Delete	red and white fairway lighted pillar buoy Mo(A), marked SC (See Chart No. 1, Qh)	46°14′37.5″N 060°11′21.0″W
	This notice affects Electronic Navigational Chart: CA376093, CA57	76095
		(G2014062) LL(777) DFO(6306795-01)
4385 - Chebuc	to Head to/à Betty Island - New Edition - 07-JUN-1996 - NAD 198	3
15-AUG-2014		LNM/D. 08-NOV-2013
Delete	pilot boarding station (See Chart No. 1, T1.1)	44°31′24.0″N 063°30′21.7″W
	This notice affects Electronic Navigational Chart: CA476009	
		DFO(6306785-01)
4466 - Hillsbor	ough Bay - New Edition - 21-MAR-2003 - NAD 1983	
15-AUG-2014		LNM/D. 21-SEP-2012
Reposition	green port hand can buoy, marked NV1 (See Chart No. 1, Qg)	from 46°02′21.2″N 062°57′45.2″W
		to 46°02′17.2″N 062°57′46.9″W
	This notice affects Electronic Navigational Chart: CA476179	
		(G2014052) DFO(6306786-01)
Delete	red starboard hand can buoy, marked NV2 (See Chart No. 1, Q21)	46°02'45.7"N 062°57'33.9"W
	This notice affects Electronic Navigational Chart: CA476179	
		(G2014053) DFO(6306786-02)
Add	red starboard hand conical buoy, marked NV2 (See Chart No. 1, Qf)	46°02'34.2″N 062°57'39.2″W
	This notice affects Electronic Navigational Chart: CA476179	
		(G2014053) DFO(6306786-03)
Reposition	green port hand spar buoy, marked NV5	from 46°02′52.0″N 062°57′01.5″W
	(See Chart No. 1, Qg)	to 46°02′49.2″N 062°56′58.8″W
	This notice affects Electronic Navigational Chart: CA476179	
		(G2014054) DFO(6306786-04)
Delete	red starboard hand lighted pillar buoy QR, marked NV4 (See Chart No. 1, Qf)	46°02′44.5″N 062°57′08.9″W
	This notice affects Electronic Navigational Chart: CA476179	(G2014055) LL(980.5) DFO(6306786-05)
Add	red starboard hand lighted spar buoy QR, marked NV4 (See Chart No. 1, Qf)	46°02'42.3"N 062°57'15.5"W
	This notice affects Electronic Navigational Chart: CA476179	(G2014055) LL(980.5) DFO(6306786-06)

SECTION 2 CHART CORRECTIONS

Reposition	red starboard hand spar buoy, marked NV6 (See Chart No. 1, Qf)	from 46°03'22.5"N 062°55'54.9"W
	This notice affects Electronic Navigational Chart: CA476179	to 46°03′22.0″N 062°56′05.2″W
		(G2014056) DFO(6306786-07)
Reposition	green port hand spar buoy, marked NV7 (See Chart No. 1, Qg)	from 46°03′24.1″N 062°55′46.3″W
	This notice affects Electronic Navigational Chart: CA476179	to 46°03′24.4″N 062°55′52.2″W
		(G2014059) DFO(6306786-08)
Reposition	red starboard hand spar buoy, marked NV8 (See Chart No. 1, Qf)	from 46°03′26.1″N 062°55′23.6″W
	This notice affects Electronic Navigational Chart: CA476179	to 46°03′27.3″N 062°55′24.7″W
		(G2014060) DFO(6306786-09)
4825 - Ship Co 08-AUG-2014	ove - New Chart - 01-MAR-2002 - NAD 1983	
Add	floating dock with legend 'Flo' (See Chart No. 1, F16)	LNM/D. 23-AUG-2013 joining 47°31′19.2″N 057°23′13.8″W
		47°31′19.0″N 057°23′14.5″W and 47°31′18.0″N 057°23′13.8″W <i>DFO(6306761-01)</i>
4846 - Motion	Bay to/à Cape St Francis - New Edition - 15-DEC-1995 - NAD 1983	
01-AUG-2014 Delete	breakwater with legend Bkw (See Chart No. 1, F4.1)	LNM/D. 10-JAN-2014 between 47°43′22.2″N 052°50′05.2″W
	This notice affects Electronic Navigational Chart: CA376015	and 47°43′21.0″N 052°50′05.1″W
	Ŭ	DFO(6306760-01)
Reposition	light 2Lts FIG & FIR (See Chart No. 1, P1)	from 47°43′21.0″N 052°50′05.1″W
		to 47°43′21.7″N 052°50′04.3″W
	This notice affects Electronic Navigational Chart: CA376015	LL(493.54) DFO(6306760-02)
Add	breakwater with legend Bkw (See Chart No. 1, F4.1)	between 47°43′20.1″N 052°50′04.3″W
		and 47°43′21.7″N 052°50′04.3″W
	This notice affects Electronic Navigational Chart: CA376015	DFO(6306760-03)

SECTION 2 CHART CORRECTIONS

4847 - Concep t 15-AUG-2014	tion Bay - New Edition - 03-AUG-2001 - NAD 1983	LNM/D. 01-AUG-2014
Delete	private yellow lighted spherical buoy Fl(5) Y 20s (See Chart No 1 Q22)	47°23′28.0″N 053°07′57.0″W
	This notice affects Electronic Navigational Chart: CA376120, CA5761	15 DFO(6306798-01)
01-AUG-2014		LNM/D. 10-JAN-2014
Delete	breakwater with legend Bkw (See Chart No. 1, F4.1)	between 47°43'22.2"N 052°50'05.2"W
	This notice affects Electronic Navigational Chart: CA376015	and 47°43′21.0″N 052°50′05.1″W
		DFO(6306760-01)
Reposition	light 2Lts FIG & FIR (See Chart No. 1, P1)	from 47°43'21.0"N 052°50'05.1"W
		to 47°43′21.7″N 052°50′04.3″W
	This notice affects Electronic Navigational Chart: CA376015	LL(493.54) DFO(6306760-02)
Add	breakwater with legend Bkw (See Chart No. 1, F4.1)	between 47°43'20.1"N 052°50'04.3"W
		and 47°43'21.7"N 052°50'04.3"W
	This notice affects Electronic Navigational Chart: CA376015	DFO(6306760-03)
4848 - Holyroo	d - New Edition - 25-JUL-2008 - NAD 1983	
15-AUG-2014		LNM/D. 03-AUG-2012
Delete	private yellow lighted spherical buoy FI(5) Y 20s (See Chart No 1 Q22)	47°23′28.0″N 053°07′57.0″W
	This notice affects Electronic Navigational Chart: CA376120, CA5761	
		DFO(6306798-01)
4857 - Indian B 15-AUG-2014	ay to/à Wadham Islands - New Chart - 29-OCT-1999 - NAD 1983	LNM/D. 09-MAR-2012
Add	Breakwater (See Chart No. 1, F4.1)	joining 49°15′32.0″N 053°29′42.0″W
		49°15′34.0″N 053°29′37.0″W and 49°15′36.0″N 053°29′38.0″W
	This notice affects Electronic Navigational Chart: CA376371	
		DFO(6306780-01)

SECTION 2 CHART CORRECTIONS

4911 - Entrée 15-AUG-2014	e a/Entrance to Miramichi River - New Edition - 27-JAN-2006 - NAD	1983 LNM/D. 07-FEB-2014
Replace	front leading beacon with beacon with legend Bn (See Chart No. 1, Q80)	47°09′28.8″N 065°02′00.0″W
	This notice affects Electronic Navigational Chart: CA476133	(G2014057) DFO(6306782-01)
Delete	rear leading beacon with leading line and bearing 132° - 312° (See Chart No. 1, Q120)	47°09′38.8″N 065°02′16.3″W
	This notice affects Electronic Navigational Chart: CA476133	(G2014058) DFO(6306782-02)
Add	beacon with legend Bn (See Chart No. 1, Q80)	47°09'38.8"N 065°02'16.3"W
	This notice affects Electronic Navigational Chart: CA476133	(G2014058) DFO(6306782-03)
4913 - Caraq	uet Harbour, Baie de Shippegan and/et Miscou Harbour - New Cha	art - 07-AUG-1992 - NAD 1983
01-AUG-2014 Add	marine farm (See Chart No. 1, K48.2)	LNM/D. 18-OCT-2013 47°53'46.2"N 064°32'58.5"W
	This notice affects Electronic Navigational Chart: CA476275	DFO(6306762-01)
5452 - Diana 22-AUG-2014	Bay - New Edition - 08-JUL-2005 - NAD 1983	LNM/D. 25-DEC-2009
Add	sounding of 4 fathoms	61°02′29.2″N 069°40′17.4″W
		DFO(6603993-01)
Add	sounding of 3 fathoms, 2 feet	61°03′05.2″N 069°39′18.5″W DFO(6603993-02)
Add	sounding of 2 fathoms, 2 feet	61°03′01.7″N 069°39′16.7″W DFO(6603993-03)
Add	sounding of 0 fathoms, 4 feet	61°02′50.4″N 069°38′57.5″W DFO(6603993-04)
	ster Sound, Eastern Approaches/Approches Est - New Edition - 02	
29-AUG-2014 Add	island with elevation of 6 meters, Rep (2014) (See Chart No. 1, K10, I3.2)	LNM/D. 16-DEC-2011 joining 74°34′18.2″N 080°59′47.3″W
		74°34′12.8″N 080°59′47.3″W 74°34′12.8″N 080°59′23.9″W
		74°34′18.2″N 080°59′23.9″W
	This notice affects Electronic Navigational Chart: CA273313	and 74°34′18.2″N 080°59′47.3″W
		DFO(6603995-01)

SECTION 2 CHART CORRECTIONS

7750 - Cambrid 22-AUG-2014	ge Bay - New Edition - 19-JAN-2007 - NAD 1983	LNM/D. 22-OCT-2010
Add	crib with depth of 6.1 metres (See Chart No. 1, Fb,Ka)	69°06′48.1″N 105°03′38.1″W
	This notice affects Electronic Navigational Chart: CA473332, CA5733	33
		DFO(6603991-02)
7750 - Cambrid 22-AUG-2014	ge Bay Harbour - New Edition - 19-JAN-2007 - NAD 1983	LNM/D. 22-OCT-2010
Add	crib with depth of 6.1 metres (See Chart No. 1, Fb,Ka) This notice affects Electronic Navigational Chart: CA473332, CA573	69°06′48.1″N 105°03′38.1″W 333
		DFO(6603991-02)
Add	submarine power cable (See Chart No. 1, L31.1)	joining 69°06′50.1″N 105°03′36.6″W
		69°06′49.5″N 105°03′38.8″W
		and 69°06′48.1″N 105°03′38.1″W
	This notice affects Electronic Navigational Chart: CA573333	

DFO(6603991-03)

SECTION 4

SAILING DIRECTIONS AND SMALL CRAFT GUIDE CORRECTIONS

ATL 105 - Cape Canso to Cape Sable (including Sable Island), First Edition, 2001 -

Chapter 3 — Paragraph 37 Delete: NE of Chebucto Head in position 44°31′24″N, 63°30′24″W Replace by: ENE of Chebucto Head in position 44°30′24″N, 63°29′30″W

(A2014-005.2)

ATL 111 - St. Lawrence River - Île Verte to Québec and Fjord du Saguenay, Third Edition, 2007 -

Chapter 2 — Paragraph 43, last line Insert: See Appendix for diagram of vertical clearances.

(Q2014-027.1)

APPENDIX A-6 — Add the **UPSTREAM BEAUMONT CABLES** — **VERTICAL CLEARANCES** Diagram.

http://www.notmar.gc.ca/eng/services/notmar/Ed 8 Sec 4 Diagramme cables beaumont.pdf

(Q2014-027.2)

SECTION 5 LIST OF LIGHTS, BUOYS AND FOG SIGNALS CORRECTIONS

No.	Name	Position Latitude N. Longitude W.	Cha	Light aracteri	stics	Focal Height in m. above water	Nomi- nal Range	Description Height in meters above ground		Remarks g Signals
The amendments have been highlighted in <mark>yellow</mark>										
NEWFO	<u>ONDLAND</u>									
129	Pass Island	47 29 24.3 56 11 46.7	FI	W R	10s 4s	85.6 85.6	12 4	White skeleton tower. 9.4	Obscured from	ose 9 s. rough N. to 118°. 177°(in a clockwise Igh E,S and W to 298° Chart:4644 Edn 08/14(N14-041)
ATLAN	<u>TIC</u>									
48 H4148	Fairhaven	On outer end of wharf. 44 57 49.8 67 00 29.5	LFI	R	<mark>6</mark>	4.2	7	Cylindrical mast. 3.7	Flash 2s; Eclip Operates at nig Year round.	
		0. 00 200								Chart:4114 Edn 08/14 (F14-024)
683.1	Guysborough Harbour light buoy CQ2	<mark>45 22 29.1</mark> 61 29 06.6	FI	R	4s			Red, marked "CQ2".	Seasonal.	Chart:4335 Edn 08/14 (G14-064)
777	Sydney Harbour Inner light buoy SC								Delete from lis	t. Chart:4266 Éd. 08/14 (G14-062)
<mark>778.2</mark>	Sydney Southeast Bar light buoy S7								Delete from lis	t. Chart:4266 Éd. 08/14 (G14-063)
<mark>951.91</mark>	Cardigan River Light Buoy (Owen's Flats) NJ23	46 13 56.2 62 36 25.6	Q	G	<mark>1s</mark>	<mark></mark>	<mark></mark>	Green, marked "NJ23".	Seasonal.	Chart:4422
<mark>957.91</mark>	Cardigan River Light Buoy (Owen's Flats) NJ23								Delete from lis	
980.5	Pinette Harbour light buoy NV4	<mark>46 02 42.2</mark> 62 57 15.5	Q	R	1s			Red spar, marked "NV4".	Seasonal.	Chart:4422 Edn 08/14 Chart:4466
1248.13 1	Shippegan South Gully light buoy TJ7	47 42 47.8 64 39 42.1	FI	G	4s			Green spar, marked "TJ7".	Seasonal.	Edn 08/14 (G14-055)
1993	Pointe Platon light buoy Q61	N. of point. <mark>46 40 37.5</mark> <mark>71 50 58.2</mark>	Q	G	1s			Green, marked "Q61".	Winter spar. Year round.	Chart:4913 Edn 08/14 (G14-065) Chart:1314 Edn 08/14(Q14-031)

SECTION 5 LIST OF LIGHTS, BUOYS AND FOG SIGNALS CORRECTIONS

							-		
No.	Name	Position Latitude N. Longitude W.	Ligh Character		Focal Height in m. above water	Nomi- nal Range	Description Height in meters above ground	Remarks Fog Signal:	S
1994	Portneuf light buoy Q63	<mark>46 40 40.6</mark> 71 51 40.2	FI G	4s			Green, marked "Q63".	Year round. Edn 08/	Chart:1314 /14(Q14-033)
1999.5	Portneuf light buoy Q65	<mark>46 40 23.7</mark> 71 52 44.3	Q G	1s			Green, marked "Q65".	Seasonal. Edn 08,	Chart:1314 /14(Q14-032)
2123.5	Cautionary light buoy LAC	46 16 03.1 72 41 43.4	FI Y	4s			Yellow, marked "LAC".	Seasonal. Edn 08/	Chart:1312 14 (Q14-019)
2389	Old Witch Shoal	45 15 58.2 72 10 05.3	Q R	1s	1.6	2	Red mast, orange rectangular daymark. 2.1	Operates at night only. Seasonal.	<mark>Chart:1360</mark> Edn 08/14
2390	Rivière Magog light buoy K20	River entrance. 45 15 45.2 72 09 42.7	FI R	4s			Red spar, marked "K20".	Seasonal.	<mark>Chart:1360</mark> Edn 08/14
2390.4	Îles Les Trois Soeurs light buoy K29	45 14 54.7 72 10 41.2	FI G	4s			Green, marked "K29".	Seasonal.	<mark>Chart:1360</mark> Edn 08/14
2390.5	Îles Les Trois Soeurs West light buoy K33	45 14 31.8 72 10 59.2	FI G	4s			Green, marked "K33".	Seasonal.	<mark>Chart:1360</mark> Edn 08/14
2392	Bryant Landing	On W. side of lake. 45 11 13.6 72 14 01.4	FI W	4s	4.1	2	Cylindrical mast. 3.2	Operates at night only. Seasonal.	<mark>Chart:1360</mark> Edn 08/14
2397.2	Information light buoy DOUA1	45 00 18 72 14 56	FI Y	4s			White and orange, marked "DOUA1".	Seasonal.	<mark>Chart:1360</mark> Edn 08/14
2397.4	Information light buoy DOUA2	45 00 19.1 72 14 21.5	FI Y	4s			White and orange, marked "DOUA2".	Seasonal.	<mark>Chart:1360</mark> Edn 08/14
2397.7	Information light buoy DOUA3	45 01 02 72 13 32	FI Y	4s			White and orange, marked "DOUA3".	Seasonal.	<mark>Chart:1360</mark> Edn 08/14

CANADIAN COAST GUARD MARINE INFORMATION REPORT AND SUGGESTION SHEET.

Name of Ship or Sende	ər:		I	Date:					
Address of Sender:	Street #		Street Name						
Town / City:	Pi	rov / State:	Postal Code	e / Zip Code:					
Tel / Fax / E-mail addre	ess of sender:								
Observation Date:	Observation Date:								
Geographical Position:									
Coordinate Position: L	.at:		. Long:						
Position Method:		GPS with WAAS	GPS	Radar	Dother				
Horizontal Datum Used	d:	□ WGS 84	□ NAD 27	Other					
Estimated Position Acc	curacy:								
Chart #:		Datum:	🗆 NAD 27		IAD 83				
Chart Edition:		Last Co	rrection applied: .						
Publications affected: (Quote Volume	and page):							
Full details (Attach additional sheets as necessary)									

Mariners are requested to notify the responsible authorities when new or suspected dangers to navigation are discovered, changes are observed in aids to navigation, or corrections to publications are seen to be necessary.

In the case of new or suspected dangers to navigation, it is important that all details be given in order to aid with future investigations. Items of interest include heights, depths, physical description, type of bottom and equipment method used to position the item. It is helpful to mark details on chart, which will be promptly replaced by the Canadian Hydrographic Service.

Reports should be made to the nearest Marine Communications and Traffic Services Centre (MCTS) and should be confirmed in writing to:

Leader, Notices to Mariners Canadian Coast Guard Department of Fisheries and Oceans Montréal, Qc H2Y 2E7 In the case of information concerning aids to navigation or the List of Lights, Buoys and Fog Signals.

Notmar.XNCR@dfo-mpo.gc.ca

OR

Director General, Canadian Hydrographic Service & Oceanographic Services Department of Fisheries and Oceans Ottawa, Ontario, K1A 0E6 In the case of new or suspected dangers to navigation or where corrections to "Sailing Directions" appear to be necessary.

CHSINFO@dfo-mpo.gc.ca

Or general questions on Coast Guard programs or services please send an e-mail message to: info@dfo-mpo.gc.ca