

**EVALUATION OF THE CLEAN-UP  
OF LEAD PAINT DUST  
IN HOUSES**

**APPENDIX 1  
DETAILED FIELD DATA**

**APPENDIX 1**  
**DETAILED FIELD DATA**

from the report:

Evaluation of the  
Clean-up of Lead Paint  
Dust in Houses

Prepared for:

Research Division  
Canada Mortgage and Housing Corporation  
700 Montreal Road  
Ottawa, Ontario  
K1A 0P7

CMHC Project Manager: Don Fugler

Prepared by:

Pinchin Environmental Consultants Ltd.  
5749 Coopers Avenue  
Mississauga, Ontario  
L4Z 1R9

Principal Consultant: Bruce Stewart, CIH, ROH

March 28, 1995

ROOM NO. 1

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: August 11, 1994  
House address: 435 Riverside Drive, Windsor  
Room: Bedroom, south end of building  
Size of room, ft by ft: 9' x 13'  
Flooring type: Vinyl-faced cellulose sheet flooring  
Flooring condition: Total of only 4 sf damage  
Weather conditions: 16-21 oC, humid, rain late in day  
XRF results for areas to be disturbed: 5.6, 3.7, 5.6  
Area of paint scraping sample taken: Not taken  
Paint scraping taken at XRF results of: Not taken

---

Area of paint disturbed (should be 0.36 m2 total): 0.44 m2

Comments, concerns:

A belt sander was used, but this was very slow; also tended to gouge deeply into the plaster wall. Removed baseboard along the longest wall, but when we did this, dust was released to the adjacent corridor.

TEST ROOM 1

DATA FORM FOR CLEANING METHOD 1

Date: August 12, 1994

House address: 435 Riverside

Room: Rear bedroom

Size of room, sf.: 9' x 13'

Air sampling information:	Cassette no.	54065
	Time on/Time off	0945 - 1010
	Pump number	54065
	Flowrate	1.995

Time:

0945 - 0950	Started/stopped vacuuming baseboards with HEPA vac
0952 - 1010	Started/stopped dry sweeping floor
1000 - 1010	Started/stopped shopvac vacuuming, N-S, then E-W

Comments or concerns? (weather, dampness of room, etc.)

Shopvac was minimum 10% full before use. We vacuumed general debris in the hallway prior to this room.

TEST ROOM 1

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEANING METHOD	SAMPLE NO.	COMMENT ON FLOOR
435 Riverside	R. Bedroom	1	1-1-1 (pre)	no comment
		1	1-1-2	5% broken floor
		1	1-1-3	no comment
		1	1-1-4	good condition
		1	1-1-5	about 40% broken
		1	1-1-6	5% damaged

TEST ROOM 2

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: August 11, 1994  
House address: 435 Riverside, Windsor  
Room: Rear upper apartment dining room  
Size of room, ft by ft: 9' x 10.5'  
Flooring type: Sheeting flooring, as per room 1  
Flooring condition: Moderate condition, approximately 10 sf damage  
Weather conditions: 16-21 oC, humid, rain later in day  
XRF results for areas to be disturbed: 4.5, 3.6 3.6  
Area of paint scraping sample taken: Not taken  
Paint scraping taken at XRF results of: Not taken

---

Area of paint disturbed (should be 0.36 m2 total): 0.36 m2

Comments, concerns:

Paint was disturbed initially with a belt sander, then changed to medium grit abrasive paper on an angle grinder. Removed baseboard along longest wall.

TEST ROOM 2

DATA FORM FOR CLEANING METHOD 2

Date: August 12, 1995  
House address: 435 Riverside  
Room: Rear apartment dining room  
Size of room, sf.: 9' x 10.5'

Air sampling information:      Cassette no.      54068  
   Time on/Time off      1018 - 1055  
   Pump number      522725  
   Flowrate      1.995 Lpm

Time:

1015 - 1018      Started/stopped vacuuming baseboards with HEPA  
1025 - 1035      Started/stopped vacuuming with Filterqueen, N-S, E-W  
1040 - 1055      Started/stopped damp mop with Mr. Clean, N-S, then E-W

Comments or concerns? (weather, dampness of room, etc.)

Visibly cleaner than Room 1

# TEST ROOM 2

## DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEANING METHOD	SAMPLE NO.	COMMENT ON FLOOR
435 Riverside	R. Dining	2	1-2-1 (400 cm2)	precleaning
		2	1-2-2	900 10% damage
		2	1-2-3	900 no comment
		2	1-2-4	900 no comment
		2	1-2-5	900 no comment
		2	1-2-6	900 no comment

Sample sizes as shown.

TEST ROOM 3

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: August 11, 1994  
House address: 435 Riverside Drive, Windsor  
Room: Bedroom of apartment at north of building  
Size of room, ft by ft: 9.3' x 17.5'  
Flooring type: Sheet flooring < 1sf damage  
Flooring condition: < 1 sf damage  
Weather conditions: 16-21 oC, humid, rain later in day  
XRF results for areas to be disturbed: 3.8 1.2, 3.7  
Area of paint scraping sample taken: Not taken  
Paint scraping taken at XRF results of: Not taken

---

Area of paint disturbed (should be 0.36 m2 total): 0.36 m2, west wall

Comments, concerns:

Did not remove baseboard.

DATA FORM FOR CLEANING METHOD 3

Floor visibly cleaner than Room 2

TEST ROOM 3

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEANING METHOD	SAMPLE NO.	COMMENT ON FLOOR
435 Riverside	Front bedroom	3 (TSP)	1-3-1	Good condition
			1-3-2	Good condition
			1-3-3	Good condition
			1-3-4	Good condition
			1-3-5	Good condition
			1-3-6	Good condition

All sample areas were 900 cm<sup>2</sup>

TEST ROOM 4

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: August 11, 1994  
House address: 435 Riverside  
Room: Kitchen for front apartment  
Size of room, ft by ft: 8.3' x 8.4'  
Flooring type: Sheet flooring  
Flooring condition: Good condition  
Weather conditions: 16-21 oC, humid; rain later in day  
XRF results for areas to be disturbed: 4.3, 4.4, 4.4  
Area of paint scraping sample taken: Not taken  
Paint scraping taken at XRF results of: Not taken

---

Area of paint disturbed (should be 0.36 m2 total): 0.36 m2

Comments, concerns:

Disturbed paint on north and south walls.

## DATA FORM FOR CLEANING METHOD 4

Air sampling information:	Cassette no.	54064
	Time on/Time off	44 minutes
	Pump number	522725
	Flowrate	1.995 Lpm

1220 - 1225	Started/stopped vacuuming baseboards with HEPA
1230 - 1237	Started/stopped vacuuming with HEPA, N-S, E-W
1241 - 1250	Started/stopped damp mop with TSP, N-S, then E-W (TSP to be made up as directions show)
1256 - 1301	Started/stopped damp rinse with clean water, N-S, E-W (use the same mop head as used for TSP)
(no comment)	Start/stopped vacuuming with HEPA, N-S, E-W

None

TEST ROOM 4

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEANING METHOD	SAMPLE NO.	COMMENT ON FLOOR
435 Riverside	Kitchen,	front apt.	4	
			1-4-1 (pre)	Good condition
			1-4-2	Good condition
			1-4-3	5% damage to area
			1-4-4	Good condition
			1-4-5	Good condition
			1-4-6	Good condition

ROOM #5

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-10-26

House address: 243 MERCER STREET

Room: RIGHT BACK ROOM

Size of room, ft by ft: 7 x 7 ft<sup>2</sup>

Flooring type: VAT

Flooring condition: POOR

Weather conditions: WARM & SUNNY

XRF results for areas to be disturbed: 2.5 mg/cm<sup>2</sup>  
2.6 mg/cm<sup>2</sup> WEST WALL  
2.6 mg/cm<sup>2</sup>

Area of paint scraping sample taken: 4 cm. x 6 cm.

Paint scraping taken at XRF results of: 2.6 mg/cm<sup>2</sup>

---

Comments, concerns:

- The total area of paint disturbed for this room was 0.36 m<sup>2</sup>
- The VAT flooring in this room was very damp and moist because it was below wet carpeting for an extended period of time.
- A large percent of the VAT tiles have lifted off the sub-floor.

TEST ROOM 5

DATA FORM FOR CLEANING METHOD 1

Date: 94-10-27  
House address: 243 Mercer Street  
Room: Right back room  
Size of room, sf.: 7 x 7 ft

Air sampling information:	Cassette no.	70157
	Time on/Time off	1005 - 1040
	Pump number	521974
	Flowrate	4.52

Time:

1003 - 1013	Started/stopped vacuuming baseboards with shopvac
1015 - 1021	Started/stopped dry sweeping floor
1021 - 1034	Started/stopped shopvac vacuuming, N-S, then E-W

Comments or concerns? (weather, dampness of room, etc.)

This room was very damp. The dampness caused the VAT floor to lift, which made cleaning difficult.

## ROOM #5

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEANING METHOD	SAMPLE NO.	COMMENT ON FLOOR
243 MERCER	R. BACK ROOM	1	5-1-1	PRECLEANING WIPES.
243 MERCER	R. BACK ROOM	1	5-1-2	
243 MERCER	R. BACK ROOM	1	5-1-3	
243 MERCER	R. BACK ROOM	1	5-1-4	VAT IN POOR CONDITION.
243 MERCER	R. BACK ROOM	1	5-1-5	
243 MERCER	R. BACK ROOM	1	5-1-6	

ROOM #6

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-10-26

House address: 243 MERCER STREET

Room: LEFT BACK ROOM

Size of room, ft by ft: 9 x 7 ft<sup>2</sup>

Flooring type: VAT

Flooring condition: POOR

Weather conditions: SUNNY & WARM

XRF results for areas to be disturbed: 3.0 mg/cm<sup>2</sup>  
2.9 mg/cm<sup>2</sup> WEST WALL  
2.1 mg/cm<sup>2</sup>

Area of paint scraping sample taken: 4 cm x 4 cm

Paint scraping taken at XRF results of: 2.9 mg/cm<sup>2</sup>

---

Comments, concerns:

- The total area of paint disturbed was 0.36 m<sup>2</sup>.
- There is approximately 5 % damage to VAT flooring.
- The VAT flooring in this room was very damp and moist because it was below wet carpeting for an extended period of time.
- The colour of paint disturbed was blue.

TEST ROOM 6

DATA FORM FOR CLEANING METHOD 2

Date: 94 - 10 -27  
House address: 243 Mercer Street  
Room: Left back room  
Size of room, sf.: 9 x 7 ft

Air sampling information:	Cassette no.	70156
	Time on/Time off	1116 - 1158
	Pump number	521974
	Flowrate	4.52 Lpm

Time:

1117 - 1120	Started/stopped vacuuming baseboards with Filterqueen
1120 - 1145	Started/stopped vacuuming with Filterqueen, N-S, E-W
1147 - 1158	Started/stopped damp mop with Mr. Clean, N-S, then E-W

Comments or concerns? (weather, dampness of room, etc.)

VAT in poor condition. Cleaning difficult due to lifting tiles.

ROOM #6

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEAN. METHOD	SAMPLE NO.	COMMENT ON FLOOR
243 MERCER	LEFT BACK ROOM	2	6-2-1	PRECLEANING WIPES.
243 MERCER	LEFT BACK ROOM	2	6-2-2	
243 MERCER	LEFT BACK ROOM	2	6-2-3	
243 MERCER	LEFT BACK ROOM	2	6-2-4	
243 MERCER	LEFT BACK ROOM	2	6-2-5	VAT WAS IN POOR CONDITION.
243 MERCER	LEFT BACK ROOM	2	6-2-6	

TEST ROOM 7

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94 - 10 - 26  
House address: 429 Pitt  
Room: Lower kitchen  
Size of room, ft by ft: 11.5' x 12'  
Flooring type: Sheet flooring  
Flooring condition: Approx. 15% damage to floor  
Weather conditions: Sunny and warm (15oC)  
XRF results for areas to be disturbed: 2.4, 2.5, 1.8  
Area of paint scraping sample taken: 4 x 4 cm2  
Paint scraping taken at XRF results of: 2.4, 2.5, 1.8

---

Area of paint disturbed (should be 0.36 m2 total): 0.36 m2

Comments, concerns:

TEST ROOM 7

DATA FORM FOR CLEANING METHOD 1

Date: 94 - 10 - 27

House address: 429 Pitt

Room: Lower kitchen

Size of room, ft by ft: 11.5' x 12'

Air sampling information:	Cassette no.	70160
	Time on/Time off	1410 - 1440
	Pump number	521630
	Flowrate	4.47 Lpm

Time:

1410 - 1412	Started/stopped vacuuming baseboards with shopvac
1412 - 1420	Started/stopped dry sweeping floor
1421 - 1440	Started/stopped shopvac vacuuming, N-S, then E-W

Comments or concerns? (weather, dampness of room, etc.)

Approximately 15% damage to floor, and 15 - 20 sf of floor patching. House was broken into overnight, poly was ripped at one end; however, no tracks within the work area, so apparently no disturbance of the site.

TEST ROOM 7

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEANING METHOD	SAMPLE NO.	COMMENT ON FLOOR
429 Pitt	Lower Kitchen	Method 1	7-1-1	(pre)
			7-1-2	(pre)
			7-1-3	on top of a patch
			7-1-4	20% broken floor
			7-1-5	5% broken floor
			7-1-6	good condition


ROOM #8

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-10-26

House address: 429 PITT STREET

Room: UPSTAIRS KITCHEN

Size of room, ft by ft:  ft<sup>2</sup> 8' x 13'


Flooring type: SHEET FLOORING

Flooring condition: GOOD

Weather conditions: SUNNY & WARM

XRF results for areas to be disturbed: 3.0 mg/cm<sup>2</sup>  
3.0 mg/cm<sup>2</sup> SOUTH WALL  
3.3 mg/cm<sup>2</sup>

Area of paint scraping sample taken: 4 cm x 4 cm

Paint scraping taken at XRF results of:  mg/cm<sup>2</sup> ?

---

Comments, concerns:

- The total are of paint disturbed was 60 cm x 60 cm on the south wall.
- The colour of paint disturbed in this room was green and is found on pressed board.
- There are two different floor patterns present in this room; with 20 linear feet of seams and a few ft<sup>2</sup> of damage.
- The cupboards present in this room were polyed off prior to commencing procedure.

TEST ROOM 8

DATA FORM FOR CLEANING METHOD 3

Date: 94 - 10 - 27  
House address: 429 Pitt Street  
Room: Upstairs Kitchen  
Size of room, sf.: (not noted)

Air sampling information:      Cassette no.              70152  
   Time on/Time off          1515 - 1545  
   Pump number              521630  
   Flowrate                  4.47 Lpm

Time:  
1515 - 1517              Started/stopped vacuuming baseboards with shopvac  
1518 - 1530              Started/stopped vacuuming with shopvac, N-S, E-W  
1531 - 1541              Started/stopped damp mop with Ledizolv, N-S, then E-W  
   (Ledizolv to be made up to 5%, 8 oz. to 160 oz water)  
1542 - 1545              Started/stopped damp rinse with clean water, N-S, E-W  
   (use the same mop head as used for Ledizolv)

Comments or concerns? (weather, dampness of room, etc.)

2 different patterns of sheet flooring, approximately 20' of seams; few sf of damage

ROOM #8

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEAN. METHOD	SAMPLE NO.	COMMENT ON FLOOR
429 PITT	UPSTAIRS KITCHEN	3	8-3-1	PRECLEANING
429 PITT	UPSTAIRS KITCHEN	3	8-3-2	WIPES.
429 PITT	UPSTAIRS KITCHEN	3	8-3-3	
429 PITT	UPSTAIRS KITCHEN	3	8-3-4	SHEET FLOORING
429 PITT	UPSTAIRS KITCHEN	3	8-3-5	WAS IN FAIR
429 PITT	UPSTAIRS KITCHEN	3	8-3-6	CONDITION.

ROOM #9

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-10-26

House address: 441 RIVERSIDE DRIVE

Room: FRONT ROOM

Size of room, ft by ft: 16 x 8 ft<sup>2</sup>

Flooring type: SHEET FLOORING

Flooring condition: POOR

Weather conditions: SUNNY & WARM

XRF results for areas to be disturbed: 3.7 mg/cm<sup>2</sup>  
4.0 mg/cm<sup>2</sup>  
4.3 mg/cm<sup>2</sup>

Area of paint scraping sample taken: 4 cm x 4 cm

Paint scraping taken at XRF results of: 3.7 mg/cm<sup>2</sup>

---

Comments, concerns:

- Two different locations of paint were disturbed, with a total disturbance of 60 cm x 60 cm. The paint at these two locations appeared to be the same.
- There is approximately 20% of the sheet flooring missing in this room.
- The paint disturbed is on textured plaster walls.

TEST ROOM 9

DATA FORM FOR CLEANING METHOD 2

Date: 94 - 10 - 27

House address: 441 Riverside Drive

Room: Front room

Size of room, sf.: 16' x 8'

Air sampling information:	Cassette no.	70162
	Time on/Time off	1656 - 1744
	Pump number	521974
	Flowrate	4.52 Lpm

Time:

1658 - 1702 Started/stopped vacuuming baseboards with Filterqueen

1703 - 1708 Started/stopped vacuuming with Filterqueen, N-S, E-W

1709 - 1725

1727 - 1743 Started/stopped damp mop with Mr. Clean, N-S, then E-W

Comments or concerns? (weather, dampness of room, etc.)

Vacuum plugged at 1708. It was emptied and the cleaning restarted at 1709.

## ROOM #9

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEAN. METHOD	SAMPLE NO.	COMMENT ON FLOOR
441 RIVERSIDE	FRONT ROOM	2	9-2-1	PRECLEANING WIPES.
441 RIVERSIDE	FRONT ROOM	2	9-2-2	
441 RIVERSIDE	FRONT ROOM	2	9-2-3	
441 RIVERSIDE	FRONT ROOM	2	9-2-4	SHEET FLOORING WAS IN POOR CONDITION.
441 RIVERSIDE	FRONT ROOM	2	9-2-5	
441 RIVERSIDE	FRONT ROOM	2	9-2-6	

TEST ROOM 10

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94 - 10 - 26  
House address: 423 Riverside Drive  
Room: Kitchen  
Size of room, ft by ft: 13' x 13'  
Flooring type: Asphalt tile, several colours, pattern  
Flooring condition: Very good  
Weather conditions: Sunny and warm  
XRF results for areas to be disturbed: 1.4, 2.6, 0.8  
Area of paint scraping sample taken: 4 cm x 4 cm  
Paint scraping taken at XRF results of: 2.6 mg/cm<sup>2</sup>

---

Area of paint disturbed (should be 0.36 m<sup>2</sup> total): 0.36 m<sup>2</sup>

Comments, concerns:

The bulk sample taken from this location was difficult to obtain, and contained a trace amount of plaster.

Yellow paint was disturbed.

TEST ROOM 10

DATA FORM FOR CLEANING METHOD 4

Date: 94 - 10 - 27  
House address: 423 Riverside Drive  
Room: Kitchen  
Size of room, ft by ft: 13' x 13'

Air sampling information:      Cassette no.              70159  
   Time on/Time off        1806 - 1910  
   Pump number            521974  
   Flowrate                4.52 Lpm

Time:

1706 - 1812	Started/stopped vacuuming baseboards with HEPA
1812 - 1827	Started/stopped vacuuming with HEPA, N-S, E-W
1832 - 1849	Started/stopped damp mop with TSP, N-S, then E-W (TSP to be made up as directions show)
1850 - 1903	Started/stopped damp rinse with clean water, N-S, E-W (use the same mop head as used for TSP)
1904 - 1910	Start/stopped vacuuming with HEPA, N-S, E-W

Comments or concerns? (weather, dampness of room, etc.)

Using spray with mop not apparently cleaner <sup>than</sup> ~~that~~ using bucket of TSP. Bucket might be cleaner. Used brush attachment for HEPA vacuuming of floor.

ROOM #10

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEAN. METHOD	SAMPLE NO.	COMMENT ON FLOOR
423 RIVERSIDE	KITCHEN	4	10-4-1	PRECLEANING
423 RIVERSIDE	KITCHEN	4	10-4-2	WIPES.
423 RIVERSIDE	KITCHEN	4	10-4-3	
423 RIVERSIDE	KITCHEN	4	10-4-4	VAT FLOORING
423 RIVERSIDE	KITCHEN	4	10-4-5	WAS IN GOOD
423 RIVERSIDE	KITCHEN	4	10-4-6	CONDITION.

ROOM #11

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-10-28

House address: 1020 CADILLAC STREET

Room: KITCHEN

Size of room, ft by ft: 12 x 10 ft<sup>2</sup>

Flooring type: VAT

Flooring condition: GOOD

Weather conditions: SUNNY & WARM

XRF results for areas to be disturbed: 3.2 mg/cm<sup>2</sup>  
3.7 mg/cm<sup>2</sup> EAST WALL  
2.9 mg/cm<sup>2</sup>

Area of paint scraping sample taken: 4 cm x 4 cm

Paint scraping taken at XRF results of: 2.9 mg/cm<sup>2</sup>

---

Comments, concerns:

- The total area of paint disturbed on the east wall was 60 cm x 60 cm.
- **AIR SAMPLING WAS PERFORMED DURING THE DISTURBANCE OF PAINT AT THIS LOCATION:**

CASSETTE # 70167  
PUMP # 523843  
FLOW RATE 1.05 lpm  
TIME ON 22 minutes

ROOM #11

DATA FORM FOR CLEANING METHOD 4

Date: 94-11-01  
House address: 1020 CADILLAC STREET  
Room: KITCHEN  
Size of room, sf.: 12 x 10 ft<sup>2</sup>

Air sampling information:	Cassette no.	70168
	Time on/Time off	0930 - 1020
	Pump number	521974
	Flowrate	4.52 lpm

Time:

0930-0935	Started/stopped vacuuming baseboards with HEPA
0935-0945	Started/stopped vacuuming with HEPA, N-S, E-W
0945-1000	Started/stopped damp mop with TSP, N-S, then E-W (TSP to be made up as directions show)
1000-1010	Started/stopped damp rinse with clean water, N-S, E-W (use the same mop head as used for TSP)
1010-1015	Start/stopped vacuuming with HEPA, N-S, E-W

Comments or concerns? (weather, dampness of room, etc.)

- There was a steady rain which caused dampness and high humidity in the room.
- The VAT present at this location was in good condition.

## ROOM #11

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEAN. METHOD	SAMPLE NO.	COMMENT ON FLOOR
1020 CADILLAC	KITCHEN	4	11-4-1	PRECLEANING
1020 CADILLAC	KITCHEN	4	11-4-2	WIPES.
1020 CADILLAC	KITCHEN	4	11-4-3	
1020 CADILLAC	KITCHEN	4	11-4-4	THE VAT WAS IN
1020 CADILLAC	KITCHEN	4	11-4-5	GOOD CONDITION.
1020 CADILLAC	KITCHEN	4	11-4-6	

ROOM #12

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-10-28  
House address: 982 CADILLAC STREET  
Room: LIVING ROOM  
Size of room, ft by ft: 14 x 9 ft<sup>2</sup>  
Flooring type: HARD WOOD STRIP FLOOR  
Flooring condition: GOOD  
Weather conditions: SUNNY & WARM  
XRF results for areas to be disturbed: 3.3 mg/cm<sup>2</sup>  
2.7 mg/cm<sup>2</sup> SOUTH WALL  
3.3 mg/cm<sup>2</sup>  
Area of paint scraping sample taken: 4 cm x 4 cm  
Paint scraping taken at XRF results of: 3.3 mg/cm<sup>2</sup>

---

Area of paint disturbed (should be 0.36 m<sup>2</sup> total):

Comments, concerns:

- The total are of paint disturbed was 3600 cm<sup>2</sup> on the west wall.
- There was no trim to disturb at this location.

**AIR SAMPLING WAS TAKEN DURING DISTURBANCE OF PAINT AT THIS LOCATION:**

CASSETTE # 70164  
PUMP # 523843  
FLOW RATE 1.05 lpm  
TIME ON 19 minutes

ROOM #12

DATA FORM FOR CLEANING METHOD 3

Date: 94-11-01  
House address: 982 CADILLAC STREET  
Room: LIVING ROOM  
Size of room, sf.: 14 x 9 ft<sup>2</sup>

Air sampling information:	Cassette no.	70173
	Time on/Time off	1318 - 1342
	Pump number	521974
	Flowrate	4.52 lpm

Time:

1318-1322 Started/stopped vacuuming baseboards with shopvac  
1322-1328 Started/stopped vacuuming with shopvac, N-S, E-W  
1328-1335 Started/stopped damp mop with Ledizolv, N-S, then E-W  
(Ledizolv to be made up to 5%, 8 oz. to 160 oz water)  
1335-1342 Started/stopped damp rinse with clean water, N-S, E-W  
(use the same mop head as used for Ledizolv)

Comments or concerns? (weather, dampness of room, etc.)

There is a vent located on the floor at the S.E. corner of the room. This vent has been sealed using poly. Care had to be taken when washing the floor not to disturb adhesive on duct tape.

The room was slightly damp due to rain.

Collect wipe samples as: Address, Room, Method, (1-6) (1&2 preclean, 3-6 postclean) ie. 429 Pitt - Upstairs - 3 - 2

ROOM #12

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEAN. METHOD	SAMPLE NO.	COMMENT ON FLOOR
982 CADILLAC	LIVING ROOM	3	12-3-1	PRECLEANING
982 CADILLAC	LIVING ROOM	3	12-3-2	WIPES.
982 CADILLAC	LIVING ROOM	3	12-3-3	
982 CADILLAC	LIVING ROOM	3	12-3-4	HARD WOOD FLOOR
982 CADILLAC	LIVING ROOM	3	12-3-5	WAS IN GOOD
982 CADILLAC	LIVING ROOM	3	12-3-6	CONDITION.

ROOM #13

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-10-28  
House address: 982 CADILLAC STREET  
Room: FRONT BEDROOM  
Size of room, ft by ft: 8 x 10 ft<sup>2</sup>  
Flooring type: HARD WOOD STRIP FLOOR  
Flooring condition: GOOD  
Weather conditions: SUNNY & WARM  
XRF results for areas to be disturbed: 4.1 mg/cm<sup>2</sup>  
3.9 mg/cm<sup>2</sup> NORTH WALL  
3.9 mg/cm<sup>2</sup>  
Area of paint scraping sample taken: 4 cm x 4 cm  
Paint scraping taken at XRF results of: 4.1 mg/cm<sup>2</sup>

---

Area of paint disturbed (should be 0.36 m<sup>2</sup> total):

Comments, concerns:

- The total area of paint disturbed was 3600 cm<sup>2</sup> on the west wall.
- The hard wood strip flooring was in good condition; no damage was noted for this floor.

ROOM #13

DATA FORM FOR CLEANING METHOD 4

Date: 94-11-01

House address: 982 CADILLAC STREET

Room: FRONT BEDROOM

Size of room, sf.: 8 x 10 ft<sup>2</sup>

Air sampling information:	Cassette no.	70158
	Time on/Time off	1351 - 1430
	Pump number	521974
	Flowrate	4.52 lpm

Time:

1351-1356	Started/stopped vacuuming baseboards with HEPA
1356-1403	Started/stopped vacuuming with HEPA, N-S, E-W
1403-1410	Started/stopped damp mop with TSP, N-S, then E-W (TSP to be made up as directions show)
1410-1415	Started/stopped damp rinse with clean water, N-S, E-W (use the same mop head as used for TSP)
1420-1430	Start/stopped vacuuming with HEPA, N-S, E-W

Comments or concerns? (weather, dampness of room, etc.)

- It was noted that the hard wood strip flooring dried alot quicker than the previous VAT flooring used for this method.

- The final vacuuming with the HEPA was not performed until the floor had time to dry. It took approximately 5 minutes for the surface of the floor to dry.

ROOM #13

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEAN. METHOD	SAMPLE NO.	COMMENT ON FLOOR
982 CADILLAC	FRONT BEDROOM	4	13-4-1	PRECLEANING
982 CADILLAC	FRONT BEDROOM	4	13-4-2	WIPES.
982 CADILLAC	FRONT BEDROOM	4	13-4-3	
982 CADILLAC	FRONT BEDROOM	4	13-4-4	HARD WOOD FLOOR
982 CADILLAC	FRONT BEDROOM	4	13-4-5	WAS IN GOOD
982 CADILLAC	FRONT BEDROOM	4	13-4-6	CONDITION.

ROOM #14

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-10-28  
House address: 982 CADILLAC STREET  
Room: BACK ROOM  
Size of room, ft by ft: 8 x 9  
Flooring type: VAT  
Flooring condition: GOOD  
Weather conditions: WARM & SUNNY  
XRF results for areas to be disturbed: 1.8 mg/cm<sup>2</sup>  
2.6 mg/cm<sup>2</sup> EAST WALL  
1.5 mg/cm<sup>2</sup>  
Area of paint scraping sample taken: 4 cm. x 4 cm.  
Paint scraping taken at XRF results of: 2.6 mg/cm<sup>2</sup>

---

Area of paint disturbed (should be 0.36 m2 total):

Comments, concerns:

- A small strip (10 in. x 8 ft.) of the VAT is missing at the south end of the room.
- the area of paint that was disturbed was 3600 cm<sup>2</sup> in total; on the east wall.

ROOM #14

DATA FORM FOR CLEANING METHOD 1

Date: 94-11-01

House address: 982 CADILLAC STREET

Room: BACK ROOM

Size of room, sf.: 8 x 9

Air sampling information:	Cassette no.	70172
	Time on/Time off	1126 - 1140
	Pump number	521974
	Flowrate	4.52 lpm

Time:

1126-1129	Started/stopped vacuuming baseboards with shopvac
1129-1133	Started/stopped dry sweeping floor
1133-1140	Started/stopped shopvac vacuuming, N-S, then E-W

Comments or concerns? (weather, dampness of room, etc.)

- A small strip (10 in. x 8 ft.) of the VAT is missing at the south end of the room.

- Room was slightly damp due to rain.

ROOM #14

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEANING METHOD	SAMPLE NO.	COMMENT ON FLOOR
982 CADILLAC	BACK ROOM	1	14-1-1	PRECLEANING
982 CADILLAC	BACK ROOM	1	14-1-2	WIPES.
982 CADILLAC	BACK ROOM	1	14-1-3	
982 CADILLAC	BACK ROOM	1	14-1-4	VAT IN GOOD
982 CADILLAC	BACK ROOM	1	14-1-5	CONDITION.
982 CADILLAC	BACK ROOM	1	14-1-6	

ROOM #15

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-10-28

House address: 982 CADILLAC STREET

Room: KITCHEN

Size of room, ft by ft: 16 x 9 ft<sup>2</sup>

Flooring type: SHEET FLOORING

Flooring condition: GOOD

Weather conditions: SUNNY & WARM

XRF results for areas to be disturbed:

5.6 mg/cm <sup>2</sup>	
6.7 mg/cm <sup>2</sup>	N.E CORNER
5.4 mg/cm <sup>2</sup>	
3.4 mg/cm <sup>2</sup>	
2.9 mg/cm <sup>2</sup>	N.W CORNER
3.2 mg/cm <sup>2</sup>	

Area of paint scraping sample taken: 4 cm x 4 cm

Paint scraping taken at XRF results of: 6.7 mg/cm<sup>2</sup>

---

Area of paint disturbed (should be 0.36 m2 total):

Comments, concerns:

- There were two areas on the north wall where paint was disturbed; both areas were 1800 cm<sup>2</sup>.
- There was no trim to be disturbed at this location.

**AIR SAMPLING WAS TAKEN DURING DISTURBANCE OF PAINT AT THIS LOCATION:**

CASSETTE #	70161
PUMP #	523843
FLOW RATE	1.05 lpm
TIME ON	21 minutes

ROOM #15

DATA FORM FOR CLEANING METHOD 2

Date: 94-11-01

House address: 982 CADILLAC STREET

Room: KITCHEN

Size of room, sf.: 8 x 9 ft<sup>2</sup>

Air sampling information:	Cassette no.	70154
	Time on/Time off	1144 - 1204
	Pump number	521974
	Flowrate	4.52 lpm

Time:

1144-1147 Started/stopped vacuuming baseboards with Filterqueen

1147-1156 Started/stopped vacuuming with Filterqueen, N-S, E-W

1156-1204 Started/stopped damp mop with Mr. Clean, N-S, then E-W

Comments or concerns? (weather, dampness of room, etc.)

- There was a small hole near the S.E. corner of the room that went through to the basement. Poly and duct tape was used to seal this hole. Care had to be taken during vacuuming and washing of the floor.
- The sheet flooring in this room was in good condition.

## ROOM #15

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEAN. METHOD	SAMPLE NO.	COMMENT ON FLOOR
982 CADILLAC	KITCHEN	2	15-2-1	0% DAMAGE FOR
982 CADILLAC	KITCHEN	2	15-2-2	ALL WIPE
982 CADILLAC	KITCHEN	2	15-2-3	SAMPLES.
982 CADILLAC	KITCHEN	2	15-2-4	SHEET FLOORING
982 CADILLAC	KITCHEN	2	15-2-5	WAS IN GOOD
982 CADILLAC	KITCHEN	2	15-2-6	CONDITION.

ROOM #16

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-10-28  
House address: 982 CADILLAC STREET  
Room: MIDDLE BEDROOM  
Size of room, ft by ft: 11 x 9 ft<sup>2</sup>  
Flooring type: VAT  
Flooring condition: GOOD  
Weather conditions: SUNNY & WARM  
XRF results for areas to be disturbed: 3.4 mg/cm<sup>2</sup>  
3.9 mg/cm<sup>2</sup> WEST WALL  
3.0 mg/cm<sup>2</sup>  
Area of paint scraping sample taken: 4 cm x 4 cm  
Paint scraping taken at XRF results of: 3.9 mg/cm<sup>2</sup>

---

Area of paint disturbed (should be 0.36 m<sup>2</sup> total):

Comments, concerns:

- There was a small patch of a different type of VAT at the S.W. corner of the room. Nails were used to secure the patch into place.
- The total are of paint disturbed was 3600 cm<sup>2</sup> on the west wall.

ROOM #16

DATA FORM FOR CLEANING METHOD 3

Date: 94-11-01

House address: 982 CADILLAC STREET

Room: MIDDLE BEDROOM

Size of room, sf.: 11 x 9 ft<sup>2</sup>

Air sampling information:	Cassette no.	70153
	Time on/Time off	1247 - 1315
	Pump number	521974
	Flowrate	4.52 lpm

Time:

1247-1250 Started/stopped vacuuming baseboards with shopvac

1250-1258 Started/stopped vacuuming with shopvac, N-S, E-W

1258-1308 Started/stopped damp mop with Ledizolv, N-S, then E-W  
(Ledizolv to be made up to 5%, 8 oz. to 160 oz water)

1308-1315 Started/stopped damp rinse with clean water, N-S, E-W  
(use the same mop head as used for Ledizolv)

Comments or concerns? (weather, dampness of room, etc.)

- There was a small patch of a different type of VAT (180 cm. x 240 cm.) at the S.W. corner of the room. Nails were used to secure this patch in place.

- Room was slightly damp due to rain when the cleaning procedures were done.

Collect wipe samples as: Address, Room, Method, (1-6) (1&2 preclean, 3-6 postclean) ie. 429 Pitt - Upstairs - 3 - 2

ROOM #16

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEAN. METHOD	SAMPLE NO.	COMMENT ON FLOOR
982 CADILLAC	MID. BEDROOM	3	16-3-1	PRECLEANING WIPES.
982 CADILLAC	MID. BEDROOM	3	16-3-2	
982 CADILLAC	MID. BEDROOM	3	16-3-3	
982 CADILLAC	MID. BEDROOM	3	16-3-4	
982 CADILLAC	MID. BEDROOM	3	16-3-5	VAT WAS IN GOOD CONDITION.
982 CADILLAC	MID. BEDROOM	3	16-3-6	

ROOM #17

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-11-02  
House address: 397 CHATHAM STREET  
Room: BACK ROOM  
Size of room, ft by ft: 10.5 x 13.5 ft<sup>2</sup>  
Flooring type: SHEET FLOORING  
Flooring condition: 5% DAMAGE  
Weather conditions: WARM & SUNNY  
XRF results for areas to be disturbed: 2.9 mg/cm<sup>2</sup>  
1.8 mg/cm<sup>2</sup>  
2.3 mg/cm<sup>2</sup>  
Area of paint scraping sample taken: 4 cm x 4 cm  
Paint scraping taken at XRF results of: 2.3 mg/cm<sup>2</sup>

---

Area of paint disturbed (should be 0.36 m<sup>2</sup> total):

Comments, concerns:

- the total aread of paint disturbed at this location was 3600 cm<sup>2</sup>.
- There was a small crease in the sheet flooring at the centre of the room; which resulted in about 5 % damage in total.

ROOM #17

DATA FORM FOR CLEANING METHOD 1

Date: 94-11-03  
House address: 397 CHATHAM STREET  
Room: BACK ROOM  
Size of room, sf.: 10.5 x 13.5 ft<sup>2</sup>

Air sampling information:	Cassette no.	70174
	Time on/Time off	0900 - 0930
	Pump number	521630
	Flowrate	4.47 lpm

Time:

0900-0905	Started/stopped vacuuming baseboards with shopvac
0905-0915	Started/stopped dry sweeping floor
0915-0930	Started/stopped shopvac vacuuming, N-S, then E-W

Comments or concerns? (weather, dampness of room, etc.)

- There was a small crease in the sheet flooring at the centre of the room. This crease did not cause any difficulties during the cleaning procedures.

- The total damage of the sheet flooring in this room was approximately 5%.

Collect wipe samples as: Address, Room, Method, (1-6) (1&2 preclean, 3-6 postclean) ie. 429 Pitt - Upstairs - 3 - 2

## ROOM #17

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEANING METHOD	SAMPLE NO.	COMMENT ON FLOOR
397 CHATHAM	BACK ROOM	1	17-1-1	There was a small crease at the centre of the room; but there was no damage inside the areas that were sampled.
397 CHATHAM	BACK ROOM	1	17-1-2	
397 CHATHAM	BACK ROOM	1	17-1-3	
397 CHATHAM	BACK ROOM	1	17-1-4	
397 CHATHAM	BACK ROOM	1	17-1-5	
397 CHATHAM	BACK ROOM	1	17-1-6	

ROOM #18

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-11-02  
House address: 397 CHATHAM STREET  
Room: MIDDLE ROOM  
Size of room, ft by ft: 5 x 15 ft<sup>2</sup>  
Flooring type: VINYL TILE  
Flooring condition: 25% DAMAGE  
Weather conditions: WARM & SUNNY  
XRF results for areas to be disturbed: 3.0 mg/cm<sup>2</sup>  
1.7 mg/cm<sup>2</sup>  
2.5 mg/cm<sup>2</sup>  
Area of paint scraping sample taken: 4 cm x 4 cm  
Paint scraping taken at XRF results of: 3.0 mg/cm<sup>2</sup>

---

Area of paint disturbed (should be 0.36 m<sup>2</sup> total):

Comments, concerns:

- the total area of paint disturbed at this location was 3600 cm<sup>2</sup>.
- There was approximately 1 sq ft. of VAT missing at the entrance to this room.
- There was approximately 25% of the VAT that was cracked throughout the entire length of the tile; although the tiles did not lift off the sub-floor. These cracks in the VAT did not cause any significant difficulties during the cleaning procedures.

ROOM #18

DATA FORM FOR CLEANING METHOD 3

Date: 94-11-03

House address: 397 CHATHAM STREET

Room: MIDDLE ROOM

Size of room, sf.: 5 x 15 ft<sup>2</sup>

Air sampling information:	Cassette no.	70166
	Time on/Time off	1100 - 1130
	Pump number	521630
	Flowrate	4.47 lpm

Time:

1100-1105 Started/stopped vacuuming baseboards with shopvac

1105-1115 Started/stopped vacuuming with shopvac, N-S, E-W

1115-1125 Started/stopped damp mop with Ledizolv, N-S, then E-W  
(Ledizolv to be made up to 5%, 8 oz. to 160 oz water)

1125-1130 Started/stopped damp rinse with clean water, N-S, E-W  
(use the same mop head as used for Ledizolv)

Comments or concerns? (weather, dampness of room, etc.)

The vinyl tile in this room had a "stone-like" pattern with deep grooves. This pattern made mopping of the floor more difficult due to the fact that the dust would collect in these grooves. Extra care was taken during the moping process of this procedure to obtain an adequate washing of the floor.

Collect wipe samples as: Address, Room, Method, (1-6) (1&2 preclean, 3-6 postclean) ie. 429 Pitt - Upstairs - 3 - 2

## ROOM #18

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEANING METHOD	SAMPLE NO.	COMMENT ON FLOOR
397 CHATHAM	MIDDLE ROOM	3	18-3-1	There was
397 CHATHAM	MIDDLE ROOM	3	18-3-2	25% damage
397 CHATHAM	MIDDLE ROOM	3	18-3-3	of the VAT
397 CHATHAM	MIDDLE ROOM	3	18-3-4	but there
397 CHATHAM	MIDDLE ROOM	3	18-3-5	was no
397 CHATHAM	MIDDLE ROOM	3	18-3-6	damage
				inside the
				areas that
				w e r e
				sampled.

ROOM #19

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-11-14  
House address: 978 CADILLAC STREET  
Room: FRONT BEDROOM  
Size of room, ft by ft: 8 x 8-6" ft<sup>2</sup>  
Flooring type: OAK STRIP FLOOR  
Flooring condition: GOOD  
Weather conditions: RAIN & HUMID  
XRF results for areas to be disturbed: 10.9 mg/cm<sup>2</sup>  
10.7 mg/cm<sup>2</sup> NORTH WALL  
6.8 mg/cm<sup>2</sup>  
Area of paint scraping sample taken: 9.5 cm x 7 cm  
Paint scraping taken at XRF results of: 10.7 mg/cm<sup>2</sup>

---

Comments, concerns:

- The total are of paint disturbed was 3600 cm<sup>2</sup> on the west wall.
- The hard wood (oak) strip flooring was in good condition with a "shiny" wax finish; no damage was noted for this floor.

**AIR SAMPLING WAS TAKEN DURING DISTURBANCE OF PAINT AT THIS LOCATION:**

CASSETTE # 70169  
PUMP # 523843  
FLOW RATE 1.05 lpm  
TIME ON 26 minutes

ROOM #19

DATA FORM FOR CLEANING METHOD 4

Date: 94-11-15  
House address: 978 CADILLAC STREET  
Room: FRONT BEDROOM  
Size of room, sf.: 8 x 8-6" ft<sup>2</sup>

Air sampling information:	Cassette no.	70176
	Time on/Time off	42 minutes
	Pump number	521630
	Flowrate	4.47 lpm

Time:

1030-1035	Started/stopped vacuuming baseboards with HEPA
1035-1047	Started/stopped vacuuming with HEPA, N-S, E-W
1047-1057	Started/stopped damp mop with TSP, N-S, then E-W (TSP to be made up as directions show)
1057-1106	Started/stopped damp rinse with clean water, N-S, E-W (use the same mop head as used for TSP)
1120-1126	Start/stopped vacuuming with HEPA, N-S, E-W

Comments or concerns? (weather, dampness of room, etc.)

- The final procedure of vacuuming with the HEPA was not performed until the floor had time to dry. It took approximately 14 minutes for the surface of the floor to completely dry.

- It was noted that the TSP detergent used to wash this floor took the "shiny" wax finish off and left the floor dull looking.

- There was a floor vent (3" x 9") along the west wall of this room. It was secured with poly and sealed with duct tape. Care had to be given during the vacuuming and washing procedures of this method not to interfere with the adhesive of this tape.

ROOM #19

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEAN. METHOD	SAMPLE NO.	COMMENT ON FLOOR
978 CADILLAC	FRONT BEDROOM	4	19-4-1	0 % DAMAGE
978 CADILLAC	FRONT BEDROOM	4	19-4-2	FOR ALL WIPE
978 CADILLAC	FRONT BEDROOM	4	19-4-3	SAMPLES.
978 CADILLAC	FRONT BEDROOM	4	19-4-4	HARD WOOD FLOOR
978 CADILLAC	FRONT BEDROOM	4	19-4-5	WAS IN GOOD
978 CADILLAC	FRONT BEDROOM	4	19-4-6	CONDITION.

ROOM #20

DATA FORM FOR DISTURBANCE OF LEAD PAINT

Date: 94-11-14

House address: 978 CADILLAC STREET

Room: MIDDLE BEDROOM

Size of room, ft by ft: 8 x 8-6" ft<sup>2</sup>

Flooring type: STRIP OAK FLOORING

Flooring condition: GOOD

Weather conditions: RAIN & HUMID

XRF results for areas to be disturbed: 10.7 mg/cm<sup>2</sup>  
10.3 mg/cm<sup>2</sup> EAST WALL  
9.8 mg/cm<sup>2</sup>

Area of paint scraping sample taken: 4 cm x 4 cm

Paint scraping taken at XRF results of: 10.3 mg/cm<sup>2</sup>

---

Comments, concerns:

- The total area of paint disturbed was 0.36 m<sup>2</sup>.
- The strip oak flooring (hard wood) present in this room had a highly polished finish.
- There was approximately 3 to 4% of carpet backing tape adhered to floor at the east end of the room. This small stripe of tape started at the north wall and extended through to the south wall of this room.

ROOM #20

DATA FORM FOR CLEANING METHOD 2

Date: 94-11-15  
House address: 978 CADILLAC STREET  
Room: MIDDLE BEDROOM  
Size of room, sf.: 8 x 8-6" ft<sup>2</sup>

Air sampling information:	Cassette no.	70165
	Time on/Time off	0850 - 0916
	Pump number	521630
	Flowrate	4.47 lpm

Time:

**0850-0856** Started/stopped vacuuming baseboards with Filterqueen

**0856-0910** Started/stopped vacuuming with Filterqueen, N-S, E-W

**0910-0916** Started/stopped damp mop with Mr. Clean, N-S, then E-W

Comments or concerns? (weather, dampness of room, etc.)

- There was a floor vent (3" x 9") at the north - west corner of the room. The hole was sealed with poly and duct tape. Care had to be taken during vacuuming and washing of the floor.

- There was a small strip of carpet adhesive stuck to the hard wood floor at the east end of the room. Wipe samples #5 and #6 had a small piece of this adhesive in the area to be wiped. Because this tape was somewhat sticky, the lead dust remained stuck to the adhesive during the procedures of vacuuming and washing the floor.

ROOM #20

DATA FORM FOR WIPE SAMPLES

ADDRESS	ROOM	CLEAN. METHOD	SAMPLE NO.	COMMENT ON FLOOR
978 CADILLAC	MIDDLE BEDROOM	2	20-2-1	PRECLEANING
978 CADILLAC	MIDDLE BEDROOM	2	20-2-2	WIPES.
978 CADILLAC	MIDDLE BEDROOM	2	20-2-3	
978 CADILLAC	MIDDLE BEDROOM	2	20-2-4	
978 CADILLAC	MIDDLE BEDROOM	2	20-2-5	5% DAMAGE
978 CADILLAC	MIDDLE BEDROOM	2	20-2-6	15% DAMAGE