



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

# Notices to Mariners

**Edition No. 11/2021**  
**November 26, 2021**



Safety First, Service Always

## Monthly Eastern Edition

Canada 

Notices to Mariners – Monthly Eastern Edition  
Edition No. 11/2021

Aussi disponible en français :  
Avis aux navigateurs – Édition mensuelle de l'Est  
Édition n° 11/2021

**Published under the Authority of:**

Canadian Coast Guard Programs  
Aids to Navigation and Waterways  
Fisheries and Oceans Canada  
Montreal, QC H2Y 2E7

For more information, contact [Notmar.XNCR@dfo-mpo.gc.ca](mailto:Notmar.XNCR@dfo-mpo.gc.ca).

© Her Majesty the Queen in Right of Canada,  
as represented by the Minister of Fisheries, Oceans  
and the Canadian Coast Guard, 2021.

Cat. No. Fs152-5E-PDF (Electronic PDF, English)  
ISSN 1719-7678

Cat. No. Fs152-5F-PDF (Electronic PDF, French)  
ISSN 1719-7694

A web version is available here:

<https://www.notmar.gc.ca/monthly-mensuel-en.php> (English)

<https://www.notmar.gc.ca/monthly-mensuel-fr.php> (French)

## Explanatory Notes – Notices to Mariners (NOTMAR)

**Geographical positions** refer directly to the graduations of the largest scale Canadian Hydrographic Service chart (unless otherwise indicated).

**Bearings** refer to the true compass and are measured clockwise from 000° (North) clockwise to 359°; those relating to lights are from seaward.

**Visibility** of lights is that in clear weather.

**Depths** - The units used for soundings (metres, fathoms or feet) are stated in the title of each chart.

**Elevations** are normally given above Higher High Water, Large Tide (unless otherwise indicated).

**Distances** may be calculated as follows:

- 1 nautical mile = 1,852 metres (6,076.1 feet)
- 1 statute mile = 1,609.3 metres (5,280 feet)
- 1 metre = 3.28 feet

### Temporary and Preliminary Notices to Mariners – Section 1A of *Notices to Mariners*

These notices are indicated by a (T) or a (P), respectively. Please note that nautical charts are not amended by the Canadian Hydrographic Service for temporary (T) and preliminary (P) notices. It is recommended that mariners chart these corrections in pencil. For the list of charts affected by (T) & (P) notices, please refer to the current [Notices to Mariners - Monthly Summary of Temporary and Preliminary Notices](#) publication.

### Suggestions and Corrections Form

This form is specifically for suggestions and corrections to Notices to Mariners publications. It is available [online](#) and also in [fillable PDF format](#) included with the monthly publication ZIP file.

To report chart discrepancies and/or corrections to the *Sailing Directions* booklets: Fill out the [Marine Information Reporting Form](#) and/or email [chsinfo@dfo-mpo.gc.ca](mailto:chsinfo@dfo-mpo.gc.ca).

To report emergencies or navigational hazards: [Contact your nearest MCTS centre](#)

- VHF channel 16 (156.8 MHz)
- MF/HF frequency 2182 kHz/4125 kHz (where available)
- \*16 on a cellphone (where available)

### NOTMAR Website – Monthly Editions, Chart Corrections and Chart Patches

The NOTMAR website allows users to access the [monthly publications](#), [chart corrections](#), and [chart patches](#).

Users can subscribe for free to the [email notification service](#) to receive notifications when charts of interest are updated, including their patches, as well as when a new Monthly Edition of *Notices to Mariners* is published.

In addition, the monthly publication and related files to download, such as chart patches and *Sailing Directions* diagrams, can be obtained all together through the download of a single ZIP file.


## Explanatory Notes – Canadian Hydrographic Service (CHS)

### Chart Corrections – Section 2 of *Notices to Mariners*

Corrections to nautical charts will be listed in numerical order by chart number. Each chart correction listed applies only to that particular chart. Related charts, if any, will have their own specific correction listed separately.

Users should also refer to CHS *Chart 1: Symbols, Abbreviations and Terms* for additional information pertaining to the correction of charts.

The illustration below describes the elements that will comprise a typical Section 2 chart correction:



The last correction number is identified with the **LNMD** or **Last Notice to Mariners Number / Date**.

Mariners are advised that only the most critical changes that directly affect safety to navigation are issued in “Section 2 – Chart Corrections.” This limitation is required to ensure that charts remain as clear and easy to read as possible. As a result, mariners may see minor discrepancies of a non-critical nature between information in official publications. For example, a small change in the nominal range or focal height of a light may not result in the production of a chart correction in *Notices to Mariners*, but may result in a correction in the [List of Lights, Buoys and Fog Signals](#) publication.

**Note:** In the case of a discrepancy between information provided on CHS charts relating to aids to navigation, and the *List of Lights, Buoys and Fog Signals* publication, the latter shall be deemed as containing the most up-to-date information.

### Canadian Nautical Charts & Publications

A source list of Canadian nautical charts and publications is published in Notice No. 14 of the *Notices to Mariners Annual Edition 2021*. The source supply and the prices effective at the time of printing are listed. For current chart edition dates, please refer to the following website: [www.chs-shc.gc.ca/charts-cartes/paper-papier/index-eng.asp](http://www.chs-shc.gc.ca/charts-cartes/paper-papier/index-eng.asp).

## Explanatory Notes – Marine Communications and Traffic Services (MCTS)

### Navigational Warnings / Notices to Shipping

The Canadian Coast Guard (CCG) is implementing a number of changes to the aids to navigation system in Canada.

These changes are advertised as Navigational Warnings, formerly called Notices to Shipping<sup>1</sup>, that are broadcast by the CCG, and are then followed up with Notices to Mariners, then charts are updated by hand correction, reprints or new editions.

Mariners are advised that all relevant Navigational Warnings (NAVWARN) should be kept until superseded by Notices to Mariners or through revised charts issued by the Canadian Hydrographic Service (CHS).

NAVWARN are accessible on the applicable regional page on the CCG Navigational Warnings website at <http://nis.ccg-gcc.gc.ca>.

CHS is reviewing the impact of these changes with CCG and together are preparing an action plan on the issuing of chart revisions.

For further information, contact your regional NAVWARN Issuing Desk.

<p><b>Atlantic Region (North)</b> <b>*Port aux Basques MCTS Centre</b></p> <p>“N” Series NAVWARN</p> <p>Canadian Coast Guard 49 Stadium Rd. P.O. Box 99 Port aux Basques, NL A0M 1C0</p> <p>Telephone: 709-695-2168 or 1-800-563-9089 Facsimile: 709-695-7784</p> <p>Email: <a href="mailto:NAVWARN.MCTSPortAuxBasques@innav.gc.ca">NAVWARN.MCTSPortAuxBasques@innav.gc.ca</a></p>	<p><b>Central Region</b> <b>*Prescott MCTS Centre</b></p> <p>“Q” and “C” Series NAVWARN</p> <p>Canadian Coast Guard 401 King Street West P.O. Box 1000 Prescott, ON K0E 1T0</p> <p>Telephone: 613-925-0666 Facsimile: 613-925-4519</p> <p>Email: <a href="mailto:NAVWARN.MCTSPrescott@innav.gc.ca">NAVWARN.MCTSPrescott@innav.gc.ca</a></p>
<p><b>Atlantic Region (South)</b> <b>*Sydney MCTS Centre</b></p> <p>“M” Series NAVWARN</p> <p>Canadian Coast Guard 1190 Westmount Road Sydney, NS B1R 2J6</p> <p>Telephone: 902-564-7751 or 1-800-686-8676 Facsimile: 902-564-7662</p> <p>Email: <a href="mailto:NAVWARN.MCTSSydney@innav.gc.ca">NAVWARN.MCTSSydney@innav.gc.ca</a></p>	<p><b>Arctic Region</b> <b>*Iqaluit MCTS Centre</b></p> <p><i>Operational from approximately mid-May until late December.</i></p> <p>“A” and “H” Series NAVWARN</p> <p>Canadian Coast Guard P.O. Box 189 Iqaluit, NU X0A 0H0</p> <p><u>“A” Series NAVWARN</u> Telephone: 867-979-5269</p> <p><u>“H” Series NAVWARN</u> Telephone: 867-979-0310 Facsimile: 867-979-4264</p> <p>Email: <a href="mailto:NAVWARN.MCTSIqaluit@innav.gc.ca">NAVWARN.MCTSIqaluit@innav.gc.ca</a></p>

\*Service available in English and in French.

<sup>1</sup> The expression “Notice to Shipping” was changed to “Navigational Warning” in January 2019.

## Table of Contents

<b>Section 1: General and Safety Information</b>	<b>1</b>
Canadian Coast Guard Publication – Comments and Suggestions on Notices to Mariners (NOTMAR) Publications .....	1
Transport Canada – COVID-19 Measures, Updates and Guidance.....	1
*1101/21 Canadian Hydrographic Service – Nautical Charts.....	1
*1102/21 Canadian Hydrographic Service – Electronic Navigational Charts.....	1
*1103/21 Canadian Hydrographic Service – Raster Digital Charts (BSB V3).....	2
*1104/21 Transport Canada – Ship Safety Bulletins #13, #15, #16 and #17/2021.....	2
*1106/21 Détroit de Northumberland / Northumberland Strait: Partie Ouest / Western Portion: Ports / Harbours – Unlit Buoy Repositioned .....	2
*1107/21 Plans Baie des Chaleurs / Chaleur Bay - Côte sud / South Shore – Unlit Buoys Permanently Changed.....	3
<b>Section 1A: Temporary and Preliminary Notices</b>	<b>4</b>
Reminder – Comment Period for Active Preliminary Notices .....	4
*1109(P)/21 Burin Harbours and Approches / et les approches – Light Buoy to be Discontinued ....	4
*1110(P)/21 Burin Peninsula to / à Saint-Pierre – Light Buoys to be Discontinued .....	5
*1111(P)/21 Cape Pine to / au Cape St Mary's – Light Buoy to be Discontinued .....	5
*1112(P)/21 Fogo Island Northern Portion / Partie Nord – Aid to navigation to be Discontinued .....	5
*1113(P)/21 Carmanville to / à Bacalhoa Island and / et Fogo – Light Buoy to be Established.....	5
*1114(P)/21 Summerland Group to/à Grindstone Island – Aid to navigation to be Discontinued .....	6
<b>Section 2: Chart Corrections</b>	<b>7</b>
<b>Section 3: Radio Aids to Marine Navigation Corrections</b>	<b>24</b>
*1115/21 Radio Aids to Marine Navigation 2021 (Atlantic, St. Lawrence, Great Lakes, Lake Winnipeg, Arctic and Pacific).....	24
<b>Section 4: Sailing Directions and Small Craft Guide Corrections</b>	<b>26</b>
<b>Section 5: List of Lights, Buoys and Fog Signals Corrections</b>	<b>32</b>

## Numerical Index of Canadian Charts Affected

This numerical index lists all nautical charts mentioned in this monthly edition of Notices to Mariners. Only charts appearing in Section 2 of this publication require a chart correction. The appearance of charts in all other sections, particularly those related to the correction of other nautical publications, is included here for reference.

Chart No.	Pages	Chart No.	Pages	Chart No.	Pages
1223	<a href="#">7</a>	4821	<a href="#">16</a>		
1437	<a href="#">6</a>	4824	<a href="#">17, 32</a>		
1438	<a href="#">7</a>	4825	<a href="#">32</a>		
1439	<a href="#">7</a>	4827	<a href="#">17</a>		
2042	<a href="#">7, 37</a>	4831	<a href="#">17, 32</a>		
2077	<a href="#">7</a>	4842	<a href="#">5</a>		
2086	<a href="#">8, 37</a>	4843	<a href="#">17</a>		
2123	<a href="#">8</a>	4849	<a href="#">33</a>		
2181	<a href="#">8</a>	4850	<a href="#">4</a>		
2235	<a href="#">1</a>	4851	<a href="#">17, 18, 33</a>		
2257	<a href="#">8, 9</a>	4852	<a href="#">33</a>		
2268	<a href="#">9, 10</a>	4854	<a href="#">33</a>		
2299	<a href="#">10, 11</a>	4861	<a href="#">5</a>		
2308	<a href="#">11</a>	4862	<a href="#">5</a>		
2309	<a href="#">11, 12</a>	4881	<a href="#">18, 32</a>		
2310	<a href="#">12</a>	4905	<a href="#">18, 36</a>		
2315	<a href="#">12</a>	4909	<a href="#">2, 18, 19, 36</a>		
4006	<a href="#">13</a>	4913	<a href="#">19, 35</a>		
4023	<a href="#">13</a>	4920	<a href="#">3, 20, 21, 22, 34, 35, 36</a>		
4024	<a href="#">13</a>	4935	<a href="#">22, 23, 36</a>		
4201	<a href="#">13, 14</a>	5031	<a href="#">23</a>		
4202	<a href="#">14, 34</a>	5179	<a href="#">32</a>		
4203	<a href="#">14, 15</a>				
4266	<a href="#">34</a>				
4281	<a href="#">15</a>				
4403	<a href="#">15</a>				
4486	<a href="#">15</a>				
4592	<a href="#">16, 33</a>				
4616	<a href="#">4</a>				
4622	<a href="#">32</a>				
4625	<a href="#">5</a>				
4642	<a href="#">16</a>				
4644	<a href="#">16, 32</a>				
4667	<a href="#">16</a>				

## Section 1: General and Safety Information

### Canadian Coast Guard Publication – Comments and Suggestions on Notices to Mariners (NOTMAR) Publications

In an effort to continuously improve the Notices to Mariners publications and to provide the most efficient service possible, the Notices to Mariners team invites all mariners and other interested parties to submit comments and suggestions on possible improvements to its various publications and services at the following email address: [Notmar.XNCR@dfo-mpo.gc.ca](mailto:Notmar.XNCR@dfo-mpo.gc.ca).

### Transport Canada – COVID-19 Measures, Updates and Guidance

(Recurrent publication of notice \*401/20, originally published in the *Notices to Mariners – Monthly Eastern Edition 04/2020* publication.)

Please refer to the link below for the latest updates to transportation related measures taken by Transport Canada in response to the evolving novel Coronavirus disease (COVID-19):

<https://www.tc.gc.ca/en/initiatives/covid-19-measures-updates-guidance-tc.html>.

For travel advice and all other updates, please visit: [Canada.ca/coronavirus](https://Canada.ca/coronavirus).

### \*1101/21 Canadian Hydrographic Service – Nautical Charts

Charts	Main Title	Scale	Published	Cat#	Price
<b>New Editions</b>					
2235	Cape Hurd to/à Lonely Island	1:60 000	2021-11-26	3	\$20.00

### \*1102/21 Canadian Hydrographic Service – Electronic Navigational Charts

S-57 ENC Number	Chart Title	ENC Compilation Scale	Published
<b>New Charts</b>			
CA373507 (Edn 1.000)	Parry Bay to/au Navy Channel	1:75 000	2021-11-12
CA373508 (Edn 1.000)	Navy Channel to/à Fury and Hecla Strait	1:75 000	2021-11-12
CA473514 (Edn 1.000)	Kangok Fiord and Approches/et les Approches	1:20 000	2021-11-12
CA676840 (Edn 1.000)	Madden Point, NS	1:500	2021-11-26
<b>New Editions</b>			
CA370381 (Edn 7.000)	Strait of Georgia, Central Portion/Partie Centrale (Part 1 of 2)	1:40 000	2021-11-26
CA376011 (Edn 11.000)	Approches to Saint John / Approches à Saint John	1:30 000	2021-11-19
CA476279 (Edn 10.000)	Hamilton Sound, Eastern Portion / Partie est	1:20 000	2021-11-05
CA479020 (Edn 12.000)	Québec à/to Donnacona	1:20 000	2021-11-12
CA479202 (Edn 3.000)	Lac Saint-Louis à/to Carillon	1:15 000	2021-11-05
CA570626 (Edn 3.000)	Kitimat Harbour	1:7 500	2021-11-26
CA573397 (Edn 2.000)	Iglolik	1:5 000	2021-11-12



S-57 ENC Number	Chart Title	ENC Compilation Scale	Published
CA573400 (Edn 2.000)	Hall Beach	1:5 000	2021-11-12
CA579046 (Edn 7.000)	Cap-aux-Meules	1:5 000	2021-11-12
CA579064 (Edn 9.000)	Sainte-Thérèse-de-Gaspé	1:2 500	2021-11-05

**\*1103/21 Canadian Hydrographic Service – Raster Digital Charts (BSB V3)**

Charts	Main Title	Scale	Published
<b>New Editions</b>			
RM-4468	Île du Petit Mécatina aux/to Îles Sainte-Marie	1:750 000	2021-11-05
RM-5373	Approches à/Approaches to Rivière George	1:60 000	2021-11-05
RM-5376	Approches à/Approaches to Rivière Koksoak	1:60 000	2021-11-05

**\*1104/21 Transport Canada – Ship Safety Bulletins #13, #15, #16 and #17/2021**

New **Ship Safety Bulletins** have recently been posted on the [Transport Canada website](#).

To view or download these bulletins, please click on the links below:

**[SSB#13/2021](#) – Trial Voluntary Protection Zone for Shipping, West Coast Haida Gwaii (amendment 2021-11-05)**  
RDIMS#17816272

**[SSB#15/2021](#) – Guidelines for the review of an applicant presenting with, or with a history of, kidney stones for the issuance of a marine medical certificate**  
RDIMS#17874630

**[SSB#16/2021](#) – Updated guidelines respecting the mobility of asymptomatic, presumed non-COVID-19-carrying\* seafarers in the marine sector during the COVID-19 pandemic**  
RDIMS#17982815

**[SSB#17/2021](#) – Measures to Mitigate the Spread of COVID-19 on Canadian Vessels and Foreign Passenger Vessels Operating in Canadian Waters**  
RDIMS#17963509

Sign up for [e-Bulletin](#) to receive an e-mail notice each time a new Ship Safety Bulletin is published on our website.

Contact us at [marinesafety-securitemaritime@tc.gc.ca](mailto:marinesafety-securitemaritime@tc.gc.ca) or 1-855-859-3123 (Toll Free).

**\*1106/21 Détroit de Northumberland / Northumberland Strait: Partie Ouest / Western Portion: Ports / Harbours – Unlit Buoy Repositioned**

Reference Chart: 4909

The following unlit buoy has been repositioned:

Aid Name	LL #	Position
Richibucto River buoy Q46	6150.13	46° 40' 26.0"N 064° 51' 36.5"W

(G2021-143)

**\*1107/21 Plans Baie des Chaleurs / Chaleur Bay - Côte sud / South Shore – Unlit Buoys  
 Permanently Changed**

Reference Chart: 4920

The following unlit buoys have been permanently changed:

Aid Name	LL #	Position	Changes
Shippegan Gully buoy TJ39	6260.1	47° 43' 53.8"N 064° 40' 13.7"W	Repositioned.
Shippegan Gully buoy TJ45	6261.1	47° 44' 05.6"N 064° 40' 42.1"W	Repositioned. Aid ID changed from TJ43 to TJ45.
Shippegan Gully buoy TJ44	6261.2	47° 44' 04.5"N 064° 40' 32.4"W	Repositioned. Aid ID changed from TJ46 to TJ44.
Shippegan Gully buoy TJ50	6261.7	47° 44' 09.4"N 064° 40' 48.5"W	Repositioned.
Shippegan Gully buoy TJ54	6261.8	47° 44' 20.9"N 064° 41' 03.6"W	Repositioned.
Shippegan Gully buoy TJ59	6261.81	47° 44' 30.7"N 064° 41' 17.5"W	Repositioned.
Shippegan Gully buoy TJ63	6261.82	47° 44' 35.5"N 064° 41' 29.6"W	Repositioned.

(G2021-193, 195, 196, 199, 200, 202, 204)

## Section 1A: Temporary and Preliminary Notices

### Reminder – Comment Period for Active Preliminary Notices

This is a reminder that the comment period is still open for the following active Preliminary notices:

Notice #	Reference Chart #	Aids Affected (LL #)	Intent of Notice
<b>Newfoundland and Labrador Coast</b>			
<a href="#">906(P)/21</a>	4850	473	Fog Signal to be Discontinued
<b>Inland Waters</b>			
<a href="#">908(P)/21</a>	N/A	1408	Aid to Navigation to be Discontinued

Please refer to the [Notices to Mariners - Monthly Summary of Temporary and Preliminary Notices](#) publication for details.

### Newfoundland and Labrador Coast

#### Temporary Notices

No notices applicable for this edition.

#### Preliminary Notices

##### Atlantic Region

##### Comment Submission

Comments on proposed changes in preliminary (P) notices are solicited from mariners and other interested parties within three months of the initial publication date. Following this date, the notices will be cancelled. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

Comments should be directed to the following:

Superintendent,  
Aids to Navigation & Waterways  
Canadian Coast Guard, Atlantic Region  
P.O. Box 1000  
50 Discovery Drive  
Dartmouth, NS B2Y 3Z8  
Telephone: (902) 802-3490  
Email: [Darlene.Sampson@dfo-mpo.gc.ca](mailto:Darlene.Sampson@dfo-mpo.gc.ca)

### \*1109(P)/21 Burin Harbours and Approches / et les approches – Light Buoy to be Discontinued

Reference chart: 4616

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Aid Name	LL #	Position
Cockle Rock light buoy PBB2	71.4	46° 59' 05.3"N 055° 09' 34.9"W

Initial publication date: Friday, November 26, 2021

[Comment submission deadline](#): Thursday, February 24, 2022

(N2021-181)

**\*1110(P)/21 Burin Peninsula to / à Saint-Pierre – Light Buoys to be Discontinued**

Reference chart: 4625

The Canadian Coast Guard proposes to permanently discontinue the following aids to navigation:

Aid Name	LL #	Position
Lord's Cove light buoy PC2	74.6	46° 52' 17.5"N 055° 39' 52.0"W
Lord's Cove Inner light buoy PC4	74.61	46° 52' 38.4"N 055° 40' 03.0"W

Initial publication date: Friday, November 26, 2021

[Comment submission deadline](#): Thursday, February 24, 2022

(N2021-181)

**\*1111(P)/21 Cape Pine to / au Cape St Mary's – Light Buoy to be Discontinued**

Reference chart: 4842

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Aid Name	LL #	Position
Point La Haye light and bell buoy MH2	7.5	46° 53' 35.8"N 053° 37' 35.9"W

Initial publication date: Friday, November 26, 2021

[Comment submission deadline](#): Thursday, February 24, 2022

(N2021-182)

**\*1112(P)/21 Fogo Island Northern Portion / Partie Nord – Aid to navigation to be Discontinued**

Reference chart: 4861

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Aid Name	LL #	Position
Fogo Light (Seal Cove)	366	49° 42' 55.2"N 054° 17' 08.1"W

Initial publication date: Friday, November 26, 2021

[Comment submission deadline](#): Thursday, February 24, 2022

(N2021-188)

**\*1113(P)/21 Carmanville to / à Bacalhoa Island and / et Fogo – Light Buoy to be Established**

Reference chart: 4862

The Canadian Coast Guard proposes to permanently established the following aid to navigation:

Aid Name	LL #	Position
Change Island light buoy DWG1	344.39	49° 40' 41.3"N 054° 22' 58.1"W

Initial publication date: Friday, November 26, 2021

[Comment submission deadline](#): Thursday, February 24, 2022

(N2021-192)

## Atlantic Coast

No notices applicable for this edition.

## Inland Waters

### Temporary Notices

No notices applicable for this edition.

### Preliminary Notices

#### Central Region

##### Comment Submission

Comments on proposed changes in preliminary (P) notices are solicited from mariners and other interested parties within three months of the initial publication date. Following this date, the notices will be cancelled. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

Comments should be directed to the following:

Superintendent, Mathieu Roy  
Aids to Navigation & Waterways  
Canadian Coast Guard, Central Region  
1550 D'Estimauville Avenue  
Québec, QC G1J 5E9  
Telephone: (418) 648-7450  
Email: [mathieu.roy@dfo-mpo.gc.ca](mailto:mathieu.roy@dfo-mpo.gc.ca)

#### **\*1114(P)/21 Summerland Group to/à Grindstone Island – Aid to navigation to be Discontinued**

Reference chart: 1437

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Aid Name	LL #	Position
Myers Island	363.2	44° 20' 54.2"N 076° 00' 36.3"W

Initial publication date: Friday, November 26, 2021

[Comment submission deadline](#): Thursday, February 24, 2022

(B2021-027)

## Section 2: Chart Corrections

### 1223 - Chenal du Bic et les approches/and approaches - New Edition - 21-MAR-2008 - NAD 1983

26-NOV-2021

LNMD. 16-APR-2021

Delete depth of 0 metres 9 decimetres 48°24'36.8"N 068°53'54.0"W  
(See Chart No. 1, I10)  
Note : On certain copies only  
*DFO(6410648-01)*

Add depth of 0 metres 9 decimetres 48°24'36.8"N 068°53'59.0"W  
(See Chart No. 1, I10)  
Note : On certain copies only  
*DFO(6410648-02)*

### 1438 - Grindstone Island to/à Carleton Island - New Edition - 31-AUG-2012 - World Geodetic System 1984

19-NOV-2021

LNMD. 17-SEP-2021

Add obstruction with known depth of 3.5 metres, Rep (2021) 44°18'16.7"N 076°14'09.0"W  
(See Chart No. 1, K41)  
This notice affects Electronic Navigational Chart: CA473025  
*DFO(6604819-01)*

Add obstruction with known depth of 2 metres, Rep (2021) 44°18'16.4"N 076°16'16.1"W  
(See Chart No. 1, K41)  
This notice affects Electronic Navigational Chart: CA473025  
*DFO(6604819-02)*

Add obstruction with known depth of 6.2 metres, Rep (2021) 44°17'07.1"N 076°18'20.7"W  
(See Chart No. 1, K41)  
This notice affects Electronic Navigational Chart: CA473025  
*DFO(6604819-03)*

### 1439 - Carleton Island to/au Charity Shoal - New Edition - 30-SEP-2020 - World Geodetic System 1984

19-NOV-2021

LNMD. 27-AUG-2021

Add obstruction with known depth of 6.2 metres, Rep (2021) 44°17'07.1"N 076°18'20.7"W  
(See Chart No. 1, K41)  
This notice affects Electronic Navigational Chart: CA473025  
*DFO(6604819-03)*

### 2042 - A à/to B - New Edition - 28-NOV-2003 - NAD 1983

12-NOV-2021

LNMD. 04-JUN-2021

Amend FI R to read FI R 9m against light 43°13'51.2"N 079°12'39.3"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA573010  
*(B2021030) LL(544.7) DFO(6604818-02)*

### 2077 - Lake Ontario/Lac Ontario (Western Portion/Partie Ouest) - New Edition - 17-JUL-2020 - NAD 1983

12-NOV-2021

Amend FI R 10m to read FI R 7m against light 43°23'34.3"N 079°42'21.1"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA373091, CA473519  
*(B2021029) LL(530) DFO(6604817-01)*

Amend FI R 13m to read FI R 9m against light 43°13'51.2"N 079°12'39.3"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA373091  
*(B2021030) LL(544.7) DFO(6604818-01)*

<b>2086 - Toronto to/à Hamilton - Sheet/Feuille 1 - New Edition - 24-MAY-2019 - World Geodetic System 1984</b>		
12-NOV-2021		LNM/D. 11-OCT-2019
Add	light FI G 7m (See Chart No. 1, P1) This notice affects Electronic Navigational Chart: CA373091, CA473519	43°23'33.7"N 079°42'24.2"W  (B2021028) LL(530.5) DFO(6604816-01)
Amend	FI R 10m to read FI R 7m against light (See Chart No. 1, P16) This notice affects Electronic Navigational Chart: CA373091, CA473519	43°23'34.3"N 079°42'21.1"W  (B2021029) LL(530) DFO(6604817-01)
<b>2123 - Pelee Passage to/à la Detroit River - New Edition - 27-JAN-2006 - NAD 1983</b>		
05-NOV-2021		LNM/D. 03-AUG-2018
Reposition	red starboard hand conical buoy, marked 2 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA373089	from 41°42'37.8"N 082°51'26.9"W to 41°42'36.8"N 082°51'31.9"W  (NOS:USLNM 17/2021) DFO(6604779-01)
Reposition	red starboard hand lighted pillar buoy FI R 6s, marked 2 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA373089	from 41°36'42.2"N 082°49'02.0"W to 41°36'38.5"N 082°49'02.3"W  (NOS:USLNM 17/2021) DFO(6604779-02)
<b>2181 - Port Stanley - New Edition - 11-MAY-2007 - NAD 1983</b>		
19-NOV-2021		LNM/D. 09-APR-2021
Reposition	green port hand spar buoy, marked ES3 (See Chart No. 1, Qg) This notice affects Electronic Navigational Chart: CA573316	from 42°39'15.1"N 081°12'47.0"W to 42°39'15.3"N 081°12'40.9"W  (B2021012) DFO(6604774-01)
Reposition	red starboard hand spar buoy, marked ES4 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA573316	from 42°39'15.6"N 081°12'42.4"W to 42°39'16.6"N 081°12'38.0"W  (B2021013) DFO(6604775-01)
<b>2257 - Clapperton Island to/à John Island - New Edition - 11-JAN-2002 - NAD 1983</b>		
05-NOV-2021		LNM/D. 11-DEC-2020
Delete	depth of 2 feet (See Chart No. 1, I10)	46°09'54.8"N 082°22'36.0"W  DFO(6604786-01)
Delete	depth of 46 feet (See Chart No. 1, I10)	46°06'47.0"N 082°20'37.7"W  DFO(6604786-02)
Delete	depth of 5 feet (See Chart No. 1, I10)	46°08'22.5"N 082°28'20.0"W  DFO(6604786-03)
Delete	depth of 43 feet (See Chart No. 1, I10)	46°07'01.0"N 082°20'27.9"W  DFO(6604786-04)
Delete	depth of 17 feet (See Chart No. 1, I10)	46°10'13.7"N 082°22'47.8"W  DFO(6604786-05)

Delete	legend Rep (2011) against crib	46°10'44.3"N 082°23'03.0"W DFO(6604786-06)
Add	obstruction with known depth of 1 foot (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°09'52.9"N 082°22'34.2"W  DFO(6604786-11)
Add	obstruction with known depth of 24 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°06'48.4"N 082°20'36.2"W  DFO(6604786-12)
Add	obstruction with known depth of 1 foot (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°08'24.8"N 082°28'18.8"W  DFO(6604786-13)
Add	obstruction with known depth of 32 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°07'00.0"N 082°20'27.9"W  DFO(6604786-14)
Add	obstruction with known depth of 2 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°10'12.5"N 082°22'46.3"W  DFO(6604786-15)
Add	legend Ru against crib (See Chart No. 1, F33) This notice affects Electronic Navigational Chart: CA473251	46°10'44.3"N 082°23'03.0"W  DFO(6604786-16)
Add	depth of 4 feet over crib (See Chart No. 1, Ka, Ib) This notice affects Electronic Navigational Chart: CA473251	46°10'44.3"N 082°23'03.0"W  DFO(6604786-17)
Add	obstruction with known depth of 48 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°08'32.6"N 082°21'24.2"W  DFO(6604786-18)
<b>2268 - Boyd Island to Spanish River - New Edition - 31-MAR-1989 - NAD 1927</b>		
05-NOV-2021		LNMD. 12-APR-2013
Delete	depth of 46 feet (See Chart No. 1, I10)	46°06'46.8"N 082°20'37.9"W  DFO(6604786-02)
Delete	legend Rep (2011) against crib	46°10'42.7"N 082°23'07.7"W DFO(6604786-06)
Delete	depth of 10 feet (See Chart No. 1, I10)	46°09'56.6"N 082°22'26.6"W  DFO(6604786-07)
Add	obstruction with known depth of 1 foot (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°09'52.8"N 082°22'34.5"W  DFO(6604786-11)



Add	obstruction with known depth of 24 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°06'48.2"N 082°20'36.5"W  <i>DFO(6604786-12)</i>
Add	obstruction with known depth of 32 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°06'59.6"N 082°20'28.1"W  <i>DFO(6604786-14)</i>
Add	obstruction with known depth of 2 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°10'12.5"N 082°22'46.7"W  <i>DFO(6604786-15)</i>
Add	legend Ru against crib (See Chart No. 1, F33) This notice affects Electronic Navigational Chart: CA473251	46°10'44.2"N 082°23'03.3"W  <i>DFO(6604786-16)</i>
Add	depth of 4 feet over crib (See Chart No. 1, Ka, Ib) This notice affects Electronic Navigational Chart: CA473251	46°10'44.2"N 082°23'03.3"W  <i>DFO(6604786-17)</i>
Add	obstruction with known depth of 48 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°08'32.6"N 082°21'24.4"W  <i>DFO(6604786-18)</i>

**2268 - Little Detroit - New Edition - 31-MAR-1989 - NAD 1927**  
05-NOV-2021

LNMD. 12-APR-2013

Delete	depth of 47 feet (See Chart No. 1, I10)	46°08'56.6"N 082°22'26.6"W  <i>DFO(6604786-08)</i>
Delete	depth of 20 feet (See Chart No. 1, I10)	46°08'54.5"N 082°22'22.6"W  <i>DFO(6604786-09)</i>
Add	obstruction with known depth of 22 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°08'56.8"N 082°22'26.4"W  <i>DFO(6604786-19)</i>
Add	obstruction with known depth of 14 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°08'54.5"N 082°22'22.6"W  <i>DFO(6604786-20)</i>

**2299 - Clapperton Island to/à Meldrum Bay - New Edition - 25-MAY-2001 - NAD 1983**  
05-NOV-2021

LNMD. 30-SEP-2016

Delete	legend Rep (2011) against crib	46°10'44.3"N 082°23'03.0"W <i>DFO(6604786-06)</i>
Delete	depth of 29 feet (See Chart No. 1, I10)	46°06'46.6"N 082°20'28.0"W  <i>DFO(6604786-10)</i>

Add	obstruction with known depth of 24 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°06'48.4"N 082°20'36.2"W  <i>DFO(6604786-12)</i>
Add	obstruction with known depth of 32 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°07'00.0"N 082°20'27.9"W  <i>DFO(6604786-14)</i>
Add	legend Ru against crib (See Chart No. 1, F33) This notice affects Electronic Navigational Chart: CA473251	46°10'44.3"N 082°23'03.0"W  <i>DFO(6604786-16)</i>
Add	depth of 4 feet over crib (See Chart No. 1, Ka, Ib) This notice affects Electronic Navigational Chart: CA473251	46°10'44.3"N 082°23'03.0"W  <i>DFO(6604786-17)</i>
Add	obstruction with known depth of 48 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA473251	46°08'32.6"N 082°21'24.2"W  <i>DFO(6604786-18)</i>
<b>2308 - Michipicoten Island to à Oiseau Bay - New Edition - 22-SEP-2006 - NAD 1983</b>		
	19-NOV-2021	LNMD. 22-MAY-2020
Reposition	Spot height (49) (See Chart No. 1, C11)	from 47°42'23.2"N 085°45'52.2"W to 47°42'18.8"N 085°45'36.6"W <i>DFO(6604770-12)</i>
Add	obstruction with known depth of 2¼ fathoms (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA373086, CA573136	47°42'25.6"N 085°45'55.0"W  <i>DFO(6604770-13)</i>
<b>2309 - Cape Gargantua to à Otter Head - New Edition - 23-JUL-1999 - NAD 1983</b>		
	19-NOV-2021	LNMD. 22-MAY-2020
Add	obstruction with known depth of 1¼ fathoms (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA373086	47°57'28.9"N 084°53'42.2"W  <i>DFO(6604770-02)</i>
Add	obstruction with known depth of 1½ fathoms (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA373086	47°57'24.5"N 084°53'21.2"W  <i>DFO(6604770-03)</i>
Delete	obstruction with known depth of 2½ fathoms Rep (2020) (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA373086	47°57'21.7"N 084°53'45.8"W  <i>DFO(6604770-06)</i>
Add	obstruction with known depth of 2½ fathoms (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA373086	47°57'22.9"N 084°53'43.9"W  <i>DFO(6604770-07)</i>

Reposition	spot height (49) (See Chart No. 1, C11)	from 47°42'24.9"N 085°45'49.1"W to 47°42'21.3"N 085°45'38.3"W <i>DFO(6604770-10)</i>
Add	obstruction with known depth of 2¼ fathoms (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA373086, CA573136	47°42'25.9"N 085°45'55.0"W  <i>DFO(6604770-11)</i>
<b>2310 - Caribou Island to Michipicoten Island - New Edition - 29-MAY-2015 - US Standard Datum</b>		
19-NOV-2021		LNMD. 09-MAR-2018
Delete	depth of 4½ fathoms (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA373086, CA573136	47°42'26.5"N 085°46'01.5"W  <i>DFO(6604770-14)</i>
Add	obstruction with known depth of 2¼ fathoms (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA373086, CA573136	47°42'25.9"N 085°45'55.4"W  <i>DFO(6604770-15)</i>
<b>2315 - Michipicoten Harbour - New Edition - 07-JUL-2006 - NAD 1983</b>		
19-NOV-2021		LNMD. 22-MAY-2020
Delete	depth of 30 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA373086	47°57'29.0"N 084°53'41.0"W  <i>DFO(6604770-01)</i>
Add	obstruction with known depth of 8 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA373086	47°57'28.9"N 084°53'42.2"W  <i>DFO(6604770-02)</i>
Add	obstruction with known depth of 10 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA373086	47°57'24.5"N 084°53'21.2"W  <i>DFO(6604770-03)</i>
Delete	depth of 33 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA373086	47°57'22.6"N 084°53'43.0"W  <i>DFO(6604770-04)</i>
Delete	obstruction with known depth of 15 feet Rep (2020) (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA373086	47°57'21.7"N 084°53'45.8"W  <i>DFO(6604770-05)</i>
Add	obstruction with known depth of 15 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA373086	47°57'22.9"N 084°53'43.9"W  <i>DFO(6604770-07)</i>
<b>2315 - Quebec Harbour - New Edition - 07-JUL-2006 - NAD 1983</b>		
19-NOV-2021		LNMD. 22-MAY-2020
Add	obstruction with known depth of 14 feet (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA373086, CA573136	47°42'25.9"N 085°45'55.0"W  <i>DFO(6604770-09)</i>

<b>4006 - Newfoundland and Labrador/Terre-Neuve-et-Labrador to Bermuda / aux Bermudes - New Edition - 08-AUG-2003 - NAD 1983</b>		
05-NOV-2021		LNMD. 22-OCT-2021
Reposition	yellow ODAS/SADO lighted super-buoy, marked 41001 (See Chart No. 1, L25)	from 34°43'27.0"N 072°19'00.0"W to 34°46'30.0"N 072°10'02.0"W (USCG:26/2021) DFO(6309741-01)
<b>4023 - Northumberland Strait / Détroit de Northumberland - New Edition - 27-DEC-2002 - World Geodetic System 1984</b>		
05-NOV-2021		LNMD. 06-AUG-2021
Delete	light FIY(2) 12s47ft10M (See Chart No. 1, P1) This notice affects Electronic Navigational Chart: CA276286, CA376076, CA476128 (G2021136) LL(1113) DFO(6309643-01)	46°19'11.8"N 064°30'47.2"W
Add	abandoned lighthouse with legend LtHo (disused) / LtHo (désaffecté) (See Chart No. 1, P1) This notice affects Electronic Navigational Chart: CA276286, CA376076, CA476128 (G2021136) LL(1113) DFO(6309643-02)	46°19'11.8"N 064°30'47.2"W
<b>4024 - Baie des Chaleurs/Chaleur Bay aux/to Îles de la Madeleine - New Edition - 06-MAR-2015 - NAD 1983</b>		
19-NOV-2021		LNMD. 30-JUL-2021
Amend	Oc(2) Y 10s to read LFI 6s12M against light (See Chart No. 1, P16) This notice affects Electronic Navigational Chart: CA279075, CA376187, CA476275 (G2021148) LL(1275) DFO(6309666-01)	47°53'03.8"N 064°37'25.0"W
26-NOV-2021		LNMD. 19-NOV-2021
Amend	FI Y 5s16m to read LFI 6s13M against light (See Chart No. 1, P16) This notice affects Electronic Navigational Chart: CA279075, CA376187, CA476275, CA576269 (G2021134) LL(1254) DFO(6309744-01)	47°43'19.7"N 064°39'38.2"W
<b>4201 - Halifax Harbour: Bedford Basin - New Edition - 25-AUG-2017 - NAD 1983</b>		
05-NOV-2021		LNMD. 15-OCT-2021
Delete	depth of 18.3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576001 DFO(6309775-01)	44°41'19.2"N 063°37'15.3"W
Add	obstruction with known depth of 15 metres (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA576001 DFO(6309775-02)	joining 44°41'18.4"N 063°37'16.5"W 44°41'19.5"N 063°37'12.1"W 44°41'20.6"N 063°37'12.6"W 44°41'19.4"N 063°37'17.1"W and 44°41'18.4"N 063°37'16.5"W
Add	obstruction with known depth of 15.9 metres (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA576003 DFO(6309775-03)	joining 44°40'40.9"N 063°37'21.1"W 44°40'44.2"N 063°37'22.9"W 44°40'44.6"N 063°37'21.5"W 44°40'41.5"N 063°37'19.6"W and 44°40'40.9"N 063°37'21.1"W

Add	anchoring prohibited symbol (See Chart No. 1, N20) This notice affects Electronic Navigational Chart: CA576001	44°41'29.0"N 063°37'10.8"W  <i>DFO(6309775-04)</i>
Add	anchorage prohibited symbol (See Chart No. 1, N20) This notice affects Electronic Navigational Chart: CA576001	44°41'17.0"N 063°37'05.0"W  <i>DFO(6309775-10)</i>
19-NOV-2021		LNMD. 05-NOV-2021
Replace	pier with pier in ruins with legend Ru (See Chart No. 1, F33)  This notice affects Electronic Navigational Chart: CA576001	joining 44°41'42.4"N 063°36'58.2"W 44°41'41.6"N 063°37'02.4"W 44°41'41.8"N 063°37'02.6"W 44°41'41.9"N 063°37'02.2"W 44°41'41.8"N 063°37'02.1"W and 44°41'42.5"N 063°36'58.3"W  <i>DFO(6309785-01)</i>
Replace	pier with pier in ruins with legend Ru (See Chart No. 1, F33) This notice affects Electronic Navigational Chart: CA576001	between 44°41'41.9"N 063°37'02.4"W and 44°41'43.7"N 063°37'04.8"W  <i>DFO(6309785-02)</i>
Replace	dolphin with an obstruction which covers and uncovers with a drying height of 1.8 metres (See Chart No. 1, F20, K41) This notice affects Electronic Navigational Chart: CA576001	44°41'43.8"N 063°37'05.0"W  <i>DFO(6309785-03)</i>
<b>4202 - Halifax Harbour: Point Pleasant to / à Bedford Basin - New Edition - 26-FEB-2016 - NAD 1983</b>		
05-NOV-2021		LNMD. 01-OCT-2021
Add	obstruction with known depth of 15.9 metres (See Chart No. 1, K41)  This notice affects Electronic Navigational Chart: CA576003	joining 44°40'40.9"N 063°37'21.1"W 44°40'44.2"N 063°37'22.9"W 44°40'44.6"N 063°37'21.5"W 44°40'41.5"N 063°37'19.6"W and 44°40'40.9"N 063°37'21.1"W  <i>DFO(6309775-03)</i>
12-NOV-2021		LNMD. 05-NOV-2021
Add	black, red and black isolated danger lighted spar buoy FI(2) 5s, marked HQD (See Chart No. 1, Q130.4) This notice affects Electronic Navigational Chart: CA576003	44°37'02.6"N 063°34'22.7"W  <i>(F2021048) LL(532.5) DFO(6309788-01)</i>
<b>4203 - Halifax Harbour: Black Point to / à Point Pleasant - New Edition - 28-DEC-2018 - NAD 1983</b>		
05-NOV-2021		LNMD. 01-OCT-2021
Add	obstruction with known depth of 21.6 metres (See Chart No. 1, K41)  This notice affects Electronic Navigational Chart: CA576002	joining 44°36'23.7"N 063°32'35.3"W 44°36'25.3"N 063°32'29.4"W 44°36'26.4"N 063°32'30.0"W 44°36'24.8"N 063°32'35.8"W and 44°36'23.7"N 063°32'35.3"W  <i>DFO(6309775-05)</i>

Add	obstruction with known depth of 15.9 metres (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA576002	44°36'35.3"N 063°32'16.7"W  DFO(6309775-06)
Add	obstruction with known depth of 31 metres (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA576002	44°36'33.7"N 063°32'24.2"W  DFO(6309775-07)
Add	obstruction with known depth of 27.6 metres (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA576002	44°36'20.2"N 063°32'26.1"W  DFO(6309775-08)
Add	obstruction with known depth of 27.2 metres (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA576002	44°36'20.2"N 063°32'33.8"W  DFO(6309775-09)
12-NOV-2021		LNM/D. 05-NOV-2021
Add	black, red and black isolated danger lighted spar buoy Fl(2) 5s, marked HQD (See Chart No. 1, Q130.4) This notice affects Electronic Navigational Chart: CA576003	44°37'02.6"N 063°34'22.7"W  (F2021048) LL(532.5) DFO(6309788-01)
<b>4281 - Canso Harbour and Approaches / et les Approches - New Edition - 27-SEP-2013 - NAD 1983</b>		
05-NOV-2021		LNM/D. 23-APR-2021
Reposition	red starboard hand spar buoy, marked PN6 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA376067, CA476675, CA576527	from 45°17'01.4"N 060°58'29.5"W to 45°17'01.4"N 060°58'28.0"W  (G2021168) DFO(6309686-01)
<b>4403 - East Point to / à Cape Bear - New Edition - 04-APR-2003 - NAD 1983</b>		
12-NOV-2021		LNM/D. 11-JUN-2021
Reposition	black, yellow and black East Cardinal spar buoy, marked NJA (See Chart No. 1, Q130.3) This notice affects Electronic Navigational Chart: CA376248, CA476490	from 46°11'09.2"N 062°23'09.3"W to 46°11'08.1"N 062°23'17.0"W  (G2021077) DFO(6309592-01)
<b>4486 - Baie des Chaleurs / Chaleur Bay - New Edition - 19-FEB-1999 - NAD 1983</b>		
19-NOV-2021		LNM/D. 16-JUL-2021
Amend	Oc(2)Y10s58ft12M to read LFI 6s12M against light (See Chart No. 1, P16) This notice affects Electronic Navigational Chart: CA279075, CA376187, CA476275	47°53'07.1"N 064°37'28.2"W  (G2021148) LL(1275) DFO(6309666-01)
26-NOV-2021		LNM/D. 19-NOV-2021
Reposition	red and white fairway lighted spar buoy Mo(A), marked TJ (See Chart No. 1, Qh) This notice affects Electronic Navigational Chart: CA376187, CA476275, CA576269	from 47°42'42.2"N 064°39'16.9"W to 47°42'34.1"N 064°39'11.3"W  (G2021181) LL(1248) DFO(6309696-01)
Amend	FIY5s54ft to read LFI 6s against light (See Chart No. 1, P16) This notice affects Electronic Navigational Chart: CA279075, CA376187, CA476275, CA576269	47°43'22.5"N 064°39'37.7"W  (G2021134) LL(1254) DFO(6309744-01)

**4592 - Little Bay Island to / à League Rock - New Edition - 10-OCT-2003 - NAD 1983**

12-NOV-2021 LNMD. 10-SEP-2021

Delete light FIR 49°37'57.0"N 055°48'23.3"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: CA376656  
(N2021139) LL(332.5) DFO(6309708-01)

Delete light FI R 49°38'30.6"N 055°47'17.8"W  
(See Chart No. 1, P1)  
(N2021140) LL(332.3) DFO(6309709-01)

**4642 - Great St. Lawrence Harbour - New Edition - 08-NOV-2002 - NAD 1983**

19-NOV-2021 LNMD. 11-OCT-2019

Add wreck showing a portion of superstructure, with legend PA 46°55'00.2"N 055°23'12.5"W  
(See Chart No. 1, K24, B7)  
DFO(6309740-01)

**4642 - Great St. Lawrence Harbour: Inner Portion / Partie Intérieure - New Edition - 08-NOV-2002 - NAD 1983**

19-NOV-2021 LNMD. 11-OCT-2019

Add wreck showing a portion of superstructure, with legend PA 46°55'00.2"N 055°23'12.5"W  
(See Chart No. 1, K24, B7)  
DFO(6309740-01)

**4644 - Bay D'Espoir and / et Hermitage Bay - New Edition - 25-JUN-1999 - NAD 1983**

05-NOV-2021 LNMD. 28-SEP-2018

Add light FI Y 47°37'52.9"N 056°13'36.4"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: CA376627, CA476479, CA576484  
(N2021101) LL(135.1) DFO(6309654-01)

**4644 - McCallum - New Edition - 25-JUN-1999 - NAD 1983**

05-NOV-2021 LNMD. 28-SEP-2018

Add light FI Y 47°37'52.9"N 056°13'36.4"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: CA376627, CA476479, CA576484  
(N2021101) LL(135.1) DFO(6309654-01)

**4667 - Savage Cove to / à St Barbe Bay - New Edition - 30-MAR-2007 - NAD 1983**

26-NOV-2021 LNMD. 17-SEP-2021

Amend FI R to read Q R against red starboard hand lighted pillar buoy, marked 51°12'43.3"N 056°46'56.4"W  
XB2  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart: CA476568, CA576587  
(N2021138) LL(216.1) DFO(6309736-01)

**4821 - White Bay and / et Notre Dame Bay - New Chart - 23-APR-2004 - NAD 1983**

12-NOV-2021 LNMD. 10-SEP-2021

Delete light FIR 49°37'54.4"N 055°48'26.9"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: CA376656  
(N2021139) LL(332.5) DFO(6309708-01)

**4824 - Garia Bay to / à Burgeo - New Chart - 25-OCT-2002 - NAD 1983**

26-NOV-2021

LNMD. 22-MAY-2020

Amend FI 3s12m6M to read FI 4s11m7M against light 47°38'31.9"N 058°13'29.3"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA276284, CA376616  
(N2021119) LL(147) DFO(6309733-01)

**4827 - Hare Bay to / à Fortune Head - New Chart - 13-AUG-2004 - NAD 1983**

05-NOV-2021

LNMD. 19-MAR-2021

Add light FI Y 47°37'52.9"N 056°13'36.4"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: CA376627, CA476479, CA576484  
(N2021101) LL(135.1) DFO(6309654-01)

**4831 - Fortune Bay: Northern Portion / Partie Nord - New Chart - 26-DEC-1986 - NAD 1983**

12-NOV-2021

LNMD. 24-SEP-2021

Amend FIR 4s to read FI Y 4s against light 47°38'08.4"N 055°12'40.4"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA376316  
(N2021165) LL(115.9) DFO(6309729-01)

**4843 - Head of / Fond de St Mary's Bay - New Edition - 26-DEC-2003 - NAD 1983**

26-NOV-2021

LNMD. 03-SEP-2021

Affix patch 46°58'00.0"N 053°31'30.0"W  
Download Patch - [https://www.notmar.gc.ca/chsftp/patches/4843\\_6309792\\_3\\_202111081501.pdf](https://www.notmar.gc.ca/chsftp/patches/4843_6309792_3_202111081501.pdf)  
This notice affects Electronic Navigational Chart: CA376293  
DFO(6309792-03)

**4843 - St Mary's Harbour and Adjacent Anchorages / et mouillages adjacents - New Edition - 26-DEC-2003 - NAD 1983**

26-NOV-2021

LNMD. 03-SEP-2021

Delete NOTE Wharf Plan - illustrated in Sailing Directions ATL 102. NOTE 46°58'29.0"N 053°32'23.0"W  
Plan du quai - illustré dans les Instructions nautiques ATL 102.  
(See Chart No. 1, A14)  
This notice affects Electronic Navigational Chart: CA376293, CA476294  
DFO(6309792-01)

Delete legend 'See NOTE/Voir NOTE' 46°57'48.0"N 053°32'09.0"W  
(See Chart No. 1, A14)  
This notice affects Electronic Navigational Chart: CA376293, CA476294  
DFO(6309792-02)

Affix patch 46°58'00.0"N 053°31'30.0"W  
Download Patch - [https://www.notmar.gc.ca/chsftp/patches/4843\\_6309792\\_4\\_202111081502.pdf](https://www.notmar.gc.ca/chsftp/patches/4843_6309792_4_202111081502.pdf)  
This notice affects Electronic Navigational Chart: CA476294  
DFO(6309792-04)

**4851 - Trinity Bay: Southern Portion / Partie Sud - New Edition - 30-SEP-2016 - World Geodetic System 1984**

19-NOV-2021

LNMD. 08-FEB-2019

Amend Iso R to read FI R against light 47°34'03.5"N 053°39'59.2"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA376153, CA576815  
(N2021147) LL(466.9) DFO(6309716-01)



Add	light Q G (See Chart No. 1, P1) This notice affects Electronic Navigational Chart: CA376153, CA576815 (N2021154) LL(466.88) DFO(6309723-01)	47°34'04.1"N 053°39'57.7"W
<b>4881 - Gregory Island to Rocky Harbour - New Chart - 26-JUL-2019 - World Geodetic System 1984</b>		
26-NOV-2021		LNm/D. 21-MAY-2021
Add	light FI Y (See Chart No. 1, P1) This notice affects Electronic Navigational Chart: CA476708, CA576710 (N2021159) LL(200.1) DFO(6309725-01)	49°30'31.7"N 057°55'01.3"W
<b>4881 - Norris Point - New Chart - 26-JUL-2019 - World Geodetic System 1984</b>		
26-NOV-2021		LNm/D. 21-MAY-2021
Add	light FI Y 4s4M (See Chart No. 1, P1) This notice affects Electronic Navigational Chart: CA476708, CA576710 (N2021159) LL(200.1) DFO(6309725-01)	49°30'32.2"N 057°55'01.9"W
<b>4905 - Cape Tormentine à / to West Point - New Edition - 29-DEC-2000 - NAD 1983</b>		
05-NOV-2021		LNm/D. 16-JUL-2021
Delete	light FI Y(2) 12s 14m 10M (See Chart No. 1, P1) This notice affects Electronic Navigational Chart: CA276286, CA376076, CA476128 (G2021136) LL(1113) DFO(6309643-01)	46°19'12.0"N 064°30'45.0"W
Add	abandoned lighthouse with legend LtHo (disused) / LtHo (désaffecté) (See Chart No. 1, P1) This notice affects Electronic Navigational Chart: CA276286, CA376076, CA476128 (G2021136) LL(1113) DFO(6309643-02)	46°19'12.0"N 064°30'45.0"W
Reposition	green port hand lighted spar buoy FI G, marked XW1 (See Chart No. 1, Qg) This notice affects Electronic Navigational Chart: CA376076 (G2021172) LL(1126.1) DFO(6309690-01)	from 46°32'21.5"N 064°41'34.3"W to 46°32'26.9"N 064°41'44.6"W
Reposition	red starboard hand lighted spar buoy FI R, marked XW2 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA376076 (G2021173) LL(1126.2) DFO(6309691-01)	from 46°32'25.6"N 064°41'40.6"W to 46°32'27.8"N 064°41'45.2"W
<b>4909 - Cocagne et / and Shediac - New Chart - 17-JUN-1988 - NAD 1983</b>		
05-NOV-2021		LNm/D. 27-AUG-2021
Delete	light FIY(2) 12s 14m 10M (See Chart No. 1, P1) This notice affects Electronic Navigational Chart: CA276286, CA376076, CA476128 (G2021136) LL(1113) DFO(6309643-01)	46°19'11.2"N 064°30'45.8"W
Add	abandoned lighthouse with legend LtHo (disused) / LtHo (désaffecté) (See Chart No. 1, P1) This notice affects Electronic Navigational Chart: CA276286, CA376076, CA476128 (G2021136) LL(1113) DFO(6309643-02)	46°19'11.2"N 064°30'45.8"W
Reposition	red starboard hand lighted pillar buoy Q R, marked XN30 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA476128 (G2021198) LL(1109.83) DFO(6309752-01)	from 46°14'38.9"N 064°32'10.5"W to 46°14'38.2"N 064°32'13.6"W

Add	red starboard hand lighted spar buoy FI R, marked XN24 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA476128	46°14'38.9"N 064°32'02.5"W  (G2021205) LL(1109.82) DFO(6309759-01)
<b>4909 - Richibucto Harbour - New Chart - 17-JUN-1988 - NAD 1983</b>		
05-NOV-2021		LNMD. 27-AUG-2021
Reposition	red starboard hand lighted pillar buoy QR, marked QA8 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA476131	from 46°42'19.5"N 064°51'37.8"W to 46°42'17.8"N 064°51'41.1"W  (G2021146) LL(1149) DFO(6309664-01)
Add	red starboard hand lighted conical buoy FI R, marked Q34 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA476131	46°42'04.4"N 064°49'26.8"W  (G2021178) LL(1147.5) DFO(6309695-01)
<b>4913 - Caraquet Harbour, Baie de Shippegan and / et Miscou Harbour - New Chart - 07-AUG-1992 - NAD 1983</b>		
19-NOV-2021		LNMD. 09-JUL-2021
Amend	Oc(2)Y 10s 18m 12M to read LFI 6s12M against light (See Chart No. 1, P16) This notice affects Electronic Navigational Chart: CA279075, CA376187, CA476275	47°53'03.8"N 064°37'25.0"W  (G2021148) LL(1275) DFO(6309666-01)
Amend	QR to read FI R against light (See Chart No. 1, P16) This notice affects Electronic Navigational Chart: CA476275, CA576263	47°47'48.9"N 064°55'31.3"W  (G2021149) LL(1319) DFO(6309667-01)
Add	light LFI R (See Chart No. 1, P1) This notice affects Electronic Navigational Chart: CA476275, CA576263	47°47'53.5"N 064°55'50.3"W  (G2021152) LL(1319.5) DFO(6309670-01)
Add	light FI R (See Chart No. 1, P1) This notice affects Electronic Navigational Chart: CA476275, CA576263	47°47'49.7"N 064°55'52.7"W  (G2021162) LL(1319.6) DFO(6309679-01)
Add	light FI G (See Chart No. 1, P1) This notice affects Electronic Navigational Chart: CA476275, CA576263	47°47'48.5"N 064°55'52.7"W  (G2021163) LL(1319.7) DFO(6309680-01)
Amend	F Y to read F G against front range/leading light (See Chart No. 1, P20.2) This notice affects Electronic Navigational Chart: CA476275	47°48'30.0"N 064°50'27.8"W  (G2021081) LL(1310) DFO(6309743-01)
26-NOV-2021		LNMD. 19-NOV-2021
Reposition	red and white fairway lighted spar buoy Mo(A), marked TJ (See Chart No. 1, Qh) This notice affects Electronic Navigational Chart: CA376187, CA476275, CA576269	from 47°42'42.2"N 064°39'16.9"W to 47°42'34.1"N 064°39'11.3"W  (G2021181) LL(1248) DFO(6309696-01)
Amend	FIY 5s 16m to read LFI 6s against light (See Chart No. 1, P16) This notice affects Electronic Navigational Chart: CA279075, CA376187, CA476275, CA576269	47°43'19.5"N 064°39'38.0"W  (G2021134) LL(1254) DFO(6309744-01)

**4920 - Caraquet - New Edition - 14-DEC-2018 - NAD 1983**

19-NOV-2021

LNMD. 02-APR-2021

- Amend Q R 7m9M to read FI R 4s7m9M against light 47°47'48.9"N 064°55'31.3"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA476275, CA576263  
(G2021149) LL(1319) DFO(6309667-01)
- Add light LFI R 6s8M 47°47'53.7"N 064°55'50.6"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: CA476275, CA576263  
(G2021152) LL(1319.5) DFO(6309670-01)
- Add light FI R 4s3M 47°47'49.7"N 064°55'52.7"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: CA476275, CA576263  
(G2021162) LL(1319.6) DFO(6309679-01)
- Add light FI G 4s3M 47°47'48.5"N 064°55'52.7"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: CA476275, CA576263  
(G2021163) LL(1319.7) DFO(6309680-01)

**4920 - Middle Caraquet - New Edition - 14-DEC-2018 - NAD 1983**

19-NOV-2021

LNMD. 02-APR-2021

- Amend FI G 4m4M to read FI G 4s4m4M against light 47°48'14.3"N 064°52'22.6"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA476275, CA576266  
(G2021147) LL(1314.1) DFO(6309665-01)
- Amend FI 3s7m9M to read FI 4s7m9M against light 47°48'13.4"N 064°52'22.4"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA576266  
(G2021150) LL(1314) DFO(6309668-01)

**4920 - Shippegan Harbour - New Edition - 14-DEC-2018 - NAD 1983**

26-NOV-2021

LNMD. 19-NOV-2021

- Reposition red and white fairway lighted spar buoy Mo(A), marked TJ from 47°42'42.2"N 064°39'16.8"W  
(See Chart No. 1, Qh) to 47°42'34.1"N 064°39'11.3"W  
This notice affects Electronic Navigational Chart: CA376187, CA476275, CA576269  
(G2021181) LL(1248) DFO(6309696-01)
- Amend FI Y 5s16m15M to read LFI 6s13M against light 47°43'19.7"N 064°39'38.2"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA279075, CA376187, CA476275, CA576269  
(G2021134) LL(1254) DFO(6309744-01)
- Delete red starboard hand conical lighted buoy FI R, marked TJ26 47°43'25.7"N 064°40'02.7"W  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart: CA576269  
(G2021191) LL(1258.125) DFO(6309745-01)
- Delete green port hand lighted can buoy FI G, marked TJ27 47°43'28.8"N 064°40'03.4"W  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational Chart: CA576269  
LL(1257.5) DFO(6309745-02)

Delete	red starboard hand pillar buoy, marked TJ30 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA576269	47°43'33.7"N 064°39'59.5"W  <i>DFO(6309745-03)</i>
Delete	green port hand lighted spar buoy Q G, marked TJ29 (See Chart No. 1, Qg) This notice affects Electronic Navigational Chart: CA576269	47°43'33.8"N 064°40'02.3"W  <i>LL(1257.7) DFO(6309745-04)</i>
Delete	green port hand lighted spar buoy FI G, marked TJ31 (See Chart No. 1, Qg) This notice affects Electronic Navigational Chart: CA576269	47°43'41.6"N 064°40'04.9"W  <i>LL(1258.1) DFO(6309745-05)</i>
Delete	red starboard hand lighted spar buoy FI R, marked TJ32 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA576269	47°43'42.1"N 064°40'02.8"W  <i>LL(1258.12) DFO(6309745-06)</i>
Delete	green port hand lighted spar buoy FI G, marked TJ35 (See Chart No. 1, Qg) This notice affects Electronic Navigational Chart: CA576269	47°43'48.7"N 064°40'08.6"W  <i>LL(1258.125) DFO(6309745-07)</i>
Delete	red starboard hand lighted pillar buoy Q R, marked TJ38 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA576269	47°43'52.2"N 064°40'08.8"W  <i>LL(1260) DFO(6309745-08)</i>
Delete	green port hand spar buoy, marked TJ39 (See Chart No. 1, Qg) This notice affects Electronic Navigational Chart: CA576269	47°43'51.6"N 064°40'11.5"W  <i>DFO(6309745-09)</i>
Delete	green port hand spar buoy, marked TJ41 (See Chart No. 1, Qg) This notice affects Electronic Navigational Chart: CA576269	47°43'58.5"N 064°40'23.1"W  <i>DFO(6309745-10)</i>
Delete	red starboard hand lighted spar buoy FI R, marked TJ42 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA576269	47°44'03.2"N 064°40'30.1"W  <i>LL(1261) DFO(6309745-11)</i>
Delete	green port hand spar buoy, marked TJ43 (See Chart No. 1, Qg) This notice affects Electronic Navigational Chart: CA576269	47°44'02.9"N 064°40'32.6"W  <i>DFO(6309745-12)</i>
Delete	red starboard hand spar buoy, marked TJ46 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA576269	47°44'09.1"N 064°40'51.6"W  <i>DFO(6309745-13)</i>
Delete	green port hand lighted spar buoy FI G, marked TJ47 (See Chart No. 1, Qg) This notice affects Electronic Navigational Chart: CA576269	47°44'09.7"N 064°40'56.5"W  <i>LL(1261.5) DFO(6309745-14)</i>

Delete	red starboard hand spar buoy, marked TJ50 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA576269	47°44'11.8"N 064°40'54.8"W  <i>DFO(6309745-15)</i>
Delete	green port hand lighted spar buoy FI G, marked TJ55 (See Chart No. 1, Qg) This notice affects Electronic Navigational Chart: CA576269	47°44'21.0"N 064°41'06.9"W  <i>LL(1261.55) DFO(6309745-16)</i>
Delete	red starboard hand spar buoy, marked TJ54 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA576269	47°44'22.2"N 064°41'04.8"W  <i>DFO(6309745-17)</i>
Delete	green port hand spar buoy, marked TJ59 (See Chart No. 1, Qg) This notice affects Electronic Navigational Chart: CA576269	47°44'29.0"N 064°41'14.3"W  <i>DFO(6309745-18)</i>
Delete	red starboard hand lighted spar buoy Q R, marked TJ60 (See Chart No. 1, Qf) This notice affects Electronic Navigational Chart: CA576269	47°44'33.2"N 064°41'15.9"W  <i>LL(1261.6) DFO(6309745-19)</i>
Delete	green port hand lighted spar buoy, marked TJ63 (See Chart No. 1, Qg) This notice affects Electronic Navigational Chart: CA576269	47°44'33.1"N 064°41'20.5"W  <i>DFO(6309745-20)</i>
Add	depth of 0.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576269	47°43'07.0"N 064°39'57.5"W  <i>DFO(6309745-21)</i>
Add	depth of 1 metre (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576269	47°42'52.0"N 064°40'07.7"W  <i>DFO(6309745-22)</i>
Add	Chenal balisé/Channel Buoyed This notice affects Electronic Navigational Chart: CA576269	47°43'21.8"N 064°39'58.0"W  <i>DFO(6309745-23)</i>
Replace	depth of 1 metre with depth of 0.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576269	47°44'19.9"N 064°41'00.8"W  <i>DFO(6309745-24)</i>
Add	Chenal balisé/Channel Buoyed This notice affects Electronic Navigational Chart: CA576269	47°44'27.0"N 064°41'00.0"W  <i>DFO(6309745-25)</i>
<b>4935 - Murray Harbour to à Boughton Bay - New Chart - 18-JAN-2019 - NAD 1983</b>		
12-NOV-2021		<i>LNMD. 27-AUG-2021</i>
Reposition	black, yellow and black East Cardinal spar buoy, marked NJA (See Chart No. 1, Q130.3) This notice affects Electronic Navigational Chart: CA376248, CA476490	from 46°11'09.2"N 062°23'09.3"W to 46°11'08.1"N 062°23'17.0"W  <i>(G2021077) DFO(6309592-01)</i>

Reposition red starboard hand conical lighted buoy FI R, marked NM6/2 from 46°01'19.3"N 062°28'52.1"W  
(See Chart No. 1, Qf) to 46°01'13.2"N 062°28'56.4"W  
This notice affects Electronic Navigational Chart: CA476490  
(G2021175) LL(964.1) DFO(6309692-01)

Reposition red starboard hand lighted pillar buoy FI R, marked NM8 from 46°01'13.1"N 062°28'56.4"W  
(See Chart No. 1, Qf) to 46°01'10.2"N 062°29'04.2"W  
This notice affects Electronic Navigational Chart: CA476490  
(G2021176) LL(966) DFO(6309693-01)

**5031 - Fox Harbour - New Edition - 31-DEC-1999 - NAD 1983**  
12-NOV-2021

LNMD. 27-MAR-2020

Affix patch 52°22'00.0"N 055°42'00.0"W  
Download Patch - [https://www.notmar.gc.ca/chsftp/patches/5031\\_6309786\\_1\\_202110071205.pdf](https://www.notmar.gc.ca/chsftp/patches/5031_6309786_1_202110071205.pdf)  
This notice affects Electronic Navigational Chart: CA576381  
DFO(6309786-01)

## Section 3: Radio Aids to Marine Navigation Corrections

### \*1115/21 Radio Aids to Marine Navigation 2021 (Atlantic, St. Lawrence, Great Lakes, Lake Winnipeg, Arctic and Pacific)

**Pages 2-3 to 2-5**

**AMEND AS FOLLOWS FOR SECTION 2.1.1:**

**Table 2-2 - Halifax MCTS/VCS - Broadcasts**

Time UTC	Site	Frequency or Channel	Contents
01:40	Yarmouth (Chebogue)	2749J3E	Radiotelephony (English followed by French) <ul style="list-style-type: none"> <li>• Technical marine synopsis, forecasts and wave height forecasts for marine forecast areas 201 to <del>244</del> 208.</li> <li>• U.S. weather forecasts for Coastal Waters (Eastport to Schoodic Point, Maine) and Offshore Waters (Gulf of Maine to the Hague Line).</li> <li>• Navigational warnings in areas Bay of Fundy, South and West Coast Nova Scotia.</li> </ul>
02:40	Sambro	2749J3E	Radiotelephony (English followed by French) <ul style="list-style-type: none"> <li>• Technical marine synopsis, forecasts and wave height forecasts for marine forecast areas <del>204</del> 206 to 211.</li> <li>• Navigational warnings in South Coast Nova Scotia area.</li> <li>• Navigational warnings revising the position of every reported offshore exploration and exploitation vessel.</li> </ul>
...	...	...	...
08:10	Sambro	2749J3E	Radiotelephony (English followed by French) <ul style="list-style-type: none"> <li>• Technical marine synopsis, forecasts and wave height forecasts for marine forecast areas <del>204</del> 206 to 211.</li> <li>• Notices to Fish Harvesters (when available).</li> </ul>
10:40	Yarmouth (Chebogue)	2749J3E	Radiotelephony (English followed by French) <ul style="list-style-type: none"> <li>• Technical marine synopsis, forecasts and wave height forecasts for marine forecast areas 201 to <del>244</del> 208.</li> <li>• U.S. weather forecasts for Coastal Waters (Eastport to Schoodic Point, Maine) and Offshore Water (Gulf of Maine to the Hague Line).</li> <li>• Notices to Fish Harvesters (when available).</li> </ul>
...	...	...	...
15:40	Sambro	2749J3E	Radiotelephony (English followed by French) <ul style="list-style-type: none"> <li>• Technical marine synopsis, forecasts and wave height forecasts for marine forecast areas <del>204</del> 206 to 211.</li> <li>• Navigational warnings in South Coast Nova Scotia area.</li> <li>• Navigational warnings revising the position of every reported offshore exploration and exploitation vessel.</li> </ul>
16:40	Yarmouth (Chebogue)	2749J3E	Radiotelephony (English followed by French) <ul style="list-style-type: none"> <li>• Technical marine synopsis, forecasts and wave height forecasts for marine forecast areas 201 to <del>244</del> 208.</li> <li>• U.S. weather forecasts for Coastal Waters (Eastport to Schoodic Point, Maine) and Offshore Waters (Gulf of Maine to the Hague Line).</li> <li>• Navigational warnings for areas Bay of Fundy, South and West Coast Nova Scotia.</li> </ul>

Notices to Mariners – Monthly Eastern Edition  
Section 3: Radio Aids to Marine Navigation Corrections

Time UTC	Site	Frequency or Channel	Contents
...	...	...	...
20:40	Yarmouth (Chebogue)	2749J3E	Radiotelephony (English followed by French) <ul style="list-style-type: none"> <li>• Technical marine synopsis, forecasts and wave height forecasts for marine forecast areas 201 to <del>214</del> 208.</li> <li>• U.S. weather forecasts for Coastal Waters (Eastport to Schoodic Point, Maine) and Offshore Waters (Gulf of Maine to the Hague Line).</li> <li>• Notices to Fish Harvesters (when available).</li> </ul>
21:20	Sambro	2749J3E	Radiotelephony (English followed by French) <ul style="list-style-type: none"> <li>• Technical marine synopsis, forecasts and wave height forecasts for marine forecast areas <del>204</del> 206 to 211.</li> <li>• Notices to Fish Harvesters (when available).</li> </ul>
...	...	...	...



## Section 4: Sailing Directions and Small Craft Guide Corrections

---

ARC 403 — Western Arctic, First Edition, 2011 —

- Chapter 7 — Paragraph 57  
Delete : **Unahitak Island**  
Replace by: **Ungahitak** (A2021-008.01)
- Chapter 7 — Paragraph 58  
Delete : **Qikirtaarjuk Islands**  
Replace by: **Qikiqtaaryuuk** (A2021-008.02)
- Chapter 7 — Paragraph 72  
Delete : **Long Point**  
Replace by: **Tikiraaryuaq** (A2021-008.03)
- Chapter 7 — Paragraph 73, 74, 75  
Delete : Long Point  
Replace by: Tikiraaryuaq (A2021-008.04)
- Chapter 7 — Paragraph 76  
Delete : **Cape Colborne**  
Replace by: **Kinngaaryuk** (A2021-008.05)
- Chapter 7 — Paragraph 77  
Delete : Cape Colborne  
Replace by: Kinngaaryuk (A2021-008.06)
- Chapter 7 — Paragraph 83  
Delete : **Simpson Rock**  
Replace by: **Aliitimaaq** (A2021-008.07)
- Chapter 7 — Paragraph 84, 85 (twice), 88  
Delete : Simpson Rock  
Replace by: Aliitimaaq (A2021-008.08)
- Chapter 7 — Paragraph 86  
Delete : **Jago Islet**  
Replace by: **Napaqtilik** (A2021-008.09)
- Chapter 7 — Paragraph 87, 88, 89, 90, 91, 92  
Delete : Jago Islet  
Replace by: Napaqtilik (A2021-008.10)

Chapter 7 — Paragraph 93 Delete : <b>West Arm</b> Replace by: <b>Kangiqhuk</b>	(A2021-008.11)
Chapter 7 — Paragraph 96, 98, 99 Delete : West Arm Replace by: Kangiqhuk	(A2021-008.12)
Chapter 7 — Paragraph 178 Delete : <b>Melbourne Island</b> Replace by: <b>Qikiqtaryuaq</b>	(A2021-008.13)
Chapter 7 — Paragraph 179 Delete : Melbourne Island Replace by: Qikiqtaryuaq	(A2021-008.14)
Chapter 7 — Paragraph 182 Delete : <b>Ellice River</b> Replace by: <b>Kuunajuk</b>	(A2021-008.15)
INDEX — After ‘Umingmaktok (outpost camp), C6/P211’ Delete : Unahitak Island, C7/P57	(A2021-008.16)
INDEX — After ‘Unark L-24, C1/P133’ Insert: Ungahitak, C7/P57	(A2021-008.17)
INDEX — After ‘Qikirtaarjuk Island, C5/P83’ Delete : Qikirtaarjuk Islands, C7/P58	(A2021-008.18)
INDEX — After ‘Qikirtaarjuk Island, C5/P83’ Insert: Qikiqtaaryuuk, C7/P58	(A2021-008.19)
INDEX — After ‘Longford Point, C11/P104’ Delete : Long Point, C7/P72	(A2021-008.20)
INDEX — After ‘Tikigayok Point, C7/P53’ Insert: Tikiraaryuaq, C7/P72	(A2021-008.21)
INDEX — After ‘Cape Cockburn, C10/P60’ Delete : Cape Colborne, C7/P76	(A2021-008.22)
INDEX — After ‘King William Island, C8/P19’ Insert: Kinngaaryuk, C7/P77	(A2021-008.23)

INDEX — After ‘Simpson River, C7/P206’  
Delete : Simpson Rock, C7/83  
(A2021-008.24)

INDEX — After ‘Alicia Island, C8/P28’  
Insert: Aliitimaq, C7/P83  
(A2021-008.25)

INDEX — After ‘Jago Bay, C4/P86’  
Delete : Jago Islet, C7/P86  
(A2021-008.26)

INDEX — After ‘Napaaktoktok River, C6/P123’  
Insert: Napaqtilik, C7/P86  
(A2021-008.27)

INDEX — After ‘Wentzel River, C6/P157’  
Delete : West Arm, C7/93  
(A2021-008.28)

INDEX — After ‘Kamakark Island, C3/P111’  
Insert: Kangiqhuk, C7/P93  
(A2021-008.29)

INDEX — After ‘Meighen Island, C12/P143’  
Delete : Melbourne Island, C7/P178  
(A2021-008.30)

INDEX — After ‘Qikiqtarjuaq Island, C8/P265’  
Insert: Qikiqtaryuaq, C7/P178  
(A2021-008.31)

INDEX — After ‘Ellice Island, C1/P121’  
Delete : Ellice River C7/P182  
(A2021-008.32)

INDEX — After ‘Kuuk (River), C4/P168’  
Insert: Kuunajuk, C7/P182  
(A2021-008.33)

ATL 101 — Newfoundland, Northeast and East Coasts, Second Edition, 2013 —

Chapter 1 – Paragraph 8  
Delete: “(235.2)”  
Replace by: (237.4)  
(N2021-03.0)

Chapter 4 – Paragraph 277, last line  
Add: A shoal marked by port hand light **buoy** DVA5 (360.47) and extending 0.05 mile from the eastern shore is located 0.3 mile SSW of the previously described rock awash.  
(N2021-03.1)

ATL 102 — Newfoundland, East and South Coasts, Second Edition, 2008

Chapter 2 – Adjacent to paragraph 161.1, add a caution pictograph.  
(N2021-03.2)

Chapter 5 – after paragraph 63

Insert: 63.1 **Tim Barrett Rock**, marked by starboard hand light **buoy** EL2 (37.45) is located on the south shore of Long Harbour about 1 mile south of the west tip of Crawley Island.

(N2021-03.3)

Chapter 5 – Paragraph 109 – after, “for over 0.1 mile.”

Add: A shoal with a least depth of 18.3 m (60 ft) and marked by starboard hand light buoy EW2 (38.65) is located about 4 miles SW of Come by Chance Point. The northern extremity of **Big Shoal** located 4 miles west of Come by Chance Point is marked by west cardinal light **buoy** EWC (38.67).

(N2021-03.4)

Chapter 6 – Paragraph 20

Delete: “A **light** (72) ... located on Long Point.”

(N2021-03.5)

INDEX – after, Tilton Head, C1/P109

Insert: Tim Barrett Rock, C5/P63.1

(N2021-03.6)

ATL 103 — Newfoundland, Southwest Coast, Second Edition, 2010

Chapter 2 – Paragraph 38

Delete: “A **light** (106.51) ... west floating wharf.”

(N2021-03.7)

Chapter 3 – after paragraph 123

Insert: 123.1 Marine farms are charted in Devil Bay, Little Bay, Rencontre Bay and Chaleur Bay; **caution** is advised.

(N2021-03.8)

Chapter 3 – Adjacent to paragraph 123.1, add a caution pictograph.

(N2021-03.9)

ATL 108 — Gulf of St. Lawrence (Southwest Portion), First Edition, 2006 —

Chapter 2 — In the vicinity of paragraph 37

Replace the **GRANDE-ENTRÉE** diagram with the new one provided in **Section 4** of this Monthly Edition.

<https://www.notmar.gc.ca/publications/monthly-mensuel/images/ed112021-sec4-atl108-Grande-Entree-20210430.pdf>

(Q2021-018.1)

Chapter 2 — Paragraph 52.1

Delete: 4.8 m

Replace by: 2.1 m

(Q2021-029.1)

Chapter 2 — Paragraph 54

Delete: close upstream of the bridge.

Replace by: under the bridge, west of the channel.

(Q2021-041.1)

Chapter 2 — In the vicinity of paragraph 112

Replace the **GROSSE-ÎLE-NORD** diagram with the new one provided in **Section 4** of this Monthly Edition.

<https://www.notmar.gc.ca/publications/monthly-mensuel/images/ed112021-sec4-atl108-Grosse-Ile-Nord-20210921.pdf>

(Q2021-032.1)

Chapter 4 — Paragraph 174

Delete: The depths alongside the irregular wharves are of 3.2 to 3.7 m (2017) and there are floating docks in the inner basin.

Replace by: Refer to the existing chart for depths inside the harbour.

(Q2021-031.1)

ATL 109 — Gulf of St. Lawrence, (Northeast Portion), First Edition, 2006

Chapter 1 – Paragraph 34

Delete: “(235.2)”

Replace by: (237.4)

(N2021-04.0)

Chapter 3 – Paragraph 170

Delete: “7 feet (2 m)”

Replace by: 4 feet (1.3 m)

(N2021-04.1)

ATL 110 — St. Lawrence River — Cap Whittle/Cap Gaspé to Les Escoumins and Anticosti Island, Third Edition, 2011 —

Chapter 1-19 — In the vicinity of paragraph 223

Replace the **RIVIÈRE-AU- TONNERRE** diagram with the new one provided in **Section 4** of this Monthly Edition.

<https://www.notmar.gc.ca/publications/monthly-mensuel/images/ed112021-sec4-atl110-Riviere-Au-Tonnerre-20210922.pdf>

(Q2021-038.1)

Chapter 1 — In the vicinity of paragraph 366

Replace the **BAIE-TRINITÉ** diagram with the new one provided in **Section 4** of this Monthly Edition.

<https://www.notmar.gc.ca/publications/monthly-mensuel/images/ed112021-sec4-atl110-Baie-Trinite-20210921.pdf>

(Q2021-020.1)

ATL 112 — St. Lawrence River — Cap-Rouge to Montréal and Rivière Richelieu, Third Edition, 2009 —

Chapter 3 — Paragraph 112, last line

Add: 870 m to the south, there is an area of submerged rocks.

(Q2021-034.1)

CEN 302 — Lake Ontario, First Edition, 1996 —

Chapter 2 — Paragraph 54

Delete : ‘*East Charity Shoal*’... to ...‘*Charity Shoal Light*.’

(C2021-003.01)

Chapter 2 — Paragraph 54

Delete : ‘...*close on this buoy and...*’

(C2021-003.02)

CEN 308 — Rideau Canal and Ottawa River, First Edition, 2003 —

Chapter 8 — After paragraph 94

Insert: 95 The Fassett marina, located in the village of Fassett, is  
0.3 m east of the public wharf and has floating pontoons.

(Q2021-042.1)

## Section 5: List of Lights, Buoys and Fog Signals Corrections

The amendments are highlighted and deletions are crossed out. For general and region-specific information on the List of Lights, click on the following links: [Newfoundland and Labrador Coast](#), [Atlantic Coast](#), [Inland Waters](#) and [Pacific Coast](#).

No.	Name	Position ----- Latitude N. Longitude W.	Light Characteristics	Focal Height in m. above water	Nomi- nal Range	Description ----- Height in meters above ground	Remarks ----- Fog Signals
-----	------	--	--------------------------	--	-----------------------	--	---------------------------------

### NEWFOUNDLAND AND LABRADOR COAST

#### PLACENTIA BAY (LL 14.4 – 79)

51.6 <del>H0386.2</del>	Graveyard Point Light	N. of Marticot. 47 20 52.6 054 35 55.6	Fl R 4s	3.7	3	Cylindrical Mast. 2.4	Flash 1 s; eclipse 3 s. Year round.  Chart:4622 Edn 11/21 (N21-103)
----------------------------	--------------------------	--	---------	-----	---	--------------------------	---

#### FORTUNE BAY (LL 100 – 120.1)

115.9 <del>H0309.5</del>	Rencontre East Wharf Light	Middle of outer wharf edge. 47 38 09.4 055 12 42.1	Fl Y 4s	.....	7	Mast. 2.6	Flash 1 s; eclipse 3 s. Year round.  Chart:4831 Edn 11/21 (N21-165)
-----------------------------	-------------------------------	---	---------	-------	---	--------------	---

#### SOUTHWEST COAST (LL 121 – 172)

135.1	McCallum Marine Wharf Light	On the ferry wharf. 47 37 52.9 056 13 36.4	Fl Y 4s	.....	2	Mast.	Flash 1 s; eclipse 3 s. Operates 24 h. Year round.  Chart:4644 Edn 11/21 (N21-101)
-------	--------------------------------	--	---------	-------	---	-------	---

144.8 <del>H0259</del>	Rencontre Island Light	E. of Burgeo Islands. 47 35 13.0 057 36 29.3	Fl W 4s	57.3	8	Square skeleton tower, red and white rectangular daymark. 4.7	Flash 1 s; eclipse 3 s. Operates 24 h. Year round.  Chart:4825 Edn 11/21 (N21-166)
---------------------------	---------------------------	---	---------	------	---	--	---

147 <del>H0254</del>	Grand Bruit Light	On Offer Island. 47 38 31.9 058 13 29.3	Fl W 4s	11.0	7	Square skeleton tower, red and white rectangular daymark. 4.6	Flash 1 s; eclipse 3 s. Year round.  Chart:4824 Edn 11/21 (N21-119)
-------------------------	-------------------	---	---------	------	---	--	---

#### WEST COAST (LL 173 – 208.2)

200.1	Curzon Village Light	Outer corner of the wharf. 49 30 32.2 057 55 01.9	Fl Y 4s	.....	4	Mast.	Flash 1 s; eclipse 3 s. Operates 24 h. Seasonal.  Chart:4881 Edn 11/21 (N21-159)
-------	-------------------------	--	---------	-------	---	-------	---

#### NEWFOUNDLAND AND LABRADOR COAST (LL 269.99 – 325.23)

270.92	Brandies Shoal light buoy NA5	Northern Ships Run. 52 32 35.6 056 02 24.9	Fl G 4s	.....	.....	Green spar, marked "NA5".	Seasonal.  Chart:5179 Edn 11/21 (N21-100)
--------	----------------------------------	--	---------	-------	-------	---------------------------	--

Notices to Mariners – Monthly Eastern Edition  
Section 5: List of Lights, Buoys and Fog Signals Corrections

No.	Name	Position ----- Latitude N. Longitude W.	Light Characteristics	Focal Height in m. above water	Nomi- nal Range	Description ----- Height in meters above ground	Remarks ----- Fog Signals
-----	------	--	--------------------------	--	-----------------------	--	---------------------------------

**NOTRE DAME BAY (LL 326 – 346.4, 354 – 395)**

332.3	Little Bay Islands Wharf						Delete from list.  Chart:4592 Edn 11/21 (N21-140)
332.5	Suley Ann Cove Ferry Wharf						Delete from list.  Chart:4592 Edn 11/21 (N21-139)

**BONAVISTA BAY (LL 396 – 449.5)**

442.8 H0540.4	Duntara Wharf Light	48 35 58.5 053 22 16.5	Fl R 4s	.....	2	Cylindrical skeleton Mast. 2.6	Flash 1 s; eclipse 3 s. Seasonal.  Chart:4854 Edn 11/21 (N21-141)
443 H0540	Kings Cove Head Light	48 34 32.0 053 19 25.0	Fl W 4s	53.6	5	White cylindrical tower. 8.3	Flash 1 s; eclipse 3 s. Seasonal.  Chart:4854 Edn 11/21 (N21-143)

**TRINITY BAY (LL 450.1 – 471.51)**

458	Manuel Island						Delete from list.  Chart:4849 Edn 11/21 (N21-229)
465.7 H0513.5	Sunnyside Wharf Light	47 51 13.1 053 53 01.4	Fl R 4s	.....	2	Mast. 2.6	Flash 1 s; eclipse 3 s. Year round.  Chart:4851 Edn 11/21 (N21-148)
466.6 H0513.9	Hickman's Harbour Wharf Light	48 05 58.8 053 44 24.8	Fl G 4s	3.4	3	Mast. 2.6	Year round.  Chart:4852 Edn 11/21 (N21-150)
466.88	Long Cove North Light	On N. side of the entrance to Long Cove Harbour. 47 34 04.1 053 39 57.7	Q G 1s	.....	.....	Mast.	Operates 24 h. Seasonal.  Chart:4851 Edn 11/21 (N21-154)
466.89 H0511.1	Long Cove Wharf Light	Inner corner of the wharf. 47 34 02.4 053 39 56.5	Fl R 4s	.....	.....	Cylindrical Mast. 2.6	Flash 1 s; eclipse 3 s. Year round.  Chart:4851 Edn 11/21 (N21-146)
466.9 H0511.15	Long Cove Light	47 34 03.5 053 39 59.2	Fl R 4s	10.8	4	Square skeleton tower, red and white rectangular daymark. 5.9	Flash 1 s; eclipse 3 s. Seasonal.  Chart:4851 Edn 11/21 (N21-147)



Notices to Mariners – Monthly Eastern Edition  
Section 5: List of Lights, Buoys and Fog Signals Corrections

No.	Name	Position ----- Latitude N. Longitude W.	Light Characteristics	Focal Height in m. above water	Nomi- nal Range	Description ----- Height in meters above ground	Remarks ----- Fog Signals
-----	------	--	--------------------------	--	-----------------------	--	---------------------------------

ATLANTIC COAST

**NOVA SCOTIA, SOUTHEAST COAST (LL 327 – 684.02)**

532.5	Northwest Arm light buoy HQD	44 37 02.6 063 34 22.7	Fl(2) W 5s	.....	.....	Black, red and black, marked "HQD".	Flash 0.3 s; eclipse 0.4 s; flash 0.3 s; eclipse 4 s. Year round.  Chart:4202 Edn 11/21 (F21-048)
-------	---------------------------------	---------------------------	------------	-------	-------	--	--

**CAPE BRETON ISLAND, N.S. (LL 704.85 – 882.5)**

785.5	Barachois light buoy S14	At entrance to creek. 46 09 32.8 060 12 53.0	Fl R 4s	.....	.....	Red spar, marked "S14".	Year round.  Chart:4266 Edn 11/21 (G21-218)
787	Dobsons Point light buoy S18	On edge of shoal. 46 08 27.7 060 12 13.7	Fl R 4s	.....	.....	Red spar, marked "S18".	Year round.  Chart:4266 Edn 11/21 (G21-219)

**GULF OF ST. LAWRENCE (LL 883.2 – 940.3, 1169.1 – 1426, 1477.5 – 1584)**

1248	Shippagan Fairway light buoy TJ	S. entrance to Shippagan Gully. 47 42 34.1 064 39 11.3	Mo(A) W 6s	.....	.....	Red and white vertical striped spar, marked "TJ".	Buoy may be repositioned due to shifting channel. Seasonal.  Chart:4920 Edn 11/21 (G21-151, 181)
1254 H1530	Big Shippagan	On sand bar, E. side of S. entrance to Shippagan Gully. 47 43 19.7 064 39 38.2	LFl W 6s	.....	13	White octagonal tower with red upper portion. 16.1	Flash 2 s; eclipse 4 s. Year round.  Chart:4920 Edn 11/21 (G21-134)
1257.5	Shippagan South Gully light buoy TJ27	47 43 28.0 064 40 03.8	Fl G 4s	.....	.....	Green, marked "TJ27".	(Winter spar.) Buoy may be repositioned due to shifting channel. Seasonal.  Chart:4920 Edn 11/21 (G21-190)
1258.125	Shippagan South Gully light spar buoy TJ35	47 43 47.6 064 40 06.1	Fl G 4s	.....	.....	Green spar, marked "TJ35".	Buoy may be repositioned due to shifting channel. Seasonal.  Chart:4920 Edn 11/21 (G21-191)
1261	Shippagan Gully light buoy TJ40	47 43 58.7 064 40 19.0	Fl R 4s	.....	.....	Red spar, marked "TJ40".	Buoy may be repositioned due to shifting channel. Seasonal (in place year round).  Chart:4920 Edn 11/21 (G21-194, 206)
1261.5	Shippagan South Gully light buoy TJ51	47 44 09.5 064 40 56.2	Fl G 4s	.....	.....	Green spar, marked "TJ51".	Buoy may be repositioned due to shifting channel. Seasonal (in place year round).  Chart:4920 Edn 11/21 (G21-197)

Notices to Mariners – Monthly Eastern Edition  
Section 5: List of Lights, Buoys and Fog Signals Corrections

No.	Name	Position ----- Latitude N. Longitude W.	Light Characteristics	Focal Height in m. above water	Nomi- nal Range	Description ----- Height in meters above ground	Remarks ----- Fog Signals
1261.6	Shippegan <b>Gully</b> light buoy TJ60	47 44 33.4 064 41 14.0	Q R 1s	.....	.....	Red spar, marked "TJ60".	Buoy may be repositioned due to shifting channel. Seasonal (in place year round). <del>(Winter spar.)</del>  Chart:4920 Edn 11/21 (G21-203, 215)
1269.2	Miscou Channel light buoy EA5	47 54 19.5 064 37 58.6	Fl G 4s	.....	.....	Green <b>spar</b> , marked "EA5".	Buoy may be repositioned due to shifting channel. Seasonal.  Chart:4913 Edn 11/21 (G21-213)
1275 H1556	Black Point	47 53 03.8 064 37 25.0	<b>LFl</b> <b>W</b> <b>6s</b>	<b>.....</b>	12	Skeleton tower with red top, enclosed central portion, red and white rectangular daymark. 17.7	Flash 2 s; eclipse 4 s. <del>flash 2 s; eclipse 2 s.</del> Year round.  Chart:4913 Edn 11/21 (G21-148)
1310 H1580	Caraquet range	NE. of Stoke Point. 47 48 30.0 064 50 27.8	F <b>G</b> .....	8.1	<b>17</b>	White square tower with red vertical stripe. 7.1	Operates 24 h. Seasonal.
1311 H1580.1		226°47' 1091.4 m from front.	F G .....	.....	<b>18</b>	Square skeleton tower, white daymark with red vertical stripe.	Operates 24 h. Seasonal.  Chart:4913 Edn 11/21 (G21-081)
1314 H1582	Middle Caraquet Wharf	On outer end of E. section of wharf. 47 48 13.4 064 52 22.4	Fl W <b>4s</b>	7.3	9	<b>Pipe swing pole.</b> 6.7	Flash 1 s; eclipse 3 s. <del>Operates at night only.</del> Seasonal.  Chart:4920 Edn 11/21 (G21-150)
1314.1 H1582.4	Middle Caraquet East Wharf	47 48 14.3 064 52 22.6	Fl G 4s	4.3	4	Pipe swing pole.	Flash 1 s; eclipse 3 s. Seasonal.  Chart:4920 Edn 11/21 (G21-147)
1319 H1583	Young Wharf	On SE. corner of wharf. 47 47 48.9 064 55 31.3	<b>Fl</b> R <b>4s</b>	7.5	9	Pipe swing pole, red and white triangular daymark, red white and red. 7.1	Flash 1 s; eclipse 3 s. Seasonal.  Chart:4920 Edn 11/21 (G21-149)
<b>1319.5</b>	<b>Caraquet Harbour Breakwater Light</b>	<b>47 47 53.7</b> <b>064 55 50.6</b>	<b>LFl</b> <b>R</b> <b>6s</b>	<b>.....</b>	<b>8</b>	<b>Pipe tower, red and white triangular daymark.</b>	Flash 2 s; eclipse 4 s. Seasonal.  Chart:4920 Edn 11/21 (G21-152)
<b>1319.6</b>	<b>Caraquet Inner Breakwater Light</b>	On the inner corner of the breakwater. <b>47 47 49.7</b> <b>064 55 52.8</b>	<b>Fl</b> <b>R</b> <b>4s</b>	<b>.....</b>	<b>3</b>	<b>Pipe tower, red and white triangular daymark.</b> 1.0	Private aid. Flash 1 s; eclipse 3 s. Operates 24 h. Seasonal.  Chart:4920 Edn 11/21 (G21-162)

Notices to Mariners – Monthly Eastern Edition  
Section 5: List of Lights, Buoys and Fog Signals Corrections

No.	Name	Position ----- Latitude N. Longitude W.	Light Characteristics	Focal Height in m. above water	Nomi- nal Range	Description ----- Height in meters above ground	Remarks ----- Fog Signals
1319.7	Caraquet Inner Breakwater Light	On the end of the inner breakwater. 47 47 48.6 064 55 52.7	Fl G 4s	.....	3	Pipe tower, green-white- black square daymark. 1.0	Private aid. Flash 1 s; eclipse 3 s. Operates 24 h. Seasonal.  Chart:4920 Edn 11/21 (G21-163)
<b>PRINCE EDWARD ISLAND (LL 942 – 1084.7)</b>							
964.1	Sable Point light buoy NM6/2	46 01 13.2 062 28 56.4	Fl R 4s	.....	.....	Red spar, marked "NM6/2".	Seasonal.  Chart:4935 Edn 11/21 (G21-175)
966	Sable Point light buoy NM8	Off Point. 46 01 10.2 062 29 04.2	Fl R 4s	.....	.....	Red, marked "NM8".	Seasonal.  Chart:4935 Edn 11/21 (G21-176)
<b>NORTHUMBERLAND STRAIT (LL 1085 – 1165.9)</b>							
1109.82	Shediac Harbour light buoy XN24	46 14 38.9 064 32 02.5	Fl R 4s	.....	.....	Red spar, marked "XN24".	Seasonal.  Chart:4909 Edn 11/21 (G21-205)
1109.83	Shediac light buoy XN30	46 14 38.2 064 32 13.6	Q R 1s	.....	.....	Red, marked "XN30".	Operates 24 h. Seasonal.  Chart:4909 Edn 11/21 (G21-198)
1113 H1350	Caissie Point						Delete from list.  Chart:4909 Edn 11/21 (G21-136)
1126.1	Saint-Édouard-de- Kent light buoy XW1	Near the wharf. 46 32 26.9 064 41 44.6	Fl G 4s	.....	.....	Green spar, marked "XW1".	Seasonal.  Chart:4905 Edn 11/21 (G21-172)
1126.2	Saint-Édouard-de- Kent light buoy XW2	Near the wharf. 46 32 27.8 064 41 45.2	Fl R 4s	.....	.....	Red spar, marked "XW2".	Seasonal.  Chart:4905 Edn 11/21 (G21-173)
1147.5	Richibucto Harbour light buoy Q34	46 42 04.4 064 49 26.8	Fl R 4s	.....	.....	Red, marked "Q34".	Operates 24 h. Seasonal.  Chart:4909 Edn 11/21 (G21-178)
1148.5	Richibucto Harbour Northwest Branch light buoy QA7	46 42 19.2 064 51 20.4	Q G 1s	.....	.....	Green spar, marked "QA7".	Buoy may be repositioned due to shifting channel. Seasonal.  Chart:4909 Edn 11/21 (G21-145)
1149	Richibucto Northwest Branch light buoy QA8	46 42 17.8 064 51 41.1	Q R 1s	.....	.....	Red, marked "QA8".	Buoy may be repositioned due to shifting channel. Seasonal.  Chart:4909 Edn 11/21 (G21-146)

Notices to Mariners – Monthly Eastern Edition  
Section 5: List of Lights, Buoys and Fog Signals Corrections

No.	Name	Position ----- Latitude N. Longitude W.	Light Characteristics	Focal Height in m. above water	Nomi- nal Range	Description ----- Height in meters above ground	Remarks ----- Fog Signals
-----	------	--	--------------------------	--	-----------------------	--	---------------------------------

INLAND WATERS

**LAKE ONTARIO (LL 403.4 – 551)**

530	Bronte	On N. pier near its outer end. 43 23 34.3 079 42 21.1	Fl R 4s	7.4	.....	White rectangular tower with red top. 5.0	Seasonal.  Chart:2086 Edn 11/21 (B21-029)
530.5	Bronte West	On the end of W. breakwall. 43 23 33.7 079 42 24.1	Fl G 4s	7.4	3	White rectangular tower with green top. 5.2	Seasonal (in place year round).  Chart:2086 Edn 11/21 (B21-028)
544.7	St. Catharines Breakwater	Outer end of marina breakwater. 43 13 51.2 079 12 39.3	Fl R 4s	8.5	.....	White cylindrical tower with red upper portion. 5.3	Seasonal.  Chart:2042 Edn 11/21 (B21-030)