Canadian General Standards Board

Office des normes générales du Canada

1-GP-71
Method 119.18
May 1979

(F)1-GP-71
Méthode 119.18
Mai 1979

WITHDRAWAL

RETRAIT

August 1988

Août 1988

CANADIAN GENERAL
STANDARDS BOARD

OFFICE DES NORMES
GÉNÉRALES DU CANADA

FLEXIBILITY
FLEXIBILITY OF STRIPPABLE COATING

This test method is hereby withdrawn. It has been determined that it is no longer used because the standard that referenced it has been withdrawn.

SOUPLESSE
REVÊTEMENTS PELABLES

Cette méthode d'essai est retirée par le présent avis. Il a été établi qu'elle n'est plus utilisée dans la mesure où la norme qui s'y référait a également été retirée.

Canada

Canadian General Standards Board

CGSB Ottawa Canada K1A 1G6	Methods of Testing Paints and Pigments	CGSB 1-GP-71
	FLEXIBILITY FLEXIBILITY OF STRIPPABLE COATING	METHOD 119.18 May 1979

Supersedes Issue of
August 1974

Remove a sufficient number of 150 mm x 25 mm strips of film to give a representative test result from panels prepared as directed in the specification, and from similar panels subjected to accelerated weathering. Place the strips, the specified mandrel and a pair of gloves* in an environment at -40 ± 2°C for 2 h and bend the film through 180° over the mandrel in the low-temperature environment in not less than 1 s and not more than 1.5 s. Care should be taken to maintain the film strips at the specified temperature during the test.

Examine the film strips under 10-power magnification.

Withdrawn/Retired

* Cooling the gloves will aid in maintaining the specified temperature during the test.

Office des normes générales du Canada

ONGC Ottawa Canada K1A 1G6	Méthodes d'essai des peintures et pigments	ONGC (F)1-GP-71
	SOUPLESSE REVÊTEMENTS PELABLES	MÉTHODE 119.18 Mai 1979

Remplace l'édition d'août 1974

Enlever un nombre suffisant de bandes de feuils de 150 mm x 25 mm pour obtenir un résultat représentatif sur des plaques préparées selon les directives de la norme et sur des plaques semblables soumises à un vieillissement accéléré. Placer les bandes de feuils, le mandrin prescrit et une paire de gants* dans un milieu ambiant à -40 ±2°C durant 2 h et plier les feuils à 180° sur le mandrin dans le milieu ambiant à basse température en un temps compris entre 1 et 1.5 s. Durant l'essai, maintenir les bandes de feuil à la température prescrite.

Examiner les bandes de feuils sous un grossissement de 10.

Withdrawn/Retirée

* Le refroidissement des gants aidera à garder la température prescrite durant l'essai.