Canadian General Standards Board

Office des normes générales du Canada

1-GP-71
Method 122.15
June 1980

(F)1-GP-71
Méthode 122.15
Juin 1980

WITHDRAWAL

RETRAIT

June 1993

Juin 1993

CANADIAN GENERAL STANDARDS BOARD

ACCELERATED WEATHERING — TEST FOR STENCIL LACQUER ON STEEL AND WESTERN RED CEDAR PANELS

With the approval of the CGSB Committee on Paint Test Methods, this test method is hereby withdrawn. It has been determined that it is no longer referenced in any of the CGSB paint standards.

OFFICE DES NORMES GÉNÉRALES DU CANADA

VIEILLISSEMENT ACCÉLÉRÉ — ESSAI DE PEINTURE-LAQUE À POCHOIR SUR DES PLAQUES EN ACIER ET EN THUYA GÉANT

En accord avec le Comité des méthodes d'essais des peintures, cette méthode d'essai est retirée par le présent avis. Il a été constaté qu'elle n'est plus référencée dans aucune des normes de l'ONGC sur les peintures.

Canada

Canadian General Standards Board

CGSB Ottawa Canada K1A 1G6	Methods of Testing Paints and Pigments	CGSB 1-GP-71
	ACCELERATED WEATHERING - TEST FOR STENCIL LACQUER ON STEEL AND WESTERN RED CEDAR PANELS	METHOD 122.15 June 1980

Supersedes Issue of May 1979

Apply (Method 98.3) two coats of the lacquer to clean steel panels (Method 100.1) and to red cedar panels (Method 97.1). Coat the backs and edges of the panels with 1-GP-93M aluminum paint and condition the panels 7 d under standard conditions (Method 103.1).

Select, measure, expose and examine panels so prepared in accordance with Methods 122.1 and 122.2.

Withdrawn/Retiree

Office des normes générales du Canada

ONGC Ottawa Canada K1A 1G6	Méthodes d'essai des peintures et pigments	ONGC (F)1-GP-71
	VIEILLISSEMENT ACCÉLÉRÉ ESSAI DE PEINTURE-LAQUE À POCHOIR SUR DES PLAQUES EN ACIER ET EN THUYA GÉANT	MÉTHODE 122.15 Juin 1980

Remplace l'édition de mai 1979

Appliquer deux couches de peinture-laque (méthode 98.3) sur des plaques en acier propres (méthode 100.1) et sur des plaques en thuya géant (méthode 97.1). Revêtir le dos et les bords des plaques avec la peinture à l'aluminium 1-GP-93M et les conditionner durant 7 d dans des conditions normales (méthode 103.1).

Puis choisir, mesurer, exposer et examiner les plaques selon les méthodes 122.1 et 122.2.

Withdrawn/Retirée