Historical File Copy

53-D-20 C.Z

Published Published by Authority of the HON. JAMES A. MACKINNON, M.P., Ministeriof Trade and Commerce

DOMINION BUREAU OF STATISTICS

TRANSPORTATION AND PUBLIC UTILITIES BRANCH OTTAMA

Dominion Statistician, S.A. Cudmore, M.A. (Oxon.), F.S.S., F.R.S.C. Chief, Transportation and Public Utilities Branch, G.S. Wrong, B.Sc.

## CHANGES IN SINGLE TRACK MILEAGE OPERATED BY STEAM RAILWAYS OF CANADA, 1943.

	Mileage	: Ir	crease	•
	at		luring	
Name of Railway and Location	Dec. 31,		lear .	Details of Increase or Decrease
	1943		rease-	):
	1010	1200	L Odibo	
CANADIAN NATIONAL AAILMAYS	03 73		07	There is a second of the second
Montreal South (Yard Limit)	81.31	(pad)	.01	Due to rechainage.
to St. Gregoire				
Central Station to Southwark	6.90		2.19	New Line opened from Central Station
E. Yard Limit				to Victoria Bridge
Jct.with St. Hyacinthe Sub.	5.55		0.85	New Line opened from Jct.with St.
M.1.16 to Turcet W. Yard				Hyacinthe Sub. to Hibernia St.
Jct. with St. Hyacinthe			0.12	At St. Henri - Jct. switch relocated.
Central Station to Mile 5.81	5.81	_	0.02	Due to track rearrangement in
Mt. Koyal Sub.				Central Station.
Gremont to Grenville	30.43	_	0.76	Jct.switch at Fresniere relocated -
				New Location Gremont.
Connection to Milton Sub.	0.26		0.05	Main track crossover shortened.
at Georgetown				
Stratford to Palmerton			0.81	Jct.switch at Palmerton relocated.
Burlington to Allandale	85.67	_		Main track crossover at Georgetown
Dat Ting bent of introducto	00.01		0,00	shortened.
Cana Jet. to Canora	54.63		0.01	Due to rechainage.
Rainbow connection to	479.77	-	0 00	Line revision at Mile 105.6 near
Brownsville	210.11	-	0.01	Lempriere.
	14.39		0.01	Jet.switch at Lumby Jet. relocated.
Lumby Jct. to Lumby	7.4 . 0.9	-		occepation at humby occ. retacated.
		_	1.46	
CANADIAN PACIFIC FAILWAY				
Portswitch to Coldwater			.7	ixtension.
			2.0	Correction in Records.
			3.3	Tt M II
		-	2.4	11 11 11
			3.6	
MARKAGOTT CONTROL O MEDITAL DAT		tea-te		
MORRISSEY, FERNIE & MICHEL RY.	5.0	-	.04	Truck abandoned and torn up.
ST. LAWKENCE & ADIRONDACK RY.	60.9		.10	Decrease for remeasurement.
HUDSON BAY RAILWAY				
Mile 13.9			07	Constant de Admodes 3 d
			.07	Spur to Airfield
Mile 506.6		_	.10	Remeasurement of spur to Airfield.
Net change		+	4.88	
SUMMARY				
New Lines				Rechainage 0.22
Relocation				Abandoned track 0.04
Revision				
IMATOTOIL *****	03			+ 4.88



the state of the s

bosensk en maremun en addresse i 1985.

the the format from the late of the late o

At the representations the party of the contract of the contra

abelet proporti se section

water and the second and

designation at larger felt righted tells

AND THE RESERVE OF THE PERSON NAMED AND ADDRESS OF THE PERSON

. The state of the late of the

ACCORDANCE OF THE PARTY OF THE PARTY OF THE PARTY.

1000

DESCRIPTION OF THE PROPERTY OF THE PARTY OF

ting dets. to Daniel to Anna de Santa d

Made of the Motor first and Discontinuous

TE CHESE E ASSESSMENT TO STERLEY