CANADIAN FARM BUILDING CODE 1983

FIRST ERRATA

Issued by the

Associate Committee on the National Building Code National Research Council of Canada Ottawa

Page	Reference	Correction
1	1.2.1.2.	In the second line of the definition of load-sharing system, change "mutally" to read "mutually".
2	1.2.2.2.	Delete the following: "wt weight" "p mass density, kg/m ³ ".
3	Table 2.2.1.A.	Delete title and substitute "Minimum Specified Live Loads Due to Use".
4	2.2.1.3.	In the second line, italicize "live load".
4	2.2.1.5.(4)	Delete the first line and substitute:
		(4) Where an area serves as a place for processing, or for loading or unloading of vehicles, the minimum
5	2.2.1.10.(5)	In the third line beneath the formula, change "Sentence" to read "Article".
5	2.2.1.10.(7)	In the second line, italicize "foundation".
6	2.3.1.2.	Italicize "load-sharing systems".
7	3.1.2.1.	In the fourth line, change "9.10.15." to read "9.10.14."
7	3.1.3.2.	In the first line, italicize "partition".
15	Appendix A 2.2.1.10.(2)	In the tenth line, delete ",H _S ,".
		In the eleventh line, add "H _S ," after "occur,".
18	Appendix A 2.2.1.13.	In the fourth line, change " $V = L/K$ " to read " $V = L/k$ ".
		After the description of ϕ , add:
		" ϕ_1 = angle of friction of material on bin wall".
20-22	Appendix A Table 3	In the title, change "Apparent" to read "Bulk".

Page	Reference	Correction
22	Appendix A Note 2 to Table 3	In the second and fifth lines, change "apparent" to read "bulk".
		In the second, fourth and fifth lines, change "D" to read " ρ ".
23	Appendix A	In the description of ϕ_1 , change "Tan ϕ_1 " to
	2.2.1.13.	read "tan ϕ_1 ".
27	Appendix A 3.1.5.1.	In the second line of Note (1), change "Article 9.10.4.1." to read "Article 9.10.3.1."